
T_195 R 78 M W



LEGEND

○ = Corner having information on form 7100-52 in this file.

FILING INSTRUCTION

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.

CORNER RECORD FILE GUIDE (Rectangular Surveys)

7100-55 (2/67)

D-7100-52 J (10/78) USDA-FOREST SERVICE Index File No. 2563 T 9 5. R. 7 E. R.D Merid. WILLAMETTE N.F	CORNER RECORD (SEARCH) Tract or Cor. N-25 (Ref. FSM 7151.4) Survey No. No. No. No. Sec. 24 DESCHUTES State OREGON SW Cov. Sec. 18
	SEE: N-01
	SEE: N-01 7.195. R.8E.

USDA-FOREST SERVICE Index File No. 2565 CORNER RECORD (SEARCH) Tract or Survey No	Cor. P-25 No. P-25 E/4 Cor. Sec. 24 W/4 Cor. Sec. 19
SEE: P-01	
SEE: P-01 -7.195. R.8E.	
	n/V9

D-7100-52 J (10/78) USDA-FOREST SERVICE Index File No		Cor. R-25 No. R-25 Ve Cor Sec 25
		our se.//
	SEE: R-01 T.195. R.8E.	
		(NO

D-7100-52d (10/78) USDA-FOREST SERVICE Index File No.			Cor. No. 7-25 IS E/4 Sec. 25- W/4 Sec. 30
	SEE:	T-01 Rie	
	T. 195.	RIE	
			4
			1

USDA-FOREST SERVICE Index File No	Cor. V-25 No. V-25 SE Cor Sec 25 NW Cor Sec 31
SEE: V-01 T195 R8E	
	8618

T /9 S. R. 7 E. R.D. BEND (Ref. FSM 7151.4) Merid. WILLAMETTE N.F. DESCHUTES State OR	Tract or Cor. X-25 Survey No. No. X-25 SCHUTES E/4 Cov Sec 36 EGON W/4 Cor Sec 3/
SEE: X-0	
SEE: X-0 T.195. R	8 E.
	$\langle \hat{O} \setminus Q \rangle$

USDA-FOREST SERVICE Index File No. 2575 T 19 S. R. 7 E. R.D. BENUD County DESCHUTES SE COR. Sec. 36 Merid. WILLAMETTE N.F. DESCHUTES State OREGON NW Cor Sec G.
SEE: Z-01 T195 R8E