

SURVEY DIAGRAM

Sec. 36 (35)
Pts A, B

LEGEND

○ = Corner having information on form
7100-52 in this file.

FILING INSTRUCTIONS

Draft tract diagram in space at left.
File 7100-52 card record in numerical
sequence behind tract file guide as the
data are obtained and recorded. Show
by above symbol, on the tract diagram
those corners having data in this file.

CORNER RECORD (SEARCH)


Index
File No. _____
T 11 S R 8 E
Meridian W.M.

R.D. Sisters
N.F. Deschutes

County Jefferson
State Oregon

Tract or
Survey No. 1113 Cor.
No. A

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Not previously set.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

Estab. By _____
Agency _____

Signature [Signature]

Title L.S.

Division _____

Headquarters _____

Date 9-18-04 7100-52

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

A 2 1/2 in. brass cap on a 2 1/2 in. diam.
by 30 ins. galvanized iron post 22 ins. in the
ground, clear DEEP-1 magnet at base.

ACCESSORIES: DESCRIBE NEW BTS, WITNESS OBJECTS, ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 2 in. aluminum cap on a 5/8" by 30" rebar marked RM-1 LS
2648 2004 with arrow bears S 40° W 28.0 ft.
A 2 in. aluminum cap on a 5/8" by 30" rebar marked RM-2 LS
2648 2004 with arrow bears N 40° W 24.0 ft.

Work Done By Wallowa Associates Title PLS State Registration No. or Agency 2648
Certified Cor. Record Prepared? Yes No ROS Filed At: Jefferson County Date: 2004

REMARKS

Idx. #

R. 8 E T. 11 S R. W.M.

Or Surv. No.

Cor. No.

A

Index
File No. _____

CORNER RECORD (SEARCH)


Tract or
Survey No. 1113 Cor. No. B

T 11 S R 8 E
Meridian W.M.

R.D. Sisters
N.F. Deschutes

County Jefferson
State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Not previously set.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

Estab. By _____
Agency _____

Signature [Signature]

Title L.S.

Division _____

Headquarters _____

Date 9-18-04

7100-52

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

A 2 1/2 in. brass cap on a 2 1/2 in. diam.
by 30 ins. galvanized iron post 25 ins. in the
ground, clear DEEP-1 magnet at base, with
rock collar.

ACCESSORIES: DESCRIBE NEW BTS, WITNESS OBJECTS, ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A ponderosa pine, 15 ins. diam., bears N 32° E 39.4 ft marked
MJW PT B BT.
A Douglas fir, 14 ins. diam., bears N 89° W 53.5 ft. marked
MJW PT B BT.

Work Done By Wallowa Associates Title PLS State Registration No. or Agency 2648
Certified Cor. Record Prepared? Yes No ROS Filed At: Jefferson County Date: 2004

REMARKS

Idx. #

R. 8 E T. 11 S R. W.M.

Or Surv. No.

Cor. No.

B