

119 Mt. Jeff. WB #1113

TRACT OR SURVEY NO.

FOREST

SURVEY DIAGRAM

Sec. 31

Pts. AA, AAA

LEGEND

○ = Corner having information on form 7100-52 in this file.

FILING INSTRUCTIONS

Draft tract diagram in space at left.
File 7100-52 card record in numerical sequence behind tract file guide as the data are obtained and recorded. Show by above symbol, on the tract diagram those corners having data in this file.

Index
File No. 9
T 11 S R 8 E
Meridian W.M.


CORNER RECORD (SEARCH)

Tract or
Survey No. 1113 Cor. No. AA

R.D. Sisters
N.F. Deschutes

County Jefferson
State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Not previously set.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

Etab. By _____
Agency _____

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature [Signature] Title L.S. Division _____ Headquarters _____ Date 9-18-04 7100-52

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

A 2 1/2 in. brass cap on a 2 1/2 in. diam.
by 30 ins. galvanized iron post 22 ins. in the
ground, clear DEEP-1 magnet at base, with
a rock collar.

ACCESSORIES: DESCRIBE NEW BTS, WITNESS OBJECTS, ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A Douglas fir, 21 ins. diam., bears N 12° E, 43.4 ft. marked
MJW PT AA BT.

A Ponderosa Pine, 26 ins. diam., bears S 44° E, 31.6 ft. marked
MJW PT AA BT.

Work Done By Wallowa Associates Title PLS State Registration No. or Agency 2648

Certified Cor. Record Prepared? Yes No ROS Filed At: Jefferson County Date: 2004

REMARKS

Idx. #

R. 8 E T. 11 S R. W.M.

Or Surv. No.

Cor. No.

AA

Index
File No.

CORNER RECORD (SEARCH)


Tract or
Survey No. 1113 Cor.
No. AAA

T 11 S R 9 E
Meridian W.M.

R.D. Sisters
N.F. Deschutes

County Jefferson
State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Not previously set.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

Estab. By _____

Agency

Signature 

Title
L.S.

Division

Headquarters

Date

9-18-04

7100-52

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

A 2 1/2 in. brass cap on a 2 1/2 in. diam. by 30 ins. galvanized iron post 24 ins. in the ground, clear DEEP-1 magnet at base, with a rock collar.

ACCESSORIES: DESCRIBE NEW BTS, WITNESS OBJECTS, ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A Douglas fir, 27 ins. diam., bears N 81° E, 13.0 ft. marked MJW PT AAA BT.
A 2 in. aluminum cap on a 5/8" by 30" rebar marked RM-1 23.7 LS 2648 2004 with arrow bears N 33° W 23.7 ft.

Work Done By Wallowa Associates Title PLS State Registration No. or Agency 2648
Certified Cor. Record Prepared? Yes No ROS Filed At: Jefferson County Date: 2004
REMARKS

Idx. #

R. 9 E T. 11 S R. W.M.

Or Surv. No.

Cor. No.

AAA