

T 13S. R 8E M W 11

# LEGEND

○ = Corner having information on form 5680-2 in this file.

LEGEND CONFORMS TO  
REPORTING FORM 9179


JE  
Mt. Jefferson WA CDA IN BACK

## FILING INSTRUCTION

File 5680-2 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 5680-2 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.



CORNER RECORD FILE GUIDE (Rectangular Surveys)

USDA-FOREST SERVICE GPO 940-117


Index

File No.

T 13 S R. 8 E

Merid.

CORNER DIAGRAM



T 13 S R 8 E

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

Signature W. Ham & S. Ketch

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_

Cor.

No. \_\_\_\_\_

R.D. Sisters

County

Jefferson

N.F. \_\_\_\_\_

State

DESCRIBE CORNER MONUMENT FOUND

SFNF

Area has been heavily logged.  
Found a piece of an old K-Tag & an E/w  
Blaze line, Tag in approx. location of protracted  
corner 33/39 T 12 S R 8 E

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Division

Headquarters

Date 8/98 7100-52-(3/68)

# CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_

10

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

12

13

Index

File No. 2351

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

T 13 S. R. 8 E.

R.D. SISTERS

Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. A-23

Merid. WILLAMETTE

N.F. DESCHUTES


County JEFFERSON

State OREGON

SC 3/4 Sec 36 ONLY

SEE : Z-23

T12S R8E



C.C. NOT SET

EV. FD.



2351

A-23

Index  
File No.

2551

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No.

Cor.  
No.

A-25

T 13 S. R. 8 E.

R.D.

31 STERS

County

JEFFERSON

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

NE Cor Sec 1

SW Cor Sec 31

SEE: 2-01  
T12S R9E

EN. P.D.

2551

A-25

Index

File No. \_\_\_\_\_

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_

Cor.


No. \_\_\_\_\_

T 13 S R. 8 ER.D. Sisters County Jefferson

Merid. \_\_\_\_\_

N.F. \_\_\_\_\_ State \_\_\_\_\_

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

SFNF - Approx position determined by  
GLO Brg & Dist from Found cor. 1 mile S,  
Location by PLGR GPS

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF - Clearcut & burnt

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

Signature W. Ham & S. Kieth Title \_\_\_\_\_

Division \_\_\_\_\_

Headquarters \_\_\_\_\_

Date 8/98 7100-52-(3/68)

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_


REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

Index

File No. **2355**T **135** R. **8 E**Merid. **W mt**

CORNER DIAGRAM



## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_

Cor.

No. **E-23**R.D. **SISTERS**County **JEFFERSON**Stn. **1/4 COR.**N.F. **DESCHUTES**State **OREGON**Sec. **1/12**

## DESCRIBE CORNER MONUMENT FOUND

**STAKE NOT IN PLACE**

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

**25" PP BRG S 18° W @ 19' " 1/4 S "**

**29 1/2" PP BRG N 22° E @ 6' " 1/4 S "**

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

**SECTION LINE MARKER ON ABBOTT BUTTER RD.**

**6 CH. WEST FROM 1/4 COR.**

Signature

**C. MINKS**Title **FORESTER**

Division \_\_\_\_\_


Headquarters \_\_\_\_\_

Date **1956** 7100-52 (3 68)

# CORNER RECORD (PERPETUATION)

MONUMENT  
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. 2355 T. 135. R. 8 E. M.

Tract or Surv. No.

Cor. 6-23

Index

File No. 2555

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

E-25

T 13 S. R. 8 E.

R.D. SISTERS

County JEFFERSON

STD. Sec. Cor.

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

SEC. 1 16

12/7

SEE T13S R9E

E-1

EV. FD.



2555

E-25

Index  
File No. 2557

CORNER RECORD (SEARCH)  
(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. 6-25

T 13 S. R. 8 E. R.D. SISTERS County JEFFERSON Std. 1/4 COR

Merid. WILLAMETTE N.F. DESCHUTES State OREGON Sec 12/7

SEE T13S R9E

6-1

2557

G-25

## USDA-FOREST SERVICE

Index

File No. 0959T 13 S R 8 EMerid. WMT

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. SISTERS

County

Jefferson

N.F. \_\_\_\_\_

State \_\_\_\_\_

Tract or

Survey No.


#1037

Cor.

No.

J-09

## CORNER DIAGRAM



## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

7

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

8

## DESCRIBE CORNER MONUMENT FOUND

FOUND - Original stone 25"x9"x8" rising 10". set firmly in the ground  
mkd. with 4 grooves on the S. and E. faces, from which:  
A stump hole at the NE BT location. No other evidence.  
No evidence of SE BT.  
A stump hole at the SW BT location. No other evidence.  
A burnt pine snag, 18" dia.. N.10°W.. 56 lks. (36.8ft.) with burnt blaze.  
No other evidence.

2

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3

Signature

Walt Muller

Title

PLS

Division

CS

Headquarters

SO

Date

8/98

FS-7100-52 (3/68)


5

# CORNER RECORD (PERPETUATION)

## MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET - A 2 1/2" dia. X 30" long steel pipe surmounted with a 2 1/2" dia. brass cap, rising 4". Original stone buried alongside. A steel fence post bears North, 3 ft.  
 A Ponderosa Pine 9" dia. bears N.48°E., 43.2 ft. dist. mkd. X BT.  
 A Lodgepole Pine 13" dia. bears S.12°E., 17.0 ft. dist. mkd. X BT.  
 A White Pine, 13" dia., bears S.37°W., 56.2 ft. dist., mkd. T13S R8E S17 BT.  
 A Ponderosa Pine 22" dia. bears N.31°W., 88.3 ft. dist. mkd. T13S R8E S8 BT.

A Location Poster on spur road bears East, approximately 800 ft.  
 Wilderness Boundary Point "Q" bears approximately N.45°E., 725 ft.



## ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By: Walt Miller Title: PLS Date: 8/98 State Registration No. 211  
 or Agency: \_\_\_\_\_  
 Certified Cor. Record Prepared? (Yes) No Filed At: Jeff. Co. Date: 5/3/99

11

### REMARKS

4. GLO record by McQuinn - Set a basalt stone 16x14x10 ins. 11 ins. in the ground for cor. of secs. 8, 9, 16 and 17, marked with 4 notches on S. and E. edges; from which:  
 A pine, 10 ins. diam. bears N.70°E., 55 lks. dist. marked T.13 S.R.8 E. S9. B.T.  
 A pine, 10 ins. diam. bears S.75°E., 27 lks. dist. marked T.13 S.R.8 E. S16. B.T.  
 A pine, 12 ins. diam. bears S.46°W., 48 lks. dist. marked T.13 S.R.8 E. S17. B.T.  
 A pine, 8 ins. diam. bears N.10°E., 52 lks. dist. marked T.13 S.R.8 E. S8. B.T.

12


Index File No. 0959 T. R. M. Tract or Surv. No. Cor. JO9

13

## LAND CORNER RECORD

J-13 5680-2

1. T 13S R 8E No. J13 Cor. Sec Mer. Will State Oregon (Rectangular)  
 2. Corner Status \_\_\_\_\_ N. F. Deschutes Dist. Sisters



## 7. Photo Identification

Photo No. \_\_\_\_\_

Ident. By: \_\_\_\_\_

## 3. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

## . Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

e-estab. \_\_\_\_\_ Survey \_\_\_\_\_

and Status \_\_\_\_\_

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: \_\_\_\_\_

5. Investigation Notes: A White Fir stub 15" d. bears S80°E, 33 lks. dist., with scribe marks T13S, R8E, S15.  
 A W. Fir 20" d. bears S51°W, 62 lks. dist. with scribe marks 13S, R8E S, W. Fir stump 26" D. bears N50°W, 30 lks. dist. with scribe marks S R8E.

6. Signed \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

# PERPETUATION RECORD

10. Monument:

Brass Cap

T13S R8E

59/510  
516/515  
1966

11. Accessories

16" W. Fir N20°E 24½ lks.

26" W. Fir S82 3/4°E 34½ lks.

11" W. Fir S56°W 58½ lks.

17" W. Fir N69½W 52½ lks.

Plus old ones

12. Set By

BLM

Title

License

Agency

Date

1966

13. Recorded By

(Agency)

Field Book

Page

Volume

Page

(Date)

(City)

(County)

(State)

14. Remarks:

Aug 1998

Walt Miller FD A 2½" dia. BLM BCSP rising 2" from which

A 17" WF brs N20°E @ 16.2' w/overgrown face

A fir <sup>windfall</sup> snag S83°E @ 22.5'

A fir <sup>12"</sup> snag (corn. BT) brs S76°E @ 21.0' w/face & scrub. vls

A 17" dia fir snag brs N69°W @ 34.7' w/face & scrub. vls

1359

J-13

## LAND CORNER RECORD

J-15 5680-2

1. T. 13S R. 8E No. J15 Cor.  $\frac{1}{4}$  Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Established Sept. 1895. Set a fir post  $3\frac{1}{2}$ ' long, 3" sq., 24" in the ground --- marked  $\frac{1}{4}$ S on N face---see #14.

5. Investigation Notes: No corner, as possible corner was destroyed by a skid trail.

No definite B.T. However, a rotten stump shows signs of axe choppings on scars. (This BT is in correct relation if corner is assumed from aluminum tag on another tree.) I went ahead and pricked the assumed corner.

About 2.2 mi. W of intersection of Rd #1319 & Rd #1210 follow spur Rd. #40 to spur junction of #44 and #45. The evidence lies about 180' SE. No definite BT's or corners - needs to be re-established.

6. Signed O. Thingvall Title Hwy. Eng. Date 5-21-62

7. Photo Identification 7-13-59  
Photo No. EGI-50-35  
Ident. By O. Thingvall

8. Plane Coordinate Position Data  
State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
Field Book No. \_\_\_\_\_  
Where Filed \_\_\_\_\_

9. Evaluation  
Authentic \_\_\_\_\_  
Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_  
Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_  
Land Status \_\_\_\_\_

10



# PERPETUATION RECORD

10. Monument: Brass cap

$\frac{1}{4}$   $\frac{S10}{S15}$

T13SR8E  
1966

11. Accessories 12" White Fir N  $34\frac{1}{2}^{\circ}$ W 23 $\frac{1}{2}$  lks.  
13" White Fir S  $2\frac{1}{2}^{\circ}$ E 42 lks.

Plus old one.

|                                   |              |                             |                                               |
|-----------------------------------|--------------|-----------------------------|-----------------------------------------------|
| 12. Set By <u>BLM</u> Title _____ |              | Field Book _____ Page _____ |                                               |
| License _____                     | Agency _____ | Date <u>1966</u>            | 13. Recorded By _____ Volume _____ Page _____ |
|                                   |              |                             | (Agency)                                      |
|                                   |              |                             | (Date) (City) (County) (State)                |

14. Remarks: (4)


A larch 18" in diam. bears N05°E, 24 lks dist., marked  $\frac{1}{4}$ S, B.T.  
" " 7" " " S15°W, 11 $\frac{1}{2}$  lks. dist., marked  $\frac{1}{4}$ S, B.T.

# LAND CORNER RECORD

J-17 5680-2

1. T 13S R 8E No. 117 Cor. Sec. Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-13-59

Photo No. EGT-50-35

Ident. By: O. Thingvall

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Sept. 22, 1895 - set a basalt stone 15"x12"x10" 10" in the ground---marked with 4 notches on S, and 2 notches on E edges---see #14.

5. Investigation Notes: Found stone 15"x12"x10" - 2" above ground in good condition. There are 4 notches on S. face and 2 notches on E. face. A 23" W.F. stump bears N73°W, 16' dist., with T13S, R8E, S10, B for markings. A 35" D.F. bears N30°E, 26.6' dist. with no visible markings. (Axe work though.) A 23" W.F. stump bears S45°W, 50.0' dist., with no visible markings.

About 2.2 mi. from intersection (W) of Rd. #1319 and Rd #1210, a spur rd. #40 leads to spur rd. #46. From the sharp turn to the right (near the end of spur) a red ribbon bears S40°E approx. 450'. This ribbon is approx. 650' due W. of sec. cor.


6. Signed O. Thingvall Title Hwy. Eng. Date 5-21-62

## LAND CORNER RECORD

J-17 5680-2

1. T 13S R 8E No. J17 Cor. Sec. Mer. Will State <sup>(Rectangular)</sup> Oregon N. F. Deschutes Dist. Sisters

## 2. Corner Status



## 7. Photo Identification 7-13-59

Photo No. EGT-50-35

Ident. By: O. Thingvall

## 8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Etab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

## 9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

## 3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Sept. 22, 1895 - set a basalt stone 15"x12"x10" 10" in the ground---marked with 4 notches on S, and 2 notches on E edges---see #14.

5. Investigation Notes: Found stone 15"x12"x10" - 2" above ground in good condition. There are 4 notches on S. face and 2 notches on E. face. A 23" W.F. stump bears N73°W, 16' dist., with T13S, R8E, S10, B for markings. A 35" D.F. bears N30°E, 26.6' dist. with no visible markings. (Axe work though.) A 23" W.F. stump bears S45°W, 50.0' dist., with no visible markings.

About 2.2 mi. from intersection (W) of Rd. #1319 and Rd #1210, a spur rd. #40 leads to spur rd. #46. From the sharp turn to the right (near the end of spur) a red ribbon bears S40°E approx. 450'. This ribbon is approx. 650' due W. of sec. cor.

6. Signed O. Thingvall Title Hwy. Eng. Date 5-21-62

# PERPETUATION RECORD

10. Monument: Brass cap

T13S R8E

S 10 | S 11  
S 15 | S 14

1966

11. Accessories 10" W. Fir S49°E 10 $\frac{1}{2}$  lks.  
8" W. Fir S78 $\frac{1}{2}$ °W 10 lks.  
18" W. Fir N23 $\frac{1}{4}$ °W 14 lks.  
18" W. Fir N71°E 31 lks.

Plus old ones.

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By BLM Title \_\_\_\_\_  
License \_\_\_\_\_ Agency \_\_\_\_\_ Date 1966

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_  
(Agency)  
(Date) (City) (County) (State)

14. Remarks: (4)  
A fir 28" in diam. bears N29 $\frac{1}{2}$ °E, 40 lks. dist., marked T13S, R8E, S11, B.T.  
" larch 18" in " " S24 $\frac{1}{2}$ °E, 40 lks. " " " S14, "  
" " 22" in " " S44°W, 76 lks. " " " S15, "  
" " 24" in " " N71°W, 25 lks. " " " S10, "

Index

File No.

2159

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.

Cor.

No.

J-21

T 13 S. R. 8 E.

R.D.

Sisters

County

Jefferson

NW

Cor. of

Merid. Willamette


N.F. Deschutes

State Oregon

Section 13

## CORNER DIAGRAM per legend

## DESCRIBE CORNER MONUMENT FOUND



Found 3/4" Brass Cap on a 2 1/2" iron post rising 5".

## Bearing Trees

- 1) 13" White Fir, N20°E at 89.8 ft., Healed over (BLM)
- 2) 8" White Fir, S20°W at 45.2 ft., Healed over (BLM)
- 3) 12" White Fir stump, N31W at 52.8 ft., marked T13SR8ES11BT (BLM)
- 4) 14" White Fir S12°E at 72.3 ft., Healed Over (BLM)
- 5) 25" White Fir snag, N44°E at 7.3 ft., visible scribe '13' (GLO)
- 6) 17" " " " , S69°E at 19.8 ft., Marked T13SR8ES13BT (GLO)
- 7) 18" " " stump, N29°W at 7.6 ft., " T13SR8ES11BT (GLO)

## OFFICIAL ACCESSORIES FOUND

## PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

7

## CORNER LEGEND:

FS or Unverified  
Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division


Headquarters

Date

## CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPEL



9

ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

New Bearing Tree

8" White Fir bears N84°W at 29.50 ft. to a 60-Penny spike in the North base marked T13SR8ES11BT.

7/05 - ALL OK  
WU

By W. Miller

10

Work Done By W. Miller  
Flat of Cor Record Prepared

ORIGINAL DESCRIPTION: Set a fir post  $\frac{3}{4}$  feet long, 4 ins. sq.

24 ins. in the ground, for cor. of secs.

11, 12, 13 and 14, marked: T.13S., S.12, on NE; R.8E., S.13, on S.E.; S.14, on S.W. and S. 11, on N.W. faces, with 4 notches on S. and 1 notch on E. edges, from which

A larch, 18 ins. diam., bears N.44°E. 10 lks. dist., marked T.13S., R.8E., S.12, B.T.;

A larch, 16 ins. diam., bears S.67°E. 29 lks. dist., marked T.13S., R.8E., S.13, B.T.;

A larch, 24 ins. diam., bears S.74°W. 11 lks. dist., marked T.13S., R.8E., S.14, B.T.;

A larch, 18 ins. diam., bears N.31°W. 11½ lks. dist., marked T.13S., R.8E., S.11, B.T.

B.L.M.-- 1966 by James E. Jelley-- Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with a brass cap mkd. ( as shown below ) from which new bearing trees

- 1) A white fir, 8 ins. diam., bears N.20°E., 136 lks. dist., mkd. T13SR8ES12BT.
- 2) A white fir, 9 ins. diam., bears S.12½°E., 109½ lks. dist., mkd. T13SR8ES13BT.
- 3) A white fir, 7 ins. diam., bears S.20°W., 68½ lks. dist., mkd. T13SR8ES14BT.
- 4) A white fir, 14 ins. diam., bears N.31½°W., 80 lks. dist., mkd. T13SR8ES11BT.

12

13

J-21

History  
of  
Surveys,  
G.L.O.,  
etc.

Index File No.

T. S., R. E., W.M.

2159

13

8

Index

File No.

2359

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.

Cor.

No.

J-23

T 13 S. R. 8 E. R.D.

Sisters

County

Jefferson

S/4

Cor. of

Merid. Willamette


N.F. Deschutes

State Oregon

Section 12

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND



Found 3/4" Brass Cap on a 2 1/2" iron post rising 5" with stone marked 1/4 alongside cap.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

1) 18" White Fir bears N14°E at 19.5 ft., in good shape and healed over. ( B.L.M. )

Found 31" White Fir Snag, S39°E at 83.5 ft., marked 1/4 SBT. ( G.L.O. )

## PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

## CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

## CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Buried The Original Stone on the West side of the cap.

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

New B.T.

9" White Fir bears S34°E at 18.77 ft. to a 60-Penny spike in the SW base, marked 13S4/1BT.

ALL OK  
7/05 WNWWork Done By W. Miller

Title

PLS

Date 11/85State Registration No.  
or Agency

2111

Certified For Record Prepared? (Yes) No

Filed At

Jolt

Co. Surveyor's Office

Date

11/85

History  
of  
Surveys,  
G.L.O.,  
etc.

Set a basalt stone 12x8x6 ins. 8 ins. in the ground, for 1/4 sec. cor., marked 1/4 on N. face, from which

A larch, 16 ins. diam., bears S. 41° E., 1 ch. and 26 lks. dist., marked 1/4S., B.T.

A pine, 32 ins. diam., bears N. 12° W., 13 lks. dist., marked 1/4S., B.T.

B.L.M.-- July, 1966, by James E. Jelley-- Set an iron post, 28 ins. 2 1/2 ins. diam., 24 ins. in the ground, with brass mkd. ( as shown below ) from which new bearing trees

1) A fir, 14 ins. diam., bears N. 14° E., 29 1/2 lks. dist., mkd. 1/4S12BT.

2) A white fir, 8 ins. diam., bears S. 27 1/4° W., 14 lks. dist., mkd. 1/4S13BT.

Index File No.

Description of Corner Evidence Found.

2359

13

8

J-23



## USDA-FOREST SERVICE

Index

File No.

2559

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

J-25


T 13 S R. 8 E

R.D. SISTERS County Jefferson

Merid. Wmr

N.F. Deschutes State Oreg. NE Cor S. 13

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

DES

Found 2 1/2" Steel Pipe with 3 1/4" BLM Brass Cap rising 8" with BT's as follows:  
 13" fir in NW 1966 record location, Standing Dead.  
 13" fir in NE 1966 record location, Dead, Down and Burnt Log.  
 13" fir in SE 1966 record location, Standing Live.  
 13" fir in SW 1966 record location, Dead, Down and Burnt Log.

## PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

## PLANE COORDINATE POSITION DATA

State Zone

X

Y

Estab. By

Agency

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Walt Miller

Title

PLS

Division

CS

Headquarters

SO


Date

7/05

FS-7100-52 (3/68)

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

2" AC on 1/2"x24" rebar, bears N 56° E @ 8.0', mkd "B01 PLS2111 2005"  
 2" AC on 1/2"x24" rebar, bears S 50° W @ 31.2', mkd "B02 PLS2111 2005"  
 2" AC on 1/2"x24" rebar, bears N 50° W @ 7.5', mkd "B03 PLS2111 2005"

Work Done By Walt Miller Title PLS Date 7/05 State Registration No. 2111  
 Certified Cor. Record Prepared ? ☒ No Filed At: Jeff co. Date 7/27/06

## REMARKS

1881, GLO, Thomas C. Judkins established corner.  
 1895, GLO, Redescribed by William E. Campbell.  
 1966, BLM, James E. Jelley set an iron post, 28" long, 2 1/2" diam., 24" in the ground, with brass cap (marked as shown below), from which new BT's:  
 1) A fir, 10" diam., bears N. 63 3/4° E., 41 1/2 links. dist., mkd. "T13S R9E S7 BT"  
 2) A fir, 6" diam., bears S. 67° E., 9 links. dist., mkd. "T13S R9E S18 BT"  
 3) A fir, 8" diam., bears S. 53 1/4° W., 48 1/2 links. dist., mkd "T13S R8E S13 BT"  
 4) A white fir, 7" diam., bears N. 29° W., 6 links. dist., mkd "T13S R8E S12 BT"

Index File No.

2559

T.

13

R.

8

M. WMT

Tract or Surv. No.

GPO: 1986 O- 439-095

Cor.


J-25 13

# LAND CORNER RECORD

L-135680-2

1. T 13S R 8E No. 113 Cor.  $\frac{1}{4}$  Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

## 2. Corner Status



## 7. Photo Identification 7-13-59

Photo No. EGI -49-127

Ident. By: O. Thingvall

## 8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

## 9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Sept. 1895 - Set a fir post  $3\frac{1}{2}'$  long,  $3''$  sq.,  $24''$  in the ground---marked  $\frac{1}{4}$ S, on W face. A larch  $22''$  in diam. bears  $S53^\circ E$ ,  $61\frac{1}{2}$  lks. dist., marked  $\frac{1}{4}$ S, B.T. A pine  $16''$  in diam. bears  $S79^\circ W$ ,  $58$  lks. dist., marked  $\frac{1}{4}$ S, B.T.

5. Investigation Notes: Stake---not original. A  $39''$  W. Fir bears  $S53^\circ E$ ,  $40.2$  ft. dist., marked  $\frac{1}{4}$ .

From southern end of Rd #1319 drive in to about Round Lake. Spur Rd #7 (1319-C) turns off to the right (E to SE). Drive in about  $0.5$  mi., W edge of wide opening along spur rd., corner is about  $50'$  south of spur.

6. Signed O. Thingvall Title Hwy Eng Date 6-25-62

# PERPETUATION RECORD

10. Monument: Brass Cap  $\frac{1}{4}$   
 S16 | S15  
 T13S R8E  
 1966
11. Accessories 9" PS Fir S34°E 55lks.  
 7" LP Pine N223/4°W 7½ lks.
- Plus old ones.

|                                             |  |                                               |         |
|---------------------------------------------|--|-----------------------------------------------|---------|
| 12. Set By <u>BCLM</u> Title _____          |  | Field Book _____ Page _____                   |         |
| License _____ Agency _____ Date <u>1966</u> |  | 13. Recorded By _____ Volume _____ Page _____ |         |
|                                             |  | (Agency)                                      |         |
|                                             |  | (Date)                                        | (City)  |
|                                             |  | (County)                                      | (State) |


14. Remarks:

# LAND CORNER RECORD

L-17 5680-2

1. T 13S R 8E No. 117 Cor.  $\frac{1}{4}$  Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

## 2. Corner Status



## 7. Photo Identification EGI

Photo No. 7-13-59, 50-34

Ident. By: O. Thingvall

## 8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

## 9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

## 3. Original Description Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Sept. 1895 - Set a fir post  $3\frac{1}{2}'$  long,  $3''$  sq.,  $24''$  in the ground---marked  $\frac{1}{4}S$  on W face.

A larch  $28''$  in diam. bears  $S30^{\circ}E$ , 7 lks. dist., marked  $\frac{1}{4}S$ , B.T.

A larch  $10''$  in diam. bears  $S69^{\circ}W$ ,  $44$  lks. dist., marked  $\frac{1}{4}S$ , B.T.

5. Investigation Notes: Found stone & post  $8'' \times 6'' \times 5''$  -  $5''$  above the ground; there isn't any marks on stone. I believe that the corner is not in correct position. A  $16''$  white fir has  $\frac{1}{4}S$ , B. visible, and a rotten stump with a piece on the ground marked  $\frac{1}{4}S$ , B.T.

Suggest monumentation. The existing corner is  $9'$  NW from my estimate of the original corner.

From Rd #1319, turn off on #1319-C and take road that goes to pond in sec. 14, T13S, R8E. Turn left at pond and proceed up spur #9 about  $0.4$  mi. to sec. line marker. Corner is about  $500'$  south.

6. Signed O. Thingvall Title Hwy Eng Date 5-14-62

# PERPETUATION RECORD

10. Monument: Brass Cap

$\frac{1}{4}$

S15 / S14

T13S R8E

1966

11. Accessories 9" D. Fir N83°W 26 $\frac{1}{2}$  lks.  
6" W. Fir S60 $\frac{1}{2}$ °E 41 lks.

Plus old ones.

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By BLM Title \_\_\_\_\_

License \_\_\_\_\_ Agency \_\_\_\_\_ Date 1966

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_

(Agency)

(Date)

(City)

(County)

(State)

14. Remarks:

USDA-FOREST SERVICE

Index  
File No. 2161

**CORNER RECORD (SEARCH)**  
(Ref. FSM 7151.4)


Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. L-21

T 13 S R. 8 E R.D. SISTERS County Jefferson W 1/4 Cor

Merid. Wmr N.F. Deschutes State OR Sec. 13

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found 3 1/4" BLM Brass Capped Steel Pipe and BT's as follows:

- A Burnt Log in 1966 NE record location.
- A Root Hole in 1966 SW record location.
- A Burnt Root Hole in 1985 NE record location.
- A Live Standing White Fir in 1985 SW record location.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature  
Walt Miller

Title  
PL

Division  
CS


Headquarters  
SO

Date  
7/05

FS-7100-52 (3/68)

# CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

- 2" AC on 1/2" x 24" rebar, bears N 44° E @ 6.0', mkd "B01 PLS2111 2005"  
 2" AC on 1/2" x 24" rebar, bears S 40° E @ 5.9', mkd "B02 PLS2111 2005"  
 2" AC on 1/2" x 24" rebar, bears N 47° W @ 5.6', mkd "B03 PLS2111 2005"

Work Done By Walt Miller Title PLS Date 7/05 State Registration No. 2111  
 or Agency  
 Certified Cor. Record Prepared ? ☒ Yes No Filed At: Jeff Co. Date 7/17/06

1966, BLM, James E. Jelley set an iron post, 28" long, 2 1/2" diam., 24" in ground, with brass cap marked (as shown below) from which new BT's:

- 1) A white fir, 18" diam., bears N 54 1/2° E., 41 links. dist., mkd "1/4 S13 BT"
- 2) A white fir, 14" diam., bears S 15 1/2° W., 61 links. dist., mkd "1/4 S14 BT"

1985 MF#156046, Walt Miller found 3 1/4" brass cap on a 2 1/2" iron post rising 6" from which:

- 1) 15" white fir stump, N54°E at 27.1 ft., marked "4S13BT"
- 2) 17" white fir snag, S15°W at 40.3 ft., healed over.

Set new Bearing Trees:

- 1) 15" White Fir bears N79°E at 23.16 ft. to a 60-Penny spike in South base, marked "1/4S13BT"
- 2) 8" White Fir bears S88°W at 8.77 ft. to a 60-Penny spike in South base, marked "1/4S14BT"

Index File No. 2161 T. 13 R. 8 M. Lot 1 Tract or Surv. No. Cor. 6-21  
 GPO: 1986 O-439-095



## USDA-FOREST SERVICE

Index

File No. 2561

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. \_\_\_\_\_

Cor.

No. L-25T 13 S R. 8 ER.D. Sisters County JeffersonMerid. W MTN.F. Deschutes State OregonE 1/4 Cor Sec. 18

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

Found 3 1/4" BLM BC on 2 1/2" Steel Pipe and BT as follows:  
26" Fir in GLO SE record location (Standing Live)  
BT in 1966 SE Location is gone, found root hole.  
DESC BT in 1966 SW Location is gone, falls in skid road.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Walt Miller

PLS

CS


SO

7/05

5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

2" AC on 1/2" x 24" rebar, N 38° E @ 15.4', mkd. "B01 PLS2111 2005"  
 2" AC on 1/2" x 24" rebar, S 49° W @ 21.7', mkd "B02 PLS2111 2005"  
 2" AC on 1/2" x 24" rebar, N 48° W @ 19.1', mkd "B03 PLS2111 2005"

Set B0's in rock collar.

Work Done By Walt Miller Title PLS Date 7/05 State Registration No. 2111  
 or Agency

Certified Cor. Record Prepared ? Yes No Filed At: PLS CO. Date 7/18/06

## REMARKS

1881, GLO, Thomas C. Judkins established corner.  
 1966, BLM, James E. Jelley set an iron post, 28" long, 2 1/2" diam., 24" in the ground, with brass cap  
 mkd (as shown below) From which new bearing trees:  
 1) A fir, 8" diam., bears S. 20° E., 20 links. dist., mkd "1/4 S18 BT"  
 2) A white fir, 5" diam., bears S. 30 1/2° W., 22 1/2 links dist., mkd "1/4 S13 BT"

Index File No. 2561 T. 13 R. 8 M. Walt Tract or Surv. No. Cor. L-25  
 GPO: 1986 O- 439-095

## USDA-FOREST SERVICE

Index

File No.

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

#1

001003

N-03

T 13 S. R. 8 E.

R.D. SISTERS

County

Jefferson

NW Cor S. 22


Merid. WILLAMETTE

N.F. DESCHUTES

State

OREGON

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

①

GLO Record of 1895 by Campbell.

Set a fir post 3 1/2 feet long, 4 ins. sq., 24 ins. in the ground, for cor. of secs. 15, 16, 21 and 22, marked:

T.13S., S.15, on N.E.; R.8E., S.22, on S.E.; S.21, on S.W. and S.16, on N.W. faces. 3 notches on S. and E. edges, from which:

A fir, 40 ins. diam. bears N.64 1/2°E., 34 1/2 lks. dist.

marked T.13S., R.8E., S.15, B.T.;

A fir, 28 ins. diam. bears S.10°E., 42 lks. dist.

marked T.13S., R.8E., S.22, B.T.;

A larch, 16 ins. diam. bears S.64 1/2°W., 21 lks. dist.

marked T.13S., R.8E., S.21, B.T.;

A larch, 20 ins. diam. bears N.28 1/2°W., 97 lks. dist.

marked T.13S., R.8E., S.16, B.T.;

FOUND - No evidence of original post. Corner position determined from found BT's. Corner falls in a clear cut.

NE BT - A fir stump, 32" dia., with overgrown BT blaze.

SE BT - A fir stump, 38" dia., with overgrown face.

SW BT - A larch snag, 17" dia., 4 ft. high with face and scribing, v.s.

No evidence of NW BT.

All three found BT's fit the GLO bearing and distance.

## PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

## PLANE COORDINATE POSITION DATA

State Zone

X

Y

Estab. By

Agency

Signature

Walt Muller

Title

PLS

Division

SO

Headquarters

CS

Date

11/97

D-7100-52 (10/78)

## USDA-FOREST SERVICE

Index

File No. \_\_\_\_\_

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_

Cor.


No. \_\_\_\_\_

T 13 S. R. 8 E.R.D. SISTERSCounty Jefferson

NW Cor S. 22

Merid. WILLAMETTEN.F. DESCHUTESState OREGON

## CORNER DIAGRAM



## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_

Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

## DESCRIBE CORNER MONUMENT FOUND

- ① GLO Record of 1895 by Campbell.  
Set a fir post 3 1/2 feet long, 4 ins. sq., 24 ins. in the ground, for cor. of secs. 15, 16, 21 and 22, marked:  
T.13S., S.15, on N.E.; R.8E., S.22, on S.E.; S.21, on S.W. and S.16, on N.W. faces. 3 notches on S. and E. edges, from which:  
A fir, 40 ins. diam. bears N.64 1/2°E., 34 1/2 lks. dist. marked T.13S., R.8E., S.15, B.T.;  
A fir, 28 ins. diam. bears S.10°E., 42 lks. dist. marked T.13S., R.8E., S.22, B.T.;  
A larch, 16 ins. diam. bears S.64 1/2°W., 21 lks. dist. marked T.13S., R.8E., S.21, B.T.;  
A larch, 20 ins. diam. bears N.28 1/2°W., 97 lks. dist. marked T.13S., R.8E., S.16, B.T.;

FOUND - No evidence of original post. Corner position determined from found BT's. Corner falls in a clear cut.  
NE BT - A fir stump, 32" dia., with overgrown BT blaze.  
SE BT - A fir stump, 38" dia., with overgrown face.  
SW BT - A larch snag, 17" dia., 4 ft. high with face and scribing.  
No evidence of NW BT.  
All three found BT's fit the GLO bearing and distance.

Signature

Walt Miller

Title

PLS

Division

SO

Headquarters

CS

Date


11/97

D-7100-52 (10/78)

5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



SET - A 2 1/2" dia. X 30" long alum. pipe surmounted with a 2 1/2" dia. alum. cap, rising 2" above ground. A steel fence post bears North, 3 ft.  
 A rebar, 5/8" dia. X 30" long bears N.45°E., 19.2 ft. dist. with a 1 1/2" dia. alum. cap marked RM S15 PLS 2111 1997.  
 A rebar, 5/8" dia. bears S.64°E., 25.6 ft. dist. with a 1 1/2" dia. alum. cap marked MJW PP NE 21 RM1 1988.  
 A Ponderosa Pine 2" dia. bears S.85°E., 105.0 ft. dist. marked X B.T.;  
 A Grand Fir, 14 ins. dia. bears S.33°W., 5.4 ft. dist. marked T.13S., R.8E., S.21, B.T.;  
 A rebar, 5/8" dia. X 30" long bears N.45°W., 10.6 ft. dist. with a 1 1/2" dia. alum. cap marked RM S16 PLS 2111 1997.  
 A location tag on N. side of road 1210-490 bears North, 550 ft.

Work Done By Walt Miller Title PLS Date 11/97 State Registration No. 2111 or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Jell Co. Date 12/08/97

REMARKS

Index File No.

T.

S., R.

E., W. M.

Tract or Surv. No.

Cor.

N-5

USDA-FOREST SERVICE GPO 940-117

Index  
File No. \_\_\_\_\_T 135 R. 8 E

Merid. \_\_\_\_\_


## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_Cor.  
No. \_\_\_\_\_R.D. Sisters County Jefferson

N.F. \_\_\_\_\_ State \_\_\_\_\_

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

SFNF - orig. was Basalt stone. - There are many fire rings in the area. The stone may be a part of one of them.

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

Signature W. Ham

Title \_\_\_\_\_

Division \_\_\_\_\_

Headquarters \_\_\_\_\_

Date 8/97 7100-52-(3/68)

## CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

12

13

## USDA-FOREST SERVICE

Index  
File No. \_\_\_\_\_

CORNER RECORD (SEARCH)  
(Ref. FSM 7151.4)


Tract or Survey No. 001003 Cor. No. N-09

T 13 S. R. 8 E. R.D. SISTERS County Jefferson

Merid. WILLAMETTE N.F. DESCHUTES State OREGON NW Cor S. 21

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



③ GLO Record of 1896 by McQuinn.

Set a pine post 3 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. of Secs. 16, 17, 20 and 21, marked:

T.13S., S.16, on N.E.; R.8E., S.21 on S.E.; S.20 on S.W. and S.17 on N.W. faces, 3 notches on S. and 4 notches on E. edges, from which:

A spruce, 18 ins. diam. bears N.30°E., 9 lks. dist. marked T.13S., R.8E., S.16, B.T.;

A pine, 18 ins. diam. bears S.65°E., 32 lks. dist. marked T.13S., R.8E., S.21, B.T.;

A pine, 16 ins. diam. bears S.30°W., 31 lks. dist. marked T.13S., R.8E., S.20, B.T.;

A pine, 18 ins. diam. bears N.74°W., 29 lks. dist. marked T.13S., R.8E., S.17, B.T.;

## PHOTO IDENTIFICATION

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signa

## PLANE COORDINATE POSI

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

8

FOUND - No evidence of original post. Corner position determined by distance-distance intersect from found BT's. Corner falls on edge of marsh.

A spruce windfall, 24" dia., N.20°E., 9 lks. (5.9ft.) with scribing visible.

A pine stump, 18" dia., S.65°E., 32 lks. (21.1ft.) with scribing visible.

A pine stump, 16" dia., S.36°W., 31 lks. (20.5ft.) with scribing visible.

A pine windfall, 20" dia., N.78°W., 29 lks. (19.1ft.) fallen on its face.

Signature Walt MillerTitle AsDivision CSHeadquarters SODate 11/97

D-7100-52 (10/78)


4

5



# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



SET - A 2 1/2" dia. X 30" long alum. pipe surmounted with a 2 1/2" dia. alum. cap, rising 6" above ground. A steel fence post bears North, 3 ft.

A Lodgepole Pine 3" dia. bears N.08°E., 22.4 ft. dist.  
marked X B.T.;

No trees available in the Southeast quadrant. Area is too swampy for a RM.

A Spruce 30" dia. bears S.89°W., 84.0 ft. dist.  
marked T.13 S., R.8 E., S.20, B.T.

A Spruce, 24 ins. dia. bears N.33°W., 34.5 ft. dist.  
marked T.13S., R.8E., S.17, B.T.;

EVIDENCE

Work Done By Walt Miller Title PLS Date 11/97 State Registration No. 2111  
or Agency \_\_\_\_\_  
Certified Cor. Record Prepared ☒ Yes ☐ No Filed At: Jedd Co. Date 12/08/97  
REMARKS

Index File No. T. S., R. E., W.M. Tract or Surv. No. Cor. N-07

## USDA-FOREST SERVICE

Index  
File No.

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No.#3  
001003Cor.  
No.

N-09

T 13 S. R. 8 E.R.D. SISTERS

County


JeffersonMerid. WILLAMETTEN.F. DESCHUTES

State

OREGONNW Cor S. 21

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



③ GLO Record of 1896 by McQuinn.

Set a pine post 3 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. of Secs. 16, 17, 20 and 21, marked:

T.13S., S.16, on N.E.; R.8E., S.21 on S.E.; S.20 on S.W. and S.17

on N.W. faces, 3 notches on S. and 4 notches on E. edges, from which:

A spruce, 18 ins. diam. bears N.30°E., 9 lks. dist.

marked T.13S., R.8E., S.16, B.T.;

A pine, 18 ins. diam. bears S.65°E., 32 lks. dist.

marked T.13S., R.8E., S.21, B.T.;

A pine, 16 ins. diam. bears S.30°W., 31 lks. dist.

marked T.13S., R.8E., S.20, B.T.;

A pine, 18 ins. diam. bears N.74°W., 29 lks. dist.

marked T.13S., R.8E., S.17, B.T.;

FOUND - No evidence of original post. Corner position determined by distance-distance intersect from found BT's. Corner falls on edge of marsh.

A spruce windfall, 24" dia., N.20°E., 9 lks. (5.9ft.) with scribing visible.

A pine stump, 18" dia., S.65°E., 32 lks. (21.1ft.) with scribing visible.

A pine stump, 16" dia., S.36°W., 31 lks. (20.5ft.) with scribing visible.

A pine windfall, 20" dia., N.78°W., 29 lks. (19.1ft.) fallen on its face.

## PHOTO IDENTIFICATION

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signe

## PLANE COORDINATE POSI

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

8

Signature

Walt Muller

Title

As

Division

CS

Headquarters

SO

Date


11/97

D-7100-52 (10/78)

4

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



SET - A 2 1/2" dia. X 30" long alum. pipe surmounted with a 2 1/2" dia. alum. cap, rising 6" above ground. A steel fence post bears North, 3 ft.

A Lodgepole Pine 3" dia. bears N.08°E., 22.4 ft. dist.  
marked X B.T.;

No trees available in the Southeast quadrant. Area is too swampy for a RM.

A Spruce 30" dia. bears S.89°W., 84.0 ft. dist.  
marked T.13 S., R.8 E., S.20, B.T.

A Spruce, 24 ins. dia. bears N.33°W., 34.5 ft. dist.  
marked T.13S., R.8E., S.17, B.T.;

Work Done By Walt Miller Title PLS Date 11/97 State Registration No. 2111  
or Agency  
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Jedd, Co. Date 12/08/97

REMARKS

Index File No.

T.

S., R.

E., W.M.

Tract or Surv. No.

Cor. N-09

## USDA-FOREST SERVICE

Index

File No. \_\_\_\_\_

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_# 2  
001003Cor.  
No. N-11

T 13 S. R. 8 E.

R.D.

SISTERS

County

Jefferson

Merid. WILLAMETTE

N.F.


DESCHUTES

State

OREGON

N/4 S. 21

## CORNER DIAGRAM



T 13 S | R 8 E

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estob. By \_\_\_\_\_

Agency

## DESCRIBE CORNER MONUMENT FOUND

② GLO Record of 1896 by McQuinn.

Set a fir post 3 ft. long, 3 ins. sq., 24 ins. in the ground, for 1/4 Sec. cor. marked 1/4 S. on N. face; from which

A fir, 18 ins. diam. bears S. 36° W., 7 lks. dist. marked 1/4 S BT.

A fir, 18 ins. diam. bears N. 35° W., 43 lks. dist. marked 1/4 S BT.

FOUND - No evidence of original post. Corner position determined from found BT's.

SW BT - A fir snag, 36" dia., with face and scribing exposed.

NW BT - Remains of a fir stump. No other evidence.

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Walt Muller

Title

PLS

Division

CS

Headquarters


SO

Date 11/9/70-7100-52 (10/78)

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Steel Fence Post Only



SET - Using GLO record bearing and distance from SW BT.

A steel fence post with a LSM sign 3 ft. N. of corner position.

A location tag on N. side of road 1210-530 bears South, 100 ft.

SERVE EXISTING EVIDENCE

Work Done By Walt Miller Title PLS Date 11/97 State Registration No. 211  
 Certified Cor. Record Prepared ☒ Yes ☐ No Filed At Jeff Co. Date 12/08/97

REMARKS


Index File No. T. S., R. E., W.M. Tract or Surv. No. Cor. N-11

# LAND CORNER RECORD

N-155680-2

T 13S R 8E No. 115 Cor. 1/2 Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

## 2. Corner Status



## 7. Photo Identification

Photo No. \_\_\_\_\_

Ident. By: \_\_\_\_\_

## 8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

## 9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Sept. 22, 1895 - Set an ironstone 20"x15"x5" - 15" in the ground---marked 1/4 on N face.  
A larch 10" in diam. bears N03°E, 1.03 chl dist., marked 1/4 S, B.T.  
A pine 8" in diam. bears S14 3/4°W, 86 1/2 lks. dist., marked 1/4 S, B.T.

5. Investigation Notes: Found what someone has used as 1/4 corner but the evidence does not correspond to original notes. The pine used for B.T. hasn't any visible markings - if it is the B.T.; then the stone is out of place. The stone hasn't any visible markings.

6. Signed O. Thingvall Title Hwy Eng Date 6-25-62

# PERPETUATION RECORD

10. Monument:

11. Accessories

|                                      |              |                             |               |
|--------------------------------------|--------------|-----------------------------|---------------|
| 12. Set By _____ Title _____         |              | Field Book _____ Page _____ |               |
| License _____                        | Agency _____ | Date _____                  |               |
| 13. Recorded By _____ (Agency) _____ |              | Volume _____                | Page _____    |
| (Date) _____                         | (City) _____ | (County) _____              | (State) _____ |


14. Remarks:

1563

N-15

Index File No. 1763 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. \_\_\_\_\_ Cor. No. N-17  
 T 135 R. 8E R.D. SISTERS County JEFFERSON SEC. COR. \_\_\_\_\_  
 Merid. WILLAMETTE N.F. DESCHUTES State OREGON 14, 15, 22, 23

## CORNER DIAGRAM



## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

## DESCRIBE CORNER MONUMENT FOUND

STONE IN ~~ROCK~~ GROUND 8 INCHES  
 ABOVE 3 GROOVES IN SOUTH SIDE  
 2 GROOVES IN EAST SIDE

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

38 1/2" PP BRG S 55° E @ 32" (T135 R 8E S 23 " BT  
 16 1/2" W. FIR BRG N 55° E @ 48 1/2" (T235 R 8E S 14)  
 46 1/2" D. FIR BRG S 35° W @ 45" (T135 R 8E S)  
 NOT OPENED

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SANTIAM HWY. SOUTH FROM SEC. COR.

Signature BEILTitle FORESTER

Division \_\_\_\_\_

Headquarters \_\_\_\_\_


Date 1956 7100-52 (3 68)



# CORNER RECORD (PERPETUATION)

MONUMENT  
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. 1763 T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. N-17

## USDA-FOREST SERVICE

Index

File No. 2163

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_

Cor.

No. N-21T 13S R. 8ER.D. Sisters

County

Jefferson


Merid. \_\_\_\_\_

N.F. \_\_\_\_\_

State

NW Cor S. 24.

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

Found 3 1/4" BLM brass capped steel pipe rising 8" and BT's as follows:

- 1) Burnt stump in NE record location. (1966)
- 2) A white fir in SE record location in good condition. (1966)
- 3) A standing dead fir in SW record location. (1966)
- 4) A root hole in NW record location. (1966)
- 5) A white fir in NW record location in good condition. (1985)

DES

2

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

7

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

8

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3

Signature

Title

Division

Headquarters


Date

FS-7100-52 (3/68)

4Walt MillerPLSCSSO7/055

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set 2" AC on 1/2" x 24" rebar, N 78° E @ 7.6', marked "B01 PLS2111 2005"  
Set 2" AC on 1/2" x 24" rebar, S 75° W @ 3.9', marked "B02 PLS2111 2005"

Work Done By Walt Miller Title PLS Date 7/05 State Registration No. 2111  
or Agency  
Certified Cor. Record Prepared ☒ Yes ☐ No Filed At: Jeffco Date 7/13/06

## REMARKS

1895, Campbell, under Contract No. 644, established corner.  
1966, BLM, James E. Jelley set an iron post, 28" long, 2 1/2" diam., 24" in ground with brass cap mkd (as shown below) from which new bearing trees:  
1) A white fir, 5" diam., bears N.58 3/4° E., 57 1/2 links. dist., mkd. "T13S R8E S13 BT"  
2) A white fir, 5" diam., bears S.58 3/4° E., 33 1/2 links. dist., mkd. "T13S R8E S24 BT"  
3) A fir, 13" diam., bears S.24° W., 135 links. dist., mkd. "T13S R8E S23 BT"  
4) A white fir, 12" diam., bears N.69° W., 112 1/2 links. dist., mkd. "T13S R8E S14 BT"

1985, Walt Miller found 3 1/4" brass cap on a 2 1/2" iron post rising 10" and set new Bearing Tree:  
A 4" white fir bears N 20° W at 15.12 ft. to a 60-Penny spike in the NE base, marked X BT.

Index File No. 2163 T. 12 R. 8 M. WMT Tract or Surv. No. N-21 Cor. 13  
GPO: 1986 O- 439-095


# LAND CORNER RECORD

N-23 5680-2

1. T. 13S R. 8E No. N23 Cor.  $\frac{1}{4}$  Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

## 2. Corner Status

⑧



## 7. Photo Identification EGI

Photo No. 7-14-59, 50-153

Ident. By: O. Thingvall

## 8. Plané Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

## 9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

## 3. Original Description Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Sept. 4, 1895 - At 38.73 ch. set an iron stone 15"x12"x10" in ground 10" - marked  $\frac{1}{4}$  on N face.

A fir 13" in diam. bears S13°E, 16 lks dist., marked  $\frac{1}{4}$ S, B.T.

" " 15" " " " N75°W, 13 lks " " " "

5. Investigation Notes: Found stone 15"x12"x10" - 6" above ground; marked  $\frac{1}{4}$  on N face in good condition. A 16" Douglas fir bears S13°E, 10.2 feet dist. - marked  $\frac{1}{4}$ S, B.T. Also, a 24" Douglas fir bears N75°W, 7.9 feet dist., marked  $\frac{1}{4}$ S.

From the junction of Rds #1317 and #1317-A, it is approx. 0.7 mi. in on Rd # 1317-A and can be seen on right side of road. (20')

18" FIR, S13°E @ 10.2', LIVE W/BURNT FACE & BLAZE  
24" " N75°W @ 7.9', STUMP W/BURNT FACE  
7/05 WNL

6. Signed O. Thingvall Title Hwy. Eng. Date 5-10-62

# PERPETUATION RECORD

10. Monument: Brass Cap

$\frac{1}{4}$   $\frac{S13}{S24}$

T13S R8E

1966

11. Accessories

15" D. Fir S35 $\frac{1}{4}$ °W 25 lks. GOOD SHAPE

8" D. Fir N18°E 8 $\frac{1}{2}$  lks. 8' HIGH BURST STUMP, SCRIBING VISIBLE

Plus old ones.

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By BLM Title \_\_\_\_\_

License \_\_\_\_\_ Agency \_\_\_\_\_ Date 1966

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_

(Agency)

(Date)

(City)

(County)

(State)


14. Remarks:

# LAND CORNER RECORD

N-25 5680-2

1. T. 13S R. 9E No. 11 Cor. Sec Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-14-59

Photo No. EGI-50-154

Ident. By O. Thingvall

5 9 62

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners:

Assumed stone, 10"x8"x4" set in ground, no visible chisel marks.

5. Investigation Notes:

A ponderosa pine, 26" diam., bears N49°E, 30.4' dist., marked T13S, R9E, S18, B.T.

A ponderosa pine, 24" diam., bears S25°W, 24.6' dist., marked B.T.

A ponderosa pine, 25" diam., bears S46°E, 41.9' dist., marked T13S, R9E.

This corner checks with distances on photo copies of General Land Office field notes.

*Fd. as set 22 June 79*

*REO / RD*

6. Signed Calvin W. Minks Title Forestry Aid Date 11-10-60

# PERPETUATION RECORD

10. Monument: Brass cap.

2 1/2" x 28" Pipe Rising 4"  
Rosette of Stones

T135

|      |      |
|------|------|
| R8E  | R9E  |
| S 13 | S 18 |
| S 24 | S 19 |

11. Accessories

5" W. Fir N57°E 12 1/2 lks. mKd T135 R9E S18 BT  
8" W. Fir S43 1/2°E 43 1/2 lks. " " " S19 "  
5" Pine S54°W 11 lks. " " R8E S24 "  
5" W. Fir N28 1/4°W 5 1/4 lks. " " " S13 "

1966

Plus old ones.

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By BLM Title \_\_\_\_\_

License \_\_\_\_\_ Agency \_\_\_\_\_ Date 1966

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_

(Agency)

(Date)

(City)

(County)

(State)

14. Remarks:

OK - 7/05 WNW

Index

File No. 0965

T 135 R. 8E

Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

#4

001003

Cor.

No.

P-9


County JEFFERSON

1/4 SEC.

State OREGON

20, 21

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

ASSUMED; ROSETTE OF STONES  
12" X 12" X 10" 6" ABOVE GROUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

10" P.P. BRG. S.35°E. @ 331' "1/4 S" BT  
DEAD & STANDING  
136" D.FIR BRG. N.42°W. @ 191' "1/4 S" BT

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SANTIAM HWY, U.S.#20 345' CHAINS SOUTH  
FROM 1/4 COR.

Signature

BEIL

Title

FORESTER

Division

Headquarters

Date

8/28/1956


7100-52 (3 63)



# CORNER RECORD (PERPETUATION)

MONUMENT  
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



④ GLO Record of 1896 by McQuinn.

On point of ridge which bears E and W.. Set a fir post  
3 ft. long, 3 ins. sq., 24 ins. in the ground, for 1/4

ACCE

Sec. cor. marked 1/4 S. on W. face; from which

VE EXIST

A fir, 10 ins. diam. bears N.53°W., 27 lks. dist. marked 1/4 S BT.

A pine, 8 ins. diam. bears S.45°E., 53 lks. dist. marked 1/4 S BT.

FOUND - Original post hole with burnt post remains.

A fir snag, 19" dia., N.53°W., 27 lks. (17.8ft.) with scribing exposed.

A pine windfall, 12" dia., S.45°E., 53 lks. (35.0ft.) with scribing visible

SET - A 2 1/2" dia. X 30" long alum. pipe surmounted with a 2 1/2" dia.  
alum. cap. rising 4" above ground. A steel fence post bears North, 3 ft.

A Grand Fir 6" dia. bears N.27°E., 33.1 ft. dist.  
marked X B.T.;

10

Work

A Ponderosa Pine 27" dia. bears S.10°E., 64.0 ft. dist.  
marked 1/4 S.21 B.T.

Cert

A Ponderosa Pine 22 ins. dia. bears S.45°W., 46.8 ft. dist.  
marked 1/4 S.20 B.T.;

11

A Grand Fir 6" dia. bears N.49°W., 2.4 ft. dist.  
marked X B.T.;

The following angle points are from the Mt. Jefferson Wilderness  
boundary description established by Public Law 90-548 dated Oct. 2, 1968.

Walt Miller PLS 12/08/97

Index  
File No. 1765

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No.

Cor.

No. P-17T 13S R. 8ER.D. SISTERSCounty JEFFERSON1/4 SEC.Merid. WILLAMETTEN.F. DESCHUTESState OREGON22, 23

## CORNER DIAGRAM



## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

## DESCRIBE CORNER MONUMENT FOUND

ASSUMED ROCK NOT IN PLACE 6"  
ABOVE GROUND

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

14" W. FIR BRG. S 52° E @ ? "1/4 5 BT"  
DEAD & STANDING TREE 10' HIGH - SCRIBING  
IS @ BASE OF TREE

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters


Date

7100-52 (3 63)

# CORNER RECORD (PERPETUATION)

MONUMENT  
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

Index File No. 1765 T. 135. R. 8 E. M.

Tract or Surv. No.

Cor. P-17

12


13

Index  
File No. 2565  
T 13S R. 8E  
Merid. WILL

CORNER RECORD (SEARCH)  
(Ref. FSM 7151.4)  
R.D. SISTERS County JEFFERSON  
N.F. DESCHUTES State OREGON

Tract or  
Survey No. \_\_\_\_\_  
Cor. No. P-25  
ST. 1/4 COR.  
See 24/19

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE T13S R9E P-1  
BC.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

O. THINGVALL, 1962: POSSIBLE BT ON EDGE of HWY. R/W. P-LINE HAS  
A BLAZE BUT NO MARKS - FIR BT & COR. SHOULD BE ON  
HWY. CUT.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA


State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
Agency

Signature \_\_\_\_\_ Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_  
7100-52 (3 68)

# CORNER RECORD (PERPETUATION)

MONUMENT  
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_  
Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. 2565 T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. P-25

12

13

Index

File No. 0167

T 13 S. R. 8 E.

Merid. Willamette

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

R.D. SISTERS

County JEFFERSON

N.F. Deschutes

State Oregon


Cor.

No. R-01

Cor. of

Section SW 19 (CC)

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

SFNF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

20" PINE S.E. MKD "T138R8E330BT"

12" PINE N.E. MKD "13SR8E314BT"

CHOPPED OPEN PINE S.E. OF CORNER

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified  
Contr. Other

☐ ☐ Searched For/Not Found

☒ ☒ Evidence Found/Accept.

☒ ☒ Permanent Mon. Set/Fd.

Searched By:

Title ST  
R. TAYLOR

Division CS


Headquarters 50

Date 7-26-84

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Plat or Cor. Record Prepared? Yes ☐ No ☐ Filed At \_\_\_\_\_ Co. Surveyor's Office Date \_\_\_\_\_

History of Surveys, G.L.O., etc.  
Post 8" PINE, N65°E, 1/3 1/5.  
12" PINE, S69°E, 158/ks.

Index File No. 0167 T. 13S., R. 8 E., W.M.

Contract or Surv. No

Cor. R-O

Index

File No. 0567

T 13 S. R. 8 E.

Merid. Willamette

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor. No. R-05

R.D. SISTERS


County JEFFERSON

N.F. Deschutes

State Oregon

Section SE Cor. of 19

CORNER DIAGRAM, per legend



DESCRIBE CORNER MONUMENT FOUND

SF/NF

PHOTO 10, LOTS OF BLOW DOWNS, VINE MAPLE, FERNS

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SF/NF

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

- |                                  |                                                            |
|----------------------------------|------------------------------------------------------------|
| FS or                            | Unverified                                                 |
| Contr.                           | Other                                                      |
| <input type="radio"/>            | <input type="checkbox"/> Searched For/Not Found            |
| <input checked="" type="radio"/> | <input checked="" type="checkbox"/> Evidence Found/Accept. |
| <input type="radio"/>            | <input type="checkbox"/> Permanent Mon. Set/Fd.            |

Searched By: R. TAYLOR

Title ST

Division CS

Headquarters 50


Date 7-26-84



# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Plat or Cor. Record Prepared? Yes No Filed At \_\_\_\_\_ Co. Surveyor's Office Date \_\_\_\_\_

History  
of  
Surveys,  
G.L.O.,  
etc.

STONE 30"x2"x24", 20" IN GROUND, 2 NOTCHES S, 5 NOTCHES E, 1.5 ch. N  
PITS 18x18x12 IN EACH SECTION 5 1/2' DIST  
MOUND OF STONE COVERED W/ EARTH 20' BASE 1 1/2' HIGH, W. OF COR.

Index File No.

0567

T. 13 S., R. 8 E., W.M.

Contract or Surv. No

Cor. R-05

Index  
File No. 20967

# CORNER RECORD (SEARCH)

Tract or  
Survey No. \_\_\_\_\_  
Cor.  
No. R-9

T 13S., R. 8E

R.D. Sisters

County Jefferson

Sec Cor


Merid. Will

N.F. Deschutes

State Oregon

20/21

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

STNF

Stone = 4x5x8 above ground; in good. Flash markings - seem to be new marks.

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

42" D.F. HEALED  
OVER, DEAD & DOWN &  
B.T. in section 20: 39" D.F. DECAYED IN S.E. LOCATION  
NOTHING IN S.W. OR S.E. NE  
Two F.S. corner tags - one on BT - one on the other  
LOC. N.W. ST NEEDS TO BE CUT  
tree (C. Beil) OPENED TO VERIFY

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_

Agency

Signature

R. TAYLOR  
H. Cordell

Title

ST  
Forester

Division

CS

Headquarters

SO

Date

7-26-84  
8-29-81

7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_ 11

REMARKS

12

Index File No.

T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. R-9

13


Index  
File No. 1167  
T 135 R. 8 E  
Merid. WILLAMETTE

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No.Cor.  
No. R-11R.D. SISTERS County JEFFERSON  
N.F. DESCHUTES State OREGON1/4 SEC.  
21, 28

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

39" G.F. BRG. N. 22° E. @ 134' " 1/4 S BT "  
22 3" G.F. BRG. S. 27° E. @ 57 1/2' NOT LEGIBLE

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_

Agency

Signature

BEIL

Title

FORESTER

Division

Headquarters

Date

8/7/56


7100-52 (3 68)

5

# CORNER RECORD (PERPETUATION)

MONUMENT  
STAMPED:

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

12

Index File No. 1167 T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. R-11

13


## LAND CORNER RECORD

R-13 5680-2

(Rectangular)

1. T. 13S R. 8E No. R-13 Cor. Sec Mer. Will State Oregon N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification

Photo No. \_\_\_\_\_

Ident. By : \_\_\_\_\_

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners:

5. Investigation Notes:


Remonumented by BLM

6. Signed \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

# PERPETUATION RECORD

## 10. Monument:

SET 2 1/2" x 28" BCSP RSG. 2"



## 11. Accessories

1969; 6" FIR N65°E 12 LKS. MKD. T13S RBE S22 BT.

FD. 30" PINE S7°E 48 LKS. MKS. VIS. T13S RBE BT on OPEN BLAZE.

28" FIR S17°W 42 LKS. NO MKS. VIS. ON OPEN BLAZE.

25" LARCH N70°W 16 1/2 LKS. MKS. VIS. T13S RBE S21 BT on OPEN BLAZE.

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By BLM Title \_\_\_\_\_

License \_\_\_\_\_ Agency \_\_\_\_\_ Date 1969

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_  
(Agency)

(Date) (City) (County) (State)

## 14. Remarks:

Index  
File No. 1567CORNER RECORD (SEARCH) Contract or  
(Ref. FSM 7151.4) Survey No. 2-2Cor.  
No. R-15T 13 S. R. B E. R.D. SISTERS County JEFFERSON N<sup>1</sup>/<sub>4</sub> Cor. of  
Merid. Willamette N.F. Deschutes State Oregon Section 27

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

B.L.M. BRASS CAP ON 2 1/2" IRON PIPE IN 2 FT.  
HIGH MOUND OF STONES.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

8" W. FIR N 26° W @ 23<sup>2</sup> FT. (SCRIBING VIS., 1966 BLM)  
12" W. FIR S 22° E @ 38<sup>3</sup> FT. (SCRIBING VIS., 1966 BLM)

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## CORNER LEGEND:

FS or Unverified  
Contr. Other☐ ☐ Searched For/Not Found☒ ☒ Evidence Found/Accept.☒ ☒ Permanent Mon. Set/Fd.Searched By: NORM NEWTONTitle PLS  
654

Division \_\_\_\_\_

Headquarters \_\_\_\_\_

Date

11/24/82




# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2'1/2" x 28" BC SP RSG. 4" in Mo./SM. 2'Ø

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

1966 BTs: 5"W. FIR N26°W 36 LKS. MKD. 1/4 522 BT.

12"W. FIRS 22°E 58 LKS. MKD. 1/4 527 BT.

FD. 40" FIR N22°E 16 LKS. MKS. VIS. "S BT" ON PARTIALLY HEALED BLAZE.

Work Done By. BLM Title \_\_\_\_\_ Date 1966 State Registration No. or Agency \_\_\_\_\_

Plate or Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Co. Surveyor's Office Date \_\_\_\_\_

History of Surveys, G.L.O., etc. ORIG. SURV. BY WILLIAM S. CAMPBELL IN 1895.  
SET IRONSTONE 15"x12"x9" 10' IN GRND., MKD. "1/4" ON N. FACE  
FIR 42" N 22°E 14 1/2 LKS.  
LARCH 12" S 28°W 38 1/2 LKS.

BLM ~ 1966: SET BC AS FOUND BY NEWTON; 1969: USED "AS IS" FOR SEC. 27 BREAKDOWN.

Index File No. 1567 T. 13 S., R. 8 E., W.M. Contract or Surv. No. 2-2 Cor. R-15 13

## LAND CORNER RECORD

R-17 5680-2

1767  
 1. T. 13S R. 8E No. R17 Cor. Sec. Mer. Will State Oregon N. F. Deschutes Dist. Sisters  
 2. Corner Status

3. Original Description Vol. Page Where Recorded

4. Description of Corners: Sept. 1895 - Set a basalt stone 15"x12"x8" - 10" in the ground---marked with 2 grooves on S & E edges.  
 (see #14)

5. Investigation Notes: Found a stone 15"x12"x8" - 9" above the ground in good condition; marked with 2 notches on S & E sides. A 41" D.F. bears N11°W approx. 38 feet...with visible markings of 8 and S22. There is a 23" pine 154' at approx S45°W; it had a slight scar - didn't open it.  
 I went south from sec. line marker on Rd #1319 between secs. 22 & 23. However, if a person can find a starting point on the Santiam Hwy it would be easier to get to corner.

6/13 B. ROGERS F.O. PIPE & CAP FOR 16. STONE, 3 ORIG. B.Ts AND 4 NEW BLM B.Ts  
 ORIG. B.Ts 40" FIR N17°W 37° FT.  
 36" FIR N11°E 42° FT.  
 14" FIR (DEAD) S48°W 153 FT.

6. Signed O. Thingvall Title Hwy. Eng. Date 5-10-62



# PERPETUATION RECORD

10. Monument: <sup>R</sup>Pass Cap T13S R8E  

$$\begin{array}{r} S22/S23 \\ \hline S27/S26 \\ 1966 \end{array}$$

ABOUT 300' NW of HWY. & 300' UP

11. Accessories

|     |       |           |                          |
|-----|-------|-----------|--------------------------|
| 8"  | Cedar | N71 3/4°W | 21½ lks. ✓               |
| 5"  | Cedar | N5½°E     | 21 lks. ✓                |
| 7"  | Cedar | S85 3/4°E | 25½ lks.                 |
| 14" | Pine  | S48°W     | 23 lks. ✓ (ORIG. & DEAD) |
| 12" | Pine  | S48°W     | 39½ lks. ✓ (DEAD 1973)   |

Plus old ones.

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By BLM Title \_\_\_\_\_  
 License \_\_\_\_\_ Agency \_\_\_\_\_ Date 1966

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_  
 (Agency)  
 (Date) \_\_\_\_\_ (City) \_\_\_\_\_ (County) \_\_\_\_\_ (State) \_\_\_\_\_

14. Remarks: (4)  
 A pine 11" in diam. bears N13°E, 52 lks. dist., marked T13S, R8E, S23, B.T.  
 " " 38" " " " S77°E, 1.92 ch. " " " S26, B.T.  
 " " 22" " " " S40½°W, 1.75 ch. " " " S27, "  
 " fir 24" " " " N11°W, 57½ lks. dist., " " " S22 "

Index

File No. R 2167

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_


Cor.

No. R-21T 135 R. 7 1/2 ER.D. SistersCounty Jefferson

STD. COR.

Merid. WillametteN.F. DeschutesState OregonSec. 23/24

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

3 B.T.'s found

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Up on Santiam Pass

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

3R William Joyner

D-5

7/59

# CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_ 11

REMARKS


Index File No. 2167 T. 13S. R. 7 1/2 E. M.

Tract or Surv. No.

Cor. R-21 12  
13

Index  
File No. 2267-A CORNER RECORD (SEARCH) Tract or  
Survey No. R-22-A  
T 13S, R. 8E, R.D. Sisters County Jefferson  
Merid. Will N.F. Deschutes State Oregon 1/6 M.C.  
Sec. 24/25

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

Found Stone 12"x12"x10" - 6" above the ground with MC on E face  
and 1 notch on N face - I believe the stone is out of place  
comparing it with original notes.

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No definite B.T.; some trees have brands and initials.

## PHOTO IDENTIFICATION DATA

Photo No. EG1-50-155Filed At. SistersObject Ident. CorIdent. By D. Thingvall*Signature*

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Follow along west trail of Suttle Lake -- yellow FS tag was  
put up by G. Garrison in 1960

Signature

D. Thingvall

Title

Hyd Eng

Division

Headquarters

Date

5-17-62

7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_ 11

GLO, 1895: SET BASALT STONE 12X12X10 REMARKS 8" in GROUND, 1 GROOVE S. FACE, "MC" on W. FACE  
38" PINE N12 1/2° E 36 LKS. MKD. T13 S R8 E S24 MC BT.  
14" PINE S22 1/2° W 55 LKS. " T13 S R8 E S25 MC BT.

12

Index File No. 2267-A T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. R-22-A

Index  
File No. 2367

## CORNER RECORD (SEARCH)

Tract or  
Survey No.Cor.  
No. R-23T 135, R. 8ER.D. Sisters


County

JeffersonS.D. 1/4 CorMerid. WillN.F. Deschutes

State

OregonSec. 24/25

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

Found post  $2\frac{1}{2} \times 2\frac{1}{2}$  - 12" above ground - in solid, and no markings.

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 16" white fir bears  $N4^{\circ}E$ , 25' dist. Also, a 26" D.F. snag bears  $S13^{\circ}W$ , 35' feet dist, marked  $\frac{1}{4}S$  BT.

## PHOTO IDENTIFICATION DATA

Photo No. EG1 50-155 (7-14-50)Filed At. SistersObject Ident. CorIdent. By O. Thingvall7-14-50 Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_  
Agency

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Santiam Hwy, drive up Rd #138 approx. 0.1 mi. to spur turning off to the right. Drive up this road for 0.1 mi. to sec. line marker. Spur Rd crosses E-W line twice. (The second time is about 0.1 past sec. line marker.) The  $\frac{1}{4}$  cor is about 800' east. No sec. line marker but well marked.

(over)

Signature

Title

Division

Headquarters

Date

7100-52

O. ThingvallHwy Eng5-15-62

REV. 65 5



# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap 1 524  
4 525  
1963

Added T13SR8E RLM 1966

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

13" W. Fir 555<sup>1</sup>/<sub>2</sub> W 28<sup>1</sup>/<sub>2</sub> Lks

17 "D. Fir N48W 40 Lks

Plus old ones

10

Work Done By.

ELM

Title

Date

State Registration No.  
or Agency

Certified Cor. Record Prepared ? Yes

No

Filed At:

Date

11

REMARKS

Index File No. 2367 T. 13. R. 8 E. M.

Tract or Surv. No.

Cor. R-23

12

13

Index  
File No. B 2567

## CORNER RECORD (SEARCH)

Tract or  
Survey No.Cor.  
No.R-25T 13S. R. 8E.R.D. Sisters

County

Jefferson


5TH Sec Cor

Merid. WillN.F. Deschutes

State

Oregon24/19

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

A stone with 4 notches on south top & 2 notches on the north bp

25/30

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A P Pine 28 in diam., bears N27°W, 44.5' dist., marked  
T13S R8E S24

A P Pine, 26" diam., bears N53°E., 3.5' dist., marked B.T.  
The tree ~~was~~ rolled down, only a stump remains

## PHOTO IDENTIFICATION DATA

Photo No. EG1-50-56Filed At. SistersObject Ident. CorIdent. By D. Ingersoll  
Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_  
Agency

Signature

Calvin Minks

Title

Forestry Aid

Division

Headquarters

Date

11-10-60

7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" W Fir N28°E 3 1/2 lks  
 7" D Fir S64 3/4°E 9 1/2 lks  
 10" W Fir S75°W 29 1/2 lks  
 10" D Fir N78°W 44 1/2 lks

Plus old ones

Work Done By. BLM Title \_\_\_\_\_ Date 1966 State Registration No. \_\_\_\_\_  
 or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. 2567 T. 13S. R. 8E. M. \_\_\_\_\_ Tract or Surv. No. \_\_\_\_\_ Cor. R-25

Index  
File No. 1768

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.

Cor.

No.


S-17T 13 S. R. 8 E. R.D. SistersCounty Jefferson

N/16 Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 27/26

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



1 1/8" IRON PIPE (INSIDE DIA.) SET BY C.E. BARKER  
(PLS #636) IN 11/79. REPLACING BLM CAP NOT FOUND,

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

11" W.FIR BRS N45 1/2°W @ 14.5 ft. This tree has  
been chopped open, presumably by BARKER  
18" W.FIR BRS, N35 3/4°E @ 35.0 ft (Healed Over)

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

located at the west side of a campsite  
adjacent to the boat launch area and is  
protected by two metal fence posts,

## CORNER LEGEND:

FS or Unverified  
 Constr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

Searched By: MH

Title

ST

Division

CS

Headquarters

SO

Date


85

# CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Replaced Barkers Pipe with a 2 1/2 x 30"  
BCSP BURIED 6" INT

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By W. Miller Title PLS Date 85 State Registration No. 2111  
or Agency

Platified or Record Prepared? ☒ Yes ☐ No Filed At Jetta Co. Surveyor's Office Date 8/1985

History of Surveys, G.L.O., etc.  
IRON POST 28" Long 2 1/2" diam. set 25" IN GD.  
JULY, 1969  
FIR 15" DIAM. BRS N 35 3/4° E - 531KS MARKED N 1/16 S 26 BT  
" 10" " " N 45 1/2° W 22 " " N 1/16 S 27 BT

Index File No. 13 T. S., R. 8 E., W.M. Contract or Surv. No. Cor.

Index

File No. 1568

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

2-2

Cor.

No.

S-15T 13 S. R. 8 E.R.D. SISTERSCounty JEFFERSONWC CN 1/16 Cor. ofMerid. WillametteN.F. DeschutesState OregonSection 27

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

As Witness Corner a

B.L.M. BRASS CAP ON STEEL PIPE 4" ABOVE GRNP.64<sup>68</sup> FT. North of True Corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

9" FIR N40°W @ 15<sup>3</sup> FT. (BT SCRIBE VISIBLE)F.S. LOC. TAG DATED 8/14/69; BT TAG DATED 7/8125" FIR N28°E @ 12<sup>2</sup> FT. (BT SCRIBE VISIBLE)F.S. LOC. TAG DATED 8/14/69; BT TAG DATED 7/81

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

WIT. COR. MON. IS APPROX. 16 MILES WESTERLY OFSISTERS ON HWY. 20, AND LOCATED APPROX. 100FT. NORTH OF HWY. ABOVE CUT BANK. A spur road  
300' West of ctr. 1/4 Line on Hwy. goes right to corner monument.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## CORNER LEGEND:

FS or Unverified  
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: R.H. GRAVE Title PLS  
950

Division

Headquarters


Date

10/25/82

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By: BLM Title: \_\_\_\_\_ Date: 1969 State Registration No. or Agency: \_\_\_\_\_  
 Plat. of Cor. Record Prepared? Yes ☐ No ☐ Filed At: \_\_\_\_\_ Co. Surveyor's Office Date: \_\_\_\_\_

History of Surveys, G.L.O., etc. DEPENDANT RESURVEY BY GERALD E. CHITICK IN JULY 1969  
SET IRON POST W/BRASS CAP FROM WHICH  
@ ~~THE~~ FIR 20" DIA BEARS N 22 1/2° E 20 LKS  
@ FIR 7" DIA BEARS N 38 1/2° W 24 LKS

Index File No. 1568 T. 13 S., R. 8 E., W.M.

Contract or Surv. No. 2-2

Cor. S-15

Index  
File No. 1369

CORNER RECORD (SEARCH)

Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. T-13

T 13S. R. 8E.

R.D. Sisters

County Jefferson

Sec. 14 Cor. 28/27


Merid. Will

N.F. Deschutes

State Oregon

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Made search but couldn't find evidence

Monumented by BLM Survey 1969

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65




# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 28" BCSP RSG. 6"

DEPOSIT ORIG. STONE ALONGSIDE BCSP



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

1969: 35" FIR N 88 1/2° E 15 LKS. MKD. 1/4 S27 BT RS 691

16" FIR N 24 1/2° W 34 LKS. MKD. 1/4 S28 BT RS 691

RD. 23" FIR N 50° E 50 LKS., ILLEGIBLE SCRIBE MARKS ON OPEN FARE.

Work Done By BLM Title \_\_\_\_\_ Date 1969 State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes \_\_\_\_\_ No \_\_\_\_\_ Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS


Index File No. 1369 T. 13S. R. 8E. M. \_\_\_\_\_ Tract or Surv. No. \_\_\_\_\_ Cor. T-13

## LAND CORNER RECORD

(Rectangular)

1. T. 13S, R. 8E No. 1469-A Cor. MC Mer. Will State Oregon N. F. Deschutes Dist. \_\_\_\_\_

2. Corner Status \_\_\_\_\_

Blue  
Lake

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: \_\_\_\_\_

5. Investigation Notes:

Monumented by BLM survey 1969

BC not found

2 BTs F.D.: 27" PP S85°E 66 FT., MMS. VIS.: 1

18

15" WF S22°W 15 FT. " "

7. Photo EO Identification

Photo No. EO

Ident. BY

8. Place EO Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. BY

Field Book No. \_\_\_\_\_

Where Filed

9. Evaluation

Authentic IO

Needs Verif. Monument

Re-esta D Survey


Land Status atus

6. Signed S. Chamberlin Title S-A Date 7/81

# PERPETUATION RECORD

## 10. Monument:

@ 160 ch. West of Record M.C., Set 2 1/2" x 28" BCSP RSG. G" in  
MOUND of STONES 3 FT. Ø x 6" HIGH



## 11. Accessories

13" FIR U22°E 23 1/2 LKS. MKD. X BT.

30" FIR N85°W 10 LKS. MKD. X BT.

|                       |        |                 |         |
|-----------------------|--------|-----------------|---------|
|                       |        | Field Book      | Page    |
| 12. Set By <u>BLM</u> | Title  | 13. Recorded By | Volume  |
| License               | Agency | (Agency)        | Page    |
| Date <u>1969</u>      |        | (Date)          | (City)  |
|                       |        | (County)        | (State) |

## 14. Remarks:

1469-A

T-14A

Index

File No. 1569-A

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey N<sup>o</sup>.2-2

Cor.


No. T-15-AT 13 S. R. 8 E.R.D. SISTERSCounty JEFFERSON

WCSMC Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 27

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

B.L.M. BRASS CAP ON STEEL PIPE FLUSH/W GEND.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

6" POND. PINE N 77° E @ 11<sup>2</sup> FT. (BLAZES HEALED OVER)F.S. LOCATION POSTER DATED 8/6915" POND. PINE S 82° W @ 85<sup>2</sup> FT. (BT SCRIBE VISIBLE)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

B.C. FALLS ON NORTHERLY EDGE OF BLUE LAKEAPPROX. 11 FT. FROM LAKESIDE TRAIL AND APPROX.250 FT. WESTERLY ALONG TRAIL FROMRESORT OFFICE.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## CORNER LEGEND:

FS or Unverified  
Constr. Other☐ ☐ Searched For/Not Found☒ ☒ Evidence Found/Accept.☒ ☒ Permanent Mon. Set/Fd.Searched By: R.H. GRAVETitle PLS  
930

Division \_\_\_\_\_

Headquarters \_\_\_\_\_


Date

10/25/82

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Plat or Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Co. Surveyor's Office Date \_\_\_\_\_

History of Surveys, G.L.O., etc. ORIG. SURV. BY WILLIAM S. CAMPBELL, 1895 POINT OF SPECIAL MEANDER COR. FALLS ON ROCK IN PLACE 3'x3'x2' ABOVE GRND. MKD. W/"X" ON EXACT PT. & MKD. "SMC" ON SO. FACE. PINE 30" N40°E 30 LKS. (19.8')

D.L.U., 1969; SET B.C. AS FOUND BY GRAVE.

Index File No. 1569-A T. 13 S., R. 8 E., W.M. Contract or Surv. No. 2-2 Cor. T-15-A

Index

File No. 1569-B

## CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

2-2

Cor.

No. T-15-BT 13 S. R. 8 E. R.D. SISTERSCounty JEFFERSON

WCSMC Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 27

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

B.C. FALLS NORTH OF BLUE LAKE APPROX.140 FT NORTHERLY FROM LAKESIDE TRAIL AND  
APPROX. 250 FT. WESTERLY ALONG TRAIL FROM  
RESORT OFFICE

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: RH GRAVE

Title

PLS  
930

Division

Headquarters

Date


5/20/83

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 30" AL. PIPE W/ 2 1/2" AL. CAP MARKED  
AS SHOWN. CAP IS 0.3' ABOVE GROUND,  
IN A MOUND OF STONES 2' Ø X 15" HIGH.

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

- 17" FIR BRS. S 16° W @ 5.92 FT. SCRIBED "WCSMC S 27 BT" PLACED 60P NAIL AND WASHER NO. 930 IN N.W. BASE 1 FT. UP.
- 12" FIR BRS. N 78° W @ 22.06 FT. SCRIBED "WCSMC S 27 BT" PLACED 60P NAIL & WASHER NO. 930 IN N.W. BASE 1 FT. UP.

Work Done By R. H. GRAVE Title L. S.

Date 5/20/83 State Registration No. 930  
or Agency

Cor. Record Prepared? ☒ Yes No Filed At JEFFERSON Co. Surveyor's Office Date 15 June 1984

History of Surveys, G.L.O., etc. ORIGINAL SURVEY BY WILLIAM S. CAMPBELL  
IN 1895

BLM, 1969: SEC. 27 BREAKDOWN

Index File No.

T. 13 S., R. 8 E., W.M.

Contract or Surv. No. 2-2

Cor.

1569-B

T-15-B

Index  
File No. 177 1769

# CORNER RECORD (SEARCH)

Tract or  
Survey No.

Cor.  
No. T-17

T 13E., R. 8E.

R.D. Sisters

County

Jefferson

STP.  $\frac{1}{4}$  Cor.

27/26


Merid. Will

N.F. Deschutes

State

Oregon

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

FD, CONCR. PIER OUT OF GROUND ~ RE-SET (6/73)

A stone marked with a + 18"x23"

The + on the corner stone appears to be new

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B-T- is P.P., 18" DBH, bears N36°E from corner to tree,

Dist. 55'±: Blage partially healed over ~ STUMP (6/73)

MADE 2 RPS (6/73) 10" P. PINE N60°W 15'± FT.

12" FIR S66°W 18'± FT. - fd.

FIR STUMP, SCAD "14" ; 14" FIR S42°E, 36 ft

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner can be located from B-T. on Suttle Lk. Loop Rd (#1340)

(LATER)

Cor reset by Land Surveyor, See survey notes cm

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

7

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

8

Signature B. ROGERS Title PLS

L.D. Weaver

FA

Division C3

Headquarters 50

50

Date 6/73

7-30-84  
6-14-60

7100-52

REV. 65 5




# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

FD. 1" PIPE W/ BC SET 12" BELOW GROUND SURFACE

ADDED MARKS: BLM, 1969



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

FD. 14" FIR STUMP N39°E 84½ LKS. MKD. 1/4 S on OPEN BLAZE.

ADDED:

15" PINE S42½°E 130 LKS. MKD. 1/4 S 26 BT

13" FIR S62¼°W 28 LKS. MKD. 1/4 S 27 BT

Work Done By BLM Title \_\_\_\_\_ Date 1969 State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. 1769 T. 13 S. R. 8 E M. \_\_\_\_\_ Tract or Surv. No. \_\_\_\_\_ Cor. T-17

Index  
File No. 2169

# CORNER RECORD (SEARCH)

Tract or  
Survey No.

Cor.  
No. T-21

T 13S. R. 8E.

R.D. Sisters

County Jefferson

STD. 1/4 Cor.


Merid. W. 11

N.F. Deschutes

State Oregon

Sec. 26/25

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

No corner found

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 38" P.P. stump with marking was found. Also, a 46" D.F. with healed blazes - did not open.

## PHOTO IDENTIFICATION DATA

Photo No. EG1 50-101

Filed At. Sisters

Object Ident. Cor

Ident. By D.T.

Signature

6

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

7

Signature

D. Thingvall

Title

Hwy Eng

Division

Headquarters

Date

5-15-62

7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

HAWTHORNE:

Brass Cap

1/4

BLM ADDED MARKS

"T13S R8E BLM 1966"

2" S. PIPE

RISING 16"

S26 | S25

AND RAISED MOUND OF

STONES 2' Ø.

1963

9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

NEW BT'S FOR

BLM

BLM FD. ORIG. BT'S: 38" SAWN PINE STUMP MKD. 1/4 SBT

8" D.F. N44 1/2° E 29 1/2' 1ks MKD. 1/4 S25 BT.

ON OPEN BLAZE @ S24° E 77 LKS.

14" P. Pine N77° W 30 1/2' 1ks MKD. 1/4 S26 BT.

42" FIR WITH FRAGMENTARY SCRIBE

MARKS VIS. ON PT. HEALED BLAZE

@ N17° W 56 1/2 LKS.

Plus old ones

10

Work Done By J. HAWTHORNE

BLM

Title

Date 1963/1966

State Registration No. or Agency

Certified Cor. Record Prepared ? Yes

No

Filed At:

Date

11

REMARKS

12

Index File No. 2169

T. 13 S. R. 8 E.

M.

Tract or Surv. No.

Cor.

T-21


13

Index  
File No. 2569

## CORNER RECORD (SEARCH)

Tract or  
Survey No. \_\_\_\_\_Cor.  
No. T-25T 13S., R. 8E.R.D. SistersCounty JeffersonSTD. 1/4 CorMerid. WillN.F. DeschutesState OregonSec. 25/30

## CORNER DIAGRAM.



## DESCRIBE CORNER MONUMENT FOUND

No corner material.

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

An 18" pine could be possible BT on NE; blaze isn't open but a tag on tree, F.S. by r.m.A.P. 12-1-40 and Beile, Hagen 3-14-50 A down snag could be 2<sup>nd</sup> BT but blaze is on the under side.

## PHOTO IDENTIFICATION DATA

Photo No. EG1 50-156Filed At. SistersObject Ident. CorIdent. By D.T.Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature

D. Thinsvall

Title

Hwy Eng

Division

Headquarters

Date

5-11-62


7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap on 2 1/2" x 28" STEEL PIPE RISING 4"



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

NEW BT'S BY BLM:

5" Fir N48°W 43 1/2 lks MKD. 1/4 S25 BT

5" Fir S66°E 145 lks MKD. 1/4 S30 BT

plus old ones: 17" PINE N32°E 78 lks. WITH VIS. MKS. 1/4 S ON PT. HEALED BLAZE.  
Root Hole S40°E 9 lks. WITH DOWN PINE, 24" Ø, WITH FRAGMENTARY SCRIBE  
MARKS VIS - ON OPENED BLAZE.

10

Work Done By. BLM

Title \_\_\_\_\_

Date 1966 State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes \_\_\_\_\_

No \_\_\_\_\_

Filed At: \_\_\_\_\_

Date \_\_\_\_\_

11

REMARKS

Index File No. 2569 T. 13. R. 8 E. M.

Tract or Surv. No. \_\_\_\_\_

Cor. T-25 13

12

Index  
File No. 1370

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey N<sup>o</sup>.2-2

Cor.

No. 4-13T 13 S. R. 8 E.R.D. SISTERS

County


JEFFERSONS<sup>1</sup>/<sub>16</sub>

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 27 & 28

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

B.L.M. BRASS CAP ON STEEL PIPE 8" ABOVE GRND.4X4 POST ALONG SIDE "STATE PARK BOUNDARY-S<sup>1</sup>/<sub>16</sub> S 27"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

23" W. FIR S 40° W @ 14<sup>2</sup> FT. (BLAZE HEALED OVER)F.S. LOC. POSTER DATED 8/13/69; BT TAG DATED 7/8116" W. FIR S 67° E @ 18<sup>2</sup> FT. (SCRIBING VISIBLE)BT TAG DATED 7/81; STATE PARKS POSTER DATED 9/17/68

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

MONUMENT FALLS APPROX. 1/4 MI WEST OF BLUELAKE. IN SWALE WHICH IS APPROX. 130 FT.WEST OF MARKED X-COUNTRY SKI TRAIL

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: R. H. GRAVETitle PLS  
950

Division

Headquarters


Date

11/1/82

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By BLM Title \_\_\_\_\_ Date 1966 State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_

Plat DE Cor. Record Prepared? Yes ☐ No ☐ Filed At: Co. Surveyor's Office Date \_\_\_\_\_

11

History of Surveys, G.L.O., etc. DEPENDANT RESURVEY BY GERALD E. CHITTICK IN JULY 1969  
END. 5/8" IRON PIN BY JOHN HOLLINGSWORTH IN 1968, SET IRON  
POST W/BRASS CAP FROM WHICH BT'S BY HOLLINGSWORTH  
a FIR 15" DIA BEARS S 69 1/2° E 29 LKS  
a FIR 24" DIA " S 41° W 22 LKS.

12

Index File No. 1370 T. 13 S., R. 8 E., W.M.

Contract or Surv. No. 2-2

Cor. 11-13 13

Index

File No. 1470-A

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.


2-2

Cor.

No. W-14-AT 13 S. R. 8 E.R.D. SISTERSCounty JEFFERSONWC SMC Cor. ofMerid. WillametteN.F. DeschutesState OregonSection 27

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND



B.L.M. BRASS CAP ON STEEL PIPE 6" ABOVE  
GRND. IN MOUND OF STONES, ± 6' FROM WATER'S  
EDGE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

31" POND. PINE N 72° W @ 16° FT. (SCRIBING VISIBLE)

B.L.M. BT POSTER DATED 5/14, STATE PKS. POSTER 9/16/68

13" WH. FIR N 12° E @ 36° FT. (BLAZES HEALED OVER)

B.T. POSTER DATED 8/13/69 & 54-4 SIGN

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

MONUMENT FALLS ON SOUTHWESTERLY EDGE  
OF BLUE LAKE APPROX. 6 FT. FROM SHORE LINE.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Yd.

Searched By: R.H. GRAVE

Title

PLS 930

Division

Headquarters

Date

11/1/82




# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

@ POINT 0<sup>45</sup> ch. WEST of RECORD MC, SET 2 1/2" x 28" BCSP  
RISING 6" in Mo. of SW. 3'Ø x 6" HIGH.

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" FIR N 11 1/2° E 55 LKS. W/ HEALED BLAZE (BT by HOLLINGSWORTH)  
30" PINE N 66 1/2° W 25 LKS " " " " " "  
#5 SR RSG. 0" in COLLAR of STONE, SOUTH 0° 4' CH. (By HOLLINGSWORTH)

Work Done By. BLM Title \_\_\_\_\_ Date 1969 State Registration No. \_\_\_\_\_  
Plat. or Cor. Record Prepared? Yes ☐ No ☐ Filed At. \_\_\_\_\_ Co. Surveyor's Office Date \_\_\_\_\_

History of Surveys, G.L.O., etc. DEPENDANT RESURVEY BY GERALD E. CHITTICK IN JULY 1969  
SET IRON POST W/ BRASS CAP FROM WITNET  
@ FIR 12" DIA. BEARS N 22° E 23 1/2 LKS. for T14 MC-C line  
@ PINE 30" DIA. BEARS N 85° W 10 LKS.

Index File No. 1470-A T. 13 S., R. 8 E., W.M. Contract or Surv. No. 2-2 Cor. U-HA 13

Index  
File No. 1570 CORNER RECORD (SEARCH) Contract or  
(Ref. FSM 7151.4) Survey No. 2-2 Cor. No. U-15  
T 13 S. R. 8 E. R.D. SISTERS County JEFFERSON CS 16 Cor. of  
Merid. Willamette N.F. Deschutes State Oregon Section 27

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

FND. B.L.M. BRASS CAP W/4x4 POST, RISING 8".

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FND: PONDEROSA PINE 24" DBH, 19.70 FT., N 31° E  
PONDEROSA PINE 24" DBH, 26.70 FT., S 50° W  
#SSR in CONCRETE PIER 15' EASTERLY.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

CORNER LEGEND:

FS or Unverified  
Constr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS ON CRATER RIM APPROX. 400 FT.  
SOUTH OF BLUE LK. & 10 FT. WEST OF HORSE  
TRAIL.

Searched By: NORM NEWTON PLS  
654

Division

Headquarters


Date

11/22/82

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By BLM Title \_\_\_\_\_ Date 1969 State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Plat PE Record Prepared? Yes ☐ No ☐ Filed At: \_\_\_\_\_ Co. Surveyor's Office Date \_\_\_\_\_

History of Surveys, G.L.O., etc. DEPENDANT RESURVEY BY GERALD E. CHITTICK IN JULY 1969  
SET IRON POST W/BRASS CAP FROM WHICH  
A PINE 24" DIA. BEARS N 30 1/2° E 30 YDS.  
@ PINE 25" DIA. BEARS S 46° W 41 YDS.

BLM/CHITTICK FOUND TOLLINGSWORTH'S STEEL ROD OUT OF POSITION S. 1 3/32 FT. X W. 3 3/16 FT. FROM P.O.

Index File No. 1570 T. 13 S., R. 8 E., W.M. Contract or Surv. No. 2-2 Cor. U-15 13

Index

File No. 1570-A

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 2-2


Cor.

No. U-15AT 13 S. R. 8 E. R.D. SISTERSCounty JEFFERSON

WCSMC Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 27

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

FD. BRASS CAP ON 2 1/2" IRON PIPE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

28" GRAND FIR, 5<sup>2</sup> FT., S 13° W, SCRIBING VISIBLE16" GRAND FIR, 15° FT., N 73° E, SCRIBING VISIBLE

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

B.C. FALLS APPROX. 6 FT. SOUTH OF WATERSEDGE ON SOUTH EDGE OF BLUE LAKE.Searched By: NORM NEWTON

Title

PLS

Division

Headquarters

Date

11/22/82

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT


Set 2 1/2" x 28" BCSF RSG. 6" in MD. of Stones 3' Ø x 6" hi.

@ 0<sup>10</sup> ch. NLY. BLU FO. ORIG. MEANER STONE LYING

IN 3' of WATER MKD. "XME" on North Face of SE BT. Now 40".

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

MONUMENT STAMPED



Work Done By: BLU Title: \_\_\_\_\_ Date: 1969 State Registration No. \_\_\_\_\_  
 Plat or Certified Cor. Record Prepared? Yes ☐ No ☐ Filed At: \_\_\_\_\_ Co. Surveyor's Office Date: \_\_\_\_\_

History of Surveys, G.L.O., etc. ORIG. SURVEY BY WILLIAM S. CAMPBELL IN 1895. SPECIAL MEAN-  
 DER COR. (S. BANK BLUE LK.) SET VOLCANIC STONE - 15" x 14" x 8"  
MKD. "SMC" ON N. FACE. { BLU, 1969: SET BC AS FOUND  
LARCH 24" S 71° E 69 LKS. (45.5') { BY NEWTON.  
LARCH 19" S 3° W 16 LKS. (10.6')


Index File No. 1570-AT. 13 S., R. 8 E., W.M. Contract or Surv. No. 2-2 Cor. U-15-A 13

Index  
File No. 0971

## CORNER RECORD (SEARCH)

Tract or  
Survey No.Cor.  
No.V-9T 13S, R. 8E,R.D. SistersCounty JeffersonS.D. Sec. Cor. 2928Merid. WillN.F. DeschutesState Oregon3233

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

Stone found but had no visible markings, but seemed in good relationship to B.T. STONE NOT A CORNER. ORIGINAL CORNER WAS A POST. SE/NIE

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.T. sect. 28: Alpine fir 14" DBH GONE 1981 } COMPLETELY DOZED OUT BY LOGGING.  
BT sect 33: W.P. - Down snag " " "  
BT sect 34: DF 36" DBH - No Vis. MKS. - AXED INTO BUT NOT ALL WAY THRU SEAM.  
S-29 - ROTTED 15" LOG, MKS. VIS. 5118/529 FT

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature ROMANH. CordellTitle P.L.S. DivisionForesterHeadquarters S.O.Date 7/81


7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" ALUMINUM-CAPPED ALUMINUM PIPE RSG. 3"  
IN AMOUND OF STONES AT BOTTOM OF CUT-BANK



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" W.F. N 31° W 19' 10" TO 60d NAIL IN SW BASE, MKD. T13S R8E S29 BT  
10" " N 0 3/4° E 42' 20" " " " " W SIDE ± 5' HI, MKD. " " S28 "  
11" HEMLOCK S 34 1/4° E 106' 47" " " " " NE BASE " " " S33 "  
19" SPRUCE S 17 1/2° W 86' 50" " " " " E " " " S32 "  
36" W.F. S 33 1/4° W 25' 70" " " " " SE " (ORIG. BT)

Work Done By. R. OMAN Title PLS Date 7/81 State Registration No. OR-702  
or Agency

Certified Cor. Record Prepared? ☒ Yes No Filed At: JEFF G. SURV. OFFICE Date 8/81

REMARKS

Index File No. 0971 T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. V-9

Index  
File No. 1171

# CORNER RECORD (SEARCH)

Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. V-11

T 13S., R. 8E.

R.D. Sisters County Jefferson


S 1/4 Cor. Sec. 28

Merid. Will.

N.F. Deschutes State Oregon

N/4 Cor. Sec. 33

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

No stone or stake found.

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

BT in section 28: White fir 21.6" DBH, DOWN LOG in 1981  
MKS. VIS.: 45 BT

ROTTED STUMP IN SW LOCATION

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature R. OMAN

H. Cordell

Title R.C.S. Division

Forester

Headquarters J. O.

Date 7/81

8-29-61

7100-52


REV. 65 5



# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" ALUMINUM-CAPPED ALUMINUM PIPE RSG. 3"  
ABOUT 50' ABOVE TIE of SLOPE, ABOUT 250' W. of small pond,  
ABOUT 500' SE of a CINDERED SPUR ROAD



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" HEMLOCK N59 1/4° W 1464 TO 60 d NAIL IN SSW CASE, MKD. S/4 S28 BT  
6" " S31 3/4° W 1524 " " " " SE " " N/4 S33 BT

Work Done By. R. OMAR Title PLS Date 7/81 State Registration No. OR-702  
or Agency  
Certified Cor. Record Prepared? ☒ Yes No Filed At: JEFF CO. SURV. OFFICE Date 8/81

REMARKS

Index File No. 1171 T. 13 S. R. 8 E. M. Tract or Surv. No. Cor. V-11

Index

File No. 1371

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

2-2

Cor.


No. V-13T 13 S. R. 8 E.R.D. SISTERSCounty JEFFERSONSW

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 27

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



FND. STONE ALONG SIDE B.L.M. BRASS CAP ON  
STEEL PIPE & 4x4 PAK BOUNDARY POST, RS6.7"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" D. FIR S 50°W @ 19° FT. (SCRIBING VIS. - ORIGINAL)

19" P. PINE N 25°W @ 20° FT. (SCRIBING VIS. - ORIGINAL)

24" D. FIR SNAG S 65°E 60° FT. (SCRIBING VIS. - ORIGINAL)

10" P. PINE N 41°E @ 61° FT. (SCRIBING VIS. - BLM 1966)

8" D. FIR S 64°E @ 32° FT. (SCRIB. HEALED OVER, BLM 1966)

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Yd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

MONUMENT FALLS APPROX. 1/4 MILE SOUTHWEST-  
ERLY FROM BLUE LAKE. 300 FT. WEST OF  
MEADOW ON RIDGE

Searched By: R.H. GRAUETitle PLS  
930

Division

Headquarters


Date

11/1/82

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

(History Cont.) 1896: J. H. QUINN FOUND AND USED CAMPBELL'S CORNER  
IN RETRACEMENT SURVEY TO ESTABLISH CORNERS IN W. 1/2 OF TOWNSHIP.  
1966: J. JELLEY RE-ESTABLISHED MONUMENT FROM EVIDENCE.

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_  
 Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Co. Surveyor's Office Date \_\_\_\_\_

History of Surveys, G.L.O., etc. ORIG. SURVEY BY WILLIAM S. CAMPBELL AUG. 1895  
SET IRONSTONE 15" X 12" X 8" 10" IN GRND., 1 GROOVE S. & 3 GROOVES  
E. EDGES  
18" PINE N 46° E 93 LKS.; 22" FR S 65° E 94 LKS.;  
24" PINE S 50° W 28 1/2 LKS.; 14" PINE N 25° W 32 LKS.

Index File No. 1371 T. 13 S., R. 8 E., W. M. Contract or Surv. No. 2-2 Cor. V-13

## LAND CORNER RECORD

V-14 5680-2

1. T. 13S R. 8E No. V-14 Cor. 1/16 Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status

34  
7. Photo Identification

Photo No. \_\_\_\_\_

Ident. By: \_\_\_\_\_

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners:

5. Investigation Notes:


Monumented by BLM survey, 1969

6. Signed \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

# PERPETUATION RECORD

## 10. Monument:

Set 2 1/2" x 28" BCSP RSG. 6" ~  
 Deposit HOLLINGSWORTH STEEL PIN ALONGSIDE



## 11. Accessories

HOLLINGSWORTH'S BT'S, ACCEPTED BY BLM:

48" PINE N 33° E 22 LKS. MKD. W 1/16 S 27 BT RS 691.

30" PINE S 42° W 43 LKS. MKD. W 1/16 S 34 BT RS 691.


|                                   |              |                             |                                               |
|-----------------------------------|--------------|-----------------------------|-----------------------------------------------|
| 12. Set By <u>BLM</u> Title _____ |              | Field Book _____ Page _____ |                                               |
| License _____                     | Agency _____ | Date <u>1969</u>            | 13. Recorded By _____ Volume _____ Page _____ |
|                                   |              |                             | (Agency)                                      |
|                                   |              |                             | (Date) (City) (County) (State)                |

## 14. Remarks:

Index  
File No. 1571CORNER RECORD (SEARCH) Contract or  
(Ref. FSM 7151.4) Survey No. 2-2Cor. No. V-15T 13 S. R. 8 E. R.D. SISTERS County JEFFERSON S 1/4 Cor. of  
Merid. Willamette N.F. Deschutes State Oregon Section 27

## CORNER DIAGRAM per legend

CORBETT PK. ROAD



## DESCRIBE CORNER MONUMENT FOUND

FD. 3" BRASS CAP ON 2 1/2' G.I.P. W/ROCK COLLAR, RSG64",

4x4 POST IS 1 FT. NW OF B.C. &amp; RED CARBONITE

POST W/ F.S. BDRY. SIGN, 54-9 SIGN 2' EAST

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

23" D. FIR S 33° E @ 36° FT. (SCRIBING VIS.; 1969 BLM)

16" FIR SNAG N 04° W 42° FT. (SCRIBING VIS.; 1969 BLM)

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
Signature \_\_\_\_\_

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

TURN SOUTH OFF BLUE LK. ROAD BEFORE CAMP  
GROUND ON ROAD TO CORBETT STATE PARK.FOLLOW ROAD APPROX. 1/2 mi. CORNER LIES ON  
NO. SLOPE OF RIDGE APPROX. 400' SOUTH OF RD.

## CORNER LEGEND:

FS or Unverified  
Constr. Other  
○ ◇ Searched For/Not Found  
⊗ ⊗ Evidence Found/Accept.  
● ◆ Permanent Mon. Set/Fd.Searched By: NORM NEWTON Title PLS  
654

Division


Headquarters

Date 11/22/82

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By BLM Title \_\_\_\_\_ Date 1969 State Registration No. \_\_\_\_\_  
 Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Co. Surveyor's Office Date \_\_\_\_\_

History of Surveys, G.L.O., etc. ORIG. SURVEY BY WILLIAM S. CAMPBELL, 1895  
SET IRONSTONE 15"X 15"X 14", MKD. "1/4" ON N. FACE  
PINE 18" N 75° E 47 LKS. (312')  
FIR 16" S 22 1/2° E 53 LKS. (352')

1969: BLM/CHITICK - RE-ESTABLISHED MONUMENT FROM EVIDENCE.

Index File No. 1571 T. 13 S., R. 8 E., W.M. Contract or Surv. No. 2-2 Cor. V-15

Index  
File No. 1771

CORNER RECORD (SEARCH)

Tract or  
Survey No.

Cor.  
No. V-17

T 13S. R. 8E.

R.D. Sisters

County Jefferson

Sec 4 Cor

Merid. Will

N.F. Deschutes

State Oregon

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

1" iron pipe - 1" iron pipe believed not to be corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.T. is snag 20' DBH, bears N80°W from corner dist. of 6'.  
Scribing visible

CORNER RESET BY LAND SURVEYOR, IS IN MIDDLE OF ROAD, SEE  
SURVEY NOTES CM #ACCEPTED BY BLM IN 1966)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is approx <sup>IN ROAD</sup> 25' from rd. to Camp Tamarack and about  
300' from mess hall.

PHOTO IDENTIFICATION DATA

Photo No. EG1-50-31

Filed At. Sisters

Object Ident. Cor

Ident. By D. THINWALL

5-25-62 Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature ROMAN

L.D. Weaver PK

Title P.C.S. Division

F.A. ST

Headquarters 250

Date 7/81

7100-52

6-24-60 7-30-64

REV. 65 5



# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BRASS CAP

S27 | S26  
S34 | S35

IN CONCRETE PIER IN ROAD, BURIED  $\pm 2"$

Reference Monument est by Hawthorne

1981: PLACED RR SPIKE AT N. END of  
MON. for MAGNETIC LOCATOR.

An iron pipe  $\frac{1}{2}$ " diam bears N63°W.,  
42 lks. dist. BLM reset and

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" W Fir S85°E 44 lks

added brass cap T13S R2E S27 RM 1966  
and arrow to corner

25" W Fir N36°E 149  $\frac{1}{2}$  lks.

23" W Fir N73  $\frac{1}{4}$ °W 75 lks

1981: REFERENCE MONUMENT LOST BY EROSION of  
BANK. NO GOOD PLACE TO RE-ESTAB-  
LISH THE R.M.

28" W Fir S30  $\frac{1}{2}$ °W 104 lks

~~R.M. Brass cap N63°W 42 lks~~

BT's FOUND 10

Work Done By BLM

Title

Date 1966

State Registration No.  
or Agency

Certified Cor. Record Prepared? Yes

No

Filed At:

Date

11

REMARKS

Index File No. 1771 T. 13S. R. 8E. M.

Tract or Surv. No.

Cor. V-17

12

13

Index  
File No. 1971

# CORNER RECORD (SEARCH)

Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. V-19

T 13S., R. 8E.

R.D. SISTERS

County JEFFERSON

Std. 1/4 COR

Merid. Will

N.F. DESCHUTES

State OREGON

Sec. 26/35

## CORNER DIAGRAM

## DESCRIBE CORNER MONUMENT FOUND

Fir post  $2\frac{1}{2}'' \times 2\frac{1}{2}''$  -  $3\frac{1}{2}'$  above ground with no markings. Not the original post --- from arcs swung, it is very close - ~~to~~.

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Fir stump (NW) is very rotten. Markings of  $\frac{1}{4}$  S BT are about to fall off. The (SW) fir is completely rotten - no markings.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

7

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From a spur road it is south approx 50' From Rd # 1357-A it is 425' north of tree w/ red blaze; about 0.5 mi. in from junction of 1357 & 1357-A. Best access is to go in Fire Rd #1 about 0.4 mi.

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

8

Signature

O. THINGVALL

Title

HWY ENR

Division

Headquarters

Date

5-15-62

7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap  
By J. H.

2" Ø RISING 1/2"

1 526  
4 535  
1963

BLM ADDED MARKS:

T13S R8E BLM 1966

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

PER BLM:

12" Fir S26°E 201KS MKD. 1/4 S35 BT

17" Fir N70°W <sup>18</sup>201KS MKD. 1/4 S26 BT.

plus old ones; 25" DECAYED FIR STUMP N24 1/2°W 24 1/2 LKS., MKS. VIS.: 1/4 S  
25" " " " 54 1 1/2°W 32 LKS., NO MKS. VIS.

10

Work Done By J. HAWTHORNE / BLM Title \_\_\_\_\_ Date 1963/1966 State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

12

Index File No. 1971 T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. V-19

13

Index  
File No. 2171 ~~#21~~

CORNER RECORD (SEARCH)

Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. V-21

T 13S. R. 8E.

R.D. SISTERS

County JEFFERSON

STD. SEC COR

Merid. Will

N.F. DESCHUTES

State OREGON

24 25

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

12"x9"x7" Stone with groove chiseled No BT Available

35 36

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No definite proof to show this is the actual corner  
3 P.P. with grown over blazes are present

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature

G. Garrison

Title

Forestry Aid

Division

Headquarters

Date

6-14-60

7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_ 11

## REMARKS

640, 1895: SET STONE 15X12X10, 10" IN GROUND, MKD. 1 GROOVE ON S & E EDGES.  
34" PINE N 61° 0' E 43 LKS.  
7" LARCH S 39° 0' E 22 LKS.  
34" PINE S 67° 0' W 50 LKS. STD. MHS.  
14" LARCH N 37° 0' W 43 LKS.

12

Index File No. 2171 T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. V-21 13

2371

Index  
File No. 123

## CORNER RECORD (SEARCH)


Tract or  
Survey No.Cor.  
No.

V-23

T 13S. R. 8E.R.D. SISTERS County JEFFERSONSTD 1/4 CORMerid. WillN.F. DESCHUTES State OREGONSec. 25 / 36

## CORNER DIAGRAM

## DESCRIBE CORNER MONUMENT FOUND



## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

P.Pine 26" diam, with markings of  $\frac{1}{4}$ S B.T. ; also,  
found a 30" P.Pine with markings of  $\frac{1}{4}$ S  
Believe or is about 14' too far north.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

6

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is about 0<sup>3</sup> mi south of junc. to Rd <sup>#</sup>138 & 1375

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

8

Signature

Title

Division

Headquarters

Date

7100-52

O. THINGVALL

HWY ENG

5-15-62

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap  
By J. HAWTHORNE 1 525  
2" Ø RISING 10" 4 536  
IN MO/STN. 2" Ø 1963

BLM ADDED M.K.S.:  
T135 R8E BLM 1966

9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Old ones still good 27' Pine N26°E, 49 lbs "1/4 S BT" vis. on OPEN BLAZE.  
30" Pine S68°W, 57 lbs "4 S" vis. on PT. HEALED BLAZE.

10

Work Done By: HAWTHORNE / BLM Title \_\_\_\_\_ Date 1963 / 1966 State Registration No. \_\_\_\_\_  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

12

Index File No. 2371 T. 13 S. R. 8 E. M.

Tract or Surv. No. \_\_\_\_\_

Cor. V-23 13

2571

## CORNER RECORD (SEARCH)

Tract or  
Survey No.Cor.  
No.

V-25

Index  
File No. ~~V-25~~

T 135, R. 8 E.,

R.D. SISTERS

County JEFFERSON

STD. SEC. COR.

Merid. WILL

N.F. DESCHUTES

State OREGON

Sec 25 30

## CORNER DIAGRAM

## DESCRIBE CORNER MONUMENT FOUND

10" x 6" x 6" STONE

34 31

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.T. Dead P.P. 12" bears S42°E for 19' to cor

B.T PP 16" bears S14°W for 17' to cor

## PHOTO IDENTIFICATION DATA

Photo No. EG1-50-157

Filed At. SISTERS

Object Ident. COR

Ident. By O. THINGVALL

Signature

7

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

8

Signature

G. GURRISON

Title

F.A.

Division

CS

Headquarters

SO

Date

7-30-84  
6-13-60

7100-52


REV. 65 5



# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap  
By J. HAWTHORNE  
2" PIPE RISING 12"



BLM ADDED MKS.:  
BLM 1966  
RAISED NO. / STN. 2' Ø

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" Fir N71°E 36 lks (23' FT.) 14" FIR, N73°E, @ 25', HEALED OVER; 13" SNAG, @ 30', N71°E, SCBD BT.  
22" Pine S36 1/4°E 48 1/2 lks (32' FT.) 8" SNAG, @ 20', S30°E, SCBD "T13SR9ES BT"; 18" PINE, S31°E @ 32'.  
22 Pine N47 1/2°W 110 1/2 lks (72' FT.) SCBD "13SR9ES"; 16" PINE, S14°W, @ 19', SCBD "T13SR8ES36".  
21" PINE, N53°W, @ 70', HEALED OVER

Plus old ones:

NE, SE & SW 12" P. SNAG N63 1/2°E 42 LKS. / 12" P. SNAG S36 1/2°E 30 LKS. / 16" P. S13°W 27 LKS.

Work Done By J. HAWTHORNE / BLM Title \_\_\_\_\_ Date 1963/1966 State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

640, 1895:

REMARKS

Index File No. 2571 T. 13 S. R. 8 E M.

Tract or Surv. No.

Cor. V-25 13

0973

## CORNER RECORD (SEARCH)

Index  
File No. ~~0973~~Tract or  
Survey No.Cor.  
No. X-9T 13S. R. 8E.R.D. SISTERS

County

JEFFERSONE 1/4 COR. SEC. 32Merid. WMN.F. DESCHUTES

State

OREGONW/4 COR. SEC. 33

## CORNER DIAGRAM

## DESCRIBE CORNER MONUMENT FOUND

NO STONE FOUND

THAT'S CUZ NO STONE WUZ SET -  
WHAT WUZ SET WUZ A POST,  
MEATHHEAD!

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

BT in section 32 - DF 60° from approx Cor. location  
BT in section 33 AF 292° from approx Cor. locationBoth BTs were opened in 1956 by HM WHO FAILED TO  
FIND ANY MARKS!

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

1981: OPENED SEAM, MKS. VIS.: 1/

ABOUT 325' E of ROAD 138 OPPOSITE LINK LK. JN.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature R. ROMANH. CordellTitle PLS DivisionForesterHeadquarters SODate 7/818-29-61


7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RSG. 4"



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

21" WF N60 3/4 W 12 46 TO 60 D NAIL IN NE BASE (ORIG. BT)  
 25" WF N66 0 E 14 46 TO " " " NW " " "  
 8" WF S44 0 W 11 43 " " " NE " , MKD; E/4 S32 BT  
 8" WF S67 3/4 E 31 08 " " " SE " " W/4 S33 BT

Work Done By R. OMAN Title PLS Date 7/81 State Registration No. OR-702  
 Certified Cor. Record Prepared? ☒ Yes No Filed At: DEEN JEFF. CO. SURV. OFFICE Date 8/81  
 REMARKS

Index File No. 0993 T. 13 S. R. 8 E. M. Tract or Surv. No. Cor. X-9

## USDA-FOREST SERVICE

Index

File No. 1373

## CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or


Survey No.

Cor.

No. X-13T. 13 S. R. 8 E. R.D. SISTERSCounty JEFFERSONW/4 COR. of SEC. 34Merid. WILLAMETTEN.F. DESCHUTESState OREGONSTD. COR. of SEC. ONLY

## CORNER DIAGRAM PER LEGEND

S.33



S.34

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

## DESCRIBE CORNER MONUMENT FOUND

STONE 14 X 11 X 11 ESG. 4", MKD. 1/4 ON W FACE

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S.33 : 14" LARCH SNAG N79°W 24<sup>32</sup> FT. TO 60d NAIL in N Side  
MKD. 1/4 S BTS.34 : 56" WHITE PINE S62 1/2°E 58<sup>1</sup> FT. TO 60d NAIL in  
S. SIDE, MKD. 1/4 S BT

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

ABOUT 150' S. of CINDERED ROAD LEADING  
FROM ROAD 128 INTO PUT. LANDSignature R. OMANTitle PLS DivisionHeadquarters SDDate 7/81 D-7100-52 (3/79)


# CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RSG. 6"

FOUND

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" W.F. S49 1/4° E 17 8/8 FT. TO 60d NAIL IN SW SIDE, MKD. W/4 S34 BT  
9" W.F. N37° W 5 8/3 FT. " " " " NE BASE " WP S33 BT

FOUND - ALIVE & WELL

Work Done By R. OMAN Title PLS Date 7/81 State Registration No. OR-702  
PLAT PREPARED OR  
Certified Cor. Record Prepared? ☒ Yes No Filed At: JEFF. Co. SURVEYOR'S OFFICE Date 8/81

## REMARKS

THE CLOSING CORNER FOR SEC. 33 WOULD LIE SOME 1.625 CH. S  
OF THIS POINT (107 3/4 FT.) BASED ON THE 3.25 CHS. DECLARED BY  
W.E. CAMPBELL IN 1896 AT THE SE COR.


Index File No. 1373 T. 13 S., R. 8 E., W.M. Tract or Surv. No. Cor. X-13

1773

## CORNER RECORD (SEARCH)

Index File No. ~~X-17~~ Tract or Survey No. \_\_\_\_\_ Cor. No. X-17  
 T 135, R. 8E., R.D. Sisters County Jefferson STD. 1/4 Cor  
 Merid. Will N.F. Deschutes State Oregon Sec. 34/35

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

No corner found - skid trail probably removed the rock for the corner.

Cor is on Wedge of Clear cut

2

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

19" W.F. stump (E.S.) ; and 27" W.F. with 1/4 S markings

6

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

7

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

8

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

4

Signature

O. THINGVALL

Title

Hwy Eng

Division

Headquarters

Date

5-17-62

7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap

$\frac{1}{4}$

on  $2\frac{1}{2}$ " x 28" STEEL PIPE RISING 4"

S34 / S35

T133 R8E

1966

9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" W.F. N65°W 16 LKS MKD.  $\frac{1}{4}$  S34 BT.

6" D.F. S41°E 50  $\frac{1}{2}$  LKS MKD.  $\frac{1}{4}$  S35 BT.

Plus old ones: 27" W.FIR N39°E 50 LKS., MKS. VIS. " $\frac{1}{4}$  S"

20" SAWN W.F. STUMP S62  $\frac{1}{2}$ °W 57 LKS., MKS. VIS. " $\frac{1}{4}$  S BT"

10

Work Done By. BLM

Title \_\_\_\_\_

Date 1966

State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes

No

Filed At: \_\_\_\_\_

Date \_\_\_\_\_

11

REMARKS

12

Index File No. 1773

T. 13 S.

R. 8 E.

M. \_\_\_\_\_

Tract or Surv. No. \_\_\_\_\_

Cor. X-17

13

Index  
File No. 2173

CORNER RECORD (SEARCH)

Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. X-21

T 135, R. 8E,

R.D. SISTERS

County JEFFERSON

STD. 1/4 COR


Merid. Will

N.F. DESCHUTES

State OREGON

Sec. 35 / 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

No corner as corner fell in middle of skid trail.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 18" W.F. snag - someone tried to open blaze's, but it was rotten.

A 24" W.F. blaze partially open - no markings visible.

PHOTO IDENTIFICATION DATA

Photo No. EG1-50-100

Filed At. Sisters

Object Ident. Cor

Ident. By D.T.

Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature

O. THINGALL

Title

Hwy Eng

Division

Headquarters

Date

5-17-62

7100-52

REV. 65 5



# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap  $\frac{1}{4}$  on 2 1/2" x 28" STEEL PIPE RISING 4"  
 535 | 536  
 T 135 | R 2 E  
 1966

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

17" W.F. S50 1/2° E 9 1/4 LKS MKD. 1/4 536 BT  
 17" W.F. S68° W 11 1/4 LKS MKD. 1/4 535 BT  
 Plus old ones: 24" W.F. S69° E 4 1/4 LKS.  
 20" W.F. SNA 571° W 26 LKS.

Work Done By. BCM Title \_\_\_\_\_ Date 1966 State Registration No. \_\_\_\_\_  
 or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS


Index File No. 2173 T. 13 S. R. 8 E. M.

Tract or Surv. No.

Cor. X-21 13

2573  
Index File No. ~~75~~  
T 13S., R. 8E., R.D. SISTERS County JEFFERSON STD. 1/4 COR  
Merid. Will N.F. DESCHUTES State OREGON See. 36/31  
Cor. No. X-25

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

No corner material found -- right on skid trail

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 31" P.P. mkd 1/4S  
A 30' P.P. Stump (fresh) mkd B-T.

## PHOTO IDENTIFICATION DATA

Photo No. E61-50-158  
Filed At. Sisters  
Object Ident. Cor  
Ident. By D.T.  
Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
Agency

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

There is a sec. line marker 10' past culvert marker 1-3.  
Cor is 700' S from Rd # 1315-C. Easiest access is to  
start from through cut about 425' S. of sec line marker.  
Follow skid trail S.E. about 550' - skid trail goes over  
1/4 Cor

Signature

D. THINGVALL

Title

ST  
HWY ENR

Division

CS

Headquarters

50

Date

7-30-62


7100-52

REV. 65 5

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap FOUND on 2 1/2" x 28" STEEL PIPE RISING 4"



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" Fir N18°E 36 1/2 lks

33" PINE, N40°E, @ 20', SCBD "1/4 5"

6" Fir S18°W 10 1/2 lks

9" FIR, N 23°E, @ 23, HEALED OVER

Plus old ones:

10" FIR, S 21°W, @ 7', HEALED OVER

27" P. N 36 1/2°E 29 LKS.

28" STUMP, S 20°W, RSNG 13", @ 43', SCBD "BT"

25" SAWN P. STUMP S17 1/2°W 64 LKS.

Work Done By. BLM

Title \_\_\_\_\_

Date 1966

State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes

No

Filed At: \_\_\_\_\_

Date \_\_\_\_\_

REMARKS

Index File No. 2573 T. 13S. R. 8E. M.

Tract or Surv. No. \_\_\_\_\_

Cor. X-25 13

## USDA-FOREST SERVICE

Index

File No. 0875-A

## CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No. Z-08-AT. 13 S. R. 8 E. R.D. SISTERS County JEFFERSON A.P. COR. of SEC 32Merid. WILLAMETTE N.F. DESCHUTES State OREGON A.P. COR. of SEC. 5

CORNER DIAGRAM PER LEGEND

J.32

J.33

T.13 S.

T.14 S.

173 CH.

393 CH.

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

J.5

DESCRIBE CORNER MONUMENT FOUND

2 1/2" BCSP RSG. 10" 134 BLM

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

20" SPRUCE N45°E MKD. CC 2 S

16" SPRUCE SNAG S10 1/4°W, MKD. 3 S

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

± 100' SW of SPUR ROAD

± 200' S. of SPUR ON SEC. LINE

6/73 B. ROGERS SET #5R AT CC for Sec. 32/33 1152 feet East

Signature R. ONANTitle PLS


Division

Headquarters 50Date 7/81 D-7100-52 (3/79)

# CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

B.L.M.  
MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

11" SPRUCE S60 1/4° E 51' TO 60' NAIL IN NNE SIDE, MKD. AP T14S R8E S5 BT  
11" " N128 3/4° E 24' " " " " NW SIDE ± 6' UP, MKD. AP T13S R8E S32 BT

10

Work Done By R. JMAN Title PCS Date 7/81 State Registration No. OR-702  
or Agency  
PLAT PREPARED OR  
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: JEFF. CO. SURVEYOR'S OFFICE Date 8/81

11

REMARKS

12

Index File No. 0875-A T. 13 S., R. 9E E., W.M.

Tract or Surv. No.

Cor. 2-08-A 13

Index

File No. ~~15~~ 0975

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 000777

Cor.

No. ~~2-09~~

T 13 S R. 8 E

R.D. Sisters

County County Line

Jefferson (N)


Merid. Will

N.F. Deschutes

State Oregon

Deschutes (S)

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND None

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Fir snag brs. N29°W 21.1' Scribes visible.

Original NE BT dead & down & pushed out of position. Unable to determine where root hole was due to logging activity.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

7

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 2075; East on Rd. 2076-600 1/4 mi. E to posted line; thence South on posted line 1/4 mi. to corner.

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

8

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

4

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Original position of CC was established for line only. Survey determined proper position for monumentation to be in slash pile containing objects too heavy to be removed by hand. Unable to monument this date.

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5/8" x 30" iron rod w/ yellow plastic cap b/s. N01°37'53"E 21.79'  
5/8" x 30" iron rod w/ yellow plastic cap b/s. S64°38'07"W 28.96'  
Steel guard posts w/ signs 54-9 set @ both iron rods.

10

Work Done By A. P. P. P. Title LS Date 4/88 State Registration No. 00065-1020  
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At Des. Jeff. Co. Surveyors Off. Date 1988

11

REMARKS

NOTE:


Above iron rod accessories are witness to proper monumentation position on 356 Standard Parallel South!

12

Index File No. 135 T. 135 R. 8E M. W11 Tract or Surv. No. Cor. 2-09

Index  
File No. 1175CORNER RECORD (SEARCH)  
(Ref. FSM 7151.4)Tract or  
Survey No. 000777 Cor.  
No. Z-11T 135 R. 8E R.D. Sisters County County Line Jefferson Co. (N)  
Merid. Will. N.F. Deschutes State Oregon Deschutes Co. (S)

## CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND None

Two original BT's established on original survey. Careful search of entire area was conducted and several old trees (3'-5' DBH) with scars were examined. Two smaller trees with scars were opened. No evidence of original BT's was found.

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Junction of Rds, 600 & 620; South on 620 100'±; thence East, on posted line, 700'± to Corner. Corner is at North edge of clear cut.

Signature

Title LS

Division

Headquarters

Date

11-88

FS-7100-52 (3/68)



# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Established corner position by "Broken Boundary" method and set 2 1/2" x 30" ACAP T135R8E 533. No stones available.

Cap. No. Rel.  
56 1/4  
T135 R8E  
533  
54  
T145  
1988

Guard Post w/ signs 54-2 & 54-9 3' East of corner. LS 1020 9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" F.I. Brs. N64°W 19.3' marked AP T135 R8E 533 BT  
12" F.I. Brs. S13°E 11.4' marked AP T145 R8E 54 BT

Work Done By

*J. Collins*

Title

LS

Date

11-88

State Registration No.

or Agency

ORPLE 1020

Certified Cor. Record Prepared?

Yes

No

Filed At

*Deputies Jefferson Co. Surveyors*

Date

1988

REMARKS

Index File No.

1175

T.

135

R.

8E

M.

Will

Tract or Surv. No.

Cor.

2-11

12

13


Index  
File No. 1375-A

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. 000777 Cor.  
No. 2-13-AT 13S R. 8ER.D. Sisters County Clatsop Jefferson (CN)Merid. Will.N.F. Deschutes State Oregon Deschutes (S)

## CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

~~At the~~  
S.C. - S.E. Cor. 534-ACAP brs. North 209° 05'  
W.P. - Old S.C. Secs. 33-34 - Alum. cap on  
5/8" iron rod brs. West 127° 36'

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Junction of Rds. 2068 & 2076-600;  
Southeasterly on Rd. 2068 1/10 mi. to posted  
forest boundary; thence South on  
posted line 1/4 mi. to corner.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" ACAP rising 6".

No stones available.

Corner position established by bearing x bearing intersect from noted official accessories found.

Steel guard post w/ signs 54-2, 54-9 West.

Cap marked  
SC  
T135 R8E  
533!  
- .X  
6  
T145  
1988  
LS 1020

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

14" F.I. brs. N 70° W 15.4' marked T135 R8E 533 SC BT

9" F.I. brs. N 15° W 19.9' marked T135 R8E 533 SC BT

10

Work Done By A. Cohen Title LS Date 11/88 State Registration No. or Agency ORPLS-1020

Certified Plat Cor. Record Prepared? ☒ Yes ☐ No Filed At: Dee. Jeff. Co. Surveyors Off. Date 12/88

11

REMARKS

12

Index File No. 1375-A, 135 R. 8E M. W. H. Tract or Surv. No. Cor. 2-13-A

## USDA-FOREST SERVICE

Index

File No. 1375-A

## CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or


Survey No.

Cor.

No. Z-13-AT. 13 S. R. 8 E. R.D. SISTERS County JEFFERSON C.C. SE COR. of SEC. 33Merid. WILLAMETTE N.F. DESCHUTES State OREGON = AP COR. of SEC. 4

## CORNER DIAGRAM PER LEGEND

S. 33 S.C. S. 34



## DESCRIBE CORNER MONUMENT FOUND

SF/NF

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SF/NF

BROOKS-SCANLON CRUISER'S POST IN APPROX.  
TURN POINT

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

## Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent MonumentSignature R. OMANTitle PLS

Division


Headquarters SODate 7/81

D-7100-52 (3/79)

# CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By

Title

Date

State Registration No.  
or Agency

**PLAT PREPARED OR**

Certified Cor. Record Prepared ? Yes

No

Filed At

**Co. SURVEYOR'S OFFICE** Date

11

REMARKS

12

Index File No. **1375A T. 13 S., R. 8 E., W.M.**

Tract or Surv. No.

Cor. **2-13-A**

## USDA-FOREST SERVICE

Index  
File No. 1375-B


## CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or  
Survey No. \_\_\_\_\_Cor.  
No. Z-13-BT. 13 S. R. 8 E. R.D. SISTERS County JEFFERSON W.P. Cor. of Sec. 4#33Merid. WILLAMETTE N.F. DESCHUTES State OREGON Cor. of Sec. 1

## CORNER DIAGRAM PER LEGEND

## DESCRIBE CORNER MONUMENT FOUND



## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S. 4: 31" DOUG. FIR SNAG S05°E 137 FT. ~ AXING BY SOMEONE  
LOOKING FOR EVIDENCE ~ OPENED UP SEAM AND  
FD. ORIGINAL HELL CUT AND TOP OF FALE BLAZE.

S. 33: ROTTED STUMP IN NE LOCATION  
ROTTED UPROOT IN NW LOCATION

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER


Signature R. OMANTitle PLS Division \_\_\_\_\_Headquarters SODate 7/81 D-7100-52 (3/79)

# CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET #5X 30" ALUMINUM-CAPPED STEEL ROD RSG. 2"

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" W.F.  $332\frac{1}{4}^{\circ}E$  1340 FT. TO 60# NAIL IN W BASE, MKD. T14S R8E S4 WP BT  
12" "  $N19^{\circ}E$  591 FT. " " " " " SIDE, " T13S R8E S33 BT

Work Done By R. OMAN Title PLS Date 7/81 State Registration No. OR-702  
PLAT PREPARED OR  
Certified Cor. Record Prepared? ☒ Yes No Filed At: JEFF. CO. SURVEYOR'S OFFICE Date 8/81

REMARKS

Index File No. 1375-B T. 13 S., R. 8 E., W.M.

Tract or Surv. No.

Cor. 2-13-B

USDA-FOREST SERVICE

Index  
File No. 1375-C

## CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No.Cor.  
No.T 13 S. R. 8 E. R.D. SISTERS County JEFFERSON NO Cor. Sec 344  
Merid. WILLAMETTE N.F. DESCHUTES State OREGON RP Sec 34SEK: A-13-C  
T14S R8E#5 A-C SR  
ret 1981 by R&D



1375-C

2-13-C

## USDA-FOREST SERVICE

Index

File No.

1575

## CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.


No.

2-15

T. 13 S. R. 8E. R.D. SISTERSCounty JEFFERSON3/4COR. of SEC. 34Merid. WILLAMETTEN.F. DESCHUTESState OREGONCOR. of SEC. only

## CORNER DIAGRAM PER LEGEND

S. 34



## DESCRIBE CORNER MONUMENT FOUND

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SF/NF

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature R. OMANTitle PCS


Division \_\_\_\_\_

Headquarters SODate 7/81

D-7100-52 (3/79)

# CORNER RECORD (PERPETUATION)

MONUMENT STAMPED



9

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

PLAT PREPARED OR  
Certified Cor. Record Prepared ? Yes

No

Filed At:

Co. SURVEYOR'S OFFICE Date

11

REMARKS

12

Index File No. 1575 T. 13 S., R. 8 E., W.M.

Tract or Surv. No.

Cor. 2-15 13

## USDA-FOREST SERVICE


Index  
File No. 1775T. 13 S. R. 8 E.Merid. WILLAMETTE

## CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

R.D. SISTERSCounty JEFFERSONN.F. DESCHUTESState OREGONTract or  
Survey No.Cor.  
No. 2-17SC COR. of SEC. 34/35WP COR. of SEC. 2

## CORNER DIAGRAM PER LEGEND



## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

## Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accepted☒ Permanent Monument

## DESCRIBE CORNER MONUMENT FOUND

2 1/2" B-C SP BURIED 6" AND CAUTED OVER BY  
LOGGING OPERATION

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S. 34: 36" WHITE PINE, MKS. VIS.: S 8E S 34

S. 35: 27" FIR STUMP, SAWN, MKS. VIS.: S 55 BT

17" FIR W/DEAD TOP, MKS. VIS.: S 8E S 35 SC BT

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature R. OMANTitle PLS

Division \_\_\_\_\_


Headquarters SDDate 7/81 D-7100-52 (3/79)

# CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

RESET 2 1/2" X 28" BRASS-CAPPED STEEL PIPE, RSG. 6"  
IN MOUND OF STONES ±100' S. of TOE of SLOPE, ±300'  
N. of top of RIDGE, AT S-EDGE of CLEARCUT UNIT

B.L.M. MONUMENT STAFFED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

3" R.P. N71°E 1266 FT. TO 60d NAIL IN N BASE, MKD. X 1BT  
96" W.P. N71°W 2530 FT. " " " S BASE (ORIG. BT)  
27" W.F. STUMP N56°E 3950 FT. TO 60d NAIL IN TOP/CTR., (ORIG. BT)  
17" W.F. W/DEAD TOP by BLM N46°E

Work Done By R. OMAN  
PLAT PREPARED OR  
Certified Cor Record Prepared? ☒ Yes ☐ No

Title

PLS

Date 7/81

State Registration No.  
or Agency

OR-702

Filed At VEIFF

Co. SURVEYOR'S OFFICE Date 8/81

## REMARKS

THIS IS A STANDARD CORNER FOR ALL 4 SECTIONS. McCLUNG'S  
1870 SURVEY CLOSED THE LINE FROM THE SOUTH ONTO THE  
EXISTING CORNER. THE BLM ERRED IN 1966 BY MARKING  
CAP AS STD. ONLY FOR SEC'S 34 & 35 and THE GLO ERRED IN  
1895 WHEN W<sup>2</sup> CAMPBELL IGNORED McCLUNG'S WORK & CREATED A HIATUS.

Index File No. 1775 T. 13 S., R. 8 E., W.M.

Tract or Surv. No.

Cor. 2-17

Signature

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" brass capped steel pipe rising 5". No stones available.

Cap marked SC  
7135 R8E  
1/4 S35  
4--  
1988  
LS 1020

Steel guard post w/ sign 54-9 North.

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" Fir brs. N26°W 7.2' marked 1/4 S35 SC BT.  
8" Fir brs. N72°E 47.1' marked 1/4 S35 SC BT.

Work Done By

*J. Colvin*

Title

LS

Date

11/88

State Registration No.

or Agency

00015-1020

Certified Cor. Record Prepared ?

Yes

No

Filed At

Deer, Jeff. Co. Surveyors Off.

Date

1988

REMARKS

Index File No.

1975 T. 135

R.

8E

M.

W-11


Tract or Surv. No.

Cor.

2-19

Index  
File No. 2175  
T 13 S. R. 8 E. R.D. SISTERS County JEFFERSON Cor. No. 2-21  
Merid. WILLAMETTE N.F. DESCHUTES State OREGON Section 36

SEE: A-21 T. 14 S., R. 8 E., W.M.







Index

File No. 2375

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.

No. 2-23

T 13 S. R. 8 E. R.D. SISTERS

County JEFFERSON

5/4 Cor. of

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

Section 36

SEE: A-23 T. 14 S., R. 8 E., W.M.

BCSP

S. 36

T. 13 S.

JEFF. CO.

T. 14 S.

DESC. CO.

S. 1  $\frac{1}{4}$



Index  
File No. 2575

# CORNER RECORD (SEARCH)

Tract or  
Survey No.

Cor.  
No. 2-25

T 13S, R 8E,

R.D. SISTERS

County JEFFERSON

STD. SEC COR


Merid. Will

N.F. DESCHUTES

State OREGON

36 31

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

Found stone 12"x8"x3" --- 3" above ground in good condition.  
Row of notches on N. face (counted 3) 1 notch on E. face  
probably more on both edges

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 24" P.P. snag (ready to fall down) mkd. visible 13S R81S31  
which bears N40°W, 118' dist

## PHOTO IDENTIFICATION DATA

Photo No. EG1-50-158

Filed At. Sisters

Object Ident. Cor

Ident. By O.T.

Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature

O. THINWALL

Title

Hwy Eng.

Division

Headquarters

Date

7-30-84  
6-5-62

7100-52

REV. 65 5

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER


In sec 31, T13S, R9E, an old rd leaves Rd 1375 and connects  
with Rd # 1315-K, there is a sec. line mrkr about 0.4 mi  
from Rd 1375. The cor is 990'S.

For update  
See T145 R9E: A-01

# CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Bronze Cap FOUND on 2 1/2" X 28" STEEL PIPE RISING 4"



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" D.F. N 22° E 15 lks HEALED OVER  
 6" Pine S 37° E 7 1/2 lks - NOW HEALED SNAG  
 6" Pine S 54 1/2° W 60 1/2 lks HEALED OVER  
 5" Pine N 66 1/2° W 27 lks HEALED OVER

Plus old one: 19" P. SNAG N 43° W 19 LKS. SCR. M.K.S. V.I.S.

10

Work Done By. TBLW Title \_\_\_\_\_ Date 1966 State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

Index File No. 2575 T. 13 S. R. 8 E. M. Tract or Surv. No. \_\_\_\_\_ Cor. 2-25 13

12