


T 13 S R 9 E M W.1



LEGEND

○ = Corner having information on form 5680-2 in this file.

FILING INSTRUCTION

File 5680-2 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 5680-2 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.

-7100-52d (10/78)
DA-FOREST SERVICE

Index
No.

0151

13 S. R. 9 E. R.D.

Merid. WILLAMETTE N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

SISTER S

County JEFFERSON

DESCHUTES

State OREGON

Tract or
Survey No.

Cor.
No.

A-01

NW 1/4 Sec 6

SE 1/4 Sec 36

SEE; 2-01

7125 R9E

11.40

A-01

Index

File No. 0351

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. A-3

T S. R. E. R.D. Sisters

County Jefferson

Merid. WILLAMETTE N.F. DESCHUTES

State OREGON

1/4 Cor

SEE: Z-3

T125, R9E

A3

Index
File No. 0551 CORNER RECORD (SEARCH)
(Ref. FSM 7151.4) Tract or
Survey No. Cor. No. A-5
T S. R. E. R.D. Sisters County Jefferson
Merid. WILLAMETTE N.F. DESCHUTES State OREGON
Sec Cor


SEE: Z-5

T123, R9E

A-5

Index
File No. ~~A-7~~ 0751 CORNER RECORD (SEARCH) Tract or
Survey No. _____ Cor. No. A-7
T 13S, R. 9E, R.D. SISTERS County JEFFERSON 1/4 Cor
Merid. Will N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: Z-7, T12S, R9E,

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

Index File No. 0751 T. 135 R. 9E. M.

Tract or Surv. No.

Cor.

12

13

Index
File No. 0951

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. A-9

T S. R. E. R.D. Sisters County Jefferson

Merid. WILLAMETTE N.F. DESCHUTES State OREGON

See: Z-9

T125, R9E

A-9

D-7100-52 d (10/78)
USDA-FOREST SERVICE

Index
File No. 1351

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. _____

Cor.
No. A-13

T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON SE COR SEC 33
Merid. WILLAMETTE N.F. DESCHUTES State OREGON NW COR SEC 3

SEE: T 12 S R 9 E Z-13

(CORNER SET WITH REFERENCE MONUMENTS)



D-7100-52 d (10/78)
USDA-FOREST SERVICE

Index
File No. 1551

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No.

Cor. E-A-15
No.

T 13 S. R. 9 E. R.D. SISTERS

County JEFFERSON

S/4 COR SEC 34

Merid. WILLAMETTE

N.F. DESCHUTES


State OREGON

N/4 COR SEC 3

JEE T125-R9E

Z-15

BC SET



Index		CORNER RECORD (SEARCH)		Tract or	Cor.
File No.	<u>1751</u>	(Ref. FSM 7151.4)		Survey No.	No. <u>A-17</u>
T <u>13</u>	S. R. <u>9</u>	E. R.D. <u>SISTERS</u>	County <u>JEFFERSON</u>	<u>NE COR. SEC. 3</u>	
Merid. <u>WILLAMETTE</u>	N.F. <u>DESCHUTES</u>	State <u>OREGON</u>	<u>SW COR. SEC. 35</u>		

SEE: Z-17

T 12S R9E

BC set 12/80
By R. OMAN

Index

File No. 2351

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

A-23

T 13 S. R. 9 E. R.D. SISTERS

County JEFFERSON

N/A COR. SEC. 1

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

3/4 COR. SEC. 36

SEE: Z-23

T12S R9E

BC Set 1980
By R. E. O.

A-23

Index
File No. 2551

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. Cor. A-25

T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON NE COR. SEC. 1

Merid. WILLAMETTE N.F. DESCHUTES State OREGON

SEE T13S R10E

A-1

~~ST/NF~~

~~Ray Oman~~

BCSP by W. Miller 8/89


H-25

LAND CORNER RECORD

5680-2

1. T 13S R 9E No. 09 Cor. $\frac{1}{4}$ Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters 29

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: _____

5. Investigation Notes: No bearing trees found. Found a metal poster on a Western Larch 21 inch. diam. Section line marker between Secs. 4 & 5 is on fire rd #6, 226 ft. north.

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed Calvin W. Minks Title Forestry Tech. Date 6-8-62

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

(Date)

(City)

(County)

(State)

14. Remarks:

0-9

Index

File No. 0155


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. E-1T 13S R. 9ER.D. SISTERSCounty JeffersonSEC. COR.Merid. WILL.N.F. DESCHUTES State OREGON

CORNER DIAGRAM

R8E R9E



DESCRIBE CORNER MONUMENT FOUND

STONE 5" x 4 x 4 SET IN GRD.
ONE NOTCH IN N. FACE; 5 NOTCHES IN W. FACE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 32" PP N31°W 8FT MKD. "T13S Sec1 R8E BT"
A 37" PP N43°E 69'S" MKD. "T13S R9E S6 BT"
A 40" PP S48°E 34.8' MKD "T13 R9E S7 BT"
A 14" PP STUMP(ROTTED) S54°W 48FT. MKD. "T13S ? BT"

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON W. SIDE OF 12" P. PINE
CORNER BEARS S64°W 54.5'

Between 1 and 6

SECTION LINE MARKER ON PINE TREE ON SPUR RD.
N. FROM SEC. CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

CALVIN W. HINKS

Title

FOR AID

Division

Headquarters

Date


7-26-56

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 0155 T. 135. R. 9E. M.

Tract or Surv. No.

Cor. E-1

Index
File No. 0355

T 13S R. 9E

Merid. WILL.

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature

Title

Division

Headquarters

Date

7100-52 (3 69)

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No. E-3

R.D. SISTERS

County

JEFFERSON

N.F. DESCHUTES

State

OREGON

1/4 COR.

DESCRIBE CORNER MONUMENT FOUND

STONE 12 X 12 X 5 IN PLACE

"1/4" CHISELED ON W. FACE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 16" P. PINE N21°W 47.7' MKD. "1/4S BT"
TREE FELLED IN 1956 - METAL POSTER ON STUMP
A 21" P. PINE S31°E 25' MKD. "1/4S BT"
TREE IS DEAD.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON 6" P. PINE. CORNER
BEARS N10°W 10.2 FT.

SEC. LINE MARKER ON TREE ON SPUR LOGGING RD.
57 FT. W. OF 1/4 COR.

CALVIN W. MINKS


FOR AID

8-21-56

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. 0355 T. 135. R. 9 E. M.

Tract or Surv. No.

Cor. E-3

12

13

Index

File No. 0555

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No. E-5T 13S R. 9ER.D. SISTERS


County

JEFFERSONMerid. WILL.N.F. DESCHUTES

State

OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

7 X 5 X 8 STONE SET IN GROUND
WITH 5 NOTCHES ON S. FACE AND 5 NOTCHES
ON E. FACE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 21" P. PINE S26°E 7 FT. MKD. "T13S R9E S8 BT"
DEAD & DOWN

A 27" P. PINE N27°W 76'9" ~~MKD~~ NO SCRIBING LEGIBLE
ALIVE

A 20" P. PINE N80°E 15'10" MKD. "B"
DEAD - 2 FT. STUMP REMAINING

A 24" P. PINE S40°W 9 FT. ~~DEAD & DOWN~~ SCRIBING NOT LEGIBLE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON NE SIDE OF S" P. PINE
CORNER BEARS N10°W 8'9"

SEC. LINE MARKER ON TREE ON WARM SPRINGS RD #14
6 1/2 CHAINS W. OF CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

CHESTER M. BEIL

Title

FORESTER, TMA

Division

Headquarters

Date


9-28-55

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____


REMARKS

LAND CORNER RECORD

5680-2

1. T 13S R 9E No. 0955 Cor. Sec Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters E-9

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

5. Investigation Notes: Found an 8"x6" stone extending 3" above ground in good condition with no markings for the corner. Found a Western Larch, down and moved from its stump hole, 11" diam., bears N70°E, 21' Dist. Marked T13S, R9E, S4. Also found another Western Larch, down, 12" diam. bearing S60°E, 28' dist., marked T13S, R9E, S9. A metal poster is on a Ponderosa Pine 5" diam., from which this corner bears N24°45'E, 9 ft. dist. Section Line markers are on Fire Rd #1 - 990 ft. west of corner and on Fire Rd #4 - 1190 ft. north of corner.

6. Signed Calvin W. Minks Title Forestry Tech. Date 6-7-62

PERPETUATION RECORD

10. Monument:


11. Accessories

		Field Book	Page
12. Set By	Title	13. Recorded By	Volume
License	Agency	(Agency)	Page
Date		(Date)	(City)
		(County)	(State)

14. Remarks:

Index
File No. 13 55 CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 4-1 Cor. No. E-13
T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON NW Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 10

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

Ed. 5/8" I.R. 0.4' BELOW
ROAD SURFACE, 4'± EAST OF ROAD ♣.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

47" P.PINE - N74 3/4°W, 32 1/2 LKS - ORIG.

39" P.PINE - S84°W, 31 1/2 LKS - ORIG.

11" P.PINE - N19°E, 96 LKS - BLM

8" P.PINE - S73°E, 42 LKS - BLM

2 1/2" B.C'd. I.P. (BLM) REF. MON - BSG 560°16'09"E, 37.10'
0.5' - STONE COLLAR

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

① Signature _____

CORNER LEGEND:

FS or Unverified
Constr. Other
○ ◇ Searched For/Not Found
⊗ ⊗ Evidence Found/Accept.
● ◆ Permanent Mon. Set/Td.

Title

Division

Headquarters

Date

Searched By: FRED ASTPLS

Division

Headquarters


Date

8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

10

11

12

13


Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938
 Certified for Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 9/85

History of Surveys, G.L.O., etc.
1882 - G.L.O. - T. JUDKINS
1966 - B.L.M. REMONUMENTATION - J.E. JOLLEY
A. PERRY - 1950 - SECTIONAL BEARDOWN SEC. 10

Index File No. 13-55 T.13 S., R. 9 E., W.M. Contract or Surv. No. 4-1 Cor. E-13

Index
File No. 13 55 CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 4-1 Cor. No. E-13
T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON NW Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 10

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

Fd. $\frac{5}{8}$ " I.R. 0.4' BELOW

ROAD SURFACE, 4'± EAST OF ROAD E.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

47" P.PINE - N74 $\frac{3}{4}$ °W, 32 $\frac{1}{2}$ LKS - ORIG.39" P.PINE - S84°W, 31 $\frac{1}{2}$ LKS - ORIG.

11" P.PINE - N19°E, 96 LKS - BLM

8" P.PINE - S73°E, 42 LKS - BLM

2 $\frac{1}{2}$ " B.C'd. I.P. (BLM) REF. MON - BSG 560°16'09"E, 37.10' O.S. - STONE COLLAR

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

①

Signature _____

CORNER LEGEND:

FS or Unverified
Constr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

Title

PLS

Division

Headquarters

Date


8/85

Searched By: FRED AST

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

10

11

12

13

Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938
or Agency

Plat DE
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 9/85

History of Surveys, G.L.O., etc.
1882 - G.L.O. - T. JUDKINS
1966 - B.L.M. REMONUMENTATION - J.E. JOLLEY
A. PERRY - 1950 - SECTIONAL BREAKDOWN SEC. 10


Index File No. 13-55 T.13 S., R. 9 E., W.M. Contract or Surv. No. 4-1 Cor. E-13

LAND CORNER RECORD

5680-2

1. T 13S R 9E No. E15 Cor. 1/4 Mer. Will State Oregon N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-14-59

Photo No. EGI-51-137

Ident. By: O. Thingvall

6-15-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 5"x5"x4" set in ground, marked $\frac{1}{4}$ on E face.

CL0 = STONE 10X18X18 MKD. 1/4 ON N. FACE

BTs = 20" PINE N30E 63 LKS. (41.5 FT.)

36" TAMARACK S53°W 109 LKS. (71.3 FT.)

5. Investigation Notes:

I could find no bearing trees. $\frac{1}{4}$ corner is 2 ft. south of old zigzag fence beside a 5 x 5 stake 18 inches high. West of Davis Creek.

9/81 ~ FD. 10"x6"x6" STONE MKD. 1/4 ALONGSIDE A 2"x18" PIPE.

POSSIBLE BTs, BUT NO POSITIVE ID ~

S. 3: A WINDTHROWN PINE OVERLAYING A SECOND PINE SUB-MERGED INTO SOIL ~ NO MARKS FOUND;

S. 10: SHARDS of a LARGE BURNT-OUT STUMP

LOCATION ~ LV. RD. 1153 ± 0.1 MILE SOUTH OF NW COR. of SEC. 10, E'LY ON DIRT ROAD ± 0.9 MILE TO SECTION LINE XING ABOUT 900 FT. WEST of 1/4 COR. ~ CONTINUE E'LY ABOUT 0.3 MILE TO LOCATION POSTER 260 FT. N. of 1/4 COR.

R. Oman

Land Surveyor


9/81

6. Signed Calvin W. Minks Title Forestry Aid Date 11-9-60

PERPETUATION RECORD

10. Monument:

SET 2 1/2" x 32" ALUMINUM-CAPPED ALUMINUM PIPE RISING 3" IN MOUND
OF STONES, ABOUT 40 FT. N. AND 80 FT. W. OF DAVIS CREEK.
BURIED STONE ALONGSIDE OF PIPE.



11. Accessories

10" PONDEROSA PINE N 17° W 5260 FT. TO 60d NAIL IN E BASE
M.K.D. S/4 S3 BT

20" PONDEROSA PINE S 60° W 7151 FT. TO 60d NAIL IN N BASE
M.K.D. N/4 S10 BT

Field Book _____ Page _____

12. Set By R. ROMAN Title P.L.S.
License OR-702 Agency USFS Date 9/81

13. Recorded By _____ Volume _____ Page _____
Jeff. Co. Surveyors Office 24 Sept. 81
(Date) (City) (County) (State)

14. Remarks:

1882, GLO
1950, A. PERRY
1985, F. AST

E-15


Index
File No. 1755T 13 S R. 9 EMerid. WILL.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor. Sec. Cor.
No. NE COR. SEC. 10R.D. Sisters County JeffersonN.F. Deschutes State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found Tag on Stump - and Monkey face
on Trees Nearby. Tag has Sec Cor $\frac{3}{10} \frac{2}{11}$
Not a BT
J.M.A.P.
12/11/40

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Tag on Stump 12" High and 18" Dia.
Not a Yellow Pine 23" dia. Bears N 78° E 13' Dist.
There had been a blaze on the west face of the Y.P. tree and a
marks showed that an attempt had been made to open
this tree. in search for scribe markings about 24" above
ground. I also attempted to open tree farther. But did

PHOTO IDENTIFICATION DATA

Photo No. ESF 4-222Filed At. DES. N.F. S.O.

Object Ident. _____

Ident. By Van Horn

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

not have any luck finding scribe marks. I put
a Bearing Tree Tag so as to preserve it.
No true evidence was found that would verify
this as a true corner

9/81 FD: S. 3~36" PP STUMP w/ LOG DOWNHILL, VIS: T135 R9

S. 2~32" PP " , THE BLAZE BURNED OUT, NO MARKS VIS.

S. 11~ ROTTED STUMP w/ BLAZE IN DEBRIS, VIS: BT

S. 10~ 36" PP STUMP, VIS: BOTTOM HACK OF THE BLAZE

Signature R. OMAN

Title

PLS Division

S.O. Headquarters

Date 9/81 7100-52 (3/68)Van Horn

Eng Tech.

S.O.


2/15/73

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 6" IN A MOUND OF STONES ON NORTH SIDE of a 23" PP (NOT A BT), ABOUT 300 FT. EAST of RIDGETOP AND 250 FT. WEST of a LOGGING SPUR.



(ABOUT 750 FT. E. of RD. #113 AND 950 FT. W. of RD. #1390)

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" PP N26°E 14²² FT. TO 604 NL. IN WNW SIDE, MKD. T135 R9E S2 BT
 9" PP S62°E 24⁴⁷ FT. TO 604 NL. IN NNE SIDE 15' HI, MKD. T135 R9E S11 BT
 8" PP S43°W 198⁵ FT. TO 604 NL. IN SE BASE, MKD. T135 R9E S10 BT
 5" TAMARACK N69°W 193³ FT. TO 604 NL. IN NNE BASE, MKD. X BT

Work Done By R. OMAN Title P. C. S. Date 9/81 State Registration No. or Agency OR-702

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: JEFF. CO. SURV. OFFICE Date 24 SEPT. 81

From Location Card - unsigned & not dated

T135, R9E, Will. Med, Sec Cor common to 2, 3, 10, & 11.

corner consists of a ~~Blaze~~ TREE Blazed on 4 Sides) from which:

① Y.P. 5" dia, Bears N.W. 30 ft. dist. Marked T13 R S3

② Y.P. 28" dia, Bears NE, 35 ft. dist.

③ Y.P. 36" dia, Bears SE, 40 ft. dist

ON side Hill Below Top of Ridge. Marker
 on Rd. on West Side of Ridge

Index File No. 1755 T. 13 R. 9 M.

Tract or Surv. No.

Cor. E-17

index
File No. 2555
T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON Cor. No. E-25
Merid. WILLAMETTE N.F. DESCHUTES State OREGON SE COR SEC 1
NW COR SEC 2

SEE: E-01

T 13 S R 10 E

~~SP/NF~~

BCSP by
Walt Miller
8/89

E-25

Index
File No.

2555

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No.

E-25

Merid.

13 S. R. 9 E.
WILLAMETTE

R.D.
N.F.

SISTERS
DESCHUTES

County
State

JEFFERSON
OREGON

SE COR SEC 1
NW COR SEC 2

SEE: E-01

T 13 S R 10 E

~~SP/NF~~

BCSP by
Walt Miller
8/89

Index

File No.

2555

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

E-25

T

13

S. R.

9

E.

R.D.

SISTERS

County

JEFFERSON

SE COR SEC 1

Merid.

WILLAMETTE

N.F.

DESCHUTES

State

OREGON

NW COR SEC 2

SEE: E-01

T 13 S R 10 E

~~SE/NF~~

BCSP by
Walt Miller
8/89

Index
File No. 0157

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. _____

Cor.
No. G-1

T. 13S R. 9E R.D. SISTERS County JEFFERSON

Merid. WILL. N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STAKE ROTTED IN GROUND
APPROX. 4" IN DIA.
HOLE FOUND W/ ROTTED WOOD IN IT.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 21" P. PINE S51°E 48.8 FT. MKD. "1/4S BT"
A 33" P. PINE N54°W 18.4 FT. MKD. "1/4S BT"

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON W. SIDE OF SEC. LINE ON
10" WHITE FIR. CORNER BEARS N110°E 2.6'
SECTION LINE MARKER ON TREE ON SPUR RD. N. OF
1/4 COR.

Signature

Title

Division

Headquarters

Date

7100-52 (3 68)

CALVIN W. MINKS


FOR. AID

8-29-56

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 0157 T. 13S. R. 9E. M.

Tract or Surv No

Cor. 6-1 12

Index

File No. 15-56

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 4-1

Cor.


No. F-15T 13 S. R. 9 E. R.D. SISTERS

County

JEFFERSONC.N. 16 Cor. ofMerid. WillametteN.F. DeschutesState OregonSection 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



FD. 3" B.C. IN CONC. BY "TENNISON ENGR. CORP"
(DID NOT HOLD), S42°14'E, 9.77' FROM
5/8" I.R. SET DURING THIS SURVEY.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

④

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Yd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3' NURLY OF SERLY SHOULDER OF
CINDER ROAD, SERVING "TRACT HOUSING"

Searched By: FRED ASTTitle PLS

Division

Headquarters

Date


8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 5/8" X 30" I.P. W/ YELLOW PLASTIC CAP,
0.6' BELOW ROAD SURFACE

MONUMENT STAMPEE



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P.PINE - N64°W, 30.70' CN 1/16 SID BT


11" P.PINE S40°W, 32.24' CN 1/16 SID BT

GOOD SPIKE W/ WASHER

~~REF. MON.~~ → N42°14'W, 14.00'


SET 2 1/2" X 30" B.C.D, I.P., ESG. O.S'

ABOVE GROUND, IN STONE MOUND



STAMPED "TENNESON"
CAP "A.M.", "RM"

9.77"



Work Done By FRED AST Title PLS Date 8/85 State Registration No 1938
or Agency

PLAT OF Cor Record Prepared? (Yes) No Filed At JEFF Co. Surveyor's Office Date 9/85

History of Surveys, G.L.O., etc.
1950 - A. PERRY - SECTION BREAKDOWN
1971 - TENNESON ENGR. CORP. - NEWTON - SURVEY FOR "JACK HERRING"

Index File No 15-56 T/3 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. F-15

12

13

Index

File No. 15-56.25

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor. F-15-DNo. F-35-15T 13 S. R. 9 E.R.D. SISTERS

County

JEFFERSON

C.N-S-N 1/2 Sec. of

Merid. WillametteN.F. DeschutesState OregonSection 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

US C-N-S-N 1/2 Sec.OIL MAT ROAD

Ed. 1 1/2" DIA ALUM. CAP IN CONC., BY "TENNISON ENGR.
CORP." (DID NOT HOLD) S55°44'E, 7.86' FROM
COR. SET DURING THIS SURVEY

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N NSN/256
LINE

PVT

Sec 10

US

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

(6)

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other

☐☐

Searched For/Not Found

☒☒

Evidence Found/Accept.

☒☒

Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

35' SOUTH OF OIL MAT ROAD E, N20°W, 6.8'
FROM A W-S FUL. COR.

Searched By: FRED AST

Title

PLS

Division

Headquarters

Date


8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" BOLD I.P., RSG. 0.2' ABOVE GROUND

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

16" FIR - S72°E, 15.98' (1/256 S10 BT)

DRIVE 60d. SPIKE W/WASHER
IN SIDE CENTER BASE OF
EACH BT.

14" FIR - S40°E, 2.48' (1/256 S10 BT)

Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938
or Agency

Plat or Cor Record Prepared? (Yes) No Filed At JEFF Co. Surveyor's Office Date 9/85

History of Surveys, G.L.O., etc. (1971 - TENNINGSON ENGR. CORP. - N. NEWTON - FOR JACK HERRING
INFERRED BY A. PERRY, 1950

Index File No. T.13 S., R.9 E., W.M. Contract or Surv. No. 4-1 Cor. F-15-D
15-56.25 15

Index

File No. 14-56

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 4-1

Cor.

No. F-14T 13 S. R. 9 E. R.D. SISTERS

County


JEFFERSON

NW 1/4 Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

(3)

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found




Evidence Found/Accept.



Permanent Mon. Set/Yd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: FRED ASTTitle PLS

Division

Headquarters

Date


8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" BCL, I.P., PSG. 0.5' ABOVE GROUND

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

17" W. LARCH - N 40 E, 14.90'

NW 1/4 S10 BT

9" W. LARCH - S 64 1/2° W, 13.43'

NW 1/4 S10 BT

GOOD SPIKE WAS

10

Work Done By FRED AST Title PLS Date 8/85 State Registration No 1938
 Established Cor Record Prepared? ☒ Yes No Filed At JEFF Co. Surveyor's Office Date 9/85

11

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD, BUT INFERRED BY A. PERRY, 1950

12

Index File No. 14-56 T.13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. F-14

13

USDA-FOREST SERVICE D-7100-52(2/82)

Index

File No. 14-56

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)


Survey No. 4-1

Cor.

No. F-14T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON NW 1/16 Cor. ofMerid. Willamette N.F. Deschutes State Oregon Section 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

(3)

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found




Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: FRED ASTTitle PLS

Division _____

Headquarters _____


Date 8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" BOLL, I.P., P.S.G. 0.5' ABOVE GROUND

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

17" W. LARCH - N 40 E, 14.90'

NW 1/4 S10 BT

9" W. LARCH - S 64 1/2° W, 13.43'

NW 1/4 S10 BT

GOOD SPIKE WAS

10

Work Done By FRED AST Title PLS Date 8/85 State Registration No. or Agency 1938

Plat. of Cor. Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 9/85

11

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD, BUT INFERRED BY A. PERRY, 1950

12

Index File No. 14-56 T.13 S., R. 9 E., W.M.

Contract or Surv. No. 4-1

Cor. F-14 13

Index

File No. 14-56.25T 13 S. R. 9 E.Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or


Survey No. 4-1Cor. F-14-DNo. F-25-14R.D. SISTERS

County

JEFFERSONC.N. SW 1/4 Cor. ofN.F. DeschutesState OregonSection 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



Fd. 3/8" I.R. - BY A. PERRY, (DID NOT HOLD),
 S50°05'E, 4.89' FROM COR SECT DURING
 THIS SURVEY.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

⑤

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

✕ ✕ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

130'± WEST OF "CAFE" BLDG. AT S. EDGE OF
 GRAVEL D/W, N55°W, 5.6' FROM N. TERMINUS
 OF N-S POLE FDC AND 80'± N. OF OIL MAT
 ROAD E.

Searched By: FRED ASTTitle PLS

Division _____

Headquarters _____


Date 8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" B.C.H.I.P. ESG. 0.12' IN STN COLLAR

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P.P.ING - N 63 1/2° W, 19.14'

1/256 S10 BT

God. SPIKE w/ WASH

11" W. LARCH - N 18 3/4° W, 27.89'

1/256 S10 BT

10

Work Done By FRED AST Title PLS Date 8/85 State Registration No 1938
or Agency

Plat of Cor Record Prepared? Yes No Filed At JEFF Co. Surveyor's Office Date 9/85

11

History of Surveys, G.L.O., etc. 1950 - A. PERRY SECTIONAL BREAKDOWN

Index File No. 14-56.25

T. 13 S., R. 9 E., W.M.


Contract or Surv. No 4-1

Cor. F-14 D
F.25 14

12

Index
File No. 0557 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. G-5
T 13S R. 9E R.D. SISTERS County JEFFERSON 1/4 COR.
Merid. WILL. N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE NOT IN PLACE, 5" ABOVE GRD.

BEIL SAYS "COULD NOT FIND ORIGINAL CORNER SO I SET STONE AT APPROX. LOCATION"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 42" P.PINE N 32°W 16' 4" MKD. "1/4 S"

A 42" P.PINE S 29°E 34' 10" MKD. "1/4 S BT"

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
METAL LOCATION POSTER ON A 5" WHITE FIR ON SW SIDE OF TREE. CORNER BEARS S 44°W 2' 6"

SEC. LINE MARKER ON TREE ON WARM SPRINGS RD.
780 FT. N. OF 1/4 COR.

Signature

Title

Division

Headquarters

Date

7100-52 (3 69)

CHESTER M. BEIL


FORESTER, DNT TMA

8-6-56

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 0557 T. 13S. R. 9E. M.

Tract or Surv. No.

Cor 6-5

12

Index

File No. 13-57

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.


4-1

Cor.

No. G-13T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON W 1/4 Cor. ofMerid. Willamette N.F. Deschutes State Oregon Section 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



FD. SPIKE, SET BY A.

PERRY AT SINGLE PROPORTIONED POSITION
(HOLD) FLUSH WITH SURFACE OF ROAD.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FD. 3/4" I.P. (NO RECORD) W 0.6' & N 1.0' FROM
SPIKE.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

(1) Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

6' EAST OF ROAD & #

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: FRED AST

Title

PLS

Division

Headquarters


Date

8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET 2 1/2" X 30" BOLD, I.P., P.S.G., 0.4' ABOVE GROUND, S78°E, 21.85'

S"P. PING - S61°W, 79.64' (1/4 S9 BT)

60d. SPIKE w/WASHER

S"P. PING - S78°E, 25.83' (1/4 S10 BT)

10

Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938
 Filed For Cor. Record Prepared? (Yes) No Filed At JEFF Co. Surveyor's Office Date 9/85

11

History of Surveys, G.L.O., etc.
1882 - G.L.O. - T. JUDKINS
1950 - A. PERRY SECTIONAL BREAKDOWN.

Index File No. 1357 T. 13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. G-13

12

13

Index

File No. 13-57

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No. 4-1

Cor.

No. G-13T 13 S. R. 9 E.

R.D.

SISTERS

County

JEFFERSONW 1/4 Cor. ofMerid. Willamette

N.F.


Deschutes

State

OregonSection 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



FD. SPIKE, SET BY A.
 PERRY AT SINGLE PROPORTIONED POSITION
 (HOLD) FLUSH WITH SURFACE OF ROAD.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FD. 3/4" I.P. (NO RECORD) W.O.G. & N.1.0' FROM
 SPIKE.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

(7) Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

6' EAST OF ROAD &

Searched By: Fred Ast

Title

PLS

Division

Headquarters


Date

8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET 2 1/2" X 30" B.C.D., I.P., P.S.G., 0.4' ABOVE GROUND, S78°E, 21.85'

S" P. PING - S61°W, 79.64' (1/4 S9 BT)

God. SPIKE w/ WASHER

8" P. PING - S78°E, 25.83' (1/4 S10 BT)

Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938

Plat PE Filed Cor. Record Prepared? (Yes) No Filed At JEFF Co. Surveyor's Office Date 9/85

History of Surveys, G.L.O., etc.
1882 - G.L.O. - T. JUDKINS
1950 - A. PERRY SECTIONAL BREAKDOWN.

Index File No. 1357 T. 13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor G-13

Index

File No. 13-57

CORNER RECORD (SEARCH)

Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.

T 13 S. R. 9 E.


R.D.

SISTERS

County

JEFFERSONNo. G-13Merid. WillametteN.F. DeschutesState OregonW $\frac{1}{4}$ Cor. ofSection 10

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

Fd. SPIKE, SET BY A.
PERRY AT SINGLE PROPORTIONED POSITION
(HOLD) FLUSH WITH SURFACE OF ROAD.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Fd. 3/4" I.P. (NO RECORD) W 0.6' & N 1.0' FROM
SPIKE.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

(7)

Signature

CORNER LEGEND:

FS or

Unverified

Contr.

Other

☐☐

Searched For/Not Found

☒☒

Evidence Found/Accept.

☒☒

Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

6' EAST OF ROAD &

Searched By:

FRED AST

Title

PLS

Division

Headquarters


Date

8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET 2 1/2" x 30" B.C.D., I.P., RSG, 0.4' ABOVE GROUND, S78°E, 21.85'

S"P. PING - S61°W, 79.64' (1/4 S9 BT)

God. SPIKE w/ WASHER

S"P. PING - S78°E, 25.83' (1/4 S10 BT)

Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938
or Agency

FILED OF Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 9/85

History of Surveys, G.L.O., etc.
1882 - G.L.O. - T. JUDKINS
1950 - A. PERRY SECTIONAL BREAKDOWN.

Index File No. 1357 T. 13 S., R. 9 E., W.M.

Contract or Surv. No. 4-1

Cor. G-13

USDA-FOREST SERVICE D-7100-52(2/82)

Index
File No. 14-57

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.

4-1


Cor.

No.

G-14T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON SW 1/4 Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 10

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

S'N & 3'W OF SW COR. OF WOOD DECK, 78'SOUTH OF GRAVEL ROAD &, IN LAWN AREA

Searched By:

FRED AST

Title

PLS

Division

Headquarters

Date


8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" B.C.D., I.P., 0.3' BELOW LAWN SURFACE

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE - N82°W, 73.55'

CW 1/16 S10 BT

60d SPIKE W/WASHER

11" P. PINE - S63 1/2°W, 103.95'

CW 1/16 S10 BT

Work Done By FRED AST

Title PLS

Date 8/85

State Registration No. or Agency

1938

Plat or

Certified Cor. Record Prepared Yes

No

Filed At JEFF Co.

Surveyor's Office

Date 9/85

History

of

Surveys,

G.L.O.,

etc.

1950 - A. PORRY - SECTIONAL BREAKDOWN - MON. NOT FOUND.

Index File No.

14-57

T13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. G-14

12

13

Index

File No. 15-57

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 4-1

Cor.

No. G-15T 13 S. R. 9 E.R.D. SISTERS

County


JEFFERSON

W.C. TO COR. OF

Merid. WillametteN.F. DeschutesState OregonSection 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

C 1/4 COR. POSITION FALLS AT VERTICAL BANK OF
METOLUS RIVER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Yd.

Searched By: FRED AST

Title

Division

Headquarters


Date 8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

DID NOT SET C¹/₄ CORNER DUE TO
IMPRACTICAL LOCATION

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
WITNESS CORNER

SET 3¹/₄" ALUM CAPPED 2¹/₂" ALUM PIPE, FLUSH WITH GROUND

24" P. PIPE - S73°W, 44.65' (GOD SPIKE W/WASHER - SOUTH BASE) (NOT SCRIBED) TO WIT. COR.

NE COR. OF BLOCK PORCH ENDT'N - S8°W, 85.00'

1/2" I.P., S11°E, 17.53 "PROP. COR."

Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938
or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 9/85

History of Surveys, G.L.O., etc.
1950 - A. PORRY - SECTIONAL BREAKDOWN
1975 - W. EINSTAD - SURVEY FOR LOAN FOSTER

Index File No.

15-57

T. 13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. G-15


Index
File No. 2557
T 13S R. 9E
Merid. WILL.

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor. No. 6-25
E/4 COR SEC. 12
W/4 COR SEC. 7

R.D. SISTERS County JEFFERSON
N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

ASSUMED STAKE
STONE 10 X 10 X 10 RSG. 4"
FAINT 1/4 ON WEST FACE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A ROTTED 16" P. PINE N38°W 19 FT. MKD. "1/4S BT"
STUMP W/ "BT" SCRIBING STILL STANDS
REMAINING ROTTEN LOG HAS "1/4S" SCRIBED ON IT. - IN
BAD STATE OF DECAY

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON E. SIDE OF 6" D. FIR
CORNER BEARS S78°E 7 FT.


PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature W. MILLER Title S.T. Division _____ Headquarters S.O. Date 7-15-59
CHARLES M. LANG ENG. AID 7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:



MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RSG. 3"
IN MOUND OF STONES ABOUT 200' E of ROAD
#1137

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE BRS. S78°E 40± FT. MKD. 1/4 S7 BT
9" W. FIR BRS. S76°W 38± FT. MKD. 1/4 S12 BT
14" P. PINE BRS. N21°W 47± FT. ~~BT~~ (ORIG. BT)

Work Done By ROMAN Title PLS Date 10/80 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared ☒ Yes No Filed At JEFF. CO. SURV. OFFICE Date 11/80

REMARKS

8/89 - Revisited by Walt Miller, PLS 2111. Monument and Accessories O.K.

Index File No. 2557 T. 135 R. 9 M.

Tract or Surv. No.


6-25 12

LAND CORNER RECORD

6-17 5680-2

1. T. 13S R. 9E No. 17 Cor. $\frac{1}{4}$ Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



3. Original Description Vol. Page Where Recorded

4. Description of Corners: ~~Didn't have original notes.~~

610 = TRAP STONE 14x12x8 INS. 9" IN GROUND, MKD. 1/4 ON W. FACE.
 BBS = 22" PINE N77°E 33 LKS. (21 1/2 FT.)
 24" PILE S80°W 89 LKS. (58 1/2 FT.)

5. Investigation Notes: Found stone 10"x8"x6"---8" in the ground in good condition, had $\frac{1}{4}$ on west face. A down snag, estimated diam. of 22" P.Pine had $\frac{1}{4}$ markings visible. Bears N66°E, 23.0' from its estimated original position. A 32" P.Pine bears S12°W, 67.5' dist., has open blaze but no markings - also a yellow tag. Not necessarily a B.T. IT SURE AIN'T, OLE!

9/81: FD. STONE 13x9x9 MKD. 1/4 ON W. FACE, SET 8" IN GROUND, IN A MOUND OF STONES.

BBS: A 20" PP WINDTHROW w/ WEATHERED FACE ~ CANNOT DECIPHER SCRIBING;

A BURNT-OUT STUMP IN LOCATION of SW CALL.

7. Photo Identification 7-14-59

Photo No. EGI-51-178

Ident. By: O. Thingvall

8. Plane Coordinate Position Data

State Zone

X

Y

Estab. By

Field Book No.

Where Filed

9. Evaluation

Authentic

Needs Verif. Monument

Re-estab. Survey

Land Status

6. Signed R. OMAN Title P.C.S. Date 9/81
 O. Thingvall Title Hwy. Eng. Date 6-18-62


PERPETUATION RECORD

10. Monument:

SET 2 1/2" X 32" ALUMINUM-CAPPED ALUMINUM PIPE RISING 8"
IN A MOUND of STONES, ABOUT 40 FT. EAST of A DIRT
SAUR AND 760 FT. EAST of E of RD. #113. BURIED
STONE ON NW SIDE of PIPE.

11. Accessories

12" PP N62°W 1730 FT. TO 60d NL. IN NNE SIDE, MKD. E/4 S10 BT
12" PP N32°E 2590 FT. TO 60d NL. IN ESE BASE, MKD. W/4 S11 BT



Field Book _____ Page _____

12. Set By ROMAN Title P.C.S.
License OR-702 Agency USFS Date 7/81

13. Recorded By _____ Volume _____ Page _____
JEFF. CO. SURV. OFFICE 24 Sept 81
(Date) (City) (County) (State)

14. Remarks:

1882, GLO
1950, A. PERRY
1985, F. AST

Index


File No. 621 2157

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. G-21T 13S., R. 9E., R.D. SISTERS County JEFFERSONMerid. Will N.F. DESCHUTES State OREGONW 1/4 Cor Sec. 11

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

WESTERLY BT IS 26" P. PINE (1/5)EASTERLY BT IS 28" P. PINE (1/5)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

1/4 Cor is 798' N. of S.L.B. btwn secs 11 & 12 on
Rd 139B. Or, follow Fire Rd 12 for 500' - cor. is
then W. approx 50'

Signature
O. THINGVALLTitle
CIVIL ENG

Division

Headquarters
S.O.Date
11-5-69

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. 2157 T. 135. R. 9E. M.

Tract or Surv. No.

Cor.


13

6-21

Index
File No. 14-58.5 CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 4-1 Cor. H-14-H
T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON No. H-14-H
Merid. Willamette N.F. Deschutes State Oregon CSSW 1/64 Cor. of
Section 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
(11) Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified
Contr. Other
☐ ☐ Searched For/Not Found
☒ ☒ Evidence Found/Accept.
☒ ☒ Permanent Mon. Set/Fd.

COR FALLS IN AREA OF HEAVY UNDERBRUSH,
8' SOUTH OF A 5' WIDE CREEK, AND N62°W,
18.5' FROM A N-E FNC COR (DOWN)


Searched By: FRED AST Title PLS Division _____ Headquarters _____ Date 8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 30" B.C.D. I.P., BSS 0.4' ABOVE
GROUND

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S" P. PINE - S35°E, 24.01' (1/64 S10 BT)

606 SPIKE W/WASHER.

S" P. PINE - S17°E, 33.94' (1/64 S10 BT)

10

Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938
or Agency
Plat or Cor Record Prepared? (Yes) No Filed At JEFF Co. Surveyor's Office Date 9/85

11

History NO PREVIOUS RECORD.
of
Surveys,
G.L.O.,
etc.


Index File No. 14-58.5 T. 13 S., R. 9 E., W.M. Contract or Surv. No. 4-1 Cor. H-14-H
H-5-14

USDA-FOREST SERVICE D-7100-52(2/82)

Index
File No. 14-58.5CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 4-1Cor. H-14-H
No. 14514T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON CSSW 1/4 Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

(11) Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other
☐ Searched For/Not Found
☒ Evidence Found/Accept.
☒ Permanent Mon. Set/Pd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

COR FALLS IN AREA OF HEAVY UNDERBRUSH,
8' SOUTH OF A S'WIDE CREEK, AND N62°W,
18.5' FROM A N-E FNC COR (DOWN)

Searched By: FRED ASTTitle PLS

Division

Headquarters


Date 8/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 30" BCD. I.P., BSG 0.4' ABOVE
GROUND

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S" P. PINE - S35°E, 24.01' (1/64 S10 BT)

Good SPIKE w/ WASHOR.

S" P. PINE - S17°E, 33.94' (1/64 S10 BT)

10

Work Done By FRED AST Title PLS Date 8/85 State Registration No. 1938
or Agency
Entered for Record Prepared? (Yes) No Filed At JEFF Co. Surveyor's Office Date 9/85

11

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD.

Index File No. 14-58.5 T. 13 S., R. 9 E., W.M.

Contract or Surv. No 4-1


H-14-11
Cor. H-14-13

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" BCL, I.P. BSG. 0.1' ABOVE GROUND.

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

25" P. PIN - 5620W, 51.21' (1/64 S10 BT)

God SPIKE w/ WASHER

20" P. PIN - 525 1/20W, 17.97' (1/64 S10 BT)

Work Done By FRED AST Title PLS Date 8/85 State Registration No 1938
 Permitted or Cor Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 9/85

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD

Index File No. 14.5-58.5 T. 13 S., R. 9 E., W.M. Contract or Surv. No 4-1 Cor. H-14-3
14.5-14.5

Index

File No. 0159

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.

No.

J-01

T 13 S. R. 9 E. R.D.

Sisters

County

Jefferson

NW

Cor. of

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON


Section

18

SEE: J-25

T. 13 S., R. 8 E., W.M.

BCSP




LAND CORNER RECORD

J-05 5680-2

1. T. 13S R. 9E No. 0559 Cor. Sec Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-14-59

Photo No. EGI-51-20

Ident. By: O. Thingvall

6-15-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

Assumed stone, 12"x8"x5", not marked.

5. Investigation Notes:

A white fir, 24" diam., bears N23°E, 38' dist., marked T13S, R9E, S8.

A white fir, 20" diam., bears S29°E, 24' dist., marked T13S, R9E, S17, B.T.

A western larch, 30" diam., bears S44°W., 54.4' dist., marked T13S, R9E, S18, B.T. This tree is dead.

A ponderosa pine, 36" diam., bears N81°W, 16' dist., T13S, R9E, S7, B.T.

Distances and bearings check with photo copies of General Land Office field notes.

6. Signed Calvin W. Minks Title Forestry Aid Date 11-10-60

PERPETUATION RECORD

10. Monument:

Brass Cap

11. Accessories

11" D.Fir N25 3/4°E 90 lks.
 18" D.Fir S65 1/4°E 34 lks.
 4" D.Fir S55 1/2°W 37 1/2 lks.
 6" W.Fir N10 1/4°W 32 lks.
 Plus old ones

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

(Date)

(City)

(County)

(State)


14. Remarks:

LAND CORNER RECORD

J-07 5680-2

1. T. 13S R. 9E No. 17 Cor. $\frac{1}{4}$ Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-14-59

Photo No. EGI-51-65

Ident. By O. Thingvall

6-15-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

An assumed stone, 5"x6"x5".

5. Investigation Notes:

A Western Larch, 28" diam., bears N82°E, 16.5' dist., marked $\frac{1}{4}$ S, B.T. This tree is dead.

A ponderosa pine, 24" diam., bears S62°W, 15.1' dist., marked $\frac{1}{4}$ S, B.T. This tree is dead.

This corner checks with distances and bearings of transcript of General Land Office field notes.

6. Signed Calvin W. Minks Title Forestry Aid Date 11-9-60

PERPETUATION RECORD

10. Monument:

Brass cap

11. Accessories

12" D. Fir N8°E 57 lks.
7" W. Pine S12°E 68 lks.

Plus old ones.

12. Set By _____ Title _____
License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
(Agency)
(Date) (City) (County) (State)


14. Remarks:

LAND CORNER RECORD

J-09 5680-2

1. T. 13S R. 9E No. 89 Cor. Sec Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-14-59

Photo No. EGI-51-65

Ident. By: O. Thingvall

6-15-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 8"x10"x12", set in ground, marked with 4 notches on E and S edges.

5. Investigation Notes:

A ponderosa pine, 41" diam., bears N30°E, 46' dist., marked T13S, R9E, S9.

A ponderosa pine, 48" diam., bears S61°E, 38.3' dist., marked B.T. This tree was cut in logging.

These distances check with transcript of General Land Office field notes.

6. Signed Calvin W. Minks Title Forestry Aid Date 11-9-60

PERPETUATION RECORD

10. Monument:

Brass Cap

11. Accessories

6" P. Pine N30°E 26 lks.
 7" P. Pine N61 $\frac{1}{2}$ °W 43 $\frac{1}{2}$ lks.
 7" P. Pine S9°W 36 $\frac{1}{2}$ lks.
 8" P. Pine S73°E 29 lks.

Plus old ones.

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
 (Agency)

(Date) (City) (County) (State)

14. Remarks:

Index

File No. 1159

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Cont. #

Survey No. 006686N


Cor.

No. J - 11T 13 S R. 9 ER.D. Sisters

County

Deschutes JeffersonMerid. W.M.N.F. DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found $2\frac{1}{2}$ " galv. iron pipe with 3" aluminum cap marked.

S 9

 $\frac{1}{4}$ —

S 16

T13S R9E

1966

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S 9 - A 36" P. Pine (orig.), scribed as called for.

S 9 - A 6" Pine, scribed as called for.

S 16 - A 30" P. Pine (orig) scribed as called for.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency

Signature

Title
SurveyorDivision
Sun Country Engineering

Headquarters

Bend office

Date

11-22-77

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By Robert M. Karl Title Surveyor Date _____ State Registration No. L.S.I.T. 104
or Agency _____

Certified Cor. Record Prepared ? Yes ☒ No Filed At: _____ Date _____

REMARKS

Index File No. 1159 T. 13S R. 9E M. WM Tract or Surv. No. 006686 N Cor. J II

5-11

Index

File No. 1359

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.

Cor.

No. J-13

T 13 S. R. 9 E. R.D.

Sisters

County

Jefferson

SW

Cor. of

Merid. Willamette

N.F.


Deschutes

State

Oregon

Section 10

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

3" BC (Tennessee Eng Corp)

3" BLM BC

T13S R9E

Flush w/shoulder

RS6.7"

2' E of edge of pavement

9 10

16 15

T13S R9E

Sec Cor

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

31" P. Pine S77°E, 25 lks. Chopped open toe blaze, nail in S face

33" P. Pine N84°W, 48.78 ft. Chopped open toe blaze, nail in N face

19" P Pine N79½°E, 79 lks. Healed blaze, nail in S face.

24" P. Pine N59°W, 123.26 ft., healed blaze, alumnail N face.

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Road No. 1304 N 1.5 mi. past head of Metolius junction.

Corner lies on east edge of pavement.

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

Searched By:

R. Taylor
MH-GS

Title

ST

Division

CS

Headquarters

SQ

Date


5/17/83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: 2½" x 28" BCSP, Brd. 10" at east shoulder of paved road.

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 15" P N79½E, 79L (52.14)

19" P N59W, 187½L (123.75)

R.M. = 2½ x 28" BCSP RS6.4" Brs. N89¼° E, 35½L (23.43)

w/BC mkd. T13S, R9E, S10 RM 1966 and

arrow pointing to COR.

*F. AST ~ 1983
F. AST ~ 1985*

Work Done By _____ Title _____ Date _____ State Registration No. _____
Plat or _____ or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc.	1881: Post	BLM 1966	Perry 1966 3/4" x 30" Pipe 2' N of Culv.	J. Wick
	24"P N37E 77L (50.82)	FD:	24"P	32"
	22" P S77E 25L (16.50)	28"P	22"P	
	24" P S42W 23L (15.18)	FD:		
	18" P N84W 74L (48.84)	28"P	18"P	32"

Index File No. 1359 T.13 S., R. 9 E., W.M.

Contract or Surv. No.

Cor. J-13

Index

File No. 1459

CORNER RECORD (SEARCH)

Contract or

Survey No.

Cor.

No. J-14

T 13 S. R. 9 E. R.D.

Sisters

County

Jefferson

W/16

Cor. of

Merid. Willamette

N.F.


Deschutes

State

Oregon

Section 10/15

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

1" ODIP set in conc.

RSG. 0.5 ft. located @ E.W. and S fence Cor.

Prop. Boundary post 0.95 ft. N. of cor.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Pines in Perry's location with blazes, no nails, visible.

PHOTO IDENTIFICATION DATA

Photo No.

Filed At

Object Ident.

Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: R. Taylor

Title ST

Division CS

Headquarters SO


Date 5/18/83

GS

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____	Title _____	Date _____	State Registration No. _____ or Agency _____
Plat or _____	Certified Cor. Record Prepared ? Yes _____ No _____	Filed At: _____	Co. Surveyor's Office Date _____
History of Surveys, G.L.O., etc.	1960: A. Perry 1/2" 1. pipe 20" P NW'L4 43.1 20" P NE'L4 23.3	F.Ast 1983 FD, S38°27'E, 1.30 from calc. position No RP's mentioned	11

12

Index File No. 1459 T. 13 S., R. 9 E., W.M.

Contract or Surv. No

Cor. J-14

13

Index

File No. 1459-B

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Contract or 43-0466-Survey No. 3-556

Cor.

No. J-14-BT 13 S. R. 9 E.R.D. SISTERSCounty JEFFERSONE-W 1/64 Cor. ofMerid. WillametteN.F. DeschutesState OregonSections 10 & 15

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.;



Permanent Mon. Set/Fd.

N16°E 12.5' TO FENCE CORNER

Searched By: F. AstTitle PLS

Division

Headquarters

Date

3/10/83

CORNER RECORD (PERPETUATION)


MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" U.S.D.A.-F.S. BRASS CAPPED, GALV.
IRON PIPE, RISING 0.1' ABOVE GROUND, IN A
STONE MOUND. ~ SET 6' CARSONITE POST, 2.2'
WEST OF CORNER

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

13" P. PINE - N 79° W - 101.36'

12" P. PINE - S 31 1/2° W - 16.63'



Work Done By F. AST

Title SURVEYOR

Date 3/83

State Registration No. or Agency

1938

Cor. Record Prepared? ☒ Yes

No

Filed At: JEFF Co.

Surveyor's Office

Date

3/83

History
of
Surveys,
G.L.O.,
etc.

ORIGINAL G.L.O. - THOMAS JUDKINS - 1881

1985 ~ F. AST

Index File No. 459-B T. 13 S., R. 9 E., W.M.

Contract or Surv. No.
43-0466-3-566

Cor. J-14-13

MONUMENT STAMPED



Index

File No. 1559

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.


Cor.

No. J-15

T 13 S. R. 9 E. R.D. Sisters County Jefferson S/4 Cor. of

Merid. Willamette N.F. Deschutes State Oregon Section 10

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND 3" BLM BC

Located at ~~the fence~~ RSG 6"

0° EAST OF FENCE COR.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

23" P. Pine S70° W, 28½ lks, top blaze burnt

16.5" P. Pine, S30½° E, 39½ lks, healed blaze

6 31" P. Pine, N67° E, 73 lks, ¼

15" P. Pine, N39½° E, 116½ lks, healed blaze

PHOTO IDENTIFICATION DATA

Photo No.

Filed At

Object Ident.

Ident. By

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other




Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.



V15, 1985 ~ F. AST ~ OK

Searched By:

R. Taylor
GS

Title

ST

Division

CS

Headquarters

SQ

Date

5/18/83

5


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: 2½" x 28" BCSP, RS6.4" 1983, Ast; RS6.6"

0.6 E of FNC. Cor.

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 12" P N39½E, 116½ lks (76.89) 1983; AST: 16"

12" P S30½E, 39½ lks (26.07) 17"

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Plat or _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc.
1881: Trap stone 10x8x8, 8" in grd.
mkd. ½ on N. Face.
25"P N67E, 71 lks. (46.86) AP - 26"P BLM = 33"P 73 lks. (48.18)
22"P S70W, 27 lks. (17.82) AP = 28"P 12 8 20"P 28½ lks. (18.81)
Both mkd. ¼ S BT

Index File No. 1559 T. 13 S., R. 9 E., W.M.

Contract or Surv. No

Cor.

J-15

Index
File No. 1759


CORNER RECORD (SEARCH) (Ref. FSM 7151.4)

Contract or Survey No. Jefferson Cor. J-17 No. SE

T 13 S. R. 9 E. R.D. Sisters County Jefferson Cor. of SE

Merid. Willamette N.F. Deschutes State Oregon Section 10

CORNER DIAGRAM per legend
S10 S11



DESCRIBE CORNER MONUMENT FOUND

3" BLM BC

Stone @ SE base of BC RSG.5"

Carsonite 2.0 NW w/LSM-130

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Pine stump N31½°W, 11.55, toe blaze burnt

28"P. Pine, N20°E, 70.95, chopped open blaze burnt

11"P. Pine, N69°E, 46.20, **35H4ESII**

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

16"P. Pine, S59°E, 58.08, blaze healed

34"P. Pine, S10½°E, 70.95, 1°13S, R9E, S14

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

6"P. Pine S15½°W, 38.61, scribing visible but healed & pitched over

12"P. Pine N72°W, 47.52 **713SRGES**

CORNER LEGEND:

FS or Unverified
Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Location tag 230' E on Rd. #113. Take Rd. #113 110 mi. N from

Metolius Obs. Pt. junct. Location tag on 4 x 4 wood post on

West side Road #113.

UNCL 1985 BY EAST ~ OK

Searched By: R. Taylor
GS

Title

ST

Division

CS

Headquarters

SQ

Date


5/18/83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: Set 2½ x 28" BCSP RS6.4"

MONUMENT STAMPED



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 8"P N69E, 70L (46.20) 11"

15"P S59E, 88L (58.08) 16"

5"P S15½W, 58½L (38.61)

10"P N72W, 72L (47.52)

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Plat or _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc.
1881: Trap stone 16x14x10, 11" in GRD
mkd. 2 notches E, 4 on S edges

BLM 1966

16"P N18E, 106L (69.96)

26" P, N20E, 107½L, (70.95)

26"P S8E, 115L (75.90)

30"P. S10½E, 116½L (76.89)

34"P S60W, 77L (50.82)

24"P N40W, 16L (10.56)

30" STP, N31½W, 17½L (11.55)

12

Index File No. 1759 T.13 S., R. 9 E., W.M.

Contract or Surv. No.

Cor. J-17

13

Index
File No. 82159

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. J-21T 13S. R. 9E.R.D. SISTERSCounty JEFFERSONMerid. WillN.F. DESCHUTESState OREGONSEC COR

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency

DESCRIBE CORNER MONUMENT FOUND

BASALT ROCK 11" x 7" x 7" ABOVE GROUND IN GOOD
CONDITION WITH $\equiv$ ON S. AND - E. EDGES

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

18" x 7' P. PINE SNAG, N40°W, 33';

26" P. PINE, N44°E, 45';

16" P. PINE, S65°E, 375';

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SEC COR IS APPROX 450' W. OF S.L.B. BTWN SECS 12 & 13
ON RD 139-B.

Signature
O. THINAVALLTitle
CIVIL ENG

Division

Headquarters
S.O.Date
11-5-69

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. 2159 T.

R.

M.

Tract or Surv. No.

Cor. J-21

13

Index
File No. 2559 ~~2557~~

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. J-25

T 13S R. 9E


R.D. SISTERS County JEFFERSON

Merid. WILL

N.F. DESCHUTES State OREGON

SEC. COR.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

CRUISERS POST

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 32" A.P. BEARS ^{60°}SW ^{27' FT} MKD. "113 R9 Sec 12" (whether fr. or chains)

A 24" A.P. BEARS ^{14°}SW ^{30' FT} MKD. "T13 R9 Sec 13"

A 24" A.P. BEARS ^{24°}SE ^{20' FT} MKD. "113 R10 S 12"

28" P.P. N10°E 24' 3" MKD. T13S R10E S7 BT

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature NJK

Title S. A. Division _____

Headquarters SO.

Date 9/80 7100-52 (3 68)

R.R. GOULD


10-30-39

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET. 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 6"
IN A MOUND OF STONES, ABOUT 140 FT. EAST
OF F.S. RD. #1137



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

4" W.F.I.R. BRS. N03°E 21 ± FT., MKD. X BT
12" " " N48°E 44 ± FT., MKD. T13S R10E S7 BT
7" " " S51°E 60 ± FT., MKD. " " S18 BT
10" " " S19°W 57 ± FT., MKD. " R9E S13 BT

Work Done By R.OMAN Title PLS Date 10/80 State Registration No. OR-702
or Agency
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At JEFF. Co. SURV. OFFICE Date 11/80

REMARKS

Index File No. 2559 T. 13 R. 10 M. Tract or Surv. No. Cor. J-25

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Cont. # _____

Cor. C-W-W-NE


Survey No. 006686N

No. 1/256

T 13 S R. 9 E R.D. Sisters County Deschutes Jefferson

Merid. W. M. N.F. Deschutes State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Camp Sherman Hwy, North $\pm$ 4 miles. Go West on Access road $\frac{1}{2}$ mile. Go South on access road $\frac{1}{4}$ mile. Take driveway West $\pm$ 500' to corner

Title
SurveyorDivision
Sun Country Engineering

Headquarters

Bend Office

Date

Nov. 22, 1977

7100-52-(3/68)

5

Signature

Robert M. Kark

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" galv. iron pipe with 2½" brass cap

T13S R9E

S16

C-W-W-NE

1/256

1977 L.S. 1046

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

No bearing Trees scribed.

10

Work Done By Robert M. Karl Title Surveyor Date Oct. 77 State Registration No. L.S.I.T. 104
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Jefferson Co. Surveyor's Off. Date 12-21-77

11

REMARKS

Witness to above corner: Tom Jackson

12

Index File No. T. 13 S R. 9 E M. WM Tract or Surv. No. 006686N Cor. 1/256

13

K9½

Index
File No. 1160

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or Cont. #

Survey No. 006686N

Cor.

No. K - 11T 13 S R. 9 ER.D. SistersCounty Deschutes JeffersonMerid. W. M.N.F. DeschutesState Oregon

CORNER DIAGRAM



Driveway (Access Road)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER MONUMENT FOUND

Found $5/8$ " iron rod $\pm 2.84'$ North of our location.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Camp Sherman Highway, North from Hwy 20, approx. 4 miles, turn West on access road $\pm \frac{1}{2}$ mile. Turn South on access road $\pm \frac{1}{4}$ mile. Turn East on driveway $\pm 200'$ to corner.

Title
SurveyorDivision
Sun Country Engineering

Headquarters

Date

Bend Office Nov. 22, 1977

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" galv. iron pipe & 2½" brass cap

T13S R9E

C
N1/16 S16
C

1977 L.S. 1046

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed 2 Bearing Trees:

A 9" D.B.H. Larch bears N 58° W 15.02'

A 10" D.B.H. Larch bears S 74° E 12.50'

10

Work Done By. Robert M. Karl Title Surveyor Date Oct. 77 State Registration No. L.S.I.T. 104
or Agency

Certified Cor. Record Prepared? Yes ☒ No Filed At: _____ Date _____

11

REMARKS

Witness to corner: Tom Jackson

12

Index File No. T. 13 S R. 9 E M. W M Tract or Surv. No. 006686 N Cor. K 11

13

Index
File No.


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No.

13 S. R. 9 E. R.D. Sister County Jefferson C.W.W. NE 1/256
Merid. WILLAMETTE N.F. DESCHUTES State OREGON



2 1/2" Brass Cap set by

Michail W. Tye LS 1046

No BT's made.

SEE Plat # 30 in Flat File.

Index

File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

T 13 S. R. 9 E.

R.D. Sister


County Jefferson

C.W.W. NE 1/256

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON



2 1/2" Brass Cap set by

Michail W. Tye LS 1046

No BT's made.

SEE Plat # 30 in Flat File.

D-7100-52d (10/78)
USDA-FOREST SERVICE

Index
File No. 0161
T 13 S. R. 9 E. R.D. Sisters County Jefferson W¹/₄ Cor. of
Merid. WILLAMETTE N.F. DESCHUTES State OREGON Section 18

CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. L-01

SEE: L-25 T. 13 S., R. 8 E., W.M.


BOSP

LAND CORNER RECORD

L-05 5680-2

1. T 13S R 9E No. 15 Cor. $\frac{1}{4}$ Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-14-59

Photo No. EGI -51-19

Ident. By O. Thingvall

6-15-62

3. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 6"x10"x14", set in ground marked $\frac{1}{4}$ on W face.

5. Investigation Notes:

A ponderosa pine, 24" diam., bears S42°W, 7' dist., marked $\frac{1}{4}$ S.

A ponderosa pine, 45" diam. bears S38°E, 54' dist., marked B.T.

These distances check with photo copies of General Land Office field notes.

6. Signed Calvin W. Minks Title Forestry Aid Date 11-10-60

PERPETUATION RECORD

10. Monument: Brass Cap

11. Accessories 16" D. Fir N14°E 28 lks.
6" D. Fir S55°W 35 $\frac{1}{2}$ lks.

Plus old ones.

		Field Book _____ Page _____	
12. Set By _____ Title _____		13. Recorded By _____ Volume _____ Page _____	
License _____ Agency _____ Date _____		(Agency)	
		(Date)	(City)
		(County)	(State)

14. Remarks:

Index

File No. 0961

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or Cont. #

Survey No. 006686N

Cor.

No. L - 9T 13 SR. 9 ER.D. SistersCounty Dischutes JeffersonMerid. W. M.N.F. DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found 3" alum. cap on 2½" galv. iron pipe.

$\frac{1}{2}$
 S17 | S16
 T13S R9E
 1966

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S 16 - A 30" P. Pine original, scribed as called for. N 25° E
 S 16 - A 17" Fir, scribed during remonumentation. N 62° E
 S 17 - A 30" P. Pine original, scribed as called for. S 50° W
 S 17 - A 12" Larch, scribed during remonumentation.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Camp Sherman Highway, North about 4 miles from Hwy 20,
 Turn left at access road West, Go $\frac{1}{2}$ mile West, turn South
 about $\frac{1}{2}$ mile, take old skid trail approx. $\frac{1}{2}$ mile West to
 corner.

Signature
Robert M. Kass

Title
 Surveyor

Division
 Sun Country

Headquarters
 Engineering, Bend Office

Date
 Nov. 22-77

7100-52 (3. 68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

No new monument set.

ACCESSORIES : DESCRIBE NEW B.T.'s WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

existing bearing trees in good condition, No new B.T.s scribed.

Work Done By Robert M. Karl Title Surveyor Date Oct. 77 State Registration No. L.S.I.T. 104
or Agency

Certified Cor. Record Prepared ? Yes (No) Filed At: _____ Date _____

REMARKS

Index File No. 0961 T. 13 S R. 9 E M. W M Tract or Surv. No. 006686 N Cor. L9

Index

File No.

T 13 S R. 9 EMerid. W. M.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. SistersN.F. DeschutesCounty Deschutes JeffersonState Oregon

Tract or

Survey No.

Cont. #

006686N


Cor.

No. 1/256

C-W-W-E

L-9 1/2

CORNER DIAGRAM



NO BT'S

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Camp Sherman Highway, North about 4 miles, turn left at access road to West. Go $\frac{1}{2}$ mile & turn South about $\frac{1}{2}$ mile. Stay on access road to Green residence. Corner is approx. 330' East along fenceline.

Title
Surveyor

Division

Sun Country Engineering Bend office

Headquarters

Date

11-22-77 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" galv. iron pipe with 2½" brass cap

T13S R9E

S 16

C-W-W-E

1/256

1977

L.S. 1046

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

No bearing trees scribed

10

Work Done By. Robert M. Karl Title Surveyor Date Oct. 77 State Registration No. L.S.I.T. 104
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Jefferson Co. Surveyor's Off. Date 12-21-77

11

REMARKS

Witness to Corner: Tom Jackson

12

Index File No.

T. 13 S

R. 9 E

M. W M

Tract or Surv. No. 006686 N

Cor. 1/256

13

L 9½

Index

File No. 1161


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Cont. #

Survey No. 006686NCor. LNo. K - 11T 13 S R. 9 ER.D. SistersCounty DeschutesJeffersonMerid. W. M.N.F. DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found 5/8" iron rod set by E. W. Graves
Also found 1" iron pipe N 37° 30' W 3.53'

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Title
Surveyor

Division
Sun Country Engineering Bend office

Headquarters

Date

11-22-77 7100-52-(3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" galv. iron pipe with 2½" brass cap
in place of 5/8" iron rod.

T13S R9E
C¼ S16
1977
L.S. 1046

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed Two Bearing Trees

A 10" D.B.H. P.Pine bears N 17° W 35.58'

A 17" D.B.H. P.Pine bears S 35° W 60.92'

10

Work Done By Robert M. Karl Title Surveyor Date Oct. 77 State Registration No. L.S.I.T. 104
or Agency

Certified Cor. Record Prepared ? ☒ Yes ☐ No Filed At: Jefferson Co. Surveyor's Off. Date 12-21-77

11

REMARKS

Witness to corner: Tom Jackson

Index File No. 1161 T. 13 S R. 9 E M. W M Tract or Surv. No. 006686N Cor. L 11

12

13

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. L-11 1/2

T 13 S. R. 9 E. R.D. Sisters

County Jefferson


Merid. WILLAMETTE


N.F. DESCHUTES

State OREGON

2 1/2" Brass Cap set by
Michail W. Tye LS 1046

No BT's Made
See Plat #30 in Flat File.





USDA-FOREST SERVICE

Index

File No. 2561

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.


No. L-25T 13 S. R. 9 E.R.D. SISTERSCounty JEFFERSON

E/4 Cor. Sec. 13

Merid. WILLAMETTEN.F. DESCHUTESState OREGON

W/4 Cor. Sec. 18

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE RISING 6" MKD. 1/4

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" P. PINE BRG. N70°W 12° FT.
VIS SCRIBE " 1/4 S "

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

W. M.

Title

L. S.

Division

Headquarters

S. O.


Date

9/80 D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 5"
IN MOUND OF STONES, ABOUT 550 FT EAST OF
F.S. RD. #1137.



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE BRS. N36°E 45⁵ FT., MKD. 1/4 S18 BT

7" " " N57°W 7³ FT., " 1/4 S13 BT

Work Done By R.OMAN Title PLS Date 10/80 State Registration No. OR-702
or Agency

Certified Cor Record Prepared? ☒ Yes No Filed At: JEFF. CO. SURV. OFFICE Date 11/80

REMARKS

Index File No. 2561 T. 13 S., R. 9 E., W. M.

Tract or Surv. No.

Cor. L-25

Ind File No. 0562

T S. R. 9E

Me d. Willamette

COR 2 E R. 13 4G (proposed)

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No.

R.D. Sisters

County Jefferson

S/16 Cor.

N.F. Deschutes

State Oregon

DESCRIBE CORNER MONUMENT FOUND

N O T H I N G

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N O T H I N G

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH

PHOTO IDENTIFICATION DATA

Photo No.

File At.

Obj Ident.

Iden By

Signature

PLANE COORDINATE POSITION DATA

Sta Zone

X

Y

Est By

Agency

Signature

Title
PLS

Division


Headquarters
DNF-SODate
5 SEP 1976

7100-52

CORNER RECORD (PERPETUATION)

DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

x 30" Aluminum-Capped Steel Rod, rising 2", stamped as shown:



9

DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

" Double Fir bears N72°E 14.65 feet, blazed and scribed "S/16 S17 BT",
h nail in North Side;

r bears N90°W 5.92 feet, blazed and scribed "S/16 S18 BT", with nail in
th side.

10

R. Oman Title PLS Date 5/76 State Registration No. OR-702 WV-2
or Agency

Record Prepared ? Yes No Filed At: Jeff. Co. Surveyor's Office Date 5/76

11

REMARKS

12

0562 T. 13S. R. 9E., W. M.

Tract or Surv. No.

Cor. M-5

13

Index

File No. 0562

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. _____

Cor. M-5

Nö. _____

T 13S. R. 9E R.D. Sisters County Jefferson S/16 Cor. S.17/18Merid. Willamette N.F. Deschutes State Oregon

CORNER DIAGRAM

13.4G (proposed)

DESCRIBE CORNER MONUMENT FOUND

N O T H I N G

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N O T H I N G

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title
PLS

Division

Headquarters
DNF-SODate
5 SEP 1976


7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 5/8" x 30" Aluminum-Capped Steel Rod, rising 2", stamped as shown:



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 4" x 9" Double Fir bears N72°E 14.65 feet, blazed and scribed "S/16 S17 BT", with nail in North Side;

A 14" Fir bears N90°W 5.92 feet, blazed and scribed "S/16 S18 BT", with nail in North side.

Work Done By R. Oman Title PLS Date 5/76 State Registration No. OR-702 WV-23
or Agency
Certified Cor. Record Prepared ? Yes No Filed At Jeff. Co. Surveyor's Office Date 5/76

REMARKS


Index File No. 0562 T. 13S. R. 9E., W. M.

Tract or Surv. No.

Cor. M-5

Index File No. 1361 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Contract or Survey No. L-13
 T 13 S. R. 9 E. R.D. Sisters County Jefferson w/4 Cor. of
 Merid. Willamette N.F. Deschutes State Oregon Section 15

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

#4 SR in pavement 1.6 E of centerline.

3" BLM BC in stone mound (RM) RSG.7"

1/4 S15
 RM
 1966

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

31" P. Pine S67 $\frac{1}{2}$ °W, 41 lks., healed blaze, finish nail S side

19.5 P. Pine, N52°W, 77 $\frac{1}{2}$ lks. 1/4 S15 ST

34" P. Pine N81°E, 41 $\frac{1}{2}$ lks., chopped out w/sign over scribing

Finish nail S. side

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Rd #1304 N. to junct. (toward Head of Metolius). Proceed on #1304 1.0 mi. past junct., stop. Corner lies 1.6 ft. E. of centerline.

CORNER LEGEND:

FS or Unverified
 Contr. Other
☐ ☐ Searched For/Not Found
☒ ☒ Evidence Found/Accept.
☒ ☒ Permanent Mon. Set/Fd.

V15, 1985 ~ F.A.S.T ~ OK

Searched By:

Title

Division

Headquarters

Date

MH-GS

B. Taylor

ST

CS

SQ

5/17/83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: FD. #4SR, flush w/pavement

Wick: FD.#5SR in pavement

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE


BLM: 17" P. S52E, 77½L (51.15)

RM: 2½ x 28" BCSP RS6.4" ~~ORG~~ S42¼E, 94½L (62.37)

Mkd. ¼ S15 RM 1966 w/arrow pointing

to cor - raised MD/Stn around R.M.

MONUMENT STAMPED



Work Done By. BLM

Title

Date 1966

State Registration No.

or Agency

Plat or

Certified Cor. Record Prepared ? Yes No

Filed At:

Co. Surveyor's Office Date

History

of

Surveys,

G.L.O.,

etc.

1881: Trap stone 10x8x8, 8" in Grd.

mkd. ¼ on W. Face

BLM

1966

Perry

1960 Fd. mkd. stone

26"P, N83E, 40L (26.40)

28", N81E, 41½L (27.39)

22"P, S65W, 40L (26.40)

28" S65W, 41L (27.06)

Index File No. 1361 T. 13 S., R. 9 E., W.M.

Contract or Surv. No.


Cor. L-13

12

13

Index File No. 1461 CORNER RECORD (SEARCH) Contract or Survey No. Cor. No. L-14
 (Ref. FSM 7151.4)
 T 13 S. R. 9 E. R.D. Sisters County Jefferson WC/16 Cor. of
 Merid. Willamette N.F. Deschutes State Oregon Section 15

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

$\frac{1}{2}$ " IP RSG.2" @ W base of fence cor.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No visible RP's.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
 Contr. Other
 ○ ◇ Searched For/Not Found
 ⊗ ⊗ Evidence Found/Accept.
 ● ◆ Permanent Mon. Set/Fd.


Searched By: R. Taylor
 MH-GS

Title ST Division CS Headquarters SO Date 8/17/83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By A. Perry Title _____ Date 1966 State Registration No. _____
 Plat or _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc.
1966: A. Perry
1/2" 1. pipe
2.2 W of Fnc. Cor.
2.25 N. of Fnc. Cor.

Index File No. 1461 T. 33 S., R. 9 E., W.M.

Contract or Surv. No. _____

Cor. L-14

Index

File No. 15-61


CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 4-1Cor. No. L-15T 13 S. R. 9 E.R.D. SistersCounty JeffersonC 1/4 Cor. ofMerid. WillametteN.F. DeschutesState OregonSection 15

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

NONE - SFNF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FND AN 8" P. Pine with "conklin" blaze of,
S78°W, 25' and facing the corner mon.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER



CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: FRED ASTTitle PLS

Division _____

Headquarters _____


Date 5/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set monument, Rsg. 0.4' in stone mound 0.8'
East of a N-W Fence corner, and 2nd N/W
of horseback trail.

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed B.T.'s

9" p. pine - S 59° W, 34 1/2'

7" p. pine - S 62 1/4° E, 33 90'

Set carsonite w/LSM & PO nails, 3' N. of monument

10

Work Done By Fred Ast Title PLS Date 5/85 State Registration No. 1938
or Agency

Plat PE For Record Prepared? ☒ Yes ☐ No Filed At JEFF. Co. Surveyor's Office Date 6/85

11

History
of
Surveys,
G.L.O.,
etc.

1971 - A. PERRY SURVEY, DTD 2/17/71

Index File No.

15-61

T. 13 S., R. 9 E., W.M.

Contract or Surv. No. 4-1

Cor. L-15

12

13

Index

File No.

1761

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 4-1

Cor.

No. 4/17

T 13

S. R. 9

E.

R.D.

Sisters

County

Jefferson

E 1/4

Cor. of

Merid. Willamette

N.F.

Deschutes

State

Oregon

Section 15

CORNER DIAGRAM

per legend

DESCRIBE CORNER MONUMENT FOUND

S F N F

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

End a 54" p. pine tagged by others as A.B.T.
but not accepted by this survey.
Tree bears S58°E @ 91' from corner

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

150' ± SOUTH OF N. ENTRANCE ROAD TO
RIVERSIDE CAMPGROUND.

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

5

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: Fred Ast

Title PLS

Division

Headquarters

Date


5/85

COMMON RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" b.c.d. l.p., Rsg. 0.4' above grnd
in stone mound.

MONUMENT STAMPE



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed B.T's.

13" P. Pine - N 34 1/2° W @ 48 1/2'

9" P. Pine - N 39 1/2° E @ 12 1/2'

Set carsonite 2.4 ft. south of cor. mon.

with LSM decal

Work Done By Fred Ast

Title PLS

Date 5/85

State Registration No. 1938
or Agency

Elaborate or Record Prepared? ☒ Yes

No

Filed At Jeff Co. Surveyor's Office Date 6/85

History of 1881 - G.L.O. - T. JUDKINS

Surveys,
G.L.O.,
etc.

Index File No. 17/61 T. 13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. L/17

Index

File No. 2 2161

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No.

Cor.

No. 2-21T T. 13S., R. 9E.R.D. SISTERSCounty JEFFERSONMerid. WillN.F. DESCHUTESState OREGON1/4 COR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

BASALT STONE 14"x13"x4" ABOVE GROUND IN FAIR CONDITION

MARKINGS NOT LEGIBLE

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

36"x45' P. PINE STUMP, N29°E, 19', (NO SCRIBING LEGIBLE)

FELLED P. PINE SNAG, S32°W, 19', SOME SCRIBING VISIBLE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

TAKE SPUR ROAD, APPROX 100' E. OF RD. JUNC. OF [#]139 & [#]139E.
PROCEED NE FOR 1/4 MI TO S.L.B. BTWN SECS 13 & 14 - 1/4 COR
IS THEN 203'S.

4

Signature
O. THINGVALLTitle
CIVIL ENG

Division

Headquarters
S.D.Date
11-5-69

7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. *L-21* 13

Index

File No. 1162

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Cont. #

Cor.

Survey No. 006686NNo. M - 11T 13 S R. 9 ER.D. SistersCounty Deschutes JeffersonMerid. W. M.N.F. DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

No monument found

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No bearing trees found

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Camp Sherman Hwy, North about 3 miles from Hwy 20 take access road left at first residence on left $\frac{1}{2}$ mile to South $\frac{1}{4}$ cor. Sec. 16. Walk approx $\frac{1}{4}$ mile North along fence to corner,

 Title
 Surveyor

 Division
 Sun Country Engineering

Headquarters

Bend Office

Date

Nov. 22, 1971

7100-52-(3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" brass cap on 2½" galv. iron pipe
(no stones available for mound)

T13S R9E

C
S1/16 | S16
C

1977

L.S.1046

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed 2 Bearing Trees

A 15" D.B.H. P.Pine bears N17° 30' W 14.97'

A 15" D.B.H. P.Pine bears S 33° E 11.81'

10

Work Done By Robert M. Karl Title Surveyor Date Oct. 77 State Registration No. L.S.I.T. 104
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Jefferson Co. Surveyor's Off. Date 12-21-77

11

REMARKS

Witness to above corner: Tom Jackson

12

Index File No. 1162 T. 13S R. 9E M. WM Tract or Surv. No. 006686N Cor. M11

13

Index

File No. 15-62

CORNER RECORD (SEARCH) Contract or


(Ref. FSM 7151.4)

Survey No. 4-1

Cor.

No. M-15T 13 S. R. 9 E. R.D. SistersCounty JeffersonMerid. WillametteN.F. DeschutesState OregonCS $\frac{1}{16}$ Cor. of
Section 15

CORNER DIAGRAM per Legend



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Ce

Signature

CORNER LEGEND:

FS or

Unverified

Contr.

Other



Searched For/Not Found




Evidence Found/Accept.



Permanent Mon. Set/Yd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: Fred AstTitle PLS

Division

Headquarters


Date 5/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" l.p., B.S. cpd., Rsg. 0.5' above grade
IN MOUND of STONE

MONUMENT STAMP



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set-carsonite 2.4' south in E-W fence
Scribed- B.T.'s

6" p. pine - S 20° W, 34.44'

7" p. pine - S 60° W, 58.15'

10

Work Done By Fred Ast Title PLS Date 5/85 State Registration No. 1938
or Agency

Flat or Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 6/85

11

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD

12

Index File No. 15-62 T. 13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. M-15 13

Index

File No. 15-62

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 4-1

Cor.

No. M-15

T 13 S. R. 9 E.

R.D. Sisters

County Jefferson

CS $\frac{1}{16}$ Cor. of

Merid. Willamette


N.F. Deschutes

State Oregon

Section 15

CORNER DIAGRAM per Legend

DESCRIBE CORNER MONUMENT FOUND



NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found




Evidence Found/Accept.



Permanent Mon. Set/Td.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER



Searched By: Fred Ast

Title PLS

Division

Headquarters


Date 5/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" l.p., B.S. c.p.d., R.S.G. 0.5' above grade
IN MOUND of STONE

MONUMENT STAMP



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set-carsonite 2.4' south in E-W fence

Scribed-B.T.'s

6" p.pine - S 20° W, 34.44'

7" p.pine - S 60° W, 58.15'

Work Done By Fred Ast Title PLS Date 5/85 State Registration No. 1938
or Agency

Flat or Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 6/85

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD

Index File No. 15-62 T. 13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. M-15

Index

File No. 15-62

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 4-1Cor.
No. M-15T 13 S. R. 9 E.R.D. SistersCounty JeffersonCS $\frac{1}{16}$ Cor. ofMerid. WillametteN.F. DeschutesState OregonSection 15

CORNER DIAGRAM per legend




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Cg

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Yd.


DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: Fred AstTitle PLS

Division

Headquarters


Date 5/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" X 30" l.p., B.S. cpd., Rsg. 0.5' above grade
IN MOUND of STONE

MONUMENT STAMP



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set-carsonite 2.4' south in E-W fence

Scribed - B.T.'s

6" p. pine - S 20° W, 34.44'

7" p. pine - S 60° W, 58.15'

Work Done By Fred Ast

Title PLS

Date 5/85

State Registration No. 1938

Flat or

Settled For Record Prepared? ☒ Yes

No

Filed At JEFF

Co. Surveyor's Office

Date 6/85

History

NO PREVIOUS RECORD

of

Surveys,

G.L.O.,

etc.

Index File No. 15-62 T. 13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. M-15

Index

File No. 17-62

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)


Survey No. 4-1

Cor.

No. M-17T 13 S. R. 9 E.R.D. SistersCounty JeffersonS $\frac{1}{2}$ Sec. ofMerid. WillametteN.F. DeschutesState OregonSection 15 & 14

CORNER DIAGRAM

per legend



DESCRIBE CORNER MONUMENT FOUND

Power/Tele. pole is AT LOCATION OF
CORNER POSITION

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found




Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: Fred AstTitle PLS

Division _____

Headquarters _____

Date 5/85


CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}" \times 30"$ l.p. bc'd. Rsg. 0.6' above ground, 18.0' westerly & on line from true $\frac{1}{16}$ position.

* WITNESS CORNER *

MONUMENT STAMP



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed B.T'S.

6" P. Pine - N $66\frac{1}{2}^\circ$ W, 118.7' } all calls relative
6" P. Pine - N 20° E, 119.3' } to true corner

10

Work Done By Fred Ast Title PLS Date 5/85 State Registration No. 1938
PLS For Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 6/85

11

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD

12

Index File No. 17-62 T.13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. M-17 13

Index

File No. 17-62

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 4-1


Cor.

No. M-17T 13 S. R. 9 E.R.D. SistersCounty JeffersonS $\frac{1}{16}$

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 15 & 14

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

Power/Tele. pole is AT LOCATION OF
CORNER POSITION

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found




Evidence Found/Accept.



Permanent Mon. Set/Yd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: Fred AstTitle PLS

Division _____

Headquarters _____

Date 5/85


CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" X 30" l.p. bc'd. Rsg. 0.6' above
ground, 18.0' westerly & on line from
true 1/4 position.

* WITNESS CORNER *

MONUMENT STAMP



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed B.T.'S.

6" P. Pine - N 66 1/2° W, 118.7' } all calls relative
6" P. Pine - N 20° E, 119.3' } to true corner

10

Work Done By Fred Ast Title PLS Date 5/85 State Registration No. 1938
Filed For Cor. Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 6/85

11

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD

12

Index File No. 17-62 T.13 S., R. 9 E., W.M.

Contract or Surv. No 4-1

Cor. M-17 13

Index

File No. 17-62

CORNER RECORD (SEARCH) Contract or


(Ref. FSM 7151.4)

Survey No. 4-1

Cor.

No. M-17T 13 S. R. 9 E. R.D. Sisters County Jefferson S $\frac{1}{16}$ Cor. ofMerid. Willamette N.F. Deschutes State Oregon Section 15 & 14

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

Power/Tele. pole IS AT LOCATION OF
CORNER POSITION

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Constr. Other



Searched For/Not Found




Evidence Found/Accept.



Permanent Mon. Set/Yd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: Fred AstTitle PLS

Division _____

Headquarters _____

Date 5/85


CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" X 30" l.p. bc'd. Rsg. 0.6' above
ground, 18.0' westerly & on line from
true 1/4 position.

* WITNESS CORNER *

MONUMENT STAMPE



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed B.T.'S.

6" P. Pine - N 66 1/2° W, 118.7' } all calls relative
6" P. Pine - N 20° E, 119.3' } to true corner

Work Done By Fred Ast Title PLS Date 5/85 State Registration No. 1938
or Agency

Flat of Cor. Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 6/85

History of No PREVIOUS RECORD
Surveys,
G.L.O.,
etc.

Index File No. 17-62 T.13 S., R. 9 E., W.M.

Contract or Surv. No 4-1


Cor. M-17

LAND CORNER RECORD

5680-2

1. T. 13S, R. 9E No. 11 Cor. SEC Mer. Will State (Rectangular) OREGON N. F. DESCHUTES Dist. SISTERS

2. Corner Status



7. Photo Identification

Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation

Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: _____

5. Investigation Notes:

SEE: N-25, T13S, R8E

B.C.

6. Signed _____ Title _____ Date _____

PERPETUATION RECORD

10. Monument:

11. Accessories

		Field Book	Page
12. Set By	Title	13. Recorded By	Volume
License	Agency	(Agency)	Page
Date		(Date)	(City)
		(County)	(State)


14. Remarks:

LAND CORNER RECORD

N-03 5680-2

1. T 13S R 9E No. 0363 ¹/₄ Cor. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-11-59

Photo No. EGI-51-19

Ident. By: O. Thingvall

6-11-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A ponderosa pine, 20" diam., marked $\frac{1}{4}$ S on N side.

5. Investigation Notes:

A ponderosa pine, 22" diam., bears S11°30'W, 12.5' dist., marked S, remainder of scribing has burned off.

A ponderosa pine, 24" diam., bears N70°E, 10' dist., marked $\frac{1}{4}$ S.

The distances and bearings check with the photo copies of General Land Office field notes.

6. Signed Calvin W. Minks Title Forestry Aid Date 11-10-60

PERPETUATION RECORD

10. Monument:

1" Iron Rod

11. Accessories

16" Fir N23 $\frac{1}{2}$ °E 24 $\frac{1}{2}$ lks.

6" Fir S65 3/4°E 23 $\frac{1}{2}$ lks.

Brass cap ref. mon N51 $\frac{1}{2}$ °W 11 lks.

Plus old ones.

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

(Date)

(City)

(County)

(State)


14. Remarks:

LAND CORNER RECORD

N-05 5680-2

1. T. 13S R. 9E No. 15 Cor. Sec Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



7. Photo Identification 7-11-59

Photo No. EGI-51-19Ident. By: O. Thingvall6 11 62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 9"x7"x5" set in ground, marked with 5 notches on E. face.

5. Investigation Notes:

A ponderosa pine, 27" diam., bears N28°30'E, 53.4' dist., marked B.T. This tree was cut in logging.

A ponderosa pine, 27" diam., bears S51°W, 53.4' dist., marked T13S, R9E, S19.

These distances check with transcript of General Land Office field notes.

6. Signed Calvin W. Minks Title Forestry Aid Date 11-10-60

PERPETUATION RECORD

10. Monument: Brass cap.

11. Accessories

18" P.Pine N68°E 39 lks.
 7" P.Pine S49½°E 95 lks.
 15" P.Pine S18°W 91 lks.
 12" P.Pine N37½°W 123½ lks.

Plus old ones.

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
 (Agency)


(Date) (City) (County) (State)

14. Remarks:

LAND CORNER RECORD

1. T. 13S R. 9E No. 0763 Cor. 1/4 Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters N-07 5680-2

2. Corner Status



7. Photo Identification 7-14-59

Photo No. EGI-51-19

Ident. By: O. Thingvall

6-11-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

and Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 8"x10"x6", set in ground, marked $\frac{1}{4}$ on N face.

5. Investigation Notes:

A ponderosa pine, 13" diam., bears N60°W, 11.9' dist., marked $\frac{1}{4}$ S, B.T.

A ponderosa pine, 24" diam., bears S16°30'E, 55' dist. This tree is down.

These distances and bearings check with transcript of General Land Office field notes.

6. Signed Calvin W. Minks Title Forestry Aid Date 11-9-60

PERPETUATION RECORD

10. Monument: Brass cap

11. Accessories

8" W. Fir N48°E 24 lks.

8" W. Fir S7 $\frac{1}{4}$ °E 33 $\frac{1}{2}$ lks.

Plus old ones

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
(Agency)

(Date) (City) (County) (State)


14. Remarks:

LAND CORNER RECORD

N-09 5680-2

1. T. 13S R. 9E No. 0963 Cor. Sec Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:
A stone, 8"x5"x9", set in ground, with 4 notches on E face and 3 notches on S. face.

5. Investigation Notes:
A Western Larch, 42" diam., bears S79°E, 22.4' dist., with scars in proper place for bearing tree.
A Western Larch, 27" diam. bears N35°W, 75.2' dist., marked T13S, R9E, S17, B.T. This tree is dead.
A Western Larch, 33" diam., bears S37°30'W, 62.7' dist., scars for bearing tree.

The distances check with photo copies of General Land Office field notes.

6. Signed Calvin W. Minks Title Forestry Aid Date 11-9-60

7. Photo Identification 7-14-59
Photo No. EGT-51-67
Ident. By: O. Thingvall
6-22-62

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Etab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____

PERPETUATION RECORD

10. Monument: Brass Cap

11. Accessories
 15" P.Pine N17 $\frac{1}{2}$ °W 52 lks.
 20" D. Fir S21 $\frac{1}{2}$ °W 63 $\frac{1}{2}$ lks.
 10" P.Pine N52°E 114 $\frac{1}{2}$ lks.

12. Set By _____ Title _____
 License _____ Agency _____ Date _____

13. Recorded By _____ Field Book _____ Page _____
 (Agency) Volume _____ Page _____
 (Date) (City) (County) (State)

14. Remarks:

Index

File No. 1163T 13 S R. 9 EMerid. W. M.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Cont. #

Cor.

Survey No. 006686NNo. N - 11R.D. SistersCounty DeschutesN.F. DeschutesState Oregon

CORNER DIAGRAM



S 21

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency

Signature

DESCRIBE CORNER MONUMENT FOUND

Found 3" aluminum cap mounted on
2½" galv iron pipe. Also found
1" iron pipe due North 0.40'

S16

¼

S21

T13S R9E

1966

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S 16 - 6" P. Pine scribed

S 21 - 7" P. Pine scribed

S 21 - 36" P. Pine stump (orig.) scribed as called for

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Camp Sherman Highway from Hwy 20, North approx. 3 miles
to first residence on left (take left fork at Junction of
Camp Sherman & Head of Metolius) Take access road West ½
mile to corner.

Title
SurveyorDivision
Sun Country EngineeringHeadquarters
Bend Office

Date

// - 22 - 77

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

No new monument set

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

No new bearing trees scribed - existing B.T.s in good condition.

Work Done By Robert M. Karl Title Surveyor Date Oct. 77 State Registration No. L.S.I.T. 104
or Agency

Certified Cor. Record Prepared ? Yes

(No)

Filed At:

Date

REMARKS

Witness to above corner: Tom Jackson

Index File No. 1163

T. 13 S

R. 9 E

M. W M

Tract or Surv. No. 006686 N

Cor. N 11

Index

File No. 1363

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.

No. N-13

T 13 S. R. 9 E. R.D. Sisters County Jefferson

SW Cor. of

Merid. Willamette N.F. Deschutes State Oregon

Section 15

CORNER DIAGRAM per legend

S16

S15



S21

RD #1304

S22

US

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: R. Taylor
MH-GS

DESCRIBE CORNER MONUMENT FOUND

3" BLM BC (RM)

Did not dig up BC by Karl

T13S R9E

S21

RM

1966

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

11.5" Larch, N32°E, 34.43 T13S R9E S16 BT

31" P. Pine, S33°W, 50.08, blaze healed

38" P. Pine, S33½E, 103.54 (22)

Set ATTN signs

9.5" P. Pine, S32½E, 140.63, blaze healed

on all BT's

30" P. Pine, N68°E, 88.34, chopped open-pitched over

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Rd #1304 N to Junct. toward Head of Metolius. Continue

on #1304 (toward Camp Sherman) 0.5 mi. past junct.

Corner falls in cinder road.

V15, 1985 ~ F. AST ~ OK

Title ST

Division CS

Headquarters SO

Date

RM 6
5/17/83

DO NOT WRITE


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: FD. 3/4" pipe, Brd, 4" below rd, surf.

R.M. Karl: Set 2 1/2 x 30" BCSP Brd. 6"

MONUMENT STAMPED



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 7" P, S33E, 213L (140.58)

RM: 2 1/2 x 28" BCSP RS6.4" BR6.S30W, 77L (50.82)

mkd. T13S, R9E, S21 RM 1966 w/arrow

pointing to corner.

Lot Cor. 30.0 west

RM Karl: 6" Larch, N32°W, 34.48 ft.

10

Work Done By R.M. Karl Title PLS Date 1977 State Registration No. 1046
or Agency

Plat or Co. Surveyor's Office Date
Certified Cor. Record Prepared ? Yes No Filed At:

11

History of Surveys, G.L.O., etc.
1881: Trap stone 14x12x10, 10" in Grd.
mkd. 3 notches E and S edges

BLM 1966

18"P, N67E, 135L (89.10)

30", N68E

28"P, S38E, 155L (102.30)

38", S35 1/4 E

24"P, S31W, 87L (57.42)

31",

34"P, N60W, 15L (9.90)

12

Index File No. 1363 T. 13 S., R. 9 E., W.M.


Contract or Surv. No.

Cor. N-13

13

Index File No. 1563
 T 13 S. R. 9 E. R.D. Sisters County Jefferson S/4 Cor. of N-15
 Merid. Willamette N.F. Deschutes State Oregon Section 15

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

3" BLM BC

RSG.

stone 14 x 11 x 9 mkd 1/4 @ E base of cap

4"

cap lies 5.0 E of N-S fence

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

37" P. Pine, S78°W, 63.36, 1/4 S BT

9.5" P. Pine, S10W, 53.79, healed blaze

8.5" P. Pine, N5 1/2 W, 111.21, healed blaze

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Rd. #1304 N to Sec. Cor. 16 | 15
21 | 22, turn right (east)

proceed 0.5 mi. to gate. Cor. lies 12' N and 5.0 E of gate.

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: R. Taylor

MH-GS

Title ST

Division CS

Headquarters SO

Date

5/17/83


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: Set $2\frac{1}{2}$ x 28 BCSP, RS6.4", Fd. orig. stone in

Fnc. S8°W, 14L (9.24)

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 6"P, N5½W, 168½L, (111.21)

8"P, S10W, 81½L, (53.79)

Work Done By BLM Title _____ Date 1966 State Registration No. _____
 Plat or _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc.	1881: Trap stone 14x12x10, 10" in Grd.	BLM 1966
	Mkd. ¼ on N. Face	
	24"P, N41E, 17L (11.22)	28", N41E, 117L (77.20)
	28"P, S78W, 96L (63.36)	37", S78W, 96L (63.36)

Index File No. 1563 T. 13 S., R. 9 E., W.M.

Contract or Surv. No.

Cor. N-15

Index

File No. 1763

CORNER RECORD (SEARCH)

Contract or

Survey No.

Cor.

No. N-17

T 13 S. R. 9 E. R.D.

Sisters

County

Jefferson

SE

Cor. of

Merid. Willamette

N.F.

Deschutes

State

Oregon

Section 15

CORNER DIAGRAM per legend

S15

S14

PVT

US

N

0.5 FT.

PVT

US

S22

S23

PHOTO IDENTIFICATION DATA

Photo No.

Filed At

Object Ident.

Ident. By

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: R. Taylor

CS

Title

ST

Division CS

Headquarters SO

Date 5/18/83

DESCRIBE CORNER MONUMENT FOUND

3" BLM BC

RSG 10"

Cor. falls 0.5 W of N-S fence.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

11"P. Pine, S76°E, 25.0 ft, T13S, R9E, S23 BT

OR16 NE tree dead & down pine, T13, R9E Stump in NW location

9"P. Pine, N40°E, 25.2, T13S, R9E, S14 BT Stump in SW location w/toe blaze

8.5"P. Pine, N34°W, 10.5, T13S, R9E, S15 BT Brg. & Dist from tags By BR 1973

8"P. Pine, S38°W, 26.7, T13S, R9E, S22 BT

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Rd. #113 N 0.1 mi past Head of Metolius Observation Point.

stop & location tag on 4 x 4 on N side road.

VIS. 1985 - F. AST ~ OK

4


5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: Set 2½" x 28" BCSP RS6.4"

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 8" P., N43E, 38½L (25.41)

9" P., S73E, 38½L (25.41)

7" P., S43W, 41L (27.06)

6" P., N28W, 16L (10.56)

Work Done By. BLM Title 1966 Date _____ State Registration No. _____ or Agency _____

Plat or _____
Certified Cor. Record Prepared? Yes ☐ No ☐ Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc.	1881: Trap stone 14x12x6, 8" in Grd. mkd. 2 notches E, 3 on S edges	BLM 1966 Fd. Stn.	11
	25"P, N77E, 97L (64.02)	Root hole and log	
	18"P, S63E, 74L (48.84)		
	30"P, S82W, 139L (91.74)	42" Sawn P. Stp. S84W	
	26"P, N50W, 102L (67.32)	30" sawn P. Stp. N49W	12

Index File No. 1763 T. 13 S., R. 9 E., W.M.

Contract or Surv. No.

Cor. N-17 13

Index
File No. 2163

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. N-21

T 13S R. 9E

R.D. SISTERS

County JEFFERSON


SEC. COR.

Merid. WILL.

N.F. DESCHUTES

State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE 6" x 9" x 8"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 20" CEDAR NW 70' MKD "T13S R9E S14 BT"

A 26" P.PINE NE 50' MKD "T13S R9E S2 BT"

A 24" P.PINE SW 30' MKD "T13S R9E S23 BT"

A 26" P.PINE SNAG SE 70' MKD. "T13S R9E S24 BT"

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON 28" P.PINE ON N. SIDE OF
CORNER. CORNER BEARS S 35 FT

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

M. A. PALMER A.A.A.

Title

Division

Headquarters

Date


11-13-40

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 2163 T. 135, R. 9E. M. Tract or Surv. No. Cor. N-21

Index
File No. 2363

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. N-23

T 13S R. 9E

R.D. SISTERS

County JEFFERSON

1/4 COR.


Merid. WILL.

N.F. DESCHUTES

State OREGON

CORNER DIAGRAM

13



24

DESCRIBE CORNER MONUMENT FOUND

STONE 8 x 8 x 6"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 24" P.PINE NW 20 FT. MKD "1/4S BT"

A 22" P.PINE SE 18 FT. MKD "1/4S BT"

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON A 18" P.PINE ON W. SIDE
OF CORNER. CORNER BEARS E. 30 FT.

Signature

M.A. PALMER

Title

A.I.A.A.

Division

Headquarters


Date
11-13-40

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. 2363 T. 13 S. R. 9 E. M.

Tract or Surv. No.

Cor. N-23

12

13

Index
File No. 2503
T 13S R. 9E
Merid. WILL.


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor. No. N-25
County JEFFERSON
State OREGON
NW COR. Sec. 13, 19

R.D. SISTERS
N.F. DESCHUTES

County JEFFERSON
State OREGON
NW COR. Sec. 13, 19

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE IN PLACE 16 x 12 x 7 1/4 HIGH RSG. 4"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 13" P.PINE SE $25\frac{1}{2}^\circ$ 25 FT. MKD. "T13S R9E S19"
A 24" P.PINE NE $30\frac{1}{2}^\circ$ 30 FT. MKD. "T13S R10E S18" @ T
A 24" P.PINE ^{SAWN STUMP} NW 35° 35 FT. MKD. "T13S R9E S24" (THIS BT IS
28" IN SEC. 13)
A 24" P.PINE SW 87° 50 FT. MKD. "T13S R9E S24"

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON 8" CUTOVER P.PINE ON THE
W. SIDE OF A BEARING TREE. CORNER BEARS
W. & SLIGHTLY N. 21 FT.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

stcd. By _____
Agency _____

Signature C.T.
M.A. PALMER

Title S.A. Division
A.A.A.

Headquarters S.O.


Date 9/80
10-12-40 7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 4"
IN MOUND OF STONES, WITH ORIG. STONE HALFBURIED
ALONGSIDE, AND ABOUT 380 FT. E. of FS RD. 1137



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE BRS. N 36° E 44 1/2 FT., MKD, T135 R10E S18 BT

6" P. PINE BRS. N 04° W 53 1/2 FT., MKD, T135 R9E S13 BT

Work Done By. ROMAN Title PLS Date 10/80 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: JEFF. Co. SURV. OFFICE Date 11/80

REMARKS

Index File No. 2563 T. 13 S. R. 9 E W M.

Tract or Surv. No.

Cor. N-25

Index

File No. 0364

CORNER RECORD (SEARCH)

Tract or


Cor. 0-3

(Ref. FSM 7151.4)

Survey No. NC/16No. S.19T 13S.R. 9E.R.D. SistersCounty JeffersonMerid. WillametteN.F. DeschutesState Oregon

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



N O T H I N G

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N O T H I N G

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature _____

Title AS

Division _____

Headquarters

DNF-SO

Date


7100-52 (3/68)

- 3 SEP 1976

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 5/8" x 30" Aluminum-Capped Steel Rod, rising 3",
about 50 feet west of Forest Road 1314, stamped as shown:



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 6" Ponderosa Pine bears N11°E 44.26 feet, blazed and scribed "NC/16 BT", with a nail in the E side;

A 16" Fir bears S86°W 17.33 feet, blazed and scribed "NC/16 BT", with a nail in the S side.

Work Done By R. Oman Title PLS Date 4/76 State Registration No. OR-702 WV-23
or Agency
Certified Cor. Record Prepared? Yes No Filed At Jeff. Co. Surveyor's Office Date 5/76

REMARKS

Index File No. 0364 T. 13S. R. 9E., W. M.

Tract or Surv. No.

Cor. 0-3

Index


File No. 0564

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor. 0-5
No. _____T 13S R. 9ER.D. SistersCounty JeffersonN/16 Cor. S.19/20Merid. WillametteN.F. DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

N O T H I N G

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N O T H I N G

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature _____

Title
PLS

Division

Headquarters
DNF-SO

Date


7100-52 (3/68)

• 5 SEP 1976

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 5/8" x 30" Aluminum-Capped Steel Rod, rising 3", stamped as shown:



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

An 11" Ponderosa Pine bears N04°W 19.8 feet, blazed and scribed "N/16 BT";

A 4" Ponderosa Pine bears N70°W 45.5 feet, blazed and scribed "N/16 BT".

Work Done By R. Oman Title PLS Date 4/76 State Registration No. OR-702 WV-23
 Certified Cor. Record Prepared? Yes No Filed At Jeff. Co. Surveyor's Office Date 5/76

REMARKS

Index File No. 0564 T. 13S R. 9E, W. M. Tract or Surv. No. Cor. 0-5


Date 5/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}" \times 30"$ B.C.D. I.P. Rsg. O.S. in mound
of stone ~~cellar~~

MONUMENT STAMP



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set: carsonite w/P.B. & L.S.M. decals 3" East of corner.

Scribed B.T.S.: 5" P. Pine - N $56\frac{1}{4}^\circ$ W, 9.18'

6" P. Pine - S $83\frac{3}{4}^\circ$ W, 21^{33'}

A N & E Fence corner brs. S 76° E @ 15'

A $\frac{1}{2}"$ I.P. (origin unknown, not held) brs. S $77^\circ 35' 39"$ E @ 14'

Work Done By Fred Ast Title PLS Date 5/85 State Registration No. 1938
or Agency

Flat or Cor Record Prepared? ☒ Yes ☐ No Filed At Jeff Co. Surveyor's Office Date 6/85

History of Surveys, G.L.O., etc. NO RECORDS

Index File No. 15/64 T. 13 S., R. 9 E., W.M.

Contract or Surv. No. 4-1

Cor. 0/15

Index

File No.

~~22~~ 1764

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

4-1

Cor.

0-17

No.

T 13 S. R. 9 E.

R.D.

Sisters

County

Jefferson

N¹/₄

Cor. of

Merid. Willamette

N.F.

Deschutes


State

Oregon

Section

22 & 23

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.


Ident. By

12

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER



CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Pd.

Searched By: Fred Ast

Title

PLS

Division

Headquarters

Date


5/85

TURNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" B.C.D. I.P. B.S. O.T.
in stone mound

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed B.T's.;

5" p.pine - ~~XXXXXXXXXX~~ S 20° W, 1929

13" P.pine - S 26° E, 1928

10

Mark Done By FRED AST Title PLS Date 5/85 State Registration No. 1938
or Agency

Flat or Certified for Record Prepared? ☒ Yes ☐ No Filed At JEFF Co. Surveyor's Office Date 6/85

11

History of Surveys, G.L.O., etc. NO PREVIOUS RECORD

Index File No. 2756 T. 13 S., R. 9 E., W.M.
1764

Contract or Surv. No 4-1

Cor. 0-17 ~~1985~~ 12
13

Ind ~~EX~~ No. 0165
File ~~EX~~ No. 0165

T 13S R. 9E

Me ~~F~~ id. Willamette

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLAN E COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Sisters

County Jefferson

N.F. Deschutes

State Oregon

Tract or
Survey No. _____

Cor. No. P-1

W/4 Cor. S.19

DESCRIBE CORNER MONUMENT FOUND

NOTHING

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 38" Fir bears N38°E 24.4 feet, B & S

A 39" burnt-out Pine stump w/scribes bears S53W 70.0 feet.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Title
PLS

Division

Headquarters
DNF-SO

Date


5 SEP 1976

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2" x 32" Brass-Capped Steel Pipe, rising 5", about 50 feet south of top of highway cutbank, stamped as shown:



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 7" Fir bears S16°W 69.4 feet, blazed and scribed "1/4 S24 BT";
An 8" Fir bears S62°E 48.8 feet, blazed and scribed "1/4 S24 BT".

Work Done By <u>R. Oman</u>	Title <u>PLS</u>	Date <u>4/76</u>	State Registration No <u>OR-702</u>	WV-23	10
		or Agency <u>Jeff. Co. Surveyor's Office</u>	Date <u>5/76</u>		11
Certified Cor. Record Prepared ? <u>Yes</u>	No	Filed At			

REMARKS

Index File No. 0165 T. 13S. R. 9 E, W. M.

Tract or Surv. No.

Cor. P-1

12

13

Index

File No. 0365

T 13S R. 9E

Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Sisters

N.F. Deschutes

Tract or

Survey No. _____

Cor.

No. _____

P-3


County Jefferson

C/4

S.19

State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

N O T H I N G

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N O T H I N G

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Section Line Marker on E Side of Rd. 1314 near Junction w/private road heading East.

Signature _____

Title
PLS

Division

Headquarters
DNF-SO


Date

5 SEP 1976 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2" x 32" Brass-Capped Steel Pipe, rising 6",
stamped as shown:



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 10" Ponderosa Pine bears S88°W 21.47 feet, blazed and scribed "C1/4 BT", with a nail in N Side;

A 7" Ponderosa Pine bears S02°W 10.02 feet, blazed and scribed "C" 1/4 BT", with a nail in E side.

10

Work Done By. R. Oman Title PLS Date 4/76 State Registration or Agency OR-702 WV-23
Certified Cor. Record Prepared ? Yes No Filed At. Jeff. Co. Surveyor's Office Date 5/76

11

REMARKS

12

Index File No. 0365 T. 13S R. 9E., W. M.

Tract or Surv. No.

Cor. P-3

13

Index

File No. 0465

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

P-4

T 13 S R. 9E

R.D.

Sisters

County

JeffersonEC/16 COR. S.19Merid. Willamette


N.F.

Deschutes

State

Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

N O T H I N G

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N O T H I N G

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature _____

Title

PLS

Division

Headquarters

DNF-SO

Date


7100-52-(3/68)

5 SEP 1976

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2" x 34" Brass-Capped Steel Pipe, rising 7", stamped
as shown:



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 4" Ponderosa Pine bears S34°W 21.20 feet, blazed and scribed "EC/16 BT", with
nail in W Side;

A 5" Ponderosa Pine bears N48°W 21.81 feet, blazed and scribed "EC/16 BT", with
nail in S Side.

10

Work Done By R. Oman Title PLS Date 4/76 State Registration No. OR-702 or Agency WV-23
Certified Cor. Record Prepared ? Yes No Filed At Jeff. Co. Surveyor's Office Date 5/76

11

REMARKS

12

Index File No. 0465 T.13S R. 9E, W. M. Tract or Surv. No. Cor. P-4


13

LAND CORNER RECORD

P-05 5680-2

1. T. 13S R. 9E No. 15 Cor. $\frac{1}{4}$ Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 13"x11"x11", set in ground, marked $\frac{1}{4}$ on W face.

5. Investigation Notes:

A ponderosa pine, 34" diam., bears S25°E, 16' dist., marked B.T.
This tree is down.

The pine in Sec. 19, that is mentioned in the photo copies of General Land Office field notes as a bearing tree, has never been blazed.

7. Photo Identification 7-14-59

Photo No. EGI-51-18

Ident. By: O. Thingvall

6-11-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed Calvin W. Minks Title Forestry Aid Date 11-10-60

PERPETUATION RECORD

10. Monument: Brass cap

11. Accessories 5" P.Pine S50 $\frac{1}{2}$ °E 16 lks.
6" P.Pine S78 $\frac{1}{2}$ °W 50 lks.
Plus old ones

12. Set By _____ Title _____		Field Book _____ Page _____	
License _____	Agency _____	Date _____	13. Recorded By _____ Volume _____ Page _____
			(Agency)
			(Date) (City) (County) (State)

14. Remarks:

LAND CORNER RECORD

209 5680-2

1. T. 13S R. 9E No. 19 Cor. 1/4 Mer. Will State Oregon (Rectangular) N. F. Deschutes Dist. Sisters

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 10"x8"x4", set in ground, marked $\frac{1}{4}$ on W face.

5. Investigation Notes:

A ponderosa pine, 17" diam., bears S30°W, 9' dist., marked $\frac{1}{4}$ S.

A ponderosa pine, 22" diam., bears N82°E, 49' dist., marked $\frac{1}{4}$ S
B.T. This tree is dead

The bearings differ by 40° with photo copies of General Land Office field notes.

7. Photo Identification 7-14-59

Photo No. EGI-51-67

Ident. By O Thingvall

6-22-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed Calvin W. Minks Title Forestry Aid Date 11-9-60

PERPETUATION RECORD

10. Monument: Brass cap.

11. Accessories 4" P.Pine N73 3/4°E 76 lks.
7" P.Pine N29°W 187 lks.
Plus old ones


12. Set By _____ Title _____
License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
(Agency)
(Date) (City) (County) (State)

14. Remarks:

Index
File No. 1365 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Contract or Survey No. Cor. No. P-13
T 13 S. R. 9 E. R.D. Sisters County Jefferson W/4 Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 22

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

3" BLM BC

RSG. 3"

Stone 13 x 11 x 6, at SE base of cap

mkd. $\frac{1}{4}$

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

OR6 25" P. Pine, N55°E, 41 lks scribed $\frac{1}{4}$ S

6.5" P. Pine, S68½E, 111 lks, healed blaze

19" P. Pine, N75½W, 162½ lks, healed blaze

Set attn. signs on all BT's

PHOTO IDENTIFICATION DATA

Photo No. Filed At. Object Ident. Ident. By Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Rd #14 (formerly 113) N. to junct. #1430, take right,

proceed 0.1 to spur rd., take left, proceed 0.1 mi. Stop.

Cor. 30' on right.

VIS. 1985 ~ F.A.S.T ~ OK


Searched By: R. Taylor
MH-GSTitle STDivision CSHeadquarters SQDate 5/17/83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: Set $2\frac{1}{2}$ x 28" BCSP RSG.4" - Dep. Orig. Stn. by pipe,

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 5"P, S68 $\frac{1}{2}$ E, 111L (73.26)

17"P, N75 $\frac{1}{2}$ W, 162 $\frac{1}{2}$ L (107.25)

10

Work Done By. <u>BLM</u>	Title <u>1966</u>	Date _____	State Registration No. _____
Plat or _____			or Agency _____
Certified Cor. Record Prepared ?	Yes _____ No _____	Filed At: _____	Co. Surveyor's Office Date _____

11

History of Surveys, G.L.O., etc.	1881: Trap stone 16 x 14 x 10, 11" in Grd.	BLM 1966
	mkd. $\frac{1}{4}$ on W. Face	Fd. Stn.
	22"P, N55E, 3L (1.98)	24"P, N55E, 4L (2.64)
	24"P, S60W, 59L (38.94)	

12

Index File No. 1365 T. 13 S., R. 9 E., W.M.

Contract or Surv. No

Cor. p-13

13

Index

File No.

15/65

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

4-1

Cor.

No. 9/15

T 13 S. R. 9 E.

R.D. Sisters

County Jefferson

C 1/4

Cor. of

Merid. Willamette

N.F. Deschutes

State Oregon

Section 22

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

14

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: Fred Ast

Title PLS

Division

Headquarters


Date 5/85

MONUMENT RECORD (PERPETUATION)
MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " x 30" b.c.d. 1.P. RSG 0.3'

ON A MODERATE NW SLOPE

MONUMENT STAMPE



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed B.T's.:

15" P. pine - S 32° W @ 2883'

13" P. pine - S 58° E @ 2965'

Work Done By Fred Ast Title PLS Date 5/85 State Registration No. 1938
or Agency
Placed or for Record Prepared ☒ Yes ☐ No Filed At Jeff Co. Surveyor's Office Date 6/85

History NO PREVIOUS RECORD
of
Surveys,
G.L.O.,
etc.

Index File No. 15/65 T. 13 S., R. 9 E., W.M.

Contract or Surv. No. 4-1

Cor. P/15

Index

File No. 1767

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.


Cor.

No. P-17

T 13 S. R. 9 E. R.D. Sisters County Jefferson E/4 Cor. of

Merid. Willamette N.F. Deschutes State Oregon Section 22

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

3" BLM BC

RSG. 7" in stone mound

Fd 12 x 10 x 9 stone mkd 1/4 W of cap in

rock mound around cap.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

16" fir, N44° E, blazes healed

33" P. Pine, N62° E, 72 lks, blaze burnt

40" P. Pine, S63° W, 62 1/2 lks, blaze burnt

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

Set attn. signs on all trees

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Rd #134 north to junct. #134-E, take left, proceed

1.6 mi. to junct. Spur Rd. #15, take right, proceed 0.4 mi.

to Spur Rd. #41, proceed 0.3 mi. to location tag on S. side

Rd., corner lies 200' S. of tag.

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: R. Taylor

Time ST

Division CS

Headquarters SO

Date 5/17/83

MH-CS

VIS. 1985 ~ F. AST ~ OK


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: Set 2½" x 28" BCSP, RS6.4" in MD/Stn,

Deposit orig. stn. alongside pipe.

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 9" Fir, N44E, 51L (33.66)

Work Done By. BLM Title _____ Date 1966 State Registration No. _____
 Plat or _____ or Agency _____

Certified Cor. Record Prepared? Yes _____ No _____ Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc. 1881: Trap stone 14 x 12 x 12, 10" in Grd. 1966: BLM
 Mkd. ¼ on W. Face Ed. Stn.

26"P, N65E, 71L (46.86) 36"P, N62E, 72L (47.52)
 28"P, S60W, 61L (40.26) 38"P, S63W, 62½L (41.25)

Index File No. 1767 T. 13 S., R. 9 E., W.M. Contract or Surv. No _____ Cor. P-17

Index

File No. 2165T 13S R. 9EMerid. WILL.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. P-21R.D. SISTERS


County

JEFFERSONN.F. DESCHUTES

State

OREGON1/4 COR.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 20" P. PINE SE MKD "1/4 S BT"

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

M. A. PALMER

Title

A. A. A

Division

Headquarters

Date

11-13-40


7100-52 (3 68)

4

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 2165 T. 13S. R. 9E. M.

Tract or Surv. No.

Cor. P-21

Index

File No. 2565

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No. P-25T 13S R. 9ER.D. SISTERSCounty JEFFERSON1/4 COR. Sec 24Merid. WILL.N.F. DESCHUTESState OREGONW/4 Cor. Sec. 19

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER MONUMENT FOUND

STONE 10 x 10 x 2" HIGH

MARKED "1/4" ON EAST FACE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 28" P. PINE NW 28 FT. MKD. "1/4 S"

A 22" P. PINE E 50 FT. MARKINGS NOT VISIBLE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON A 18" P. PINE, ON THE
N. SIDE OF A BT, FROM WHICH CORNER BEARS
SE 28 FT.


Signature C. F. PALMERTitle S. A. Division A. A. A.Headquarters S. O.Date 9/80
10-12-40 7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 7"
IN MOUND of STONES.; PLACED ORIG. STONE IN
HOLE ALONGSIDE PIPE; ABOUT 530 FT. E. of
ROAD



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P. PINE BRS. S76°W 47 1/2 FT., MKD. 1/4 S24 BT
11" " " N45°E 101 3/4 FT., " 1/4 S19 BT.
30" " " N48°W 23 3/4 FT. (ORIG. BT.)

Work Done By. R. OMAN Title PLS Date 10/80 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared ☒ Yes No Filed At: JEFF. CO. SURV. OFFICE Date 11/80

REMARKS

Index File No. 2565 T.13S. R. 9E W M.

Tract or Surv. No.

Cor. P-25

Index

File No.

0566

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor. Q-5

No.

Cor. S.19/20

T 13S

R. 9E

R.D.

Sisters

County

Jefferson

S/16

Merid. Willamette


N.F.

Deschutes

State

Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

N O T H I N G

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N O T H I N G

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

PLANE COORDINATE POSITION DATA

State

Zone

X

Y

Estab. By

Agency

Signature

Title
PLS

Division

Headquarters
DNF-SO

Date


5 SEP 1976

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 5/8" x 30" Aluminum-Capped Steel Rod, rising 3",
about 642 but N of FS Rd. 1314-A and S80° W 400 feet
from junction FS Rd. 1314-A & 1314-B, stamped as shown:



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 3" Ponderosa Pine bears S20°E 11.0 feet, blazed and scribed "S/16 BT";

A 6" Ponderosa Pine bears N76°W 72.4 feet, blazed and scribed "S/16 BT".

Work Done By R. Oman Title PLS Date 4/76 State Registration No. OR-702 WV-23
Certified Cor. Record Prepared? Yes No Filed At: Jeff. Co. Surveyor's Office Date 5/76

REMARKS

Index File No. 0566 T. 13S R. 9E, W. M. Tract or Surv. No. Cor. Q-5

Index

File No. 0167


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. R-1T 13 S R. 9 ER.D. Sisters County JeffersonMerid. WillametteN.F. Deschutes State Oregon

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



Brass Cap

See = R-25 T13S R9E Wm.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Six bearing trees

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. 0167 T. 13S. R. 9E. M.

Tract or Surv. No.

Cor. R-1


13

LAND CORNER RECORD

(Rectangular)

5680-2

0367
 1. T 13 S. R 9 E. No. R-3 Cor. 1/4 Mer. W State Oregon N. F. Deschutes Dist. Metolius R-03

2. Corner Station 19

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

This corner is located in roadbed of U. S. Highway 20.

5. Investigation Notes:

I found mistakes in the bearings of the bearing trees in the photo copies of General Land Office field notes. The bearings formed nearly parallel lines that do not intersect in the area.

Brass Cap - Under Left Shoulder of Highway

7" W. Fir N 85 1/2° W 58 lks

8" W. Fir S 22° W 79 lks

Ref.
 Brass Cap Mon. S 17 1/2° W 35 lks
 Plus Old One

from 11/10/60

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane. Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic? _____

Needs Verif. Yes Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed Calvin W. Munk Title Forestry Aid Date 11/10/60

41

R-3

Index

File No.

0467

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No.

R-4

T 13S

R.

9E

R.D.

Sisters

County

Jefferson

E/16

Cor. S.19/30

Merid.

Willamette


N.F.

Deschutes

State

Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

N O T H I N G

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N O T H I N G

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____

Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title
PLS

Division

Headquarters
DNF-SO

Date


5 SEP 1976

7100-52 (3-68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 5/8" x 30" Aluminum-Capped Steel Rod, rising 9",
stamped as shown:



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 7" Ponderosa Pine bears N12°E 17.1 feet, blazed and scribed "E/16 BT";

An 8" Ponderosa Pine bears S56°W 20.1 feet, blazed and scribed "E/16 BT".

Work Done By R. Oman Title PLS Date 4/76 State Registration No. OR-702 WV-23
or Agency

Certified Cor. Record Prepared? Yes ☐ No ☒ Filed At: Jeff. Co. Surveyor's Office Date 5/76

REMARKS

Index File No.

T. 13S

R. 9E., W. M.

Tract or Surv. No.

Cor.

R-4

12

13


LAND CORNER RECORD

(Rectangular)

R-05 5680-2

1. T 13 S. R 9 E. No. R 5 Cor. Sec. Mer. W State Oregon N.F. Deschutes Dist. Metolius

2. Corner Status 19 20



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:
A stone with 3 notches on the East face.

7. Photo Identification 7-14-59
Photo No. EG1-51-127
Ident. By: O. HINGVALL
6-18-62

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation 11/20/64
Authentic 30%
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____

5. Investigation Notes:
A ponderosa pine, 15 inches diam., bears S. 21° E., 15.3 ft. dist., marked T. 13 S., R. 9 E., S. 29.

A ponderosa pine, 30 inches diam., bears S. 76° W., 13.3 ft. dist., marked T. 13 S., R. 9 E., S. 30, B. T.

A ponderosa pine, 26 inches diam., bears N. 27° W., 51.5 ft. dist., marked T. 13 S., R. 9 E., S. 19.

A ponderosa pine, 27 inches diam., bears N. 11° E., 22.6 ft. dist., marked T. 13 S., R. 9 E., S. 20, B. T. This tree is down.

The distances check with photo copies of General Land Office field notes. The bearings differ greatly.

Brass Cap 18" Pine N42E 128 1/2 ft
10" WFT 57 1/4 W 48 1/2 ft
Pine Old One

6. Signed Calvin W. Hinkle Title Forestry Aid Date 11/10/64

50

R-5

LAND CORNER RECORD


(Rectangular)

R07 5680-2

1. T 13 S. R 9 E. No. R-7 Cor. 1/4 Mer. W State Oregon N.F. Deschutes Dist. Metolius

2. Corner Status

20



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 7 x 7 x 7 inches, set in ground, marked 1/4 on North face.

5. Investigation Notes:

A ponderosa pine, 15 inches diam., bears S. 57° W., 39.6 ft. dist., marked 1/4 S. This tree is down.

The bearing and distance check with transcript of General Land Office field notes.

7. Photo Identification 7-14-59

Photo No. EG1-51-68

Ident. By: O. THURMAN
6-22-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation 11/20/60

Authentic yes

Needs Verif. _____ Monument x

Re-estab. _____ Survey _____

Land Status _____

Brass Cap

11" D. Fir S 13 3/4 E 163 1/2 lks

6" D. Fir N 17 173 lks

Plus Old Dues

6. Signed Calvin W. Minkes Title Forestry Aid Date 11/9/60

LAND CORNER RECORD


(Rectangular)

5680-2

R-9

1. T. 13 S. R. 9 E. No. R-9 CorSec. Mer. W State Oregon N.E. Deschutes Dist. Metolius

2. Corner Status 20 21



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:
A rock monument with no visible chisel marks on any stone.

5. Investigation Notes:

A ponderosa pine, 27 inches diam., bears S. 59° E., 43 ft.
dist., marked T. 13 S., R. 9 E., S. 28.

A ponderosa pine, 24 inches diam., bears N. 32° E., 11.5 ft.
dist., marked T. 13 S., R. 9 E., S. 21.

A ponderosa pine, 19 inches diam., bears N. 67° W., 25.2 ft.
dist., marked T. 13 S., R. 9 E.

A ponderosa pine, 26 inches diam., bears S. 11° W., 42.8 ft.
dist., marked T. 13 S., R. 9 E., S. 29.

The distances in the General Land Office photo copies overlap
2 to 4 ft. The bearings are as much as 40° off.

Biase Cap
Old Ones Still Good

See back

7. Photo Identification 7-14-59

Photo No. EG-1-51-68

Ident. By: O. THINGVALL
6-22-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation *11/9/60*

Authentic yes

Needs Verif. _____ Monument ☒

Re-estab. _____ Survey _____

Land Status _____

6. Signed Calvin W. Minko Title Forestry Aid Date 11/9/60

Reported 1952 Brass Cap - Four L.T.s in good condition.

Index
File No. 1167

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. _____Cor.
No. R-11T 13 S R. 9 ER.D. SISTERS County Jefferson

Merid. _____

N.F. Deschutes State Oregon

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

One old bearing tree stump 4' high.
Very poor condition posted as by Surveyor
in 1940
One location tree.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

1972 7100-52 (3/68)

D-5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

This information turned in by Sisters Dist. 1972

So?

12

Index File No. *1167* T. *135.* R. *9E.* M. Tract or Surv. No. Cor. *R-11* 13

Index
File No. 1367

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. R-13T 13S R. 9ER.D. SISTERSCounty JEFFERSON

SEC. COR.

Merid. WILLN.F. DESCHUTESState OREGON

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER MONUMENT FOUND

STONE 6 x 8 x 3" HIGH

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 48" P. PINE NW 50 FT. MKD. "T13S R9E S21 BT"

A 26" P. PINE SW 50 FT. MKD. "T13S R9E S22" ~~BT~~

A 28" P. PINE NE 30 FT. MKD. "T13S R9E S28"

A 22" DOWN P. PINE SE 20 FT. MKD. "T13S R9E S29" BEARING FACE UP

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON 40" P. PINE ON E. SIDE
OF BT FOR SEC. 28, FROM WHICH CORNER BEARS
NE 50 FT.

Signature

M.A. PALMER

Title

A.A.A.

Division

Headquarters

Date


10-31-40

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 1367 T. 13 S. R. 9E M.

Tract or Surv. No.

Cor. R-13


Index
File No. 1567

CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Contract or Survey No. _____ Cor. No. R-15

T 13 S. R. 9 E. R.D. Sisters County Jefferson S/4 Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 22

CORNER DIAGRAM per legend

DIRT ROAD



DESCRIBE CORNER MONUMENT FOUND

3 1/4" BLM BC

RSG.6"

Stone 17 x 12 x 8 lying N. of cap

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

7" Fir, N58°W, 9 lks, blazes healed

8" Fir, S55°E, 49 1/2 lks, blazes healed

6 19" P. Pine, (Orig) scribed 1/4 S, toeblaze healed S37°E, 69 lks

NW orig. tree dead and down and shoved downhill by cat.

Set attn. signs on standing BT's

3

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Take Rd #134 N to junct. of Rd. #134E, take left, proceed

1.6 mi. to junct. of Spur Road 15, take left, proceed 0.4 mi.

to junct. of Spur #10, take right, proceeds 1.5 mi. Stop. Set

location take on Road stating cor. lies 130' south of road.

VIS. 1985 - F. ASTON OK

4

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

Searched By: R. Taylor
MH-GS

Title ST Division CS Headquarters SQ Date 5/17/83


5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BLM: Set $2\frac{1}{2}$ " x 28" BCSP RS6.4"

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BLM: 6"W. Fr. N58 $\frac{1}{2}$ W, 9L (5.94)

6" Fir., S55 $^{\circ}$ E, 49 $\frac{1}{2}$ (32.67)

Work Done By. BLM Title _____ Date 1966 State Registration No. _____
or Agency _____

Plat or _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History 1881: Trap stone 16 x 12 x 8 $\frac{1}{2}$ 11" in Grd. BLM 1966

of Mk'd. $\frac{1}{4}$ on N. Face

Surveys, 26"P., N62W, 24L (15.84) Root/hole/log

G.L.O., etc. 18"P., S37E, 69L (45.54) 20"P

Index File No. 1567 T. 13 S., R. 9 E., W.M.

Contract or Surv. No.

Cor. R-15

Index

File No. 1767

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No.

Cor.

No. R-17T 13S R. 9ER.D. SISTERS County JEFFERSON SEC. COR.Merid. WILL.N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE 8" x 8" x 10" HIGH IN GOOD CONDITION

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 22" P.PINE SE 7 FT. MKD. "T13S R9E S26 BT"

A 26" P.PINE S 15 FT. MKD. "T13S R9E S27 BT"

A 16" P.PINE W 18 FT. MKD. "S22"

A 20" P.PINE NE 42 FT. MKD. "S23"

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

M.A. PALMER

Title

A.A.A.

Division

Headquarters

Date


10-29-40

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 1767 T. 135. R. 9 E. M.

Tract or Surv. No.

Cor. R-17

12
13

Index
File No. 1967


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. R-19

T 13S R. 9E R.D. SISTERS County JEFFERSON 1/4 COR.
Merid. WILL. N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

A STONE 6 x 5 x 4" HIGH

MKD. "1/4" ON N. FACE

"1/4" WELL DEFINED

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 14" P. PINE NW 15 FT. MKD. "1/4 BT"

A 22" P. PINE SE 25 FT. HEALED OVER

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON 6" P. PINE ON SE
SIDE OF BT FROM WHKH CORNER BEARS SE 15 FT.

Signature

M. A. PALMER

Title

A. A. A.

Division

Headquarters

Date


10-1-40

7100-52 (3 69)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 1967 T. 133. R. 9 E. M.


Tract or Survey No.

R-19₁₂

2167
 1. T. 135, R. 9E, No. 21 Cor. Sec. Mer. Will State Oregon N. F. Deschutes Dist. Matolius
 (Rectangular)

2. Corner Status

3. Original Description Vol. Page Where Recorded



4. Description of Corners: 1881 --- Set a trachyte stone 16x12x6 in., 11 ins. in the ground --- 1 notch on E. and 2 notches on S. edges; --- see #14

7. Photo Identification 7-14-59
 Photo No. EG1-51-181
 Ident. By: Direct

5. Investigation Notes: Broken stone 14x12x6 ins, 4 ins. above ground in fair condition - 4 notches on N. face. A 29" P. Pine marked. T135, R9E, S.; Bears S45°E, 23°'; a 43" P. Pine, markings visible 1-S, bears N21°E, 63°'; a 26" P. Pine, stump 4' high, has markings of S2-, bears S82°W, 13°'; and NW B.T. is downed snag.

8. Plane Coordinate Position Data
 State Zone
 X
 Y
 Estab. By
 Field Book No.
 Where Filed

Leave Santiam Hwy at Indian Ford taking Rd 139.2 then take Rd #1339 to the left as if going to Head of Matolius. Drive past sec. line marker between secs 24 & 25 and turn left on spur rd. before you get to power line. Drive up spur rd. to clearing where spur rd. forks. Cor. is just over two big logs about 100'.

9. Evaluation
 Authentic
 Needs Verif. Monument
 Re-estab. Survey
 Land Status

6. Signed O. Tringali Title Hwy. Eng. Date 6-12-62

R-21

PERPETUATION RECORD

R-21

10. Monument:

BRASS COP

11. Accessories

7" D Pin S 61 1/2° E 13 LBS
 8" D Pin N 49 1/8° W 9 LBS
 5" D Pin S 53° W 16 LBS
 7" D Pin N 56° E 42 LBS
 Plus old ones

Field Book _____ Page _____

12. Set By _____ Title _____
 License _____ Agency BLM Date _____

13. Recorded By _____ Volume _____ Page _____
 (Agency)
 (Date) (City) (County) (State)

14. Remarks: ④ A pine, 30 ins. diam., bears N 20° E., 96 lks dist., mkd T135, R9E, S24, 8-T.
 " " 12 " " " S 53° E, 36 " " " " S 25 "
 " " 10 " " " S 85° W, 21 " " " " S 26 "
 " " 30 " " " N 58° W, 151 " " " " S 23 "

2167 T135 R9E

LAND CORNER RECORD

(Rectangular)

R-23


5680-2

T 135, R 9E No. 23 Cor.

1/4 Mer. Will State Oregon

N.F. Daschutes Dist. Matolius

2. Corner Status



7. Photo Identification 7-14-59

Photo No. EG1-52-61

Ident. By: O. THINGVALL

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 1881 - Set a basalt stone, 20x18x4 in., 15 ins. in the ground --- mkd. 1/4 on N-face; see #14

5. Investigation Notes: Found stone 20"x18"x4" --- 10" above ground in good condition; marked 1/4 on N-face. A 26" P. Pine bears S78°E, 27' dist., mkd 1/4. A 32" P. Pine bears N26°W, 13' dist., mks. are not legible. About 200' N. of Rd. junction to Rds 139 & 1339, a spur rd. goes NE. (or right). Take this road for 0.25 mi and cor is on the right about 60'.

6. Signed O. Thingvall Title HWY. ENG. Date 6-14-62

PERPETUATION RECORD

R-23

10. Monument:

Grass Cap

11. Accessories

10" D. Pin N 48 1/2° W 97 Lbs

7" P. Pin S 31° E 1 lb 1/2 Lb

Plus 16 pins

Field Book _____ Page _____

12. Set By _____ Title _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____

License _____ Agency _____ Date _____

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks: (A) A pine, 24 ins. in diam. bears N 28° W, 20 lbs. dist., mtd. 1/4 SBT.
" " 20 " " " " 578° E, 42 " " " "

R-23

Index

File No. 2567

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. R-25

T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON
Merid. WILLAMETTE N.F. DESCHUTES State OREGON

SEE T13S R10E

R-1

Brass Cap

Index
File No. 1568

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. S-5T 135 R. 9E

R.D. _____

County

DeschutesMerid. WillN.F. Deschutes

State

Oregon

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



no original BT's or post found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2"x30" pipe & cap, 5" above ground.

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's 1. 13" Fir N 56°W 41°4'
2. 7" P. Pine N 37°E 27°58'

10

Work Done By BR Title CS LS 706 Date 1/10/77 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. 0568 T. 135 R. 9E M.

Tract or Surv. No.

Cor. S-5 13

Index
File No. 0668

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. S-6T 13S R. 9E

R.D. _____

County JeffersonMerid. WillN.F. DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

No original BT's or Post found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2"x30" pipe & cap, 5" above the Ground.

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's 1. 7" fir bears N 89° E 54' 43"
2. 15" fir bears S 28° W 44' 85"

10

Work Done By. B.R. Title GS. L.S. 706 Date 1/77 State Registration No. or Agency

Certified Cor. Record Prepared? Yes No Filed At: Date

11

REMARKS

12


Index File No. 0668 T. 135. R. 9 E. M.

Tract or Surv. No.

Cor. S-6 13

Index
File No. 0169 CORNER RECORD (SEARCH) Tract or
Survey No. T-1
T 13S. R. 9E. R.D. Sisters County Jefferson
Merid. Will N.F. Deschutes State Oregon
1/4 cor

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SEE: T-25, T13S, R8E, WM

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

Reported 1972 - Brass Cap - 2 B.T.s

REMARKS

Index File No. *0169* T. *135* R. *9E* M.

Tract or Surv. No.

Cor,


T-1

12

13

1. T 13 S. R 9 E. No. T 5 Cor. 1/4 Mer. W State Oregon N.F. Deschutes Dist. Metolius

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where recorded _____

4. Description of Corner:

According to General Land Office field notes, this 1/4 cor. was a 6 inch tree. The tree is no longer here. I dug away topsoil and found bits of decayed bark and roots. I placed a stone over these bits.

5. Investigation Notes:

A ponderosa pine, 21 inches diam., bears S. 37° W., 6.2 ft., marked 1/4 S.

A ponderosa pine, 15 inches diam., bears N. 3° E., 10.5 ft. dist., marked 1/4. This tree is down.

7. PHOTO IDENTIFICATION

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Est. By _____

Field Book No. _____

Where Filed _____

9. EVALUATION

11/20/00 Hein

Authentic ☒ Yes

Needs Verif. _____ Manum. ☒

Re-Est. _____ Survey _____

Land Status _____

Brass Cap

25" P. Pine N9E 36 1/2 S


17" P. Pine S27W 29 1/2 N S

Plus Old Dues

6. Signed Calvin W. Mink Title Forestry Aid Date 11/10/60

Index
File No. 0669CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)Tract or
Survey No. _____ Cor.
No. T-6T 13S R. 9E R.D. _____ County Jefferson
Merid. Will N.F. Deschutes State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

no original BTs or Post found

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Etab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2"x30" pipe & cap, 5" above the Ground.

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's 1. 13" Fir Bears N48°E 41°2'
2. 15" Fir Bears S72°E 91°1'

10

Work Done By. BR Title C-S LS 706 Date 1/12/77 State Registration No. or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Date

11

REMARKS

12

Index File No. 0669 T. 135 R. 9E M. Tract or Surv. No. Cor. T-6

13

Index
File No. 0769

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. T-7T 13S R. 9E

R.D. _____

County JeffersonMerid. WillN.F. DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

no original BT's or Post Found
crusiers Tag about 110' East

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2½'x30' pipe & cap, 5' above the ground.

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's 1. 8" fir bears N26°W 18⁶⁰'
2. 4" P. Pine bears N45°E 13³¹'

Work Done By. B.R. Title C-S L.S. 706 Date 1/5/77 State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 0769 T. 135. R. 9E. M.

Tract or Surv. No.

Cor. T-7

Index

File No. 0869

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. _____

Cor.

No. T-8T 13 S R. 9 ER.D. Sisters County JeffersonMerid. Will. N.F. Deschutes State Oregon

CORNER DIAGRAM



(over)

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

one location tree
1/16TH Corner.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters


Date

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2"x30" pipe & cap, 5" above the ground,
marked as:



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's A 5" Fir Bears N 40° W 11 72'
A 7" Fir Bears N 78° E 52 65'

10

Work Done By. BR Title CS L.S. 706 Date 1/12/77 State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

This information
Turned in by Sisters
Dist. 1972
Copied and filed as turned in
By H.M. Van Horn 12-19-72

12

Index File No. 0869 T. 135 R. 9E M.

Tract or Surv. No.

Cor. T-8 13

0969

LAND CORNER RECORD
(Rectangular)

7-09 5680-L

1. T13 S. R 9 E. No. T-9 Cor. 1/4 Mer. W State Oregon N.F. Deschutes Dist. Metolius

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 10 x 10 x 12 inches, set in ground, marked 1/4 on West face.

5. Investigation Notes:

A ponderosa pine, 24 inches diam., bears S. 38° E., 43.6 ft. dist., marked 1/4 S.

A ponderosa pine, 30 inches diam., bears N. 59° W., 63 ft. dist. Blaze charred by fire. Tree was cut by logging.

The distances check with photo copies of General Land Office field notes but the bearings have changed.

Brass Cap

32" P. Pine 569W 941Ks

Plus Old Ones

over

7. Photo Identification 7-14-59

Photo No. 561-51-69Ident. By: O. HINGVAHL
6-18-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic yes

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed Calvin Whimke Title Forestry Aid Date 11/9/60

6-L

Reported 1972 - Brasscap - 2 B.T.s
Good location trees condition.

LAND CORNER RECORD
(Rectangular)

5680-2

2169 T21
1. T 135 R 9E No. 721 Cor. 1/4 Mer. Will State Oregon N.F. Deschutes Dist. Matolius

2. Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 1881 --- Set a basalt stone 12"x10"x10",
8 ins. in the ground --- mtd. 1/4 on W. face --- see #14


5. Investigation Notes: No evidence of a cor., but found the
S.E. B.T. --- a down snag in poor condition marked
1/4 S & B.T. Suggest resurvey
From junction of Rds 139.2 & 1318; it is approx.
0.8 mi to sec. line marker on Rd #1318 --- between 25 & 26.
Cor is 104' North.

6. Signed O. Inguval Title Hwy. Eng. Date 6-14-62

7. Photo Identification 7-14-59
Photo No. EGL-52-61
Ident. By: O. Inguval

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Etab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____



10. Monument: BRASS CAP

11. Accessories

8" P.F.M. S $23\frac{1}{2}^{\circ}$ E 47 LKS

5" P.F.M. N 45° W 58 LKS

plus old ones

Field Book _____ Page _____

12. Set By _____ Title _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____

(License _____ Agency BLM Date _____)

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks: ④ A pine, 24 ins. in diam., bears N 47° W, 53 lks. dist., mkd. 145BT
 " " " " " " " S 15° E, 54 " " " " "

2169 T135 R9E

T-21

Index
File No. ~~725~~ 2569

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. T-25T 13 S R. 9 E R.D. SISTERS County JEFFERSONMerid. WILLAMETTE N.F. DESCHUTES State OREGON

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

NOTHING



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NOTHING

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

± 500' South of yellow Posters Along F.S. Rd. 1139

Signature

Title

Division

Headquarters


Date

7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 SET 2" X 32" BRASS-CAPPED GALVANIZED STEEL PIPE RISING
 6" ABOVE GROUND IN A MOUND OF STONES, STAMPED
 AS SHOWN:



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 14" P. PINE BEARS S81°W 44.9 FT., BLAZED & SCRIBED "S25 1/4 BT"

A 9" P. PINE BEARS N76°E 67.0 FT., BLAZED & SCRIBED "S30 1/4 BT"

10

Work Done By R.E. OMAN Title P.L.S. Date 11 July 75 State Registration No. OK-702 & WV-23
 or Agency

Certified Cor. Record Prepared? ☒ (Yes) No Filed At: JEFFERSON COUNTY Date

11

REMARKS

SET BY TRAVERSE BETWEEN THE NW and SW CORNERS of SEC. 30;
 S00°11'06"E 5243.40 FT.; SEMI-DIST. = 2621.70 FT.

12

Index File No. 2569 T. 13 S. R. 9 E. M. Willamette Tract or Surv. No.

Cor. T-25 13

Index
File No. 171


CORNER RECORD (SEARCH)

Tract or
Survey No. _____
Cor.
No. V-1

T 13S., R. 9E., R.D. Sisters County Jefferson

Merid. Will N.F. Deschutes State Oregon Sec cor

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: V-25, T13S, R8E, WM

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

*Reported 1972 - Brass Cap - 6 B.T.s - 4 Recently located - 2 old B.T.s
in poor condition*

12

Index File No. *0171* T. *135* R. *96* M.

Tract or Surv. No.

Cor. *V-1* 13

Index
File No. 371

CORNER RECORD (SEARCH)

Tract or
Survey No. _____

Cor.
No. V-3

T 13S. R. 9E.

R.D. SISTERS County JEFFERSON

1/4 Cor

Merid. Will

N.F. DESCHUTES State OREGON

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

Found stone 12"x10"x8", 35° N 34° W from B.T., but believe it isn't original stone

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

BT 38" P. Pine miked 1/4 S

PHOTO IDENTIFICATION DATA

Photo No. EG1-51-16

Filed At. Sisters

Object Ident. Cor

Ident. By O.T.

Signature

6

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Near culvert marker 0-8 on Rd #1315-C a sec line marker states sec cor is 1610' W --- then the 1/4 cor is about 600' E from marker

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

O. THINKVALL

Title

Hwy Eng

Division

Headquarters

Date

6-13-62

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

13" Fir S 35 1/2° W 14 1/2 lks

6" Fir N 52 1/2° W 48 lks

plus old ones

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Reported in 1972 - Brass Cap - 2 B.T.s

Index File No. 0371 T. 135. R. 9E. M.

Tract or Surv. No.

Cor. V-3

Index
File No. 10571

CORNER RECORD (SEARCH)

Tract or
Survey No. _____

Cor.
No. V-5

T 13S, R 9E,

R.D. SISTERS

County JEFFERSON

SEC COR

Merid. Will

N.F. DESCHUTES

State OREGON

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

Found stone 12x10x8 with 5 notches on S. face; 1 on E. face
(Cor. has been disturbed)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 32" P.P., S28°W, 13' - blazes not open
A 34" P.P., N26°W, 24' - Blaze but no markings

PHOTO IDENTIFICATION DATA

Photo No. EG1-51-16

Filed At. Sisters

Object Ident. Cor

Ident. By D.T.

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Title

Division

Headquarters

Date

7100-52

4

O. THINGVALL

HWH/ENG

6-7-62

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Brass Cap

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

4" P.P. N14°W 631ks

13 P.P. N66½°E 741ks

7" P.P. S42°E 62½1ks

Plus old ones

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Reported in 1972 - Brass Cap - 5 B.T.s

12

Index File No. 0571 T. 13S. R. 9E. M.

Tract or Surv. No.

Cor. V-5 13

LAND CORNER RECORD

(Rectangular)

V-7

5680-2

1. T 13 S. R 9 E. No. V-7 Cor. 1/4 Mer. W State Oregon N.F. Deschutes Dist. Metolius

2. Corner Station 29



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 6 x 10 x 8 inches, set in ground, marked 1/4 on North face.

5. Investigation Notes:

A ponderosa pine, 29 inches diam., bears S. 48° W., 38.5 ft. dist., marked 1/4 S., B. T.

A ponderosa pine, 30 inches diam., bears N. 47° E., 70 ft. dist., marked 1/4 S., B. T. This tree is down.

These bearings and distances check with transcript of General Land Office field notes.

Brass Cap

6" P. Pine N 39 1/2° E 45 1/2 lks
16" P. Pine S 47° E 69 lks

Plus Old Ones

over.

7. Photo Identification 7-14-54

Photo No. EG1-50-69

Ident. By: O. THINGYALL
6-7-62

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

11/20/60

Authentic yes

Needs Verif. _____ Monument ☒

Re-estab. _____ Survey _____

Land Status _____

6. Signed Calvin W. Minter Title Forestry Aid Date 11/9/60

L-V

Reported in 1972 - Brass Cap - 3 BTs
1 Location free } Good condition.

Index

File No. 18 0891

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No. _____

Cor.

No. V-8T 13 S R. 9 ER.D. Sisters County JeffersonMerid. WillN.F. Deschutes State Oregon

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

N
↑

(over)

no original evidence found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

one location Tree surveyed 1961
1/16 corner located west of tree.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency

Signature

Title

Division

Headquarters


Date

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2½"x30" pipe & cap, 5" above ground.



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's 1. 9" P. Pine Bears N 16°E 78³⁶'
2. 13" P. Pine Bears S 64°E 117³⁰'

10

Work Done By. BR Title CS LS. 706 Date 1/4/77 State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Turned in by Sisters Dist. 1972 Copied and posted by
H M Van Horn 12-19-72

12

Index File No. 0871 T. 135. R. 9E. M. _____ Tract or Surv. No. _____ Cor. V-8

13

LAND CORNER RECORD
(Rectangular)

5680-2

V-9

0971

1. T. 13 S. R. 9 E. No. V 9 Cor. Sec. Mer. W State Oregon N. E. Deschutes Dist. Metolius

2. Corner Status 29 28



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

A stone, 13 x 20 x 4 inches, set in ground, with 3 notches on East side.

5. Investigation Notes:

A ponderosa pine, 35 inches diam., bears N. 55° E., 12.5 ft. dist., marked T. 13 S., R. 9 E., S. 28.

A ponderosa pine, 35 inches diam., bears N. 33° W., 14.4 ft. dist., marked T. 13 S., R. 9 E., S. 29.

A ponderosa pine, 26 inches diam., bears S. 43° W., 32.6 ft. dist., marked T. 13 S., R. 9 E., S. 32.

A ponderosa pine, 22 inches diam., bears S. 10° E., 53.5 ft. dist., marked T. 13 S., R. 9 E., S. 33, B. T. This tree is down.

The distances check with photo copies of General Land Office field notes but the bearings have changed.

Brass Cap 5" P. Pine 538 1/2 E 701 Ks
Plus Old Ones

OVER

7. Photo Identification 7-14-59

Photo No. EG1-51-69

Ident. By: O. THINGVAHL
6-11-67

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic yes

Needs Verif. _____ Monument ✓

Re-estab. _____ Survey _____

Land Status _____

6. Signed Calvin W. Minkes Title Forestry Aid Date 11/9/60

Reported in 1972 - Brass Cap - 3 old B.T.s } Good
1 Young Pine BT } Condition.

Index
File No. 1171

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. V-11T 13S R. 9ER.D. SISTERS County JEFFERSON 1/4 COR.Merid. WILL.N.F. DESCHUTES State OREGON

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

STONE WITH IRON MARKS FOUND28

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A P. PINE BEARS SW MKD. "4S" BT SECTION NOT
OPENED33

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency _____

Signature

M.A. PALMER

Title

A.A.A.

Division

Headquarters

Date


10-29-40

7100-52 (3 63)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. 1171 T. 135. R. 9E. M.

Tract or Surv. No.

Cor. V-11

12

13


Index
File No. V-17 1771

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. V-17T 13 S R. 9ER.D. Sisters County JeffersonMerid. WillN.F. Deschutes State Ore.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE 10 X 8 X 6

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

36" D.F. S21° W 23± FT. ~ NOT OPENED, "13T"

16" PINE, DEAD N 88° E 23 FT. VIS: T135 R9E 26 BT

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

LOC. TAG ON 8" W.F. BRG. N46° E 5'

LOC. TAG ALONG ROAD 1318A ON LINE TREE BETW. SEC. 26 / 27

173 CH. FROM CORNER

Signature C.M. LAING Title E.A. Division D-4 HeadquartersHM Van Name Eng TechS.O.Date 10/59 7100-52 (3/68)2/16/73

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. 1771 T. 135 R. 9E M. Tract or Surv. No. Cor. V-17 13

Index
File No. 2171

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. V-21

T 13S R. 9E R.D. SISTERS County JEFFERSON SEC. COR.

Merid. _____ N.F. _____ State _____

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER MONUMENT FOUND

STONE 10 x 10 x 6" HIGH IN PLACE
MKD. WITH 2 NOTCHES ON N. FACE, ONE NOTCH
ON E. FACE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 28" P. PINE NE 28 FT. MKD. "T13S R9E S25 BT"
A 26" P. PINE SW 18 FT. MKD. "T13S R9E S35 BT"
A 16" P. PINE SE 20 FT. MKD. "T13S R9E S36 BT"

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

METAL LOCATION POSTER ON 24" P. PINE ON W. SIDE
OF B.T. CORNER BEARS NE 18 FT.

Signature

M.A. PALMER

Title

AAA.

Division

Headquarters

Date


10-1-40

7100-52 (3 60)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. 2171 T. 13S. R. 9E. M. Tract or Surv. No. Cor. V-21

12

13

LAND CORNER RECORD

(Rectangular)

V-23

5680-2


2371
1. T 135 R 9E No. 425 Cor.

1/4 Mer. Will State Oregon N.F. Daschutes Dist. Malheur

2. Corner Status

3. Original Description Vol. Page Where Recorded

4. Description of Corners: 1881 --- Sat a basalt stone 14 x 10 x 8 ins.,
10 ins. in the ground --- mkd. 1/4 on N. face --- see #14



5. Investigation Notes: Found stone 12 x 12 x 8 ins --- 4 ins above
ground in poor condition. Couldn't see any markings
as a "cat" had done some work in area and stone
is broken. A 28" P. Pine marked 1/4 S, BT, S22°E,
214 ft. And 28" P. Pine marked 1/4 S (in fire scar)
bears N30°W, 162'

The sec. line to secs 25 & 26 crosses Rd #139.2
near junction with Rd #1318 (about 100'S); the cor.
is approx 750' W. of Rd #139.2

Brass Cap

6" D. Fir N 1/2 W 79 1/2 1/4 S

11" P. Pine S47W 71 1/4 S Plus Old Ones

6. Signed O. Thingvall Title HWK. ENG. Date 6-14-62

7. Photo Identification 7-14-54

Photo No. EG-1-52-60

Ident. By: O. THINGVALL

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

Index
File No. 2571

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. Cor. No. V-25

T 13 S. R. 9 E. R.D. SISTERS County JEFFERSON
Merid. WILLAMETTE N.F. DESCHUTES State OREGON

SEE T13S R10E

V-1

B.C.

Index
File No. X-1 0123

CORNER RECORD (SEARCH)

Tract or
Survey No. _____

Cor.
No. X-1

T 13S. R. 9E.

R.D. SISTERS

County JEFFERSON


1/4 COR

Merid. Will

N.F. DESCHUTES

State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: X-25, T13S, R8E, WM

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. 0173 T. 135. R. 9E. M. _____ Tract or Surv. No. _____ Cor. X-1

13

USDA-FOREST SERVICE

Index

File No. 0573

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4) (Contract Survey No. 9-02208N)

Cor.

No. 11T 13 S. R. 9 E.R.D. SistersCounty Deschutes JeffersonV₄ CornerMerid. WILLAMETTEN.F. DESCHUTESState OREGON

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

3 1/2" Brass Cap on Galv. steel pipe

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 36" Ponderosa bears N 33° E @ 22' Partially Healed
A 9" " " S 80° W @ 20' Healed
A 24" " " N 71° E @ 125' Partially Healed
Guard Post with Property boundary sign 3' ± North

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From intersection of roads #1325 & 1375B, Corner
lies 0.1 miles East along road #1375B, then
2250' North along posted line.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature G.W. Colvin, Jr.Title #1020

Division

Headquarters

Date 11/59


D-7100-52 (10/70)

X-05

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Posted line from S.E. Cor S. 31 to Corner



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Posted line from SE Corner Sec. 31 to Corner

Work Done By GWC Title PLS Date 11-15 State Registration No. 1020
or Agency

Certified Cor. Record Prepared? Yes ☐ No ☒ Filed At: _____ Date _____

O. Thingvall, Hwy Eng 6-7-62 REMARKS

A 42" P.P. marked $\frac{1}{4}$ s SW BT would have been in Road.

Index File No. 0573 T. 13 S., R. 9 E., W.M.

Tract or Surv. No. 31

Cor. E $\frac{1}{4}$

X-05

Index

File No. ~~759~~ 0973

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. X-9T 13 S R. 9 ER.D. SistersCounty Jeff.

Merid. _____

N.F. Des.State Oregon.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None found in middle of road

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

One bearing tree in good condition

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Turned in by Sister Dist. 1972
Copied by H.W.H. 12-19-73

12

Index File No. 0973 T. 135. R. 9E. M.


Tract or Surv. No.

Cor. X-9

13

File No. 2173 CORNER RECORD (SEARCH) Tract or Cor.
(Ref. FSM 7151.4) Survey No. No. X-21
T 13S R. 9E R.D. SISTERS County JEFFERSON 1/4 COR.
Merid. WILL. N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

10 X 10 X 8" STONE SET IN PLACE IN GRD

SIX NOTCHES ON S. FACE, ONE NOTCH ON E. FACE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 22" P.PINE N 30° E 29 FT. MKD. "T13S R9E S36 BT"

A 16" P.PINE N 66° W 38 FT. MKD. "T13S R9E S35 BT"
DEAD & STANDING

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3 53)

CHESTER M. BEIL


FORESTER, TMA

12-4-56

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 2173 T. 135. R. 9E. M. Tract or Surv. No. Cor. X-21

LAND CORNER RECORD

(Rectangular)

5680-2
X-25

1. T 13S R 9E No. X-25 Cor. ¼ Mer. WILL State OREGON N. F. DESCHUTES Dist. SISTERS

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: Set trapstone 16x12x10 ins. - 10 ins. in the ground for ¼ Sec. Cor. marked ¼ on W. face; from which A pine 24" dia. bears N 55°E, 58 lks dist. marked ¼SBT - A pine 18" dia. bears S 60°W, 28 lks. dist. marked ¼SBT.

5. Investigation Notes:

Material - stone 14" x 11" - 4" above ground - in good condition ¼ on East face.

PPine 13.2" dia. bears S 59°15' E, 13.6 ft. dist. marked ¼SBT
PPine stump bears N 53°E , 49.2 ft. dist. Blazed for B.T. markm, but rotted.

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed C. M. Long Title Survey Tech. Date 12-24-63

PERPETUATION RECORD

10. Monument: Brass Cap

11. Accessories 20" PPine S 80°E, 32 lks.
 20" PPine S 41°W, 38 lks.
 Plus old ones

12. Set By _____ Title _____		Field Book _____ Page _____	
License _____	Agency _____	Date _____	13. Recorded By _____ Volume _____ Page _____
			(Agency)
			(Date) (City) (County) (State)

14. Remarks:

Index
File No. 0175

CORNER RECORD (SEARCH)

Tract or
Survey No. _____

Cor.
No. Z-1

T 13S. R. 9E.

R.D. SISTERS

County JEFFERSON

SEC COR


Merid. Will

N.F. DESCHUTES

State OREGON

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



SEE: Z-25, T13S, R8E, WM
Brass Cap "BLM"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. 0175 T. 135 R. 9E M. _____ Tract or Surv. No. _____ Cor. 2-1 13

Index
File No. 0375

CORNER RECORD (SEARCH)

Tract or
Survey No. _____

Cor.
No. Z-3

T 13S., R 9E.

R.D. SISTERS

County JEFFERSON

S.E. 1/4 Cor Sec 31

Merid. Will


N.F. DESCHUTES

State OREGON

ONLY

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No evidence

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

Title

Division

Headquarters

Date

7100-52

OTHINGALL

Hwy Eng

6-5-62

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. 0375 T. 135. R. 9E. M.

Tract or Surv. No.

Cor. 2-3

12

13

USDA-FOREST SERVICE

Index

File No. 0575T 13 S. R. 9 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4) (Contract Survey No. 9-02208 N)

Cor.

No. 2-05R.D. SistersCounty JeffersonN.F. DESCHUTESState OREGON

CORNER DIAGRAM

7135 R9E



DESCRIBE CORNER MONUMENT FOUND

A 3" Brass Cap on Galvanized steel pipe, SET BY BCM —
Monument Found is 18' North of True Position of Corner.
Set Amended Corner (see opposite side)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 38" ponderosa brs. N 72° E 41.5'
Scribed marks visible on partially healed blaze.
A 43" ponderosa brs. N 25° W 60.0'
Scribe marks visible on partially healed blaze.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From intersection of roads # 1375 and 1375B,
Corner is 0.1 miles Easterly along # 1375B, then
50' North.

Signature G.W. Colvin, Jr.

Title

PLSO #1020

Division

Headquarters

Date

11/79


D-7100-52 (10/78)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" brass cap on Galvanized steel pipe
Set guard post w/signs 54-2 and 54-4
Posted lines North and East and West



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 4" ponderosa bears N 29° W 9.8' Scribed T135 R9E 531 BT

A 5" ponderosa bears N 4° E 15.7' Scribed T135 R9E 532 BT

Work Done By: GWC Title: PLS Date: 11-30-79 State Registration No. or Agency: 1020

Certified Cor. Record Prepared? Yes ☐ No ☐ Filed At: _____ Date: _____

REMARKS

O. THINGUHL:

FOUND ALUMINUM ROD SURROUNDED BY STONES - NOT ORIGINAL
CORNER & I BELIEVE IT IS ABOUT 10' TOO FAR NEW

Z-05

Index File No. 0575 T. 13 S., R. 9 E., W.M.

Tract or Surv. No. 31

Cor. SE


LAND CORNER RECORD

5680-2

(Rectangular)

1. T. 13S. R. 9E. N. 7-7 Cor. 1/4 Mer. Will State Oregon N. F. Deschutes Dist. Sisters 2-7

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 10-9-1870 Set stone 11x9x6 for $\frac{1}{4}$ sec. cor. ----
(marked $\frac{1}{4}$ on N. face 11-3-1881).

5. Investigation Notes: Found pile of stones - no B.T.'s.
Believe corner is an approximate corner as a yellow section corner tag by M. A. Palmer 11-2-40 has it as "Approx" with the "Approx" scratched out, and a B-S Inc. tag in 8-7-57.

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed O. Thingvall Title Hwy. Eng. Date 4-23-63

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

(Date)

(City)

(County)

(State)

14. Remarks: *Reported 1972 - No Monument - 2 B.Ts*

LAND CORNER RECORD

2-09 5680-2


0975

CC

(Rectangular)

1. T. 13S. R. 9E. No. 2-9 Cor. Sec. 32 Mer. Will. State Oregon N. F. Deschutes Dist. Metolius

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 11-3-1881 set a trapstone 16x14x9 ins. 11 ins. in ground for cor. to secs. 32 & 33 marked with 4 notches on E. and 2 notches on W. edges, from which a pine 22 ins. diam. bears N 48°E. 17 lks. dist. marked T. 13 S., R. 9 E., S. 33 B.T.
(see #14)

5. Investigation Notes:
Corner destroyed during construction of Santiam Highway.

7. Photo Identification

Photo No. _____
Ident. By: _____

*T.M. Miller 6/19/79 Civil Eng. LS 1508
Corner Falls near edge of U.S. 20. One tree
w/healed blaze; unlikely but could be opened.*

8. Plane Coordinate Position Data

State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation

Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____

6. Signed O. Tringali Title _____ Hwy. Eng. _____ Date 4-23-63

PERPETUATION RECORD

10. Monument:

11. Accessories

		Field Book	Page
12. Set By	Title	13. Recorded By	Volume
License	Agency	(Agency)	Page
Date		(Date)	(City)
		(County)	(State)

14. Remarks: (4) A pine 30 ins. diam. bears N. 40^O W. 41 lks. dist. marked T. 13 S.,
R. 9 E., S 32 B.T.

Index


File No. 0975A

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. Z-09 AT 13 S. R. 9 E.R.D. SistersCounty Deschutes~~_____~~ Sec. 32Merid. Wmt.N.F. DeschutesState Oregon~~SC~~ **SC**

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: 0951/A-09, T. 14 S., R. 9 E.

"Brass Cap"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters


Date

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By: _____ Title: _____ Date: _____ State Registration No. or Agency: _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date: _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor.

13

2-09A


LAND CORNER RECORD

(Rectangular)

2-25 5680-2

1. T. 13S R. 9E No. 7-25 Cor. SEC Mer. WILL State OREGON N. F. DESCHUTES Dist. SISTERS

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: The cor. to Townships 13 & 14 S., R 9 & 10 E. which is a trap rock 13x12x 5 ins., set in mound of stone marked with 6 notches on N & E edges; from which: A pine 28" dia. bears S 45°E, 11 lks dist. marked T14SR10E Sec. 6 BT; A pine 12" dia. bears S 50°W, 12 lks dist. marked T14SR9E Sec 1 BT

5. Investigation Notes:

Material - Stone 14" x 12" - height above ground 6 inches - condition good. 6 notches on South face and 6 notches on the E.

PP, 10" dia. bears S 60° 30'W, 12.4 ft. dist, marked T14SR9E Sec. 1 B

Position of stone is assumed

6. Signed _____ Title _____ Date _____

PERPETUATION RECORD

10. Monument:

Brass Cap

11. Accessories

15" PPine N42½°E 97 lks
 11" PPine N 08°W, 129 lks
 21" PPine, S 75°W, 49 lks
 4" PPine, S 22°E, 52 lks
 Plus old one

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
 (Agency)

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks: