

T 185 R 10E M W

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
C	+	6	+	+	+	5	+	+	+	4	+	+	+	3	+	+	+	2	+	+	+	+	1	+	+
D	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
E	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
F	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
G	+	7	+	+	+	8	+	+	+	9	+	+	+	+	+	+	+	11	+	+	+	12	+	+	+
H	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
J	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
K	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
L	+	18	+	+	+	17	+	+	+	16	+	+	+	15	+	+	+	14	+	+	+	13	+	+	+
M	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
N	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
O	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
P	+	19	+	+	+	20	+	+	+	21	+	+	+	22	+	+	+	23	+	+	+	24	+	+	+
Q	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
R	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
S	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
T	+	30	+	+	+	29	+	+	+	28	+	+	+	27	+	+	+	26	+	+	+	25	+	+	+
U	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
V	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
W	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
X	+	31	+	+	+	32	+	+	+	33	+	+	+	34	+	+	+	35	+	+	+	36	+	+	+
Y	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
Z	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+

LEGEND

○ = Corner having information on form 7100-52 in this file.

Legend conforms to

Reporting forms NPMFC 11/79

TR 0103 IN BACK

FILING INSTRUCTION

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.

USDA-FOREST SERVICE

Index

File No. 0151

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. 02211N

Cor.

No. A-1T 18S R. 10ER.D. Bend County DeschutesMerid. WillametteN.F. Deschutes State OregonSE Cor Sec 36NW Cor Sec 6

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Original called - for post not found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found one original bearing tree dead & down (stump still in place) N 32° E 5.3'

Scribed "R10E, S 31"

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is approx. 12 miles west of Bend, Ore.

Near F.S. Road No. 1722. - Now Rd 4601 W 1-17-92

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

Surveyor

S.C.E & S.

Bend

8/21/80

5

T
CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 $\frac{1}{2}$ " X 30" Alum. pipe & 2 $\frac{1}{2}$ " alum. cap marked:
No stone available for mound
Cap rises 4" above ground

T17S
R9E T17S R10E
S36 S31
S1 S6
T18S
PLS 1642
1980

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed 4 new bearing trees:

A 10" L.P. Pine bears N 55° E 21.6' Scribed: "T 17 S, R 10 E, S 31 BT"
A 12" L.P. Pine bears S 38° E 60.3' Scribed: "T 18 S, R 10 E, S 6 BT"
A 8" Mtn Hemlock bears S 35° W 25.4' Scribed: "T 18 S, R 9 E, S 1 BT"
A 11" L.P. Pine bears N 14° W 14.5' Scribed: "T 17 S, R 9 E, S 36 BT"

10

Work Done By Robt. M. Karl Title Land Surveyor Date 7/15/80 State Registration No. 1642
or Agency

Certified Cor. Record Prepared? Yes ☒ No ☐

Filed At:

Date

11

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REMARKS

OREGON
JULY 14, 1978
ROBERT M. KARL
1642

Index File No. 0151

T.

18° R.

10° M.

Tract or Surv. No.

Cor.

U.S. G.P.O. 1977-725-576/586

A-01/12
13

USDA-FOREST SERVICE

Index

File No.

0351

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

02211N

Cor.

No.

A-3

T 18S R 10E

R.D. Bend

County

Deschutes

Merid. Willamette

N.F. Deschutes


State

Oregon

N/4 Cor Sec 6
S/4 Cor Sec 31

CORNER DIAGRAM

T 17S R 10E



DESCRIBE CORNER MONUMENT FOUND

Searched for, not found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Searched for, not found.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

Land Surveyor

SCE&S

Bend

9-17-80

7100-52 (3.68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By Robert M. Karl Title Land Surveyor Date _____ State Registration No. 1642
or Agency _____

Certified Cor. Record Prepared ? Yes ☒ No ☐ Filed At _____ Date _____

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REMARKS

OREGON
JULY 14, 1978
ROBERT M. KARL

Index File No. 0351 Tract or Surv. No. 18⁵R. 10⁶M. Cor. A-23

USDA-FOREST SERVICE

Index

File No. 0551

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

02211 N

Cor.

No. A-5T 18 S. R. 10 E.R.D. Bend

County

DeschutesMerid. WillametteN.F. Deschutes

State

OregonNE CN Sec 6SW CN Sec 32

CORNER DIAGRAM

T17S R10E

S31 S32

S 6 S 5

T18S

DESCRIBE CORNER MONUMENT FOUND

Original called-for post not found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found root holes and remains of four original bearing trees (one scribe partially visible).

N 59° E 29.8 Fd. stump hole and remains of rotted tree.

S 13° E 46.9 Fd. remains and root hole.

S 57° W 26.6 Fd. scribing "T18S R10E" 56" face down.

N 40° W 31.3 Fd. root hole and piece with axe marks.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is approx. 11 miles West of Bend, Oregon,
near F.S. Road 1722.

Signature

Title

Division

Headquarters

Date

, Surveyor, Sun Country Eng. & Surveying, Inc. 7100-52 (3/68)

Bend, OR

T CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 21½" x 30" galv. l. Pipe & 2½" Brass cap marked:
(Set from original bearing trees in NE & SE quadrants)
(used as best mean location of corner)
Cap rises 8" above ground.

T17S R10E
S31 | S32
S 6 | S 5
LS T18S
1642
1980

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed four new bearing trees:

A 7" L.P. Pine bears N 21° E 24.0' scribed "T17S R10E S32, BT"
A 7" L.P. Pine bears S 75° E 30.2' scribed "T18S R10E S5, BT"
A 9" L.P. Pine bears S 47° W 21.6' scribed "T18S R10E S6, BT"
A 7" L.P. Pine bears N 43° W 48.6' scribed "T17S R10E S31, BT"

10

Work Done By Robt M. Karl Title Land Surveyor Date 8/11/80 State Registration No. 1642
or Agency

Certified Cor. Record Prepared Yes

(No)

Filed At:

Date

11

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REMARKS

Robert M. Karl

OREGON
JULY 14, 1978
ROBERT M. KARL
1642

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

12

U.S. G.P.O. 1977-725-576/586

13

0551

18° R. 10°

A-5

USDA-FOREST SERVICE

Index

File No. ~~0751~~ 0751

T 18S R 10E

Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 02211N

Cor.

No. A-7

R.D. Bend County Deschutes

N.F. Deschutes State Oregon

N/A Cor Sec 5
S/4 Cor Sec 32

CORNER DIAGRAM

T 17S R 10E

S 32
1/4
S5

T 18S

N

DESCRIBE CORNER MONUMENT FOUND

Searched for, not found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Searched for, not found.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Robert M. Karl Land Surveyor

Title

Division SCE&S

Headquarters Bend

Date

9-17-80

7100-52 (3.68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By Robert M. Karl Title Land Surveyor Date _____ State Registration No. 1642
or Agency _____

Certified Cor. Record Prepared? Yes ☒ No ☐

Filed At: _____

Date _____

REMARKS

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
ROBERT M. KARL
1642

Index File No. 0751

T.

18^S R.

10^E M.


Tract or Surv. No.


Cor.

A-7

Index
File No. 0951
T 18 S. R. 10 E. R.D. Bend County Deschutes NW Cgr. of
Merid. WILLAMETTE N.F. DESCHUTES State OREGON Section 4

CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. A-09
SEE: 2-09 T. 17 S., R. 10 E., W.M.





USDA-FOREST SERVICE

Index

File No. 1151T 18S R. 10EMerid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 02211N

Cor.

No. A-11R.D. Bend County DeschutesN.F. Deschutes State OregonN/4 Cor Sec 4
S/4 Cor Sec 33

CORNER DIAGRAM

T 17S R 10E

S 33

 $\frac{1}{4}$

S 4

T 18S

LS 1642

1980

N

DESCRIBE CORNER MONUMENT FOUND

Original called-for post not found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No original bearing trees found.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is $+ 11\frac{1}{2}$ miles West of Bend, Oregon
near F.S. Road # 1722.

Signature

Surveyor

Title

Division
SCE&SHeadquarters
Bend

Date

7100-52 (3.68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " x 30" G.I.P. & $2\frac{1}{2}$ Brass Cap Marked:

(Set by single proportionate measure)

T 17S R 10E
S 33
 $\frac{1}{4}$ S 4
T 18S
LS 1642
1980

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed 2 new bearing trees:

A 7" L.P. Pine bears S 55° W $24\frac{6}{8}$, scribed " $\frac{1}{4}$ S 4, BT"

A 7" L.P. Pine bears N 02° E $20\frac{8}{8}$, scribed " $\frac{1}{4}$ S 33, BT"

Work Done By Robert M. Karl Title Land Surveyor Date 9/4/80 State Registration No. 1642 Ore.
or Agency

Certified Cor Record Prepared? Yes ☒ No ☐ Filed At:

Date

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REMARKS

OREGON
JULY 14, 1978
ROBERT M. KARL
1642

Index File No.

T.

1151 18^S 10^E M.

Tract or Surv. No.

Cor.

A-11
A-11

USDA-FOREST SERVICE

Index
File No. 1351

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

02211N

Cor.
No. A-13T 18S R. 10ER.D. Bend


County

DeschutesMerid. WillametteN.F. Deschutes

State

OregonNE Cor Sec 4SW Cor Sec 34

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Original called for post not found.

12/06 - Wm Miller (PLS 2111) FD BC. RSG. 3".

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No original bearing tree evidence found (with exception of some axe-marked wood pieces of which no origin could be determined.)

12/06 - W.M. FD. 3 BTs By KARL, SW BT WAS REMOVED BY WOODCUTTERS.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is + 10 miles West of Bend, Oregon near F.S. Road #1750.

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

4

Surveyor, Sun Country Engineering, Inc.

Bend, OR

8/21/80

5

T CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" G.I.P. & 2½" Brass cap marked:
(Set by single-proportionate measure)

T17S R10E
 S33 | S34
 S44 - i - S3
 T18S
 LS 1642
 1980

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed four new bearing trees:

An 8" L.P. Pine bears N 54° E 75.3' scribed: "T17S R10E S34 BT"

An 8" L.P. Pine bears S 38° E 27.4' scribed: "T18S R10E S3 BT"

An 8" L.P. Pine bears S 67° W 23.6' scribed: "T18S R10E S4 BT" - Gone 12/86

A 7" L.P. Pine bears N 39° W 18.0' scribed: "T17S R10E S33 BT"

12/86 - Walt Miller replaced SW BT WITH:
 A 10" L.P. PINE BRS S 86½° W @ 25.4 FT TO A 60-d SPIKE N. base, MKD "T17SR10ES4BT"

10

Work Done By Robert M. Karl Title Land Surveyor Date 8/15/80 State Registration No. 1642
or Agency

Certified Cor. Record Prepared By

☒ Yes

☐ No

Filed At:

Des County

Date

12/18/86

11

REMARKS By Walt Miller.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

OREGON
 JULY 14, 1978
 ROBERT M. KARL
 1642

Index File No.

1351

T.

18

R.

10

M.

Tract or Surv. No.

U.S. G.P.O. 1977-775-547-886

Cor.

A-13
12
13

USDA-FOREST SERVICE

Index

File No.

1951

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

02211N

Cor.

No.

A 14

T 18S

R. 10E

R.D.

Bend

County

Deschutes

Merid. Willamette

N.F.

Deschutes

State

Oregon

W/16 Cor

Sec 3/34

CORNER DIAGRAM

T17S R10E

W1/16 $\frac{S34}{S3}$

T18S

N

DESCRIBE CORNER MONUMENT FOUND

No original monument set

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

PLANE COORDINATE POSITION DATA

State Zone

X

Y

Estab. By

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is + 10 miles West of Bend, Oregon
near F.S. Road #1750

Signature

Title

Division

Headquarters

Date

Surveyor

SCE&S

Bend, OR

8/21/80

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" G.I.P. & 2½" Brass Cap marked:

T17S R10E
W1/16 S34
S 3
T18S
LS 1642
1980

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

2 Bearing Trees scribed:

A 10" White Fir bears N 50° E 18.4' scribed "W1/16 S34 BT"

A 10" L.P. Pine bears S 20° E 38.0' scribed "W1/16 S3 BT"

Work Done By: Robert M. Karl Title Land Surveyor Date 8/15/80 State Registration No. 1642
or Agency

Certified Cor Record Prepared? Yes

No

Filed At:

Date

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REMARKS

OREGON
JULY 14, 1978
ROBERT M. KARL
1642

Index File No.

T.

1451 185 R.

100 M.

Tract or Surv. No.

Cor.

A-14

A-14

USDA-FOREST SERVICE

Index

File No. 1551

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. 02211NCor.
No. A-15T 18S R. 10ER.D. Bend County DeschutesMerid. WillametteN.F. Deschutes State OregonN/4 Cor Sec 3
S/4 Cor Sec 34

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

Original called for post not found.

T17S R10E

S34

 $\frac{1}{4}$

S3

T18S

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found one original bearing tree, a 26" Ponderosa Pine bears N4⁰W 38.3'. Scribe visible (upper blaze previously opened to reveal "S"-lower blaze unopened)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is approximately 9 miles west of Bend, Ore.
near F.S. Road No. 1750

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

4

5

Surveyor

S.C.E. &

S. Bend

8/21/80

+ CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" X 30" Galv. 1. pipe & 2½" brass cap marked:
Rising 5" above ground
Placed stone mound around cap

T17S R10E
1/4 S34
S3
T18S
PLS 1642
1980

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed two new bearing trees:

A 7" Ponderosa Pine bears S 48° E 28.9' scribed "1/4 S 3 BT"

A 7" Ponderosa Pine bears N 44° E 47.0' scribed "1/4 S 34 BT"

10

Work Done By Robt. M. Karl Title Land Surveyor Date 7/22/80 State Registration No. 1642
or Agency

Certified Cor. Record Prepared Yes ☒ No

Filed At:

Date

11

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REMARKS

OREGON
JULY 14, 1978
ROBERT M. KARL
1 6 4 2

12

Index File No. 1551 T. 18 R. 10 E M.

Tract or Surv. No.

Cor. A-15
U.S. G.P.O. 1977-725-576/586

13

USDA-FOREST SERVICE

Index

File No. 1751

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No.

Cor.

No.

A-17T 18 S. R. 10 E. R.D. BEND County DESCHUTES NE COR. SEC. 3Merid. WILLAMETTE N.F. DESCHUTES State OREGON SW COR. SEC. 35

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SF/NF

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

AREA IN BRIDGE CR. BURN. STANDING STEMS
BURNT DEEP. SALVAGE OPERATION HAS CUT
STUMPS SO LOW THAT PRACTICALLY IMPOSSIBLE
TO IDENTIFY QUALIFYING DIAMETERS.

Signature R. OMAN

Title

PLS

Division

Headquarters

50


Date

6/80

D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 1751 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. A-17

USDA-FOREST SERVICE

Index


File No. 1951T 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. A-19R.D. BENDCounty DESCHUTESN/4 COR. SEC. 19N.F. DESCHUTESState OREGONS/4 COR. SEC. 35

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SF/NF

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER


AREA IN BRIDGE CR. BURN.Signature R. OMANTitle PLS

Division _____

Headquarters SODate 6/80 D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____ 10

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

Index File No. 1951 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. A-19 12 13

USDA-FOREST SERVICE

Index


File No. 2151T 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. BENDCounty DESCHUTESN.F. DESCHUTESState OREGONTract or
Survey No. _____Cor.
No. A-21NW COR SEC 1SE COR SEC. 35

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SE/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SP/NF

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

AREA IN BRIDGE CR. BURNSignature R. OMANTitle AS

Division _____


Headquarters SODate 6/80 D-7100-52 (10/70)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. 2151 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. A-21 13

USDA-FOREST SERVICE

Index

File No. 2351T 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No. _____

Cor.

No. A-23R.D. BENDCounty DESCHUTESN/A COR. SEC. 1N.F. DESCHUTESState OREGONS/A COR. SEC. 36.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



— NOTHING —

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" HIGH X 24" Ø P.PINE SAWN STUMP WITH TOE BLAZE, "B" SCRIBE VISIBLE, S50°E 15² FT.12" L.PINE, DEAD & DOWN, WITH WEATHERED BLAZE NO SCRIBE VISIBLE, COMPLETELY UPROOTED AND APPEARS TO HAVE BEEN TRANSPORTED. N05°E 19⁸ FT.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

11.50' EAST OF LOGGING SPUR.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

R. OMAN

Title

PLS

Division

Headquarters

S.O.

Date

6/80 D-7100-52 (10/78)


4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 3"
ABOVE GROUND IN A MOUND of STONES.



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

a 7" P. PINE BEARS S78°E 10⁸⁵ FT. TO 60d NAIL IN S. SIDE, MKD. "1/4 S1 BT";
a 4" P. PINE BEARS N21°E 18⁴⁹ FT. TO 60d NAIL IN W. SIDE, MKD. "X BT".

Work Done By R. OMAN Title PLS Date 6/80 State Registration No. OR-702
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: _____ Date _____

REMARKS

Index File No. 2351 T. 18 S., R. 10 E., W. M.

Tract or Surv. No.

Cor. A-23

USDA-FOREST SERVICE

Index

File No. 2351

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. _____

Cor.

No. A-23T 18 S. R. 10 E. R.D. BEND County DESCHUTES N/A COR. SEC. 1Merid. WILLAMETTE N.F. DESCHUTES State OREGON S/A COR. SEC. 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

— NOTHING —

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature R. OMANTitle PLS

Division _____

Headquarters S.O.Date 6/80 D-7100-52 (10/78)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" HIGH X 24" Ø P. PINE SAWN STUMP WITH THE BLAZE, "B" SCRIBE VISIBLE, S50°E 15² FT.12" L. PINE, DEAD & DOWN, WITH WEATHERED BLAZE NO SCRIBE VISIBLE. COMPLETELY UPROOTED AND APPEARS TO HAVE BEEN TRANSPORTED. N05°E 19⁸ FT.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

1150' EAST OF LOGGING SPUR.

USDA-FOREST SERVICE

Index

File No. 2351

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.


No. A-23T 18 S. R. 10 E.R.D. BENDCounty DESCHUTES

N/A COR. SEC. 1

Merid. WILLAMETTEN.F. DESCHUTESState OREGON

S/A COR. SEC. 36,

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

— NOTHING —

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" HIGH X 24" Ø P. PINE SAWN STUMP WITH TOE BLAZE, "B" SCRIBE VISIBLE, S50°E 15² FT.12" L. PINE, DEAD & DOWN, WITH WEATHERED BLAZE NO SCRIBE VISIBLE. COMPLETELY UPROOTED AND APPEARS TO HAVE BEEN TRANSPORTED. N05°E 19⁸ FT.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

1150' EAST OF LOGGING SPUR.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estob. By _____

Agency

8

Signature

R. OMAN

Title

PLS

Division

Headquarters

S.O.

Date

6/80 D-7100-52 (10/70)


4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 3"
ABOVE GROUND IN A MOUND OF STONES.



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

a 7" P. PINE BEARS S78°E 10⁸⁵ FT. TO 60d NAIL IN S. SIDE, MKD. "1/4 S 1 BT";
a 4" P. PINE BEARS N21°E 18⁴⁹ FT. TO 60d NAIL IN W. SIDE, MKD. "X BT".

Work Done By R.OMAN Title PLS Date 6/80 State Registration No. or Agency OR-702 10

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: _____ Date _____ 11

REMARKS

USDA-FOREST SERVICE

Index
File No. 2551

CORNER RECORD (SEARCH)
(Ref. FSM 7.151.4)


Tract or
Survey No. _____

Cor.
No. A-25

T. 18 S. R. 10 E. R.D. BEND County DESCHUTES SE COR. of SEC. 36

Merid. WILLAMETTE N.F. DESCHUTES State OREGON NW COR. of SEC. 6

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

searched for - nothing found

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PONDEROSA DOWN (ROTTING) APX 18" S. 30° E. 24' 4"

FND. SCRIBBING BT 1 R. 11 E. FND OLD SEC. MARKER

FND. PONDEROSA STUMP APX. 28" FND. AT BEARING AND

DISTANCE NOTED. NO SCRIBBING N. 02° W. 39'

FND. DOWN PONDEROSA (ROTTING) APX 32" AT BEARING

AND DISTANCE NOTED. NO SCRIBBING FND, S. 80° W. 27'

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

Corner Legend:

- ☐ Searched for/Not Found
- ☒ Evidence Found/Accept.
- ☒ Permanent Monument

Signature R. H. Debrand

Title RLS

Division

Headquarters Bend


Date 5/22/87 100-52 (3/7)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2 X 32" BRASS CAP - STEEL PIPE RISING UP
4" IN A MOUND OF STONES

MONUMENT SET



ACCESSORIES DESCRIBE NEW B^Y'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

- A. 7" PONDEROSA PINE - BEARS S. 48° W. 13.4 FEET { B/S T. 18 S. R. 10 E.
SECTION 1 B.T.
B. 11" PONDEROSA PINE - BEARS N. 59° W. 13.4 FEET. {
B/S. T. 17 S. R. 10 E. SEC 36 B.T.
C. 7" PONDEROSA PINE - BEARS N. 38° E. 9.4 FEET.
B/S. T. 17 S. R. 11 E SEC 31 B.T.
D. 10" PONDEROSA PINE - BEARS S. 37° E. 19.6 FEET. { B/S T. 18 S. R. 11 E.
SEC 6 B.T.

Work Done By R. Hildebrand

Title PLS

Date 5/81

State Registration No. 1898
or Agency

PLAT PREPARED OR

Certified Cor. Record Prepared? Yes

No

Filed At

Deschutes Co. SURVEYOR'S OFFICE Date

REMARKS

See: 001004 (#12/97)

Index File No. 2551 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. A-25

USDA-FOREST SERVICE

Index

File No.

~~1352~~ / 352

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 02211N

Cor.

No. B15

T 18S R. 10E

R.D. Bend

County

Deschutes

Merid. Willamette

N.F. Deschutes

State

Oregon

N/16 Cor
Sec 4/3

CORNER DIAGRAM

T 18S R 10E

N 1/16

S4

S3



DESCRIBE CORNER MONUMENT FOUND

No original monument set.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is + 11 miles West of Bend, Oregon + $\frac{1}{4}$ mile South of intersection of Road 1750 and Spur Rd.

Signature

Title

Surveyor

Division

SCE&S

Headquarters

Bend

Date

9/8/80

7100-52 (3. 68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT T 18S R 10E

Set 2 1/2" x 30" G.I.P. & 2 1/2" Brass Cap Marked:
(set by single-proportionate measure)

N 1/16
S 4 | S 3
LS 1642
1980

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed 2 bearing trees:

A 10" L.P. Pine bears N 43° W 41 0, scribed "N 1/16 S 4, BT"
A 7" L.P. Pine bears S 11° E 10 6, scribed "N 1/16 S 3, BT"

Work Done By Robert M. Karl Title Land Surveyor Date 9/3/80 State Registration No. Ore. 1642
or Agency

Certified Cor. Record Prepared? Yes ☒ No

Filed At:

Date

REMARKS

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert M. Karl

OREGON
JULY 14, 1978
ROBERT M. KARL
1642

Index File No. 1352 T.

18° R. 10° E. M.

Tract or Surv. No.

Cor. B-13

USDA-FOREST SERVICE

Index

File No. 229 0953T 18 S. R. 10 E.Merid. WILLAMETTE

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. E197-7937-13

Filed At. _____

Object Ident. Approx cornerIdent. By M. Newcomb

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No.R.D. BENDCounty DESCHUTESE/4 Cor. Sec. 5N.F. DESCHUTESState OREGONW/4 Cor. Sec. 4

DESCRIBE CORNER MONUMENT FOUND

Could not find corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No BT's Found.SEE REMARKS

Jim Tye of Sun County
confirms that search
area is now a logged
area. 1980

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

K-Tag that I posted showing center of search
area is approx 250' North of road located
East of a clear cut.

Signature M. Newcomb

Title

Division

Headquarters


Date

10-1-79

D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At _____ Date _____

REMARKS

Area that I searched has been had some logging
done and then this year fire has burned it.
Surveyor in 1880 calls for a large pine
but could not find any that shows axe work.

Index File No. **0953** T. **18** S., R. **10** E., W.M.

Tract or Surv. No.

Cor. **C-9**

CORNER RECORD (PERPETUATION)

MONUMENT

STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE
 RISING 3" IN MOUND OF STONES.



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

30" P. PINE BAG. Due West 198 FT. (ORIG. BT)

30" P. PINE " S82°E 64? FT. (ORIG. BT)

BT'S REMOVED AS FIRE SALVAGE

Work Done By R. OMAN Title PLS Date 9/79 State Registration No. OR-702Certified Cor. Record Prepared ☒ Yes ☐ No Filed At DES. CO. SURV. OFF. Date 9/79 16/80

RE-WITNESSED

REMARKS

a #5X36" PLASTIC-CAPPED STEEL ROD RISING 3" IN MOUND OF STONES ON S. SIDE OF
 BURNT 4" L. PINE BEARS S86°E 31 3/4 FT., MKD. "BEARING OBJECT";
 a #5X36" PLASTIC-CAPPED STEEL ROD RISING 0" IN MOUND OF STONES AT E. BASE
 OF ORIG. BT STUMP BEARS S88°W 16 1/2 FT., MKD. "BEARING OBJECT".

Index File No. 1353 T. 18 S. R. 10 E. M.

Tract or Surv. No.

Cor. C-13

12

13

Index

File No.

1353

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

C-23

T 18 S R. 10 E

R.D.

BEND

County

DESCHUTES

E/46 Sec 4

Merid. 10m

N.F.


DESCHUTES

State

OREGON

W/46 Sec 3

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SP/NE

OVER →

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

2 BTs, charred ponderosa pine
w/ scribing

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

PLANE COORDINATE POSITION DATA

State

Zone

X

Y

Estab. By

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

30' N. of Spur Rd. 12 D

OFF of Rd. 1750

Checked by Robert Karl Surveyor #1642

for Contract # 02211N - 8/21/80

Signature

R. HILDEBRAND

Title

ST

Division

Headquarters

50

Date

8/8/79

7100-52 (3 6B)

USDA-FOREST SERVICE

Index

File No.

1753

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

C-17

T 18 S. R. 10 E. R.D. BEND County DESCHUTES E/A COR. SEC. 3Merid. WILLAMETTE N.F. DESCHUTES State OREGON W/A COR. SEC. 2

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

POSSIBLE EAST BT.... SO BADLY BURNED
THAT ID IS NEARLY IMPOSSIBLE

AS OF 11 June 1980 No possible BTs REMAIN AS LOGGING
OPERATION HAS CLEARED AREA.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

AREA ALL IN BRIDGE CR. BURN

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

R-OMAN

Title

PLS

Division

Headquarters

SO


Date

2/80

D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 1753 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. C-17

USDA-FOREST SERVICE

Index


File No. 2153T 18S R. 10EMerid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Bend County DeschutesN.F. Deschutes State OregonTract or
Survey No. 02211NCor.
No. C-21E/4 Sec 2w/4 Sec 1

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found mound of stone at corner location.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Ponderosa Pine, 24" diameter bears S60°E -7.9'
1/4 S visible on upper blaze, lower blaze open but
burned out making no scribing visible.
Fd pieces of burned wood near original location of
Sec2 bearing tree, but could not establish original
location.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Located approximately 150' N. of USFS road.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature

Title

Division Bend, Headquarters

Date

7100-52 (3/68)

RLS 1104, Sun Country Engineering & Surveying

5-23-80

T **CORNER RECORD (PERPETUATION)**

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" galv. iron pipe with a 2½" Brass Cap and marked T18S R10E
 as shown:
 Set iron pipe 16" deep and built a mound of stone around the
 pipe.

1
 1
 1
 S2 S1
 LS 1104
 1980 9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A Ponderosa Pine, 6", diam, bears N32°E 26.7', scribed ¼S1, BT.
 A Ponderosa Pine, 6", diam, bears N45°W 42.1', scribed ¼S2, BT.

Work Done By James R. Tye Title Party Chief Date 5-23-80 State Registration No. ORLS 1104
 or Agency

Certified Cor. Record Prepared Yes No Filed At: Deschutes County Surveyor Date

REMARKS

Witness to corner:

Larry G. Wiley, L.S.I.T.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

James R. Tye

OREGON
 JULY 22, 1977
 JAMES R. TYE
 1104

Index File No. 2153 T. 18 S. R. 10 E. M.

Tract or Surv. No. C-21

USDA-FOREST SERVICE

Index

File No. 2553

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or 001004

Cor.

No. C-25

Survey No.

T 18 S. R. 10 E. R.D.Bend

County

Deschutes

Cor. of

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

Section

SEE: C-01 T. 18 S., R. 11 E., W.M.

BCSP



USDA-FOREST SERVICE

Index
File No. 2154

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No. D-21T 18 S. R. 10 E.R.D. BENDCounty DESCHUTES3/16 COR. ofMerid. WILLAMETTEN.F. DESCHUTESState OREGONSEC. 2 & 1

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

OLD FS SHINY ALUMINUM LOCATION POSTER
PURPORTING S/16 COR. IN 6" FIR AT
S. EDGE of PRIMITIVE CAMP

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature R. OMANTitle PLS


Division

Headquarters SODate 2/80 D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

AT MID-POINT OF TRUE LINE $(2628.69 \div 2 = 1314.34)$ SET $2\frac{1}{2}" \times 3\frac{1}{2}"$
B-C SP KSG. 2" IN SMALL MOUND OF STONES, ABOUT 590'
N. of SKYLINERS ROAD $\frac{1}{4}$ 100' E. of PUT. DIRT ROAD.



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" PP S $39\frac{3}{4}^{\circ}$ W 590' FT. TO 60d NL. IN NW SIDE, MKD. 5/16 SZ BT

9" PP N 73° E 4135 FT. TO 60d NL. in S. BASE, MKD. 5/16 S1 BT

Work Done By. R. OMAN Title PLS Date 7/81 State Registration No. OR-702
or Agency
Certified Cor. Record Prepared? ☒ Yes No Filed At DESCH. CO. SURV. OFFICE Date 7/81

REMARKS

Index File No. 2154 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. D-21

USDA-FOREST SERVICE

Index

File No. E-1 0155

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No.

Cor.

No. E-1T 18 S. R. 10 E. R.D. BEND County DESCHUTES NW Cor. Sec. 7Merid. WILLAMETTE N.F. DESCHUTES State OREGON SE Cor. Sec. 1

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

No remains of original Post.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Pine 10" dia. dead & down, bears N 55° W, 12 LKS dist. with scribe 'MKs (T1851) (BT) on a partly healed double blaze.

A Pine 11" Dia. bears S 50° W, 12 LKS dist; on a almost completely healed double blaze.

- SEE REMARKS -

PHOTO IDENTIFICATION DATA

Photo No. 127-7937-7

Filed At. _____

Object Ident. Section cornerIdent. By H. Newcomb
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER


From the 1/4 corner to the south there are scattered blazes along section line which I tied ribbon to. Corner falls on a south slope.

Signature Thomas L. Newcomb Title Survey Tech. Division PST Headquarters 10/16/79 Date D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 4"



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

~~Lost BT TAGS & attention signs on BT's.~~

A 9" L. PINE BBS. S 47° W 72 FT. (ORIG. BT);

A 6" GRAND FIR BBS. S 67° E 143 FT., MKD. T 185 R 10 E 57 BT

A 10" " " " N 46° E 126 FT., " " " 56 BT

A 8" " " " N 58° W 72 FT., " " " R 9 E 51 BT

10

Work Done By: R.OMAN Title: PLS Date: 8/80 State Registration No. or Agency: OR-702

Certified Cor. Record Prepared? ☒ Yes No Filed At: DES. CO. SURVEYORS OFFICE Date: 5 SEPT, 1980

11

REMARKS

A Pine 11" dia. bears S 31° E. 17 LKS dist. with scribe MKS (R 10 E) (BT) on a partly healed double blaze. Note: BT's with visible scribe marks are not complete. NE BT could not get close to because of bees. NE BT GONE!

Index File No.
0155

T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. E-1

12

13

USDA-FOREST SERVICE

Index

File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

File No. E-3 0355T 18 S. R. 10 E. R.D. BEND

County

DESCHUTESMerid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON3/4 Cor. Sec. 6N/A Cor. Sec. 7CORNER DIAGRAM¹

DESCRIBE CORNER MONUMENT FOUND

Could not locate 1/4 corner.~~DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND~~*From the section corner to the west, found a blazed line that started at 2 chains east of section corner. Looks like surveyor didn't run this line because of the blazing and also the chaining calls don't fit. The surveyor states that at*~~DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER~~*33 chains he descends hill and at 42.17 chains he sets corner. He does not mention that there is a cliff approx 150 ft high which is almost impossible to traverse around unless you go approx. 700 ft north or south. Search area falls in this year's fire.*

PHOTO IDENTIFICATION DATA

Photo No. E197-7937-2

Filed At. _____

Object Ident. approx cornerIdent. By K. Newcomb

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature Thomas L. Newcomb

Title

Division

Headquarters


Date

D-7100-52 (10/78)

Survey Tech.PVT.10/17/74

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



MONUMENT
STAMPED

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 0355 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor.

E-3

12

13

USDA-FOREST SERVICE

Index

File No. ~~0555~~ 0555

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

E-5

T 18 S. R. 10 E.

R.D.

BEND

County

DESCHUTES

SW Cor. Sec. 5

Merid. WILLAMETTE

N.F.


DESCHUTES

State

OREGON

NE Cor. Sec. 7

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Could not find corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Could not find bearing trees

See Remarks

PHOTO IDENTIFICATION DATA

Photo No. E 197-7937-7

Filed At.

Object Ident. Approx. Corner

Ident. By L. Neumann

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature Thomas L. Neumann

Title

Survey Tech.

Division


Headquarters

1-3-79

Date

D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW ST'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____ 10
Certified Cor. Record Prepared? Yes No Filed At: _____ or Agency _____

REMARKS

Date _____ 11

Area has been burned by this years fire.
The chaining calls look like they fit, but
could not find any evidence of the surveyor
ever being there.

Index File No. 0555 T. 18 S., R. 10 E., W.M.

Tract or Surv. No. _____

Cor. E-5 13

USDA-FOREST SERVICE

Index

File No. ~~0755~~ 0755T 18 S. R. 10 E.Merid. WILLAMETTE

CORNER DIAGRAM

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No.R.D. BEND

County

DESCHUTESN.F. DESCHUTES

State

OREGONCor. E-7
No. 5
Cor. Sec. 5
No. 8

DESCRIBE CORNER MONUMENT FOUND

Could not find corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Could not find bearing trees

PHOTO IDENTIFICATION DATA

Photo No. E 197-7937-S

Filed At.

Object Ident. Approx. cornerIdent. By Thomas L. Newcomb
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Posted K-tag showing search area.
USE Photo to locate this area.

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency


Signature Thomas L. Newcomb Title Survey Tech Division _____

Headquarters _____

Date 10-2-79 D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES DESCRIBE NEW ST's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At _____ Date _____ 11

REMARKS

*Search ~~area~~ Falls in Heavily burned and Logged.
IT LOOKS LIKE SURVEYOR STUBBED THE LINE FROM THE
WEST TO THIS CORNER.*

12

Index File No. *0755* T. *18* S., R. *10* E., W.M.

Tract or Surv. No.

Cor. *E-7*

13

USDA-FOREST SERVICE


Index
File No. 0955

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No. E-9T 18 S. R. 10 E. R.D. BEND County DESCHUTES SW Cor. Sec. 4
Merid. WILLAMETTE N.F. DESCHUTES State OREGON NE Cor. Sec. 8

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Could not find corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

*Could not find bearing trees.*SEE REMARKS*SF/NF using
Compass & Chain
Jim Iye/Sun Country
1980*

PHOTO IDENTIFICATION DATA

Photo No. E197-7937-5

Filed At. _____

Object Ident. Approx. cornerIdent. By Th. Newcomb
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____
Agency


DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

*Posted K-TAG showing search area.
Search area falls in a rocky steep slope.
There is no easy way to this corner.*Signature Thomas L. NewcombTitle Survey Tech.Headquarters PT.Date 10-1-79

D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



MONUMENT
STAMPED

ACCESSORIES DESCRIBE NEW ST'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At _____ Date _____

11

REMARKS

The surveyors calls don't fit and leave out
any mention to the south. East & West.
To the north of corner he calls the cliff
which he offset to avoid but no mention to the
west which would be been much clearer.

12

Index File No. 0955 T. 18 S., R. 10 E., W. M.

Tract or Surv. No.

Cor. E-9

13

Index
File No. 1155

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No. E-11

T 18 S. R. 10 E.

R.D. BEND

County DESHUTES

Merid. WILLAMETTE

N.F. DESCARTES


State OREGON

5/4 Cor. Set. 2

N/4 COR. SET 9

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

BT in 5.9

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At.

Object Ident.

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X

Y

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature H. HILDEBRAND

Title S.T.

Division


Headquarters *S.O.*

Date 8/79 D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE RISING 3"
IN MOUND OF STONES



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 24" P. PINE BRS. S05°W 4° FT. (ORIG. BT.), BURNT & DEAD;
AN 8" W. FIR BRS. N72°E 15° FT. MKD. "1/45 S4 BT", BURNT & DEAD.

~~Revised 12/97 by Walt Miller~~

Work Done By R. OMAN Title PLS Date 8/79 State Registration No. OR-702
or Agency
Certified Cor. Record Prepared? (Yes) No Filed At: DES. CO. SURV. OFFICE Date 5 Sept. 1979
UPDATE CERT. ✓ REMARKS ✓ 5 Sept. 1980

A #5X30" PLAS-CAPPED STEEL ROD RSG. 2" AT EAST BASE of 4' H1 P. PINE STUMP
BRS. N76°W 25.55 FT., MKD. "BEARING OBJECT"; AND

A #5X30" PLAS-CAPPED STEEL ROD RSG. 3" AT WEST BASE of 8" H1 BT
BRS. N72°E 14.05 FT., MKD. "BEARING OBJECT".

STEEL GUARD POSTS AT 10 EAST & 15 SW.

Index File No. 1155 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. E-11

Index
File No. 1355

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

T 18 S. R. 10 E.Merid. Wmt.R.D. BendN.F. DeschutesCounty DeschutesState Oregon


Tract or

Survey No.

Cor.

No. E-13NW Cor. Sec. 10SE Cor. Sec. 4

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

#4 steel rod rising 3" in rock outcrop

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Two original BT's

PHOTO IDENTIFICATION DATA

Photo No. Filed At. Object Ident. Ident. By

Signature

PLANE COORDINATE POSITION DATA

State Zone X Y Estab. By

Agency

Signature

Title

PLS

Division

Eng.

Headquarters

SO

Date


7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " X 30" brass-capped steel pipe rising 18" above ground
at edge of lava dike, IN A LARGE MOUND OF STONES.



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

gone a 26" ponderosa pine bears S 42° E 20.8 feet, (original BT); STUMP 6/80 *Red*

a rock outcrop 6' X 3' X 6' bears N 86° E 23.5 feet, chiselled "B" X 0" & painted red;
a " " 4' X 3' X 5' " N 72° W 21.3 feet, " " " 4 " yellow;

gone a 6" ponderosa pine bears S 58° E 97.4 feet, on slope, B/S "T18S R10E S10 BT"; and
gone an 8" " " " S 72° W 140.7 feet on slope, B/S "T18S R10E S9 BT".

Work Done By. R. Oman Title PLS Date 7/78 State Registration No. OR-702
or Agency
Certified Cor. Record Prepared? ☒ (Yes) No Filed At Desch. Co. Surv. Office Date 7/78

CERTIFICATE FILED W/NEW ACCESSORIES

5 SEPT. 1980

A #5 X 30" PLAS-CAPPED STEEL ROD RSG. 6" AT S. BASE of 6' HI BOULDER
BRS. 563° E $21\frac{3}{4}$ FT., MKD. "BEARING OBJECT"; (STEEL GUARD POST 15 EAST);
in mound of stones
A #5 X 30" PLAS-CAPPED STEEL ROD RSG. 4" AT S. BASE of 10' HI SLOPING BOULDER
BRS. 578° W 28 1/5 FT., MKD. "BEARING OBJECT"; (STEEL GUARD POST 15 NE).

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

1355

25 18 S. 10 E.

Wmt.

E-13

Index


File No. 1555

T 18 S. R. 10 E.

Merid. Wmt.

CORNER DIAGRAM

S. 3



S. 10

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. E-15

R.D. Bend

County

Deschutes

N.F. Deschutes

State

Oregon

N/4 Cor. Sec. 10

S/4 Cor. Sec. 3

DESCRIBE CORNER MONUMENT FOUND

2" steel pipe rising 4" in a mound of stones
with 3 RP's as set by John Eaton, 1958

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Title

PLS

Division

ENG.

Headquarters

SO

Date

26 OCT 1978


7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " X 30" brass-capped steel pipe rising 6" above ground
in a mound of stones.



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

a 5" ponderosa pine bears N 20° W 27.9 feet, B/S " $\frac{1}{4}$ S3 BT"; and } BURNT IN
a 6" ponderosa pine bears S 72° W 19.9 feet, B/S " $\frac{1}{4}$ S10 BT". } BRIDGE CR.
FIRE

REWITNESSED 6/80

~ 10' X 6' BEDDED BOULDER RISES 5' ON DOWNHILL SIDE BRS. N 85° W 24⁸⁷ FT, MKD. "BO X" 9

~ TILTED BEDR. 4' X 8' RISING 9' ON DOWNHILL SIDE BEARS S 43° E 28⁹⁵ FT, MKD "X BO" 10

Work Done By. R. Oman Title PLS Date 7/78 State Registration No. OR-702
or Agency
Certified Cor. Record Prepared? (Yes) No Filed At: Deschutes Co. Surv. Office Date 7/78 11

REMARKS
CERT. REFILED w/ COUNTY SURVEYOR

Index File No. 1555 T. 18 S. R. 10 E. M. Wmt.

Tract or Surv. No.

Cor. E-15

12

13

Index
File No. 1755

T 18 S. R. 10 E.

Merid. Wmt.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor. E-17
No.

R.D. Bend

County

Deschutes

N.F. Deschutes


State

Oregon

NE Cor. Sec. 10

SW Cor. Sec. 2

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

2½" steel pipe rising 2" above ground.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No BT's or RP's, but stumps and root wells match descriptions.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title
PLSDivision
ENG.Headquarters
SO

Date

7100-52 (3 68)


26 OCT 1970

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " X 30" brass-capped steel pipe rising 2" above ground.



9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

- a 4" ponderosa pine bears N 56° W 35.6 feet, B/S "T18S R10E S3 BT";
- a 9" lodgepole " " N 21° E 44.5 feet, B/S "T18S R10E S2 BT";
- an 8" " " " S 45° E 24.2 feet, B/S "T18S R10E S11 BT"; and
- a 6" " " " S 33° W 8.1 feet, B/S "T18S R10E S10 BT".

10

Work Done By. R. Oman Title PLS Date 7/78 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared ? (Yes) No Filed At: Deschutes Co. Surv. Office Date 7/78

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. E-17
1755 18 S. 10 E. Wmt.

12

13

US ~~D~~A-FOREST SERVICEIn ~~S~~ exFile No. 1955T 18SR. 10EMe ~~s~~ id. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. 02211N

Cor.

No. E-19R.D. BendN.F. DeschutesCounty DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 12" diam snag bears N5°E 10.2' "-4S" visible on upper blaze, scribe not visible on lower blaze.

A 30" diam stump bears South 6.2' w/ no scribes visible.

PHOTO IDENTIFICATION DATA

Phot ~~O~~ No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is approx. 200' Southeast of small swampy meadow.

Signature

Title

Division

Headquarters

Date

RLS 1104, Sun Country Engineering & Survey. 7100-52 (3-68) 6/17/80

T **CORNER RECORD (PERPETUATION)**

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" galv. iron pipe with
2 1/2" Brass Cap rising 4" above the
ground. Marked as shown.

T18S R10E

1/4 S2

S11

LS1104

1980

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A Lodgepole Pine 7 in. diam bears N25°E 26.8' scribed 1/4 S2, BT.

A Lodgepole Pine 7 in. diam bears S34°E 45.2' scribed 1/4 S11, BT

10

Work Done By James R. Tye Title Party Chief Date 6-17-86 State Registration No. ORLS 1104
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Deschutes County Surveyor Date

11

REMARKS

Witness to corner:

Larry G. Wiley, L.S.I.T.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

James R. Tye

OREGON

JULY 22, 1977

JAMES R. TYE 12

Cdr104

13

Index File No. 1955 T. 18th R. 10th E M.

Tract or Surv. No.

U.S. G.P.O. 1977 725-576/588

USDA-FOREST SERVICE

Index

File No. 2155T 18S R 10EMerid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.02211NCor.
No.E-21R.D. BendN.F. Deschutes


County

Deschutes

State

OregonSE Cor Sec 2NW Cor Sec 12

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found mound of stone at corner location.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Ponderosa Pine stump, 36" diam. bears N61°E--20.5'.
Scars and axe marks visible on lower blaze. No scribing found. Down Ponderosa Pine, 30" diam. bears N59°W--54.8'. Scars but no scribing visible. Root structure, bears S45°W--27.8'. Found scar on fir bark. Down Fir, 15" diam. bears S57°E--59.4'. "-S 12 visible on upper blaze, BT" visible on lower blaze.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Established corner from mean location of original N.E., N.W., and S.E. B.T.s.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature _____

Title

Division

Headquarters

Bend, OR

Date

RLS 1104,

Sun Country

Eng. & Surveying

June 18, 1980

7100-52-13/68)

5

T **CORNER RECORD (PERPETUATION)**

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" galv. iron pipe with 2½" brass cap, rising 6" above ground, as shown:

T18S	R10E
S2	S1
S11	S12
LS 1104	
1980	9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 17" diam. Ponderosa Pine bears N74°E--21.2', Scribed	T18S R10E S1, BT
A 7" diam. Ponderosa Pine bears N30°W--25.4', Scribed	T18S R10E S2, BT
A 7" diam. Ponderosa Pine bears S13°W--13.5', Scribed	T18S R10E S11, BT
A 7" diam. Ponderosa Pine bears S29°E--23.5', Scribed	T18S R10E S12, BT

Work Done By James R. Tye Title Party Chief Date 6-18-80 State Registration No. ORLS 1104
or Agency

Certified Cor. Record Prepared ☒ Yes ☐ No Filed At: County Surveyor's Office Date

REMARKS

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

James R. Tye

OREGON
JULY 22, 1977
JAMES R. TYE
1104

Index File No. 2155 T. 18^S R. 10^E M.

Tract or Surv. No.

U.S. G. P. O. 1977-725-576/586

USDA-FOREST SERVICE

Index

File No. **2355**T. **18** S. R. **10** E. R.D. **BEND**Merid. **WILLAMETTE**N.F. **DESCHUTES**County **DESCHUTES**State **OREGON**Tract or
Survey No.Cor.
No. **E-23**C.O.R. of SEC. **1****3/4**C.O.R. of SEC. **12**

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

Searched For Nothing Found.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S.F. - N.F.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☒ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Signature _____

N.C.P.

Title _____

Division _____


Headquarters **BEND**Date **5/8/**

D-7100-52 (3/75)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFF



ACCESSORIES DESCRIBE NEW B^Y'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 PLAT PREPARED OR
 Certified Cor Record Prepared? Yes No Filed At: Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No. 2355 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor E-23

Index

File No. 2555

T 18 S. R. 10 E. R.D. Bend

Merid. WILLAMETTE N.F. DESCHUTES

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

County

State

Contract or

Survey No.

Cor.

No.

Cor. of

001004

E-25

Deschutes

OREGON

Section

SEE: E-01

T. 18 S., R. 11

E.W.H.

BCSP



USDA-FOREST SERVICE

Index

File No.

T 18 S 1556 R. 10 EMerid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D.

BEND

N.F.

Deschutes

County

Deschutes

State

Oregon

Tract or

Survey No.

Cor.

No.

F-15

CORNER DIAGRAM

CN 1/16

S 10

DESCRIBE CORNER MONUMENT FOUND

Found 3/4 O.D. iron pipe in ground.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Corner is approximately 170 ft. W. of Tumalo Creek.

4


5

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" Brass Capped Steel Pipe.



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Established 2 B.T.'s:

... An 8" P.Pine bears N. 10 W. 24.2 ft. blazed and scribed -
" CN 1/16 Sec. 10 B.T."

... A 7" L.P. Pine bears S. 43 W. 21.5 ft. blazed and scribed -
" CN 1/16 Sec. 10 B.T."

Work Done By. Jan Wick Title Surveyor Date 12/78 State Registration No. OR 1539
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Date

REMARKS

Index File No. 1556 T. 18 S. R. 10 E. M.

Tract or Surv. No.

U.S. G.P.O. 1977-725-576/586
Cor. P15 13

USDA-FOREST SERVICE

Index

File No. 1656T 18 S R. 10 EMerid. WM

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.000846Cor.
No.F-16

R.D.

Bend

County

Deschutes


N.F.

Deschutes

State

ORNE 1/4 S. 10

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Not orig. set

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Not orig. set

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Tom Miller

Title

PLS

Division

CS

Headquarters

SO

Date

12/87


FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2 BCSP, RISING 2"



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By Tom Miller Title PLS Date 12/87 State Registration No. 1508
or Agency

Certified Cor. Record Prepared? ☒ Yes No Filed At: Des. Co. Date 6/11/91

REMARKS

Index File No. 1656 T. 18 R. 10 M. 10 Tract or Surv. No. 000846 Cor. F-16
GPO: 1986 O - 439-095

USDA-FOREST SERVICE

Index

File No.

T 18 S 10 EMerid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D.

N.F.

BENDDeschutes

County

State

Tract or

Survey No.

DeschutesOregon

Cor.

No.

F-17

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

Found axle with original guard stake.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)


5

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED-

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½ x 30" Brass Capped Steel Pipe.



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Established 2 B.T.'s:

a 5" P.Pine bears N. 60 E. 16.5 ft. blazed and scribed "N. 1/16 S. 11 B.T."

a 5" P.Pine bears N. 65 W 24.1 ft. blazed and scribed " N. 1/16 S/ 10 B.T."

10

Work Done By. Jan Wick Title Surveyor Date 12/78 State Registration No. OR 1539
or Agency

Certified Cor. Record Prepared ? Yes No Filed At:

Date

11

REMARKS

Revisited by Tom Miller: See 000846

12

Index File No. 1756 T. 185 R. 106 M.

Tract or Surv. No.

U.S. G.P.O. Cor. F-17 1977-725-576/586

13

USDA-FOREST SERVICE

Index

File No. G-1 0157T 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. BENDN.F. DESCHUTESCounty DESCHUTESState OREGONTract or
Survey No. _____Cor.
No. G-01W/4 COR. SEC. 7E/4 COR. SEC. 12

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. 197-7937-7

Filed At. _____

Object Ident. 44 CornerIdent. By T. Newcomb

Signature

6

DESCRIBE CORNER MONUMENT FOUND

No remains of original Post.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A burnt Pine Stump bears S 79° W, 42
Lks dist. with burnt remains of scribe
HKs (BT) along side of stump.
A stump base bears S 75° E, 30 Lks dist.
ROUTED

2

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Posted K-tag 6 chains South of corner
on a 10" pine. Pine is on the South side
of Turnalo creek trail 38 ft East from
The Junction to Swampy Lakes trail.
Corner falls on South slope.

3

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Title

Division

Headquarters

Date

D-7100-52 (10/78)

4

5

Signature Thomas G. Newcomb Survey Tech. ROT.10/16/79


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set fence post w/ sign attached

2³/₄ FT south of corner.

SET 2 1/2" X 32" ALUM.-CAPPED ALUM. PIPE FLUSH WITH GROUND
LEVEL IN MOUND OF STONES.



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Posted K-tag on a 5" line which bears
N 54° E, 5⁵/₈ FT FROM CORNER.

A 9" L. PINE BRS. N 57° E 5³⁶/₆₄ TO 60 d. SPIKE IN SE BASE, MKD. 1/4 S7 BT

AN 8' X 5' BOULDER RSG. 4' ON DOWNHILL SIDE BRS. N 39° W 56²/₃ FT., MKD. B.O
X

10

Work Done By R. OMAN Title PLS Date 29 MAY 80 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared ☒ Yes ☐ No Filed At: DESCH. CO. SURVEYORS OFFICE Date 3 JUNE 80
UPDATE CERT REMARKS 5 SEPT. 1980

A #5X36" PLAS-CAPPED STEEL ROD RSG. 2" AT SW BASE of 9" DEAD BT BRS. N 57° E 4⁸⁰/₁₆₀ FT.
MKD. " BEARING OBJECT".

Index File No.

0157

T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. G-01 13

12

Index

File No. 1357

T 18 S. R. 10 E.

Merid. Wmt.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor. G-13
No.

R.D. Bend

County

Deschutes

N.F.

Deschutes


State

Oregon

W/4 Cor. Sec. 10

E/4 Cor. Sec. 9

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Two original BT's, one down and rotting.
This corner was not found by John Eaton in his survey of 1958.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

PLS

Division

ENG.

Headquarters

SO


Date

26 OCT 1978

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:



MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " X 30" brass-capped steel pipe rising 4" above ground in a mound of stones.

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

an 18" lodgepole pine bears S 50° E 30.6 feet, (original BT);
 an 8" " " " N 42° E 37.0 feet, B/S $\frac{1}{4}$ S10 BT"; and
 a 4" " " " N 76° W 14.2 feet, B/S $\frac{1}{4}$ S9 BT".

10

Work Done By. R. Oman Title PLS Date 7/78 State Registration No. OR-702
 Certified Cor. Record Prepared? ☒ Yes No Filed At Deschutes Co. Surv. Office Date 7/78

REMARKS

12

13

Index File No. 1357 T. 18 S. R. 10 E. M. Wmt. Tract or Surv. No. G-13 Cor.

USDA-FOREST SERVICE

Index

File No. 1457T 18 S 10 EMerid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. BEND

County

Deschutes

N.F. Deschutes

State

Oregon

Tract or

Survey No. CU/16

Cor.

No. G-14

CORNER DIAGRAM

CW

1/16

S 10

DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is in the center of Forest Service Rd. # 26,
6" below the surface of the ground.

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT
STAMPED:

Set 2½"x 30" Brass Capped Steel Pipe, 6" below the surface of the ground.

T185 RIOE
CW 1/16

SIO
1958
J. Wick
1539 OR

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Establish 2 B.T.'s:

... An 8" DBH Fir bears N. 26°E. 37.8 ft. blazed and scribed-
" CW 1/16 S. 10 B.T.:"

... An 8" DBH Fir bears S. 32° E. 43.8 ft. blazed and scribed-
" CW 1/16 S. 10 B.T."

Work Done By Jan Wick Title Surveyor Date 12/78 State Registration No. OR 1539
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Date

REMARKS

Index File No. 1457 T. 18 R. 10 M.

Tract or Surv. No.

U.S. G.P.O. 1977 Cor. G-14 13
5576 586

USDA-FOREST SERVICE

Index

File No. 1557T 18 S R. 10 EMerid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. BENDCounty Deschutes

Tract or Survey No. _____

N.F. DeschutesState OregonC/A See 10Cor. No. G-15C/A See 10

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

Corner not previously set.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date


7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" Brass Capped Steel Pipe.



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Established 2 B.T.'s:

... A 6" L.P. Pine bears S. 89°W. 23.7 ft. blazed and scribed-

"C ¼ S. 10 BT."

... A 7" L.P. Pine bears N. 10E. 18ft. blazed and scribed-

"C ¼ S. 10 BT."

10

Work Done By Jan Wick Title Surveyor Date 12/78 State Registration No. OR 1539
or Agency

Certified Cor. Record Prepared? Yes ☐ No ☐ Filed At: _____ Date _____

11

REMARKS

12

Index File No. 1557 T. 18S R. 10E M.

Tract or Surv. No.

Cor. G-15
U.S. G.P.O. 1977 5-586

13

Index

File No. 1757

T 18 S. R. 10 E.

Merid. Wmt.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No. G-17

R.D. Bend

County

Deschutes

N.F.

Deschutes


State

Oregon

E/4 Cor. Sec. 10

W/4 Cor. Sec. 11

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Cruiser's post in a mound of stones

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

One BT, down & rotting.

This corner not found by John Eaton in his survey of 1958.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3 68)

PLS

ENG.

SO


26 OCT 1978

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " X 30" brass-capped steel pipe rising 4" above ground,
in a mound of stones.



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

a 4" ponderosa pine bears N 57° W 17.6 feet, B/S $\frac{1}{4}$ S10 BT"; and
a 12" " " " N 88° E 37.7 feet, B/S $\frac{1}{4}$ S10 BT".

Work Done By. R. Oman Title PLS Date 7/78 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared ☒ Yes No Filed At Deschutes Co. Surv. Office Date 7/78

REMARKS

Index File No.	T.	R.	M.	Tract or Surv. No.	Cor.
1757	18 S.	10 E.	Wmt.		G-17

USDA-FOREST SERVICE

Index

File No.

2157

T. 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

R.D. BENDN.F. DESCHUTES

County

DESCHUTES

State

OREGON

Tract or

Survey No.


Cor.

No.

G-21COR. of SEC. 11COR. of SEC. 12

CORNER DIAGRAM PER LEGEND

S.11



S.12

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

DESCRIBE CORNER MONUMENT FOUND

SP/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

M. HEATH

Title

S.T.

Division

Headquarters

S.O.

Date


11/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared ? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

REMARKS

Index File No. **2157 T. 18 S., R. 10 E., W.M.**

Tract or Surv. No.

Cor. **6-21**

USDA-FOREST SERVICE

Index

File No. 2557T. 18 S. R. 10 E. R.D. BENDMerid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

County DESCHUTESState OREGON


G-25

Cor.

No. G-57COR. of SEC. 12

COR. of SEC.

CORNER DIAGRAM PER LEGEND



RIOE R11E 6

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature 7

Corner Legend:

☒ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

DESCRIBE CORNER MONUMENT FOUND

Searched For Nothing Found

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S.F. - N.F.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

D.E.P.

Title


Division

Headquarters BENDDate 5/8/ D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



ACCESSORIES DESCRIBE NEW B^Y'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

REMARKS

Index File No. **2557 T. 18 S., R. 10 E., W.M.**

Tract or Surv. No.

Cor. **G-25**

Index
File No. 0959
T 18 S. R. 10 E. R.D. Bend County Deschutes NW Cor. of
Merid Willamette N.F. Deschutes State Oregon Section 16

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No. 3011

Cor.

No. T-09

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

BCSP rising 2" in
stone mound.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

18" P.P. N28°W 48 2'
9" Fir S50°E 17 3'
13" L.P. S40°W 7 5'

NE BT standing but dead.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is located at Northwest
corner of Tumalo Lake.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other
☐ ☐ Searched For/Not Found
☒ ☒ Evidence Found/Accept.
☒ ☒ Permanent Mon. Set/Yd.

Searched By:

Title

Division


Headquarters

Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

9" R.P. Bks. N29°E 18' to 60-D in SE base, MKD, T185 R10E 39 BT.
 Line posted East and South from corner.

10

Work Done By J. L. Phillips Title LS Date 6/85 State Registration No. OR-1020
 or Agency

Flat of Cor Record Prepared? Yes ☒ No ☐ Filed At Douglas Co. Surveyor's Office Date 1985

11

History of Surveys, G.L.O., etc.
G.L.O. - Past 4 BTs.
R. Oman - Perpetuation 1979 - 1 new BT.

12

Index File No. 0959 T. 18 S., R. 10 E., W.M.Contract or Surv. No 3011Cor. J-09

13

Index

File No. 1159T 18 S. R. 10 E.Merid. Willamette

CORNER DIAGRAM, per legend

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.

000572

Cor.

No.

J-11

County

Deschutes

State

OregonSection 9-16

DESCRIBE CORNER MONUMENT FOUND

SFNF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Skyliner's Road; Westerly on
Rd. # 4601-430 1.1 mi.; thence
West on posted line 500' to
corner.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
 Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Yd.

Searched By: J. ColvinTitle LS

Division

Headquarters

Date


6/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" Alum. capped Alum. monument
rising 4". No stones available.

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" Fir Brs. N 30° W 26' ¹⁵ to 60-D in SW base, mkd. 1/4 59 BT.
9" Spruce Brs S 60° ¹⁵ 37' to 60-D in ~~NE~~ _W base, mkd. 1/4 516 BT.

10

Work Done By A. Cohen Title LS Date 6/85 State Registration No. or Agency OR-1020

Plat DE For Record Prepared? Yes ☒ No ☐ Filed At Draft Co. Surveyor's Office Date 1985

11

History of Surveys, G.L.O., etc. G.L.O. - Past & 2 BTs.

12

Index File No. 1159 T. 18 S., R. 10 E., W.M.

Contract or Surv. No. 3011

Cor. J-11 13

Index

File No. 1359

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor. J-13

No.

T 18 S. R. 10 E.

R.D.

Bend

County

Deschutes

SW Cor. Sec. 10

Merid. Wmt.

N.F.


Deschutes

State

Oregon

NE Cor. Sec. 16

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

1" steel pipe buried 3" below surface,

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Two original BT's, both sawn stumps with visible scribing.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

J. D. CRIVIAL

Title

J. T. Division

Headquarters

Date 8/81

7100-52 (3 68)


2 6 005 1070

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " X 30" brass-capped steel pipe rising 4" above ground
in a mound of stones.



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

a 6" white fir bears N 58° W 21.1 feet, B/S "T18S R10E S9 BT";
an 8" " " " N 43° E 13.5 feet, B/S "T18S R10E S10 BT";
an 8" " " " S 70° E 61.7 feet, B/S "T18S R10E S15 BT"; and
a 10" lodgepole pine bears S 68° W 59.4 feet, B/S "T18S R10E S16 BT".

10

Work Done By R. Oman Title PLS Date 7/78 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? Yes No Filed At Deschutes Co. Surv. Office Date 7/78

11

REMARKS

12

Index File No. 1359 T. 18 S. R. 10 E. M. Wmt. Tract or Surv. No. J-13 Cor. J-13

13

USDA-FOREST SERVICE

Index

File No. 1459

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. J-14T 18 S R. 10ER.D. BENDCounty DeschutesMerid. WillametteN.F. DeschutesState OregonW/16Sec 10/15

CORNER DIAGRAM

S 10

W 1/16

cor.

S 15

DESCRIBE CORNER MONUMENT FOUND

Found cruiser's tag on 7" DBH Fir.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)


CORNER RECORD (PERPETUATION)

MONUMENT

STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" Brass Capped Steel Pipe



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Established 2 B.T.'s:

A 7" Fir bears S. 69° E. 4.6 ft. blazed and scribed -

" W. 1/16 S. 15 B.T.;"

A 7" Fir bears N. 12° E. 6.8 ft. blazed and scribed-

"W 1/16 S. 10 B.T."

10

Work Done By Jan Wick Title Surveyor Date 12/78 State Registration No. OR 1539
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Date

11

REMARKS

Index File No. 1459 T. 18^S R. 10^E M.

Tract or Surv. No.

U.S. G.P.O. 1977 Cor. J-14 13
125-576-586

12

USDA-FOREST SERVICE

Index

File No. 1559

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. _____

Cor.

No. J-15T 18 S 10 ER.D. BENDCounty DeschutesMerid. WillametteN.F. DeschutesState OregonS/4 Sec 10N/4 Sec 15

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is approx. 450' West of Rd.# 1826 on side of hill.

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)


5

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½"x 30" Brass Capped Steel Pipe.



ACCESSORIES: DESCRIBE NEW B.T.'s WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Established 2 B.T.'s:

... A 6" P.Pine bears N. 35°W. 4.2 ft. blazed and scribed "¼ S. 10 B.T."

... A 9" P.Pine bears S. 17°E. 49.1 ft. blazed and scribed "¼ S. 15 B.T."

10

Work Done By. Jan Wick Title Surveyor Date 12/78 State Registration No. OR 1539
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Date

11

REMARKS

12

Index File No. 1559 T. 18 R. 10 M.

Tract or Surv. No.

Cor. J-15 13
U.S. G.P.O. 1977 25-675-586

Index

File No. 1759T 18 S. R. 10 E.Merid. Wmt.R.D. BendN.F. Deschutes

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. J-17County DeschutesSE Cor. Sec. 10State OregonNW Cor. Sec. 14

CORNER DIAGRAM

S.10

S.11



S.15

S.14

DESCRIBE CORNER MONUMENT FOUND

1" steel pipe rising 2" above ground.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Three RP's as set by John Eaton, 1958
and verified from line trees.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

8

Title

PLS

Division

ENG.

Headquarters

SO

Date

26 OCT 1978

9

5


CORNER RECORD (PERPETUATION)

MONUMENT

STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set $2\frac{1}{2}$ " X 30" brass-capped steel pipe rising 6" above ground
in a mound of stones.



9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

a 4" ponderosa pine bears N 30° W 8.0 feet, B/S "T18S R10E S10 BT";

a 7" " " " N 54° E 38.4 feet, B/S "T18S R10E S11 BT";

a 7" " " " S 66° E 45.3 feet, B/S "T18S R10E S14 BT"; and

a 7" " " " S 22° W 34.2 feet, B/S "T18S R10E S15 BT".

10

Work Done By R. Oman Title PLS Date 7/78 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? Yes No Filed At Deschutes Co. Surv. Office Date 7/78

11

REMARKS

Index File No. 1759 T. 18 S. R. 10 E. M. Wmt.

Tract or Surv. No.

Cor. J-17

12

13

USDA-FOREST SERVICE

Index

File No.

T. 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or
Survey No.Cor.
No.COR. of SEC. 11NW COR. of SEC. 13R.D. BENDCounty DESCHUTESState OREGON

CORNER DIAGRAM PER LEGEND

N.F. DESCHUTES

DESCRIBE CORNER MONUMENT FOUND

S. 11

S. 12

SP/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S. 14

S. 13

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

Signature

M. HEATH

Title

S.T.

Division

Headquarters

S.O.


Date 11/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____
 REMARKS

Index File No. **2159** T. **18** S., R. **10** E., W.M.

Tract or Surv. No.

Cor. **J-21**

USDA-FOREST SERVICE

Index

File No. 2559T. 18 S. R. 10

E. R.D.

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No. J-25Merid. WILLAMETTEN.F. DESCHUTESCounty DESCHUTESState OREGONSE COR. of SEC. 12NW COR. of SEC. 18

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

Searched For Nothing Found

SEE J-1 T18S R11E WH 4/97

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S.E.-N.F.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

Corner Legend:

☒ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

Signature

D.E.P

Title

Division


Headquarters BENDDate 5/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATE



ACCESSORIES DESCRIBE NEW B's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

REMARKS


Index File No. **2559 T. 18 S., R. 10 E., W.M.**

Tract or Surv. No.

Cor. **J-25**

Index
 File No. 0961
 T 18 S. R. 10 E. R.D. Bend County Deschutes Survey No. 3011 Contract or 000572 Cor. No. 1-09
 Merid. Willamette N.F. Deschutes State Oregon Section 16-17
 (Ref. FSM 7151.4)

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

SFNF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____

Signature

CORNER LEGEND:

FS or Unverified
 Contr. Other
☐ ☐ Searched For/Not Found
☒ ☒ Evidence Found/Accept.
☒ ☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From "Swede Shelter" go East on
 Skyliner's trail 500'±; thence South
 on posted line 200'± to corner.

Searched By: J. L. ColvinTitle LS Division

Headquarters


Date 6/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" Alum. capped Alum. pipe
 rising 4". No stones available.

MONUMENT STAMPED



9

ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

11" Fir Brs. S20°E 7^{85'} to 60-D in W base, MKD. 1/4 516 BT.
 6" LP Brs. N57°W 23^{3'} to 60-D in SW base, MKD. 1/4 517 BT.
 Line posted North & South from corner.

10

Work Done By

Title

Date

State Registration No
or Agency

Estate of

Cor Record Prepared? Yes ☒ No

Filed At

Dechler Co.

Surveyor's Office

Date 1985

11

History

of

Surveys,

G.L.O.,

etc.

G.L.O. - Post & 2 BTs.

12

Index File No. 0961 T. 18 S., R. 10 E., W.M.

Contract

or Surv. No

3011


Cor. L-09

13

Index
File No. 1362 1361 CORNER RECORD (SEARCH) Contract or 000572
(Ref. FSM 7151.4) Survey No. 3011 Cor. No. E-13
T 18 S. R. 10 E. R.D. Bend County Deschutes 1/4 Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 15-16

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



SFNF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

Old fire area. All down trees in search area badly decomposed. Little hope of recovery. Set corner at proportionate position.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From junction of Rds. 4615-254 & 4615-258; West on 254 200'±; thence South 1150' to corner. Line posted from Rd. 254.

CORNER LEGEND:

FS or Unverified
Contr. Other
☐ ☐ Searched For/Not Found
☒ ☒ Evidence Found/Accept.
☒ ☒ Permanent Mon. Set/Fd.


Searched By: A. C. Smith Title LS Division _____ Headquarters _____ Date 6/85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" Alum. capped Alum. mon-
ument rising 5". No stones available
Line posted N & S from corner.

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" P.P. Brs. S 44° W 26' to 60-D in ~~SE~~^S base, mrd. 1/4 S16 BT.
6" L.P. Brs. N 63 1/2° E 22' to 60-D in NW base, mrd. 1/4 S15 BT.

10

Work Done By J. Cohen Title LS Date 6/85 State Registration No. OR-1020
or Agency

Plat. or Cor Record Prepared? Yes ☒ No Filed At Dartmouth Co. Surveyor's Office Date 1985

11

History G.L.O. - Post & 2 BTs.
of
Surveys,
G.L.O.,
etc.

12

Index File No. 1361 T18 S., R10 E., W.M.

Contract or Surv. No 3011

Cor. L-13

13

USDA-FOREST SERVICE

Index

File No. 2561

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No. L-25T. 18S. R. 10

E.

R. D. BENDCounty DESCHUTESE/4COR. of SEC. 18Merid. WILLAMETTEN. F. DESCHUTESState OREGONW/4COR. of SEC. 18

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

Searched For Nothing Found.Shewlin-Hixon BOSP 12/97

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S.F. N.F.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

See: ~~1811~~ ~~L-25~~ 001001 (12/97)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Title

Division

Headquarters


BENDDate 5/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



ACCESSORIES DESCRIBE NEW B^Y'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By

PLAT PREPARED OR

Certified Cor Record Prepared ? Yes

Title

No

Filed At

Date

State Registration No.

or Agency

Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No. 2561 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. L-25

Index

File No. 0963

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or 000572

Cor.

No. N-09T 18 S. R. 10 E.R.D. BendCounty DeschutesSurvey No. 3011

SW Cor. of

Merid WillametteN.F. DeschutesState OregonSection 16

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

17 16

Alum. pipe capped
Alum. pipe rising 3".

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

4" Fir Bts. N 13 1/2° E 24 1/2'
3" Fir Bts. N 80° W 12 1/2'

SE & SW Bts. standing but dead.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Yd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: _____

Title _____

Division _____


Headquarters _____

Date _____

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

4" Fir Brs. $552^{\circ}E$ 23° $4'$ to 60-0 in SW base, mkd. X BT.
 3" Fir Brs. $524^{\circ}W$ 38° $5'$ to 60-0 in NW base, mkd. X BT.
 Line posted North and East from corner.

10

Work Done By J. L. Cohen Title LS Date 6/85 State Registration No. OR-1020
 or Agency

Plat of Cor Record Prepared? Yes ☒ No ☐ Filed At Debut Co. Surveyor's Office Date 1985

11

History of Surveys, G.L.O., etc. G.L.O. - Past 4 BTs.
R. Oman - Perpetuation, 1982 - 2 new BTs.

12

Index File No. 0963 T. 18S., R. 10E., W.M. Contract or Surv. No 3011 Cor. N-09

13

Index

File No. 1363

CORNER RECORD (SEARCH) Contract or

000572

(Ref. FSM 7151.4)

Survey No. 3011

Cor.

No. N-13T 18 S. R. 10 E. R.D. BendCounty DeschutesMerid. WillametteN.F. DeschutesState Oregon

Sec. Cor. of

Section 15-16-21-22

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

Rd. 4615-200

None

N

16

15

900'

21

22

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NW BT---Dead, down & rotten. Found BT brand
with markings "516 BT" Visible. NE, SE
& SW BTs dead, down & decomposed.
Old blazed line trees found South and
East.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 4615, West on Rd. 4615-200 0.8 mi.
thence South on posted line 900' to
corner.

Searched By: J. ColvinTitle LS Division

Headquarters


Date 1985

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" Alum. capped Alum. pipe
 rising 4". No stones available.

MONUMENT STAMPED



9

ACCESSORIES. DESCRIBE NEW BT $\frac{1}{2}$ WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

13" Fir Brs. N39°E 29' ⁸ to 60-D in NW base, MKD. TIBS RIDE S15 BT
 6" Fir Brs. S81°E 39' ⁰ to 60-D in N base, MKD. TIBS RIDE S22 BT
 4" LP Brs. S80°W 7' ³ to 60-D in N base, MKD. X BT.
 6" LP Brs. N34°W 3' ⁵ to 60-D in NE base, MKD. TIBS RIDE S16 BT

10

Work Done By J. C. Cline Title LS Date 5/85 State Registration No. or Agency OR-1020

Flat of Cor Record Prepared? Yes ☒ No ☐ Filed At Deschutes Co. Surveyor's Office Date 1985

11

History of Surveys, G.L.O., etc.
G.L.O. - Post & 4 BTs.

12

Index File No.

1363

T18 S., R. 10 E., W.M.

Contract or Surv. No 3011

Cor. 14-13 13

Index

File No. 1763

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.

No. N-17T 18S R. 10ER.D. BENDCounty DES.SE Cor. of Sec. 15Merid. WILL.N.F. DES.State OR.NE Cor. of Sec. 22

CORNER DIAGRAM

S.15

S.14

N

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 2NW: ROTTED LOG, FOUND BOTH BLADES IN DEBRIS; UPPER BLADE BURNT, WITH
AXE MARKS, LOWER BLADE, VIS.: bNE: STUMP HOLE IN LOCATIONSE: ROTTED LOG, FOUND UPPER BLADE IN DEBRIS, VIS.: T185 523SW: ROTTED WOOD IN LOCATIONDESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 3ON A SE SLOPE ABOUT 460 FT. NORTH OF A SECTION LINE POSTER
ON THE SOUTH SIDE OF A JEEP TRAIL NEAR THE BOTTOM OF
A DRAW.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature

R.OMAN

Title

PLS

Division

CADAST./S.O.

Headquarters

DES. N.F./BEND


Date

10/82

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 SET 2 1/2" X 30" ALUMINUM-CAPPED ALUMINUM PIPE, RISING 2"
 ABOVE GROUND. STAMPED AS SHOWN.



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 12" P. PINE N 51 1/4° W 41.18 FT TO A 60 D NAIL IN THE BASE, MARKED T185 R10E 515 BT.
 A 10" P. PINE N 22° E 5.64 FEET TO A 60 D NAIL IN THE ESE BASE, MARKED T185 R10E 514 BT
 AN 18" P. PINE 514° E 34.10 FEET TO A 60 D NAIL IN THE INSW BASE, MARKED T185 R10E 523 BT
 A 12" P. PINE S 65 3/4° W 31.18 FEET TO A 60 D NAIL IN THE NW BASE, MARKED T185 R10E 522 BT

10

Work Done By. R. OMAN Title PLS Date 10/82 State Registration No. OR. PLS 702
 or Agency
 Certified Cor. Record Prepared? ☒ No Filed At: DESOH. CO. SURV. OFFICE Date 10/82

11

REMARKS

12

Index File No. 1763 T. 185 R. 10E M. WILL

Tract or Surv. No.

Cor. N-17

13

USDA-FOREST SERVICE

Index

File No.

T.

S. R.

E. R.D.

Merid. WILLAMETTE

N.F. DESCHUTES

County

DESCHUTES

State

OREGON

Tract or

Survey No.

Cor.

No.

N-19

COR. of SEC.


A

COR. of SEC.

23

CORNER DIAGRAM PER LEGEND

S.14



J.23

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept☐ Permanent Monument

Signature

M. HEATH

Title

S.T.

Division

Headquarters

S.O.

Date

4/81

D-7100-52 (3/79)

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

1 BT


20" LOG, BURNED, BOTH BLADES BUT
SCRIBING ILLEGIBLE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By

PLAT PREPARED OR

Certified Cor. Record Prepared ? Yes

No

Filed At:

REMARKS

Title

Date

State Registration No.
or Agency

Co. SURVEYOR'S OFFICE Date

Index File No. **1963 T. 18 S., R. 10 E., W.M.**

Tract or Surv. No.

Cor. **N-19**

Index
File No. 2163

Index
File No. 2163

T. 18 S. R. 10

Merid. WILLAMETTE

CORNER DIAGRAM PER LEGEND

S.14

3.7-

[illegible]

100

100

23 5.24

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature 7

Inner Legend:

Searched for/Not Found

Evidence Found/Accent

Permanent Member

Permanent Monument

Signature _____

M. HEATH

.....

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or
Survey No.

Cor. No. N-21

COR. of SEC.

COR. of SEC.

R.D. BEND County DESCHUTES
N.F. DESCHUTES State OREGON

DESCRIBE CORNER MONUMENT FOUND

M.D. / STONES

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

40" Ø x 2' HI. STUMP (S.13) TOE BLAZE, NO SCR.
30" Ø x 4' HI. STUMP (S.24) BURNT, TOE BLAZE, SCR.
LOG, DETAILING (S.23) SCR VIS: RILE 3 BT

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Title S. T.

Division


Headquarters S.O.

Date 11/81 D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: Co. SURVEYOR'S OFFICE Date

11

REMARKS

Index File No. 2163 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. N-21

USDA-FOREST SERVICE

Index

File No.

2363

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No.

N-23

T. 18 S. R. 10 E.

R.D. BEND

County

DESCHUTES

S/4

COR. of SEC. 13

Merid. WILLAMETTE

N.F. DESCHUTES

State


OREGON

N/4

COR. of SEC. 24

CORNER DIAGRAM PER LEGEND

S. 13



S. 24

DESCRIBE CORNER MONUMENT FOUND

SF/NF.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept☐ Permanent Monument

Signature

J. CHAMBERLIN

Title

S.T.

Division

Headquarters

S.O.

Date


11/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 PLAT PREPARED OR
 Certified Cor. Record Prepared ? Yes No Filed At: Co. SURVEYOR'S OFFICE Date

11

REMARKS

Index File No. 2363 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. N-23

12

13

Index

File No. 0963

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. N-09T 185 R. 10ER.D. BENDCounty DES.Merid. WILL.N.F. DES.State OR.SW Cor. of Sec. 16NW Cor. of Sec. 20

CORNER DIAGRAM

S.17

S.16

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NE: ROTTED LOG IN LOCATION

NW: 7" LODGEPOLE PINE, DEAD & DOWN, VIS.: T185 S17 BT

SW: 14" LODGEPOLE PINE, VIS.: 10E S20

SE: 14" LODGEPOLE PINE, SCRIBING VISIBLE BUT ILLEGIBLE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

R. OMAN

Title

PLS

Division

CADASTRAL

Headquarters

DES. N.F. 120/BEND

Date

10/82


FS-7100-52 (3/68)

4

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" ALUMINUM-CAPPED ALUMINUM PIPE RISING 3" ABOVE GROUND LEVEL IN A PINE BEETLE KILL AREA. STAMPED AS SHOWN:



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 4" WHITE FIR BEARS N 13 1/2° E 24.70 FT. TO A 60D NAIL IN THE WNW BASE, MARKED X BT
 A 3" WHITE FIR BEARS N 80° W 12.41 FT. TO A 60D NAIL IN THE S BASE, MARKED X BT
 A 14" LODGEPOLE PINE BEARS S 08 1/4° W 16.40 FT. TO A 60D NAIL IN THE W BASE, (ORIGINAL BT)
 A 14" LODGEPOLE PINE BEARS S 24 1/2° E 24.00 FT. TO A 60D NAIL IN THE SW BASE, (ORIGINAL BT)
 ALL HAVE BRASS WASHERS DENOTING L.S. REGISTRATION NUMBER ON THE 60D NAILS.

10

Work Done By. R. OMAN Title P.L.S. Date 10/82 State Registration No. or Agency OR. PLS 702

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: DESCH. CO. SURV. OFFICE Date 10/82

11

REMARKS

Index File No. 0963 T. 185 R. 10E M. WILL

Tract or Surv. No.

Cor. N-09

12

13

Index

File No. 1163

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. _____

Cor.

No. N-11T 185 R. 10ER.D. BENDCounty DES.Merid. WillN.F. DES.State OR.S/4 COR. OF S. 16N/4 COR. OF

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NE: 12" LODGEPOLE PINE SNAG, VIS.: 1/4 S BT

EE: 13" LODGEPOLE PINE, DEAD & DOWN, CAT FACES, SCRIBING NOT
VISIBLE.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

ABOUT 300 FEET NORTH OF THE NORTH EDGE OF A CLEARCUT
UNIT ABOUT MIDWAY ALONG ITS NORTH BOUND.

Signature

R. OMAN

Title

PLS

Division

CADAST./SO

Headquarters

DES. NF./BEND

Date


10/82

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS-CAPPED STEEL PIPE RISING 3" ABOVE
GROUND LEVEL.



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 4" WHITE FIR BEARS S 25 1/4° E 6.38 FT. TO A 60D NAIL IN THE SW BASE, MARKED X BT
A 4" WHITE FIR BEARS N 49° W 22.28 FT. TO A 60D NAIL IN THE NE BASE, MARKED X BT

10

Work Done By. R. DMAN Title PLS Date 10/82 State Registration No. or Agency OR. PLS 702
Certified Cor. Record Prepared? ☒ Yes No Filed At: DESCA. CO. SURV. OFFICE Date 10/82

11

REMARKS

12

Index File No. 1163 T. 185 R. 10E M. WILL. Tract or Surv. No. Cor. N-11

13

USDA-FOREST SERVICE

Index

File No. 1363T. 18 S. R. 10 E. R.D. BENDMerid. WILLAMETTE

CORNER DIAGRAM PER LEGEND




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☒ Searched for/Not Found☒ Evidence Found/Accept☒ Permanent MonumentSignature LP

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. N-13

County

DESCHUTES

State

OREGONCOR. of SEC. 16COR. of SEC. 22

DESCRIBE CORNER MONUMENT FOUND

S F N F

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S F N FOld fire area

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Title S.T.

Division


Headquarters

S.O.Date 8/84 7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: Co. SURVEYOR'S OFFICE Date _____

REMARKS

Index File No. 1363 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. N-13


File No. 1563T. 18 S. R. 10 E. R.D. Bend

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or
Survey No. _____Cor.
No. 14-15Merid. WILLAMETTEN.F. DESCHUTESCounty Deschutes5/4 COR. of SEC. 15State OREGONN/A COR. of SEC. 22

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

S F X F

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S F N F

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature LPTitle S.T.

Division _____


Headquarters _____

S.O.Date 8/81 D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. PLAT PREPARED OR Title Co. SURVEYOR'S OFFICE Date 1963 State Registration No. 1563
 Certified Cor. Record Prepared ? Yes ☐ No ☐ Filed At: Co. SURVEYOR'S OFFICE Date 1963

REMARKS

Index File No. 1563 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.


Cor. N-15

LAND CORNER RECORD

N-25 5680-2

1. T. 18S, R. 10E No. N-25 Cor. 7 Mer. Will State OREGON N. F. DESCHUTES Dist. BEND

2. Corner Status



7. Photo Identification

Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation

Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

BCSP (12/97)

5. Investigation Notes:

Brass Cap and Metal Pipe set and established by
Brooks Scanlon Inc. (or Shevlin-Kinon?)

5/81: SF/NF by H.C.P.

ALSO SEARCHED BY RICH.
REO
STEVE CHAMBERLAIN
ET AL

See: 18/11 N-01 001004 # (12/97)

6. Signed D.C. Hansen Title Forester Date 1-24-61

PERPETUATION RECORD

10. Monument:

11. Accessories

		Field Book	Page
12. Set By	Title	13. Recorded By	Volume
License	Agency	(Agency)	Page
Date		(Date)	(City)
		(County)	(State)

14. Remarks:

USDA-FOREST SERVICE

Index

File No. 0965T. 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

R.D. BENDN.F. DESCHUTES

Tract or

Survey No.

County DESCHUTESState OREGON

Cor.

No. P-09COR. of SEC. 20COR. of SEC. 21

CORNER DIAGRAM PER LEGEND

S. 20



S. 21

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept☐ Permanent Monument

Signature

S. CHAMBERLIN

Title

S.T.

Division

Headquarters

S.O.


Date 9/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By.

Title

Date

State Registration No.
or Agency

PLAT PREPARED OR
Certified Cor. Record Prepared ? Yes

No

Filed At.

Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No.

0965 T. 18 S., R. 10 E., W.M.

Tract or Surv. No


Cor. P-09

USDA-FOREST SERVICE

Index

File No. 1365T. 18 S. R. 10 E. R.D. BendMerid. WILLAMETTEN.F. DESCHUTESCounty DeschutesState OREGONTract or
Survey No. _____Cor.
No. P-13COR. of SEC. 21COR. of SEC. 22

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

S F N F ✓

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S F N F ✓

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☐ Evidence Found/Accept.☐ Permanent Monument

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature SP R.T.

Title

S.T.

Division

Headquarters

S.O.


Date

8/8/07 6/82 100-52(3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared ? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

11

REMARKS

12

Index File No. **1365 T. 18 S., R. 10 E., W.M.**

Tract or Surv. No.

Cor. **P-13** 13

USDA-FOREST SERVICE

Index

File No. 1765T. 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No. P-17R.D. BEAD


County

DESCHUTESN.F. DESCHUTES

State

OREGONCOR. of SEC. 22COR. of SEC. 23

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

SP/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent MonumentSignature
S. CHAMBERLIN

Title

S.T.

Division

Headquarters


S.O.Date 11/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STARTED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By
PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No

Title
 Filed At.

Date

State Registration No.
 or Agency

Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No. **1765 T. 18 S., R. 10 E., W.M.**

Tract or Surv. No.

Cor. **P-17**

USDA-FOREST SERVICE

Index

File No.

T. 18 S. R. 10 E. R.D. BENDMerid. WILLAMETTEN.F. DESCHUTES

County

DESCHUTES

State

OREGONTract or
Survey No.Cor.
No.P-21

COR. of SEC.

23

COR. of SEC.

24

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

Signature

S.C./M.H.

Title

S.T.

Division

Headquarters

S.O.


Date

11/81 D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT SET



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By

Title

Date

State Registration No.
or Agency

PLAT PREPARED OR
Certified Cor. Record Prepared? Yes

No

Filed At

Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No

2165

T.

18 S., R.

10

E., W.M.

Tract or Surv. No.

Cor.


P-21

USDA-FOREST SERVICE

Index

File No. 2565T. 18 S. R. 10 E. R.D. BENDMerid. WILLAMETTEN.F. DESCHUTESCounty DESCHUTESState OREGONTract or
Survey No.Cor.
No. P-25Cor. of SEC. 24COR. of SEC. 19

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

SF/NFShevlin-Hixon BCSA 12/97

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

See: ~~P 01 18/11~~ 001004 # 12/97For UpdateSignature
S. CHAMBERLINTitle
S.T.


Division

Headquarters
S.O.Date 11/81 D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT - DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STARTED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By

PLAT PREPARED OR

Certified Cor. Record Prepared ? Yes

Title

No

Filed At

Date

State Registration No.
or Agency

Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No.

2565 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.


Cor.

P-25

USDA-FOREST SERVICE

Index
File No. 1367T. 18 S. R. 10 E. R.D. Bent County Deschutes SE Cor. of SEC. 21
Merid. WILLAMETTE N.F. DESCHUTES State OREGON NW Cor. of SEC. 27

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

S.F.M. ✓

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S.F.M. ✓

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____


Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent MonumentSignature JP LP R.T. Title S.T. Division _____ Headquarters S.O. Date 8/80 6/82 7700-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared ? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

11

REMARKS

12

Index File No. **1367** T. **18** S., R. **10** E., W.M.

Tract or Surv. No.

Cor. **R-13** 13

USDA-FOREST SERVICE

Index

File No.

T. 18 S. R. 10 E.Merid. WILLAMETTE

CORNER DIAGRAM PER LEGEND

S.22

N

S.27

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No.

R.D. BEND County DESCHUTESN.F. DESCHUTES State OREGONCOR. of SEC. 22COR. of SEC. 27

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

SC/MH

Title

ST

Division

Headquarters


SO

Date 4/8/00 D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATED



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: Co. SURVEYOR'S OFFICE Date

11

REMARKS

Index File No. 1567 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. R-15

12

USDA-FOREST SERVICE

Index

File No.

T. 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No.

R.D. BEND

County


DESCHUTESN.F. DESCHUTES

State

OREGONSECOR. of SEC. 22NWCOR. of SEC. 26

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept☐ Permanent Monument

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

S. CHAMBERLIN

Title

S.T.

Division

Headquarters

S.O.

Date


11/61

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

PLAT PREPARED OR
Certified Cor. Record Prepared? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

REMARKS

Index File No. **1767** T. **18** S., R. **10** E., W.M.

Tract or Surv. No.

Cor. **R-17**

USDA-FOREST SERVICE

Index

File No. 1967T. 18 S. R. 10Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

E. R.D. BENDN.F. DESCHUTES

Tract or

Survey No. _____

County DESCHUTESState OREGON

Cor.

No. P-19COR. of SEC. 23COR. of SEC. 26

CORNER DIAGRAM PER LEGEND

S. 23

N

S. 26

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

S. CHAMBERLIN

Title

S.T.

Division

Headquarters

S.O.


Date 1/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT SET



ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No. 1967 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. R-19

USDA-FOREST SERVICE

Index

File No. 2167T. 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No. P-21R.D. BEND

County


DESCHUTES

State

OREGONCOR. of SEC. 23COR. of SEC. 25

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

15" X 4' STUMP SCR. VIS: TIBS S25 BT24" ROTTING STUMP w/ BT BLADE, SCR. ILLEG.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

Signature

S. CHAMBERLINTitle S.T.


Division

Headquarters S.O.Date 4/81 D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

REMARKS

Index File No. **2167 T. 18 S., R. 10 E., W.M.**

Tract or Surv. No.

Cor. **R-21**


USD -FOREST SERVICE D-7100-52(2/82)

Inde
File **2167**T **18 S. R. 10 E. R.D. Bend**Mer **id. Willamette**N.F. **Deschutes**Contract or
Survey No. **Deschutes**Cor.
No. **R-21**

NW Cor. of

CORN E R DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND



A depression in the original post position, determined by the best fit from available evidence.

SCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

- Remains of a pine at NE BT location. N.28°E. 33 lks.
- A stump hole, N.72°W. 34 lks.
- A pine stump, 5' high, 18" dia., S.66°W. 61 lks. with face and scribing visible.
- A pine windfall, 20" dia. S.56°E. 19 lks. with face and scribing visible.
- A location poster on spur road 2 chs. West.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

MAG. DECL. 17° East

Bearings by Hand Compass

Mapping Grade GPS

Differentially corrected

NAD 7 ORE S. Zone Coords.

N = 849591

E = 740926

el. = 4932 ft. MSL

CORNERS LEGEND:

FS or Contr -

Unverified

Other

Searched For/Not Found

Evidence Found/Accept.

Permanent Mon. Set/Pd.

Searched By:

William B. Ham

Title

ALS

Division

CS

Headquarters

SO

Date


6/2001

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

- Set a 2 1/2" dia. x 30" long Steel pipe surmounted by a 2 1/2" dia. brass cap rising 6". A penny at base of pipe. A steel fence post 3 ft. North.
- A Lodgepole Pine 7" dia., N.39°E., 30.6 ft., mkd. X BT.
- A Ponderosa Pine 8" dia., S.62°E., 27.7 ft., mkd. X BT.
- A Grand Fir 8" dia., S.71°W., 26.9 ft., mkd. T18S R10E S26 BT.
- A Ponderosa Pine 13" dia., N.62°W., 31.3 ft., mkd. T18S R10E S23 BT.
- A 1" dia. brass washer mkd. LS 2396 nailed to the blaze between the B & T of the scribing.
- Distances measured to side center at the root crown.

MONUMENT STAMPED



RESERVE EXISTING EVIDENCE

Work Done By Bill Ham Title PLS Date 6/20/01 State Registration No. 2396
 Certified or Cor. Record Prepared? Yes No Filed At Des Co. Surveyor's Office Date

History of Surveys, G.L.O., etc.
 GLO survey of 1880 by Thompson, Meldrum and Moore under Contract # 345.
 Set post for corner to secs. 23, 24, 25 & 26, from which:
 A Pine 16 in. diam. bears N.25°E. 33 lks. dist.
 A Pine 16 " " " N.70°W. 35 " "
 A Pine 20 " " " S.69°W. 60 " "
 A Pine 24 " " " S.62°E. 18 " "

Index File No. 2167 T. S., R. E., W.M. Contract or Surv. No. R-21

Cor. 13

Index


File No. 2567

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. R-25T 185 R. 10ER.D. BENDCounty DES.SE COR. of SEC. 24Merid. WILLN.F. DES.State OR.NW COR. of SEC. 30

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND A 3" SHEVLIN-HIXON BRASS CAP ON A 1 1/4" X 42" PIPE PROTECTING 18" OUT OF GROUND, BADLY BENT OVER ... APPARENTLY RUN OVER BY TRACTOR. ORIGINAL STONE NOT IN SIGHT.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
ABOUT 107 FEET NORTH OF A MARKER ON THE SOUTH SIDE OF SPUR #6.

Signature

R. OMAN

Title

PLS

Division

CAPAST/S.O.

Headquarters

DES. N.F./BEND

Date

10/82


FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

STAMPED:

SET A 2 1/2" X 30" BRASS-CAPPED STEEL PIPE IN THE CENTROID
OF THE HOLE WHERE THE CONKLIN MONUMENT EMANATED FROM THE
GROUND.



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 10" PONDEROSA PINE N 81 3/4° W 31.56 FT. TO A 60D NAIL IN THE S. BASE, MARKED T185 RIDE S24 BT
A 12" PONDEROSA PINE N 17 1/2° E 29.78 FT. TO A 60D NAIL IN THE W. BASE, MARKED T185 R 11 E 519 BT
A 12" PONDEROSA PINE S 82 3/4° E 14.81 FT. TO A 60D NAIL IN THE S. BASE, MARKED T185 R 11 E S30 BT
A 9" PONDEROSA PINE S 35° W 9.62 FT. TO A 60D NAIL IN THE NW BASE, MARKED T185 RIDE S25 BT

10

Work Done By. R. OMAN Title PLS Date 10/02 State Registration No. CR. PLS 702
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Date

11

REMARKS

See: 001004 # 12/97 for update.

12

Index File No. 2567 T. 185 R. 10E M. WILL Tract or Surv. No. Cor. R-25

13

Index

File No.

1369

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

T-13

T 185

R.

10E

R.D.

BEND

County

DES.

Merid.

WILL

N.F.

DES.

State


OR.

E/4 COR. of Sec. 28

W/4 COR. of Sec. 27

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SE: ROOTS AND DEPRESSION IN LOCATION

SW: BADLY ROTTED LODGEPOLE PINE, SCRIBE BLADES, VIS.: 1/4 S BT

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

ABOUT 250 FT. EAST OF A MARKER ON FOREST ROAD # 1826

Signature

ROMAN

Title

PLS

Division

CADAST./S.O.

Headquarters

DES. N.F./BEND

Date


10/82

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS-CAPPED STEEL PIPE RISING 2" ABOVE GROUND.



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 5" LODGEPOLE PINE N80°W 18.08 FEET TO A 60D NAIL IN THE S. BASE, MARKED E/4 S28 BT

A 5" LODGEPOLE PINE N80 3/4°E 15.10 FEET TO A 60D NAIL IN THE S. BASE, MARKED W/4 S27 BT

10

Work Done By R. OMAN Title PLS Date 10/82 State Registration No. or Agency OR. PLS 702

Certified Cor. Record Prepared ? ☒ Yes ☐ No Filed At: DESCH. CO. SURV. OFFICE Date 10/82

11

REMARKS

12

Index File No. 1369 T. 185 R. 10E M. WILL. Tract or Surv. No.

Cor. T-13


13

LAND CORNER RECORD

T-25 5680-2

1. T 18S, R 10E No. T-25 Cor. 1/4 Mer. Will State (Rectangular) OREGON N. F. DESCHUTES Dist. BEND

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

5. Investigation Notes:

Brass Cap and Metal Pipe set and established by
Brooks Scanlon Inc. (or Shulin-Hixon?)

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed D-C Hansen Title Forester Date 1-24-61

PERPETUATION RECORD

10. Monument:

11. Accessories

12. Set By _____ Title _____		Field Book _____ Page _____
License _____	Agency _____ Date _____	13. Recorded By _____ Volume _____ Page _____
		(Agency)
		(Date) (City) (County) (State)

14. Remarks:

USDA-FOREST SERVICE

Index

File No. 1371

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

Cor.

No. V-13T. 18 S. R. 10 E. R.D. BEND County DESCHUTES SE COR. of SEC. 28Merid. WILLAMETTE N.F. DESCHUTES State OREGON NW COR. of SEC. 34

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

J.28

S.27

SE/NF

N



2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NE BT: 14" D&D SCR. VIS.: S2 7' BT

NW BT: STUMP VIS.: BT

J.33

S.34

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

3

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FLAGGING ON RD. 1852, THEN 280' S. TO COR.

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

Signature

R. T. ALLEN Title

S.T. Division

Headquarters

S.D.

Date

10/21/82 6/82 7100-52 (3/79)


S. CHAMBERLIN

S.T.

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT SITED



ACCESSORIES. DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By

Title

Date

State Registration No.
or Agency

PLAT PREPARED OR

Certified Cor. Record Prepared? Yes

No

Filed At

Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No. **1371** T. **18** S., R. **10** E., W.M.

Tract or Surv. No.

Cor. **V-13**

USDA-FOREST SERVICE

Index

File No.

1771

T. 18 S. R. 10 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

V-17

R.D. BEUD County DESCHUTESN.F. DESCHUTES State OREGONSE COR. of SEC. 27
NW COR. of SEC. 35

CORNER DIAGRAM PER LEGEND

S.27

S.26

SF/NF

N

S.34

S.35

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

7

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

Signature

S. CHAMBERLIN

Title

S.T.

Division

Headquarters

S.O.


Date 1/81

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 PLAT PREPARED OR
 Certified Cor. Record Prepared ? Yes No Filed At: Co. SURVEYOR'S OFFICE Date

REMARKS

Index File No. 1771 T. 18 S., R. 10 E., W.M. Tract or Surv. No. Cor. V-17


Index
File No. 2171

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. V-21T 18 S. R. 10 ER.D. BENCounty DESCHUTESSE Cor Sec 26Merid. W NITN.F. DESState ORNW Cor Sec 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

34" PP(Dead) MKD R10E S26 BT

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature O. BEIL

Title

Division


Headquarters

Date 5/51 7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 2171 T. 18^s R. 10^e M.

Tract or Surv. No.

Cor. V-21

USDA-FOREST SERVICE

Index

File No. 1373T. 18 S. R. 10 E. R.D. BENDMerid. WILLAMETTEN.F. DESCHUTES


CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or
Survey No.Cor.
No.X-13County DESCHUTESState OREGONCOR. of SEC. 33W/A COR. of SEC. 34

CORNER DIAGRAM PER LEGEND

S.33



S.34

DESCRIBE CORNER MONUMENT FOUND

SF/NF

RE-SEARCHED 6/82

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

Signature

J. CHAMBERLIN R. TAYLOR

Title

S.T. S.F. Division

Headquarters

S.O.


Date

10/10/82 6/82 D-1100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT SET



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared ? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

REMARKS

Index File No. **1373** T. **18** S., R. **10** E., W.M.

Tract or Surv. No.

Cor. **X-13**

USDA-FOREST SERVICE

Index

File No. 1175T. 18 S. R. 10 E. R.D. BENDMerid. WILLAMETTEN.F. DESCHUTES

County

DESCHUTES

State

OREGON

Tract or

Survey No.

Cor.

No.

Cor. of SEC. 33Cor. of SEC. 3

CORNER DIAGRAM PER LEGEND

T 18 S

33

34

4
T 19 S

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

DESCRIBE CORNER MONUMENT FOUND

SPINE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SW BT Scribed T 19 S 4 BT - Dead & Down 8" LP

No evidence of other BT's

Logged & cat. Piled area

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Flagged line to RD 1834, $\pm 650'$ N of RD.

Signature

GS SC

Title

S.A.

Division

ST

Headquarters

S.O.

Date

8/81


D-110-52 (3/79)

11/81

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STARTED



9

ACCESSORIES DESCRIBE NEW B^{ts} WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

PLAT PREPARED OR
Certified Cor. Record Prepared ? Yes

No Filed At:

Co. SURVEYOR'S OFFICE Date

11

REMARKS

12

Index File No. 1175 T. 18 S., R. 10 E., W.M.

Tract or Surv. No.

Cor. Z-13

13

Index
File No. _____

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)


Tract or
Survey No. _____

Cor.
No. 2-25

T 185 R. 10E R.D. BEND County DES. SE Cor. of Sec. 36

Merid. WILL. N.F. DES. State OR. NE Cor. of Sec. 1

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

S/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

MARKER ON E. SIDE OF ROAD 1830. ILLEGIBLE - CANNOT READ
DISTANCE TO CORNER. PACED EAST 1/2 MILE PER SCALING
ON CONTOUR MAP.

Signature

R. OMAN

Title

PLS

Division

CAPASTRAL

Headquarters

DES. N.F. / BEND

Date

10/82

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. T. 185 R. 10E M. WILL Tract or Surv. No. Cor. Z-25 13