



LEGEND

Corner having information on form 7100-52 in this file.

Legend Confirms to Reporting Form & 3/

FILING INSTRUCTION

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.

CORNER RECORD FILE GUIDE (Rectangular Surveys)

7100-55 (2/67)

usda-Forest Service Index File No. 2155	CORNER RECOR		Tract or Survey No	Cor. No. E-21
T RIS R. 6 E.	R.D. <u>Bend</u>	County	Deschutes	NW Sec. 12
Merid. WMT	N.F. Deschutes	State	OR	
CORNER DIAGRAM	DESCRIBE CORNER MONUN	ENT FOUND		
ORIGH X ORIGH	SF/NF			
ORIG BT SEBT	DESCRIBE BEARING TREES	٠		
PHOTO IDENTIFICATION DI A 23" . Photo No. A 15"	fir snag bears N69°E a! 1 fir snag (burnt) bears S3 fir snag bears N18°W at 9 was decayed and rotted ma	0°W at 19.0 f .6 feet with	eet, with scribing v a healed over blace.	ze and scribing visible. isible.
Object Ident. Ident. By Signature				LSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA				
State Zone Zone				
Estob. By	B			4
Signature Walt Miller	Title Division PLS CS			dte FS-7100-52 (3/68) 5

USDA-FOREST SERVICE				
Index File No. 2155	CORNER RECO	RD (SEARCH) 5M 7151.4)	Tract or Survey No	Cor. E-2
T & L S R. 6 E.	R.D. Bend		Deschutes	NW Sec. 12
Merid. WMT	N.F. <u>Deschules</u>		OR_	
CORNER DIAGRAM S2 51 + NEW	DESCRIBE CORNER MONU	JMENT FOUND		
ORIG X X ORIG	SF/NF		, <u>, , , , , , , , , , , , , , , , , , </u>	
* * * * * * * * * * * * * * * * * * * *	DESCRIBE BEARING TREES	S OR OTHER OFFIC	CIAL ACCESSORIES	POUND
ORIG-BT SEB	/ fir snag bears N69°E at	11.5 feet, with	a chopped open	blaze and scribing visible
	tir snag bears N18°W at	9.6 feet with a	healed over bla	g visible. .ce.
Filed At. There	was decayed and rotted m	naterial in the	SE location.	
Object Ident	_ DESCRIBE CORNER LOCAT	ION RELATIVE TO	NEAR-BY FEATURE	S, ALSO HOW TO REACH CORNE
Ident. By				
Signature				
PLANE COORDINATE POSITION DATA				
State Zone				
🗶 <u>vidamina militari (</u>				
Estab. By				
Signature	Title Divis		quarters	Doțe FS-7100-52 (3/68
Walt Miller	PLS C	ع الله الله الله	0	9/99

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT I eastablished the corner using record bearing and distances from the original calls because some distances did not intersect. I further used the faces of the blaze to pull distances as this made for a tighter pattern from which to set the new monument.

PLS 2111 1999

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I set a $2\frac{1}{2}$ " X 30" Aluminum Capped Aluminum Pipe Rising 2 " above ground in a rock collar from which I established 2 new accessories being: A 5" Fir bears S59°E at 79.0 feet, marked X BT A 23" Fir bears N49°E at 64.7 feet, marked T21SR6ES1BT.

The Meander Corner to Sections 1 and 12 on the West end of Lily Lake bears S87°E at 53.9 feet and is marked with a $2\frac{1}{2}$ " X 30" Aluminum Capped Aluminum Pipe.

Work Done By. Walt Miller Tifle PLS State Registration No. 2111 Filed Al: Deschutes Certified Cor. Record Prepared 7 Yes HISTORY OF ORIGINAL CORNER AND / OR PREVIOUS RENEWALS: 7/11/1884 - H. Perkins, G.L.O. surveyor, under group No. 508, subdivided T21S, R6E and set

the section corner common to sections 1, 2, 11, and 12 as follows: Set a post 4 ft. long 4 ins. square 24 ins. in the ground for cor. to secs. 1,2,11 and 12 marked. T.21S. S.1 on NE. R.6E. S.12 on S.E. S.11 on S.W. and S.2 on the N.W. faces with 5 notches on S. and one notch on E. edges from which.

GPO: 1986 0 - 439-095

A fir 12 in. diam. bears N.70°E. 17 lks. dist. marked T.21S.R.6E.S.1 B.T. A fir 16 in. diam. bears S.56°E. 27 lks. dist. marked T.21S.R.6E.S12 B.T. A fir 24 in. dism. bears S.30°w. 27 lks. dist. marked T.21S.R.6E.S.11 B.T.

Index File No. fir 12 in. diam. bears N.26°W. 13 Iks. dist. maRKED T.21S.R.6E. S.2 B.T.

2155

USDA-FOREST SERVICE			
Index File No.	CORNER RECORD		
	R.D. Bend (Ref. FSM)	County <u>Deschu</u>	
Merid. With	N.F. Deschutes	State OR	15 Me 181 3C 1/1=
DUAL PART DIAGRAM Lily Lake DUAL Pateronacy OFIGE 11 112 DUAL PART BT > 6 PHOTO IDENTIFICATION DATA Photo No.	DESCRIBE CORNER MONUME	NT FOUND 11.9 feet, standing de	ad tree with a healed over blaze. ad tree with a healed over balze.
Filed At. Object Ident. Ident. By	DESCRIBE CORNER LOCATION	RELATIVE TO NEAR-BY F	EATURES, ALSO HOW TO REACH CORNER
Signature 7 7 7 7 7 7 7 7 7			
Signature Walf Miller	Title Division		Date 9/99 FS-7100-52 (3/68)

Norway (new

CORNER RECORD (PERPETUATION) MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Using a distance-distance intersection with record GLO distances from the faces of the original bearing trees; I set a $2\frac{1}{2}$ " X 30" Aluminum Capped Aluminum Pipe flush in the ground 1 foot from the west bank of Lily Lake, in a small rock collar...

T21S **S1** MC **S12** R6E PLS 2111 1999

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

The Section Corner common to Sections 1, 2, 11, and 12 bears N87°W at 53.9 feet. (GLO Record is N89° 41'W at 87 lks. or 57.4 feet.)

Due to fire in the area of the corner as well as bug kill, there were no available trees to blaze and scribe to replace the dead original trees. I therefore will call the two new trees that were scribed for the section corner of sections 1, 2, 11, and 12 as follows: A 23" fir bears NO7°W at 45.1 ft., marked T21SR6ES1BT. (This BT References the Sec. Cor.) A 5" fir bears S21°E at 39.8 ft., marked X BT (BT references the Sec. Cor.)

Work Done By Walt Miller 69 State Registration No. 2111 Certified Cor. Record Prepared 7 Yes No Filed At: Deschite Country Date REMARKS

7/11/1884 - H. Perkins, G.L.O. surveyor, under Group No. 508, subdivided T21S,R6E and set the Meander Corner for Sections 1 and 12 on the West side of Lily Lake as follows: West bank of lake. Set a post 4 ft. long 4 ins. square 24 ins. in the groundfor Meander cor. to fractional secs. 1 and 12 marked. M.C.T.21S. on W. R.6E. S.1 on N and S12 on S faces from which A fir 6 In. diam. bears N.80°W. 101ks. dist. marked T.21S.R.6E. S.1 M.C.B.T. A fir 20 in. diam. bears S.30°W. 18 lks. dist. marked T.21S.R.6E.S.12 M.C.B.T.

Index File No. Т.

Tract or Surv. No. Cor.

21

GPO: 1986 0 - 439 - 095

USDA-FOREST SERVICE Index File No. 2555 T 2 (S. R. 6 F. R.D Merid. WILLAMETTE N.F	CORNER RECORD (SEARCH) ConTract or Survey No	Cor. E-25 No. Cor. of Section 116
		, R. 7 E. W.M.
		(13 M . 9
		1 960

USDA-FOREST SERVICE ,Index File No. T 2/ S. R. 6 Merid. WILLAMETT	2559 E. R.D. 4 E. N.F.		7 15 1 . 4)	Centract or Survey No SESC /+C OREGON	Co N N N N N N N N N N N N N N N N N N N	Cor. of 12/7
		SEE: J		T. 21	s., R. 7	E. W.M.
					- (6	9
						100
					, Co	

Merid WILLAMET	SEE: N-	_ StateOF	REGON 21 S., A	Section	73/18 13/18 4/19 E., W.M.
				2/3/6	F
				Co	

Index File No. 256 T 21 S. R. 6 E. R. Merid. WILLAMETTE N.	D. BEND County	DESCHUTES STD Cor. of
	SEE: <u> R-0/</u>	T. 21 s., R. 7 E., W.M.
		-/6
		Sept 2

Corner Status	3. Original DescriptionVolPageWhere Recorded
36 8 31	4. Description of Corners:
	5. Investigation Notes: No corner monument found.
Photo Identification	14 LOR B.T. FOUND AS DESCRIBED IN FOLLOWING DIAGRAM - ALSO SEE LAND CORNER RECORD FOR SEC COR IN SE COR
lent. By:	$oldsymbol{\lambda}$
Plane Coordinate Position Data	
ateZone	R6E-536 SEC31-R7E
stab. By	NO BTFOUND IN SEL & BT-STANDING DEAD LPP 36 DBH 17"
eld Book No	36 DBH 17"
Evaluation uthentic	
eeds VerifMonument	
e-estabSurvey	6. Signed P. SHOEMAKER Title FORESTER Date 9-21-65
and Status	6. Signed P. SHOEMAKER Title FORESTER Date 9-21-65

2. Corner Status	3. Original DescriptionVol	Page Where Recorded	
292	4. Description of Corners:		
36 31	No corner monument four	ıd	
72/5	5. Investigation Notes: Sec. cor. B. following diagram.	T.'S found as described in the	
7. Photo Identification	R.6E.	R. 7 E.	
dent. By:	Sec. 36 B.T.	Sec. 31 BT - MH - DBH 10.2"	
3. Plane Coordinate Position Data StateZone	leaning dead LP DBH 9.9" ©	0	T2lS
<u>C</u>	0	0	
Y Estab. By Field Book No Where Filed	Sec. 1 BT MH-DBH-14.2"	Sec. 6 BT MH-DBH-14.9"	T22S
O. Evaluation Authentic Needs VerifMonument Re-estabSurvey and Status	6. Signed Philip Shoemake Title	Forester Date 9-21-65	

T. S. R. E. R.D. County Cor. of Merid. WILLAMETTE N.F. DESCHUTES State OREGON Section SEE: T. S., R. E. W.M. SEE: T. S., R. E. W.M.	D-7100 USDA-F Index File No.		CORNER RECORD (Ref. FSM 7) <i>□n</i> Tract or Survey No	Co No	
	T Merid.	S. R. WILLAMETTE	DESCHUTES	OREGON	Section	Cor. of
						E.W.M.