

T 215, R 9E, M 11

LEGEND

○ = Corner having information on form 7100-52 in this file.

LEGEND CONFORMS TO
REPORTING FORM

103/179

FILING INSTRUCTION

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.

US DA-FOREST SERVICE

Index

File No. 1130-0151T 21 S R. 9 EMerid. Wmt

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____

Film and At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Established By _____

Agency _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. A-01R.D. Bend County DeschutesN.F. Deschutes State Oregon NW CC
Sec. 6

DESCRIBE CORNER MONUMENT FOUND

Original corner post, 4 in. below ground, squared off and ending in a point 14 in. down.

A Ponderosa pine, 28 in. dia., S.11°W., 31 lks., with face & scribing visible.

A Ponderosa pine stump, S.76°E., 29 lks., with BT blaze overgrown.

A Ponderosa pine, 19 in. dia., N.49°E., 32 lks., with face and scribing visible.

Distances to original B.T.'s measured to face.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Location Poster on road
13 chains South of corner.
Mag. Dec. 20° E.

Signature

William B. Ham

Title

PLS

Division

CS

Headquarters

SO

Date

6/92

FS-7100-52 (3/68)

3

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

	T20S	
R	<u>331</u>	R
8	C/C	9
E	S11S6	
	T21S	
	PLS 2396	
	1992	

A 2½ in. X 30 in. alum. pipe with alum. cap, set 26 in. in the ground. A penny at base of pipe. A steel fence post bears North, 3 ft.
 Original BT, A Ponderosa pine, 19 in. dia., N.49° E., 21.1 ft. Not re-marked.
 A Ponderosa pine, 28 in. dia, S.49° E., 53.6 ft., marked T21S R9E S6 B T
 Original BT, A Ponderosa pine, 28 in. dia., S.11° W., 20.5 ft. Not re-marked.
 A Grand fir, 8 in. dia., S.51° W., 34.3 ft., marked T21S R8E S1 B T

WORK DONE TO PRESERVE EXISTING EVIDENCE

Bearings by staff compass. Distances to a nail in side of tree.

10

Work Done By William B. Ham Title PLS Date 6/92 State Registration No. 2396
 or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Deschutes Date 6/10/92

REMARKS

GLO survey of 1880 by Thompson, Meldrum & Moore.
 Set post for closing corner to Township 21 S. Range 8 & 9 E. From which:
 A pine 18 in. diam. bears S.10° W. 31 lks. dist.
 A pine 12 " " S.70° E. 29 " "
 A pine 10 " " N.68° E. 32 " "

12

Index File No. 130 0151 T. 21 R. 9 W.M.T. Tract or Surv. No. Cor. A-01
 GPO: 1986 O - 439-095

13

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. A-13T 21S. R. 9E.R.D. BENDCounty DESCHUTESNECN Sec. 4

CC

Merid. WillN.F. DESCHUTESState OREGONNW Sec (or Sec) 3

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

CHARRED 2"x38" WOOD POST SUPPORTED BY A
RED METAL FENCE POST.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

40" P. PINE, S76°E, 29' WITH 33 VISIBLE.

L. PINE APPROX 18" DIA., N. 11°E, 47' 33 VISIBLE
(BLOW DOWN)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

COR. IS 310' E OF SLB ON RD[#] 2021 BETWEEN SECS
4 & 34. S.L.B. STATES COR. (33 & 34) IS 764' WEST

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

O. THINGVALL

Title

CIVIL ENG

Division

Headquarters

S.O.

Date

11/4/69

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

A-13

12

13

Index

File No.

2151

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.
No.

A-21

T 21 S. R. 9 E.

R.D.

BEND

County

DESCHUTES

CC

Merid. Willamette

N.F.

Deschutes

State

Oregon


Section

Cor. of

211

CORNER DIAGRAM, per Legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N BT

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

ca 1968

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Plat of _____
 Certified Cor. Record Prepared? Yes No Filed At _____ Co. Surveyor's Office Date _____

11

History of Surveys, G.L.O., etc. _____

12


Index File No. _____ T. S., R. E., W.M. _____ Contract or Surv. No. _____ Cor. _____

13

Index
File No. 2351
T 21 S. R. 9 E. R.D. BEND County DESCHUTES NW Cor. of 1
Merid. WILLAMETTE N.F. DESCHUTES State OREGON Section 1

SEE: A-01 T. 21 S., R. 10 E. W.M.

B.C/S.P.
~



Index
File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. **B-25**

T 21 S. R. 9 E. R.D. BEND

County DESCHUTES

N/16 Cor Sec 1 & 6

Merid. WILLAMETTE


N.F. DESCHUTES

State OREGON

SEE: B-01

T215 R10E

R9E R10E



T215

BLM
PL 104 1008

B-25

Index
File No. 1353

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.
No. C-13T 21 S. R. 9 E.R.D. Bend

County

DeschutesW 1/4

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 3

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No evidence of original post.

Ponderosa Pine 32" dia. with overgrown face and snow blaze. Set corner at GLO bearing and distance from this tree. Measured distance from the chaining notch.

A Pine windfall, fallen on its face in the NW BT location. I cut the log and exposed the burnt and rotted face.

p MAG. DECL. 17° East

p Bearings by Hand Compass

F Mapping Grade GPS

C Differentially corrected

NAD 27 ORE S. Zone Coords.

N = 779456E = 1698440el. = 4371 ft. MSL

CORNERS LEGEND

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By:

William B. Ham

Title

PLS

Division

CS

Headquarters

SO


Date

7/2001

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



SERVE EXISTING EVIDENCE

9

Set a 2 1/2" dia. x 30" long Alum. Pipe surmounted by a 2 1/2" dia. alum. cap rising 2".
A penny at base of pipe. A steel fence post 4 ft. North.

A Ponderosa Pine 7" dia., N.50°E., 11.0 ft. mkd. 1/4 S3 BT.

A Lodgepole Pine 5" dia., S.76°E., 9.3 ft. mkd. X BT.

A Ponderosa Pine 32" dia., S.61°W., 40.8 ft. Orig. BT, not re-mkd.

A Ponderosa Pine 17" dia., N.65°W., 28.0 ft. mkd. 1/4 S4 BT.

A location poster S.60°E., 90 ft. from cor. on Rd. 4240-100.

A brass washer, 1" dia. mkd. LS 2396 nailed to the blaze between the B & T of the scribing.
Distances measured to the side center at the root crown.

10

Work Done By Bill Ham Title PLS Date 7/17/01 State Registration No. 2396
or Agency

11

Plat. or Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Des. Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

GLO Survey of 1880 by Thompson, Meldrum and Moore under contract # 345.
Set post for 1/4 Sec. corner, from which:
A Pine 30 in. diam. bears S.61°E. 57 lks. dist.
A Pine 30 " N.26°W. 60 "

12

Index File No.

T.

S., R.

E., W.M.

Contract or Surv. No.

Cor.

13

1353

C-13

Index

File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

C-25

T 21 S. R. 9 E.

R.D. BEND

County DESCHUTES

Elk Co. Sec. 1

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

all Cor Sec 6

SEE: C-01

T215 RIDE

BLM
10-1-58

C-25

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. _____

D-25

T 21 S. R. 9 E.

R.D. BEND

County DESCHUTES

5/16 Cor Sec 1 & 6

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

SEE: D-01

T215 R10E

OK by BLM
5/16/88

D-25

USDA-FOREST SERVICE

Index

File No. 1129 0155T 21 S R. 9 EMerid. WMT

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. E-1R.D. Bend

County

DeschutesN.F. Deschutes


State

Oreg.

NW cor

Sec. 7

CORNER DIAGRAM



T21S

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

William B. Ham

Title

PLS

Division

CS

Headquarters

SO

Date

6/92

FS-7100-52 (3/68)

DESCRIBE CORNER MONUMENT FOUND

Found no evidence of original post. From position determined by distance intersect from NE, NW & SW BT's:

A pine windfall, 18" dia., brs. S 12°E, 47 lks. (31.2'), face & scribing visible.

A Ponderosa pine, 33" dia., brs. N 24°E, 32 lks. (21.1'), overgrown face.

A Lodgepole pine, 20" dia., brs. N 18°W, 41 lks. (27.1'), face & scribing visible.

A Ponderosa pine, 19" dia., brs. S 11°W, 38 lks. (25.1'), overgrown face.


I believe the GLO surveyor reversed his brgs. to the NE & NW BT's. I don't know why he was so far off to the SE BT.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

A 2½" X 30" alum. pipe with alum. cap, set 26" in the ground. A penny at base of pipe. A steel fence post brs. North, 3 ft.



ACCESSORIES : DESCRIBE NEW BT^h WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Original BT, a Ponderosa pine, 33" dia., N 24° E, 21.1 ft., not re-marked.
A Ponderosa pine, 15" dia., S 29° E, 7.1 ft., mkd. T21S R9E S7 BT
Original BT, a Ponderosa pine, 19" dia., S 11° W, 25.1 ft., not re-marked.
Original BT, a Lodgepole pine, 20" dia., N 18° W, 27.1 ft., not re-marked.

Bearings by staff compass. Distances to a nail in side of tree. A brass washer marked LS 2396 nailed between the B & T in the scribing. Location poster on back of NW BT on South side of RD 4250.

Work Done By B. L. Ham Title PLS Date 6/92 State Registration No. 23 76
or Agency
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Deschutes Co. Date 6/10/92

REMARKS

GLO Survey by Thompson, Meldrum & Moore in 1880.
Set post for corner to Secs. 6, 7, 1 & 12, from which:
A pine 20 in. diam. bears S 37° E 42 lks. dist.
A pine 20 " " " N 19° E 32 " "
A pine 12 " " " N 28° W 41 " "
A pine 6 " " " S 9° W 38 " "

Index File No. H29 0155 21 T. 9 R. 9 WMT Tract or Surv. No. 9 Cor E-1
GPO: 1986 O- 439-095

USDA-FOREST SERVICE

Index

File No. 1131-0955

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. E-09T 21 S. R. 9 E.R.D. Bend

County

Deschutes

NW


Sec CorMerid. WmtN.F. Deschutes

State

OregonS. 9

CORNER DIAGRAM

T21S R9E

~~1131~~

6

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER MONUMENT FOUND

Original corner post hole.

A Lodgepole pine, 13 in. dia., N.16°E., 11 lks., with face & scribing exposed. _____ 2

Remains of a large Ponderosa pine, S.79°W., 38 lks., no other evidence.

A Ponderosa pine stump, 39 in. dia., N.54°W., 147 lks., face & scribing visible.

A Lodgepole pine stump, 13 in. dia., S.28°E., 43 lks., face & scribing exposed.

All distances to original B.T.'s measured to the face.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3

Signature

William B. Ham

Title

PLS

Division

CS

Headquarters

SO

Date

6/92

FS-7100-52 (3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT DETAIL

A 2 1/4 in. X 30 in. alum. pipe with alum cap, set 26 in. in the ground. A penny at base of pipe. A 6 ft. steel fence post bears North, 3 ft.
Original BT, a Lodgepole pine, N.16°E., 7.3 ft., not re-marked.
A Ponderosa pine, 4 in. dia., S.71°E., 35.5 ft., marked X B T
A Ponderosa pine, 5 in. dia., S.19°W., 4.3 ft., marked X B T
A Ponderosa pine, 21 in. dia., N.20°W., 124.6 ft., marked T21S R9E S5 B T

T21S
S5 | S4 R
S8 | S9 9
E
PLS 2396
1992

ACC

PRESERVE EXISTING EVIDENCE

All distances to a nail at side center of the tree. A brass washer marked LS 2396 nailed between the B & T.

Work Done By W.B. Ham Title PLS Date 6/92 State Registration No. 2396
Certified Cor. Record Prepared (Yes) No Filed At: Deschutes Co. Date 6/10/92

REMARKS

GLO survey of 1880 by Thompson, Meldrum & Moore.
Set post for corner to Secs. 4, 5, 8 & 9. From which:
A pine 10 in. diam. bears N 22°E 11 lks. dist.
A pine 30 " " " S 80°W 38 " "
A pine 30 " " " N 57°W 148 " "
A pine 6 " " " S 31°E 43 " "

Index File No. 113-1 0955 T. 21 R. 9 WMT Tract or Surv. No. GPO: 1986 O-439-095 Cor. E-09

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. E-25

T 21 S. R. 9 E.

R.D. BOND

County DESCHUTES

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

SEE: E-01

T21S R10E

Blk
by
58

E-25

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. **F-25**

T 21 S. R. 9 E.

R.D. BEND

County DESCHUTES

N/16 Sec 12 & 7

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

SEE: F-01
T215 RIDE

60 by BLM
258

F-25

Index
File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. **G-25**

T 21 S. R. 9 E.

R.D. BEND

County DESCHUTES

E/4 Cor Sec 12

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

W/4 Cor Sec 7

SEE: G-01
T215 B10E

BLM
N.B. 10/15/88


G-25

LAND CORNER RECORD

J-01 5680-2

1. T 21S, R 9E No. J-1 Cor. SEC Mer. Will State OREGON (Rectangular) N. F. DESCHUTES Dist. BEND

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

5. Investigation Notes:

See: J-25, T21S, R8E, WM

SF/NF

6. Signed _____ Title _____ Date _____

Index

File No.

J 7

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.


Cor.

No.

J-07

T 215 R. 9ER.D. Bend County Deschutes3/4 Cor. Sec. 8Merid. WillametteN.F. Deschutes State OregonN/A Cor. Sec. 17

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Northerly BT
16" L.P. Pine 1/4s visible

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____ 11

REMARKS

Set lath at approx cor. S 20° W - 58 1/2' From B.T. Thingvall
6-25-76

12

Index File No. T. R. M. Tract or Surv. No. Cor. J-07 13

Index

File No. _____

T 21 S R. 9 EMerid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. _____

Cor.

No. J-23R.D. D-2County DeschutesS/4 Cor. Sec. 12N.F. DeschutesState OregonN/4 Cor. Sec. 13

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

wood post 1"x4" painted white

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.T. 13" L. pine az - 328° @ 27' w/ scribing
24" stump 154° @ 15' possible B.T.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature

L. Moore

Title

Forestry Tech

Division

D-2

Headquarters

Date

4/25/74

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No.

Cor. J-23 13

D-7100-52 d (10/78)
USDA-FOREST SERVICE

Index
File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. _____

J-25

T 21 S. R. 9 E. R.D. BEND County DESCHUTES
Merid. WILLAMETTE N.F. DESCHUTES State OREGON

SEE: J-01

T21S R10E

copy BLM


J-25

LAND CORNER RECORD

N-01 5680-2

1. T. ^{21S}~~23S~~, R. ^{9E}~~10E~~ No. N-1 Cor. SEC Mer. Will State ^(Rectangular) OREGON N. F. DESCHUTES Dist. BEND

2. Corner Status



7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: _____

5. Investigation Notes:

SEE: N-25, T ²¹~~23~~S, R ⁸~~9~~E, WM

EV. FD.
3 BT's

6. Signed _____ Title _____ Date _____

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

(Date)

(City)

(County)

(State)

14. Remarks:

N-01

Index

File No. 0963

T 21 S. R. 9 E. R.D.

Merid. WILLAMETTE N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

BEND

County

DESCHUTES

State

Tract or

Survey No.

DESCH.

OREGON

Cor.

No.

N-09

SEC. COV.

~~SEE: CERT. BOOK~~

See Cards at back of

T21S R9E.

Copies of Cert. Book.

BE Set
1978
✓60

N-09

Index

File No. 0963

21 S. R. 9 E. R.D.

Merid. WILLAMETTE N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

BEND County

DESCHUTES State

Tract or

Survey No.

DESCH.

OREGON

Cor.

No.

N-09

SEC. COV.

~~SEE: CERT. BOOK~~

See Cards at back of

TZ1S R9E.

Copies of Cert. Book.

BE Set
1978
K60

Index

File No. 1163

T 21 S. R. 9 E. R.D. BEND

Merid. WILLAMETTE N.F. DESCHUTES

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.

No. N-11

County DESCH.

State OREGON

5/4 Cor. Sec. 16

N/4 Cor. Sec. 21

~~SEE: CERT. BOOK~~

See Cards at back of
T215 R9E

Be Set 1978
R40

Index
File No. 1363

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. N-13

T 21 S. R. 9 E. R.D. BEND County DESCH. Sec. Cor.

Merid. WILLAMETTE N.F. DESCHUTES State OREGON

SEE: CERT. BOOK

See Cards at Back
of T21S R9E

BC Set 1978
Reg

Index

File No. 1563

21 S. R. 9 E. R.D.

Merid. WILLAMETTE

N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

BEND

County

DESCH.

DESCHUTES

State

OREGON

Tract or

Survey No.

Cor.

No.

N-15

3/4 Cor. Sec. 15

N/4 Cor. Sec. 22

SEE: CERT. BOOK

See back of T215R9E

Cards are copies of Cert. Book

215R9E
N/4
3/4
1918
1910

Index
File No. N-17 1763T 215 R. 9EMerid. Will

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. BenCounty DeschutesN.F. DeschutesState OregonTract or
Survey No. _____Cor.
No. N-17Sec. Cor.Dist. D-1

CORNER DIAGRAM

↑
N1514
●
22123

DESCRIBE CORNER MONUMENT FOUND

(over)

SEE: CERT. BOOK BO Let 1978
R₂

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

See Cards at Back of T215 R9E

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

~~Steel Post~~

BC by R 1978

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Sec Corner within Cutting unit #14 of Indian Creek Sale (To sell 1977)
I painted Steel post w/blue paint & flagged 5 (Lp)
BT's w/pink Ribbon. Trees marked Adjacent w/blue paint for Removal.

10

Work Done By Ray Wiggins Title Forester Date 1977 State Registration No. or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Date

11

REMARKS

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor N-17 13

Index

File No. 1963

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.

No. N-19T 21 S R. 9 ER.D. BENDCounty DoschS 1/4 COR See 14Merid. WillN.F. DoschutesState OREN 1/4 COR See 23

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

~~IRON PIPE~~ 2" Replaced

4" Above ground

condition good.

Wood plug with hub tack

SEE: CERT. BOOK

B@ Set 1978 Pro

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

18" PPINE S 37° E 17'

* See Cards
at Back
of T215R9E

USDA FS. CAP(4") w/ PP2 4271 58' S45W

PHOTO IDENTIFICATION DATA

Photo No. R19 EXP. 213Filed At. EGR. (SO)

Object Ident. _____

Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

COR is approx 60 on south side of road #205 about 0.3 mi.
NE of its Junc. with RD 2016

Signature

George Foster

Title

Division

Headquarters

Date

12/7/72

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____


Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. *N-19*

Index
File No. 2163CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)Tract or
Survey No. _____Cor.
No. N-21T 21 S R. 9 ER.D. BEND County DeschutesSec. Cor.Merid. WillN.F. DESCHUTES State OREGON

CORNER DIAGRAM

23 24
PHOTO IDENTIFICATION DATAPhoto No. Roll 19 Exp 213Filed At. Eng

Object Ident. _____

Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____
Agency

DESCRIBE CORNER MONUMENT FOUND

Pile of STONESSEE: CERT. BOOK
BC by Green Empire* See Cards at Back
T215 R9E.Fd 1978

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N 58° W 14' to LP PINE 15" DBHS 28° W 30' to LP PINE 15" DBH.S 28° E 11' to P. PINE BLAZES headed 284N 19° E 29' to L.P. PINE 13" DBH.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SEC COR. is approx 400 feet before you get to PringleFalls C.G. Just prior to steep pitch in road and SW 250-300 FT.

Signature

George Foster

Title

Division

Headquarters

Date

12/7/72

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. *N-21*

13

USDA-FOREST SERVICE

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. _____

Cor.

No. N-21T 21 R. 9R.D. Bend County Deschutes NW cor S 24Merid. WN.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

FD: 2 1/2" BC rising 4" in ring of stone

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FD 4 BTs: 16" LP S24°W 31' Dead Leaning
32" DP S26°E 11' 116
12" LP N17°E 29' 116
14" LP N54°W 14' 116 Down dead

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor is 200' West of Pringle falls
Road (To campground)

Signature

Scutts

Title

ST

Division

CS

Headquarters

SO

Date

5/10/93

FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set 2 new BTs: 14" LP N49°W 175' scribed T215 R9E S14 BT
Brass washer between B & T (LS 2396)
nail in E face.

16" PP S69°W 993' scribed T215 R9E S23 BT
Brass washer as above nail in N Face

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No.

T.

21

R.

9

M.

4

Tract or Surv. No.

Cor.

Index

File No. 2363

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. N-23

21 S. R. 9 E. R.D.

BEND

County DESCHUTES

Merid. WILLAMETTE N.F.

DESCHUTES

State OREGON

5/4 Cor. Sec. 13

N/4 Cor. Sec. 24

SF/NF 1978 *Ruo*

N-23

Index

File No. 2363

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. N-23

T 21 S. R. 9 E. R.D. BEND

County DESON.

3/4 Cor. Sec. 13

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

N/4 Cor. Sec. 24

SF/NF 1978 *Ruo*

D-7100-52d (10/78)
USDA-FOREST SERVICE

Index File No.	<u>2563</u>								
T	<u>21</u>	S. R.	<u>9</u>	E.	R.D.	<u>BEND</u>	County	<u>DESCH.</u>	Cor. No. <u>N-25</u>
Merid.	<u>WILLAMETTE</u>	N.F.	<u>DESCHUTES</u>		State	<u>OREGON</u>			

SEE: CERT. BOOK

See Cards at Back
of T21S R9E

Bo by Leo
1978

Index

File No. 196A-H

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.
No.0-19-HT 21 S. R. 9 E.R.D. BENDCounty DESCHUTES

CSN/ACor. of

Merid. WillametteN.F. DeschutesState OregonSection 23

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

2" I.P. SET BY HAWTHORNE IN 1972 - INITIAL POINT OF
WILD RIVER ESTATES SUBDIVISION

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

200' N. OF RD. #43

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: W. MILLER

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

REPLACE 2" I.P. WITH 2 1/2" X 30" BCSP RISING 3"

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P.PINE - S16 1/4° W @ 26.87' - 60 PENNY IN ESE BASE, MKD. CSN/6A S23 BT.
5" " - S80 1/2° E @ 57.50 - " " " N. " " " X BT.

10

Work Done By W. MILLER Title L.S. Date 11/84 State Registration No. OR. #2111
or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At DES. Co. Surveyor's Office Date 12/84

11

History of Surveys, G.L.O., etc. 1972 - HAWTHORNE SET 2" I.P. FOR INITIAL POINT OF WILD RIVER ESTATES

12

Index File No T. S., R. E., W.M. Contract or Surv. No Cor. 0-19-H

13

Index

File No. 206A-H

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.

No. 0-20-HT 21 S. R. 9 E. R.D. BENDCounty DESCHUTESMerid. WillametteN.F. DeschutesState OregonCSNE 1/4 Cor. of
Section 23

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

#5 SR SET BY HAWTHORNE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

REPLACED #5 SR BY HAWTHORNE WITH 2 1/2" x 30"
BCSP RISING 2"

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P. PINE - NB 1 1/2° W @ 38.81' TO A 60-PENNY IN NINE. BASE, MKD CSNE/6A 523 BT.
7" " - S 62 1/2° W @ 45.31' " " " " " " NW. " " CSNE/6A 523 BT.

Work Done By W. MILLER Title L.S. Date 11/84 State Registration No. OR-2111
or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At. DES. Co. Surveyor's Office Date 12/84

History of Surveys, G.L.O., etc. 1972 - JEAN HAWTHORNE SET #5 SR.

Index File No. T. S., R. E., W.M. Contract or Surv. No. Cor.

Index
File No. 0965

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. P-09

T 21 S. R. 9 E. R.D. BEND County DESCHUTES E/4 W/4 Sec. 20
Merid. WILLAMETTE N.F. DESCHUTES State OREGON W/4 Sec. 21

SEE: CERT. BOOK

See Cards at Back
of TZ15 R9E

BC Set 1942 by USA
Fd 1978
R9E

P-09

Index

File No. 1365

21 S. R. 9 E. R.D.

Merid. WILLAMETTE N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

BEND

County

DESCH.

State

OREGON

Tract or

Survey No.

Cor.

No.

P-13

E/4 Cor. Sec. 21

W/4 Cor. Sec. 22

SEE: CERT. BOOK

See Cards at Back
of TZIS R9E

BT POSITIVE
1/10/80
1/10/80

P-13

index File No. <u>1768</u>	CORNER RECORD (SEARCH) (Ref. FSM 7151.4)	Tract or Survey No. _____	Cor. No. <u>P 17</u>
T <u>21</u> S. R. <u>9</u> E. R.D. <u>BEND</u>	County <u>DESCH.</u>	E/4 Cor. Sec. 22	
Merid. <u>WILLAMETTE</u>	N.F. <u>DESCHUTES</u>	State <u>OREGON</u>	W/4 Cor. Sec. 23

SEE: CERT. BOOK

See Cards at Back
of T215 R9E

BC by USDA 1942
Fd 1978 Rho

Index

File No. 1965

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. _____

Cor.

No. P-19T 21 S. R. 9 E. R.D. BENDCounty DESCHUTESMerid. WillametteN.F. DeschutesState Oregon

C/4 Cor. of

Section 23

CORNER DIAGRAM per legend

RD#43

DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" P. PINE - S16°W @ 36.7', MKD. 1/4573 (NO RECORD OF WHO DID IT)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other☐ ☐ Searched For/Not Found☒ ☒ Evidence Found/Accept.☒ ☒ Permanent Mon. Set/Fd.Searched By: W. MILLER

Title

L.S.

Division

ENG.

Headquarters

S.O.

Date


10/84

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" x 30" BCSP - RISING 2" - SET FROM SURVEY

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE - N 88° E @ 44.72' TO A 60 PENNY SPIKE IN N. BASE MKD. C/4 S23 BT.
10" " - S 30 1/2° W @ 72.27' " " " " " " SE. " " C/4 S23 BT.

10

Work Done By W. MILLER Title L.S. Date 10/84 State Registration No. OR # 2111
or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes No Filed At DES. Co. Surveyor's Office Date 12/84

History of Surveys, G.L.O., etc. 1972 - HAWTHORNE COMPUTED LOCATION BUT DID NOT SET.
(HE MAY HAVE STARTED TO BUT DECIDED NOT TO)

Index File No. T. S., R. E., W.M. Contract or Surv. No. Cor. P-19

12

13

Index

File No. 2065

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)


Survey No.

Cor.

No. P-20T 21 S. R. 9 E. R.D. BEADCounty DESCHUTESMerid. WillametteN.F. DeschutesState OregonCE 116 Cor. of
Section 23

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Pd.

Searched By: W. MILLER

Title

Division

Headquarters

Date


L.S.ENG.S.D.11/84

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" X 30" BCSP - RISING 4" - SET FROM SURVEY

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" PINE - S36 1/2° E @ 41.15' - LOD IN N.E. BASE, MKD. CE/16 S23 BT.

4" " - S79° W @ 20.26' - " N S.E. " , " X BT.

Work Done By W. MILLER Title L.S. Date 10/84 State Registration No. PLS # 2111 (OR) or Agency

Plat or Cor. Record Prepared? ☒ (Yes) No Filed At. DESCHUTES Co. Surveyor's Office Date 12/84

History
of
Surveys,
G.L.O.,
etc.

Index File No.

T.

S., R.

E., W.M.

Contract or Surv. No

Cor.

12

13

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor. No. P-21

ST 215 R. 9 E


R.D. BEND County Deschutes

E/4 Cor. Sec. 23
W/4 Cor. Sec. 24

Merid. _____

N.F. Deschutes State Ore.

DESCRIBE CORNER MONUMENT FOUND



See
Survey For H.O. ADAIR by Aubrey Perry 10/17/65
SET: CERT. BOOK No. 1978 Run 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

See Cards at Back of
T215 R9E

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At: _____

Object Ident.

Ident. By _____

Signature 7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency B

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

See Cert Book

Signature

Title

Division

Headquarters

Date _____


7100-52 (3/68)

Signature
H M Van Horn

Date
1/22/73

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

7/11/89 Monument box & cap set in conjunction w/road crest
per Bob Davis, Proj Engr. (Const is under Desobates Co. contract)

12

Index File No. T. R. M. Tract or Surv. No. Cor. **P-21**

13

Index
File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No.

T 21 S. R. 9 E. R.D.

R.D.

BEND

County

DESCH.

Merid. WILLAMETTE N.F.

N.F.

DESCHUTES

State

OREGON

E/4 Cor. Sec. 24
W/4 Cor. Sec. 19

SF/NF 1978/8

P-25

LAND CORNER RECORD

5680-2

1. T 21S, R 9E No. R-1 Cor. SEC Mer. Will State OREGON (Rectangular) N. F. DESCHUTES Dist. BEND

2. Corner Status

3. Original Description

Vol.

Page

Where Recorded

4. Description of Corners:

5. Investigation Notes:

7. Photo Identification

Photo No.

Ident. By:

8. Plane Coordinate Position Data

State

Zone

X

Y

Estab. By

Field Book No.

Where Filed

9. Evaluation

Authentic

Needs Verif. Monument

Re-estab. Survey

Land Status

6. Signed

Title

Date

SEE: R-25, T21S, R9E, WM

EV. ED.
2 BT's

PERPETUATION RECORD

10. Monument:

11. Accessories

12. Set By _____ Title _____		Field Book _____	Page _____
License _____	Agency _____	Date _____	
13. Recorded By _____ (Agency) _____		Volume _____	Page _____
(Date) _____	(City) _____	(County) _____	(State) _____

14. Remarks:

R-01

Index

File No. 0967

T 21 S. R. 9 E. R.D. BEND

Merid. WILLAMETTE N.F. DESCHUTES State OREGON

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. R-09

See. Cor.

SEE: ~~BOOK~~ CERT. BOOK

See Cards at Back of
TZ1S R9E

FD. BC by USDA
Fd 1978
Rus

R-09

Index

File No. 7167

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

R-11

21 S. R. 9 E. R.D.

BEND

County

DESCH.

3/4 Cor Sec 21

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

N/4 Cor Sec 28

SF/NF 1978
Two

R-11

Index

File No. 1367

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. R-13

21 S. R. 9 E. R.D. BEND

County DESCH.

See Cor.

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

SEE: CERT. BOOK

See Cards at Back of
TZ15 R9E

Handwritten notes and scribbles, including "S.D." and "TZ15 R9E".

R-13

Index

File No. 1367

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

R-13

21 S. 9 E. R.D.

BEND

County DESN.

See. Cor.

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

SEE: CERT. BOOK

See Cards at Back of

TZIS R9E

Handwritten notes and arrows pointing to the bottom right corner of the page.

Index
File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No.

T 21 S. R. 9 E. R.D. BETUD County DESCH. S/4 Cor. Sec. 22
Merid. WILLAMETTE N.F. DESCHUTES State OREGON N/4 Cor. Sec. 27

SF/NF 1978 *Kuo*

index
File No. 1767
T 21 S. R. 9 E. R.D. BEND County DESCH. Cor. No. R-17
Merid. WILLAMETTE N.F. DESCHUTES State OREGON Sec. Cor.

SEE: CERT. BOOK

~~See Back~~

See Cards in Back of

T21S R9E

BC Set 1978
Rm

Index
File No. 1967
Tract or
Survey No. R-19
CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)
County DESCH. 3/4 Cor. Sec. 23
N.F. DESCHUTES State OREGON N/4 Cor. Sec. 26
S. R. 3 E. R.D. BEND
Merid. WILLAMETTE

SEE! CERT. BOOK

See Cards in Back of
T21S R9E

BC by KCO
1978

Index

File No. 2167

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.

No. R-21T 21S R. 9ER.D. BandCounty DeschutesSee Cor.Merid. Will.N.F. DeschutesState OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

~~2 1/2" PINE BEST OVER - NO CAP~~ReplacedSquare post about 3' NorthSEE: CORN. BOOK
BC Set 1978* See cards in Back
of TZ1S R9E

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S42°E P. PINE 26" diam. 7E34" P. PINE SNAG S44°W 26E721 L-23
Stop disk18" PPINE N 38°W 40E Blazed open but not deep enough. BT BlazeNE BT IS DOWN SNAG

PHOTO IDENTIFICATION DATA

Photo No. Roll 19 Exp 213Filed At. Engle

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

George J. H.

Title

Division

Headquarters

Date

12/7/72

7100-52 (3/68)

5

Index

File No.

T 21 S. R. 9 E. R.D. BEND

Merid. WILLAMETTE N.F. DESCHUTES

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

County DESCH.

State OREGON

Tract or

Survey No.

Cor.

No.

R-23

S/4 Cor. Sec. 24

N/4 Cor. Sec. 25

SP/NF 1978 *Ruo*

Index

File No.

2567

21 S. R. 9 E.

R.D.

BAND

County

DESON.

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

Tract or
Survey No.

Cor.
No.

P-25

See. Cor.

SEE: CERTI BOOK

See Cards in Back of
TZIS R9E

BC by Shw. - H/KM
1930
1978
RHO

USDA-FOREST SERVICE

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____


Cor.

No. T-09T 215 R. 9E

R.D. _____

County DESCHUTESE/4 COR SEC 29Merid. WillN.F. DESCHUTESState OREGONW/4 COR SEC 28

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

USDA - FS - BRASS CAP ON A STEEL PIPE - NO DATE
THAT HAS BEEN BENT OVER BY LOGGING.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 16" LPP - N 52° E - 16 FT

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

LOCATION POSTER ON 16" LPP - N 52° E - 16 FT ±
50' N. OF RD.
100' N. OF JCT.

Signature _____

Title _____

Division _____

Headquarters _____


Date _____

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

NEW FENCE POST 3' N - LSM SIGN



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By WH 7/27/92 Title LS Date _____ State Registration No. 2396 or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

Index

File No.

0969

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

7-09

21 S. R. 9 E. R.D.

BEND

County

DESCH.

E/4 Cor. Sec. 29

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

W/4 Cor. Sec. 28

SEE: CERT. BOOK

See Cards in Back of
T21 S R9E

Fd BC by USDA 1942
1978 fms

Index

File No.

21 S. R. 9 E. R.D.

Merid. WILLAMETTE N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

BEND

County DESCH.

State OREGON

Tract or
Survey No.

Cor.
No.

T-13

E/4 Cor Sec 28

W/4 Cor Sec 27


SF/NF 1978 Reg

Index
File No. 1769
Tract or
Survey No. 21 S. R. 9 E. R.D. BEND County DESCHUTES Cor. No. T-17
Merid. WILLAMETTE N.F. DESCHUTES State OREGON EA Cor. Sec. 27
W/A Cor. Sec. 26

~~ST/UF~~ 1978 _{Rev}

Fd 18" & 17" BTs w/ Scribers
Fd Orig Cor Post scr. 1/4
out of Ground

ORIG. 13T'S = 12" P. N69E 139 FT.
12" P. S42W 59 FT.



Index
File No.

21 S. R. 9 E. R.D.
Merid. WILLAMETTE N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

BEND

County

DESCH.

State

OREGON

Tract or
Survey No.

Cor.
No. T-21

E/A Coy. Sec. 26
W/A Coy. Sec. 25

SF/NF 1978
R_{mo}

Index

File No. 2569

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

T 21 S. R. 9 E. R.D. BEND

R.D.

BEND

County

DESCH.

Merid. WILLAMETTE N.F. DESCHUTES

N.F.

DESCHUTES

State

OREGON

E/4 Cor. Sec. 25

W/4 Cor. Sec. 30

SEE: CERT. BOOK

See Cards in Back of
T21S R9E

DE by Shw. - Hixson
1929
Ed. 1978
Rho

LAND CORNER RECORD

(Rectangular)


V-01/5680-2

1. T. 21S, R. 9E No. V-1 Cor. SEC Mer. Will State _____ N. F. _____ Dist. _____

2. Corner Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: _____



5. Photo Identification _____

Photo No. _____

Ident. By: _____

6. Plane Coordinate Position Data _____

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

7. Evaluation _____

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

5. Investigation Notes: _____

SEE: V-25, T21S, R9E, WM

LD.
V-25
R9E
WM

6. Signed _____ Title _____ Date _____

Index
File No. V-9 0971

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. V-09T 215 R. 9E

R.D. _____

County

DeschutesSec. Cor.Merid. WillN.F. Deschutes

State

Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Brass Cap on pipe 2", 20" Height above ground

USDA- ES. good condition

SEE: CERT. BOOK

Ed 1978 Rev 2

* See Cards
in Back
of T215R9E

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

P.P 36" dia. N72°E, 27.5' FT SIDE CENTER

FACE: SCRIBING VISIBLE - NO EVIDENCE OF SE BT

LPP 11" DIA. S 32°W, 11.3' FT

FACE: FAINT SCRIBING VISIBLE - NO EVIDENCE OF NW BT

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Pringle Falls Research Natural Area

(Survey Done 10-76, Filed in CALASTAL PLATS)

Signature

Title

Division

Headquarters


Date

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

RESET CAP - NOW RISING 9" ABOVE GROUND
SET 6' METAL FENCE POST 3' NORTH - WH



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By WH 7/27/92 Title LS Date _____ State Registration No. 2396
or Agency _____
Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Survey done 10-76, Filed in Cadastral Plats

Index File No. T. R. M. Tract or Surv. No. Cor. V-09

Index

File No.

117

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

V-11

T. 21 S. R. 9 E. R.D.

BEND

County DESCH.

3/4 Cor Sec 28

Merid. WILLAMETTE N.F.

DESCHUTES

State OREGON

1/4 Cor Sec 33

JF/NF 1978 Ruo

V-11

Index

File No.

117

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

V-11

21 S. R. 9 E. R.D.

BEND

County DESCH.

3/4 Cor Sec 28

Merid. WILLAMETTE N.F.

DESCHUTES

State OREGON

1/4 Cor Sec 33

JF/NF 1978 Ruo

Index
File No. 1371
CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)
Tract or
Survey No. Cor. V-13
21 S. R. 9 E. R.D. BEND County DESCH. See. Cor.
Merid. WILLAMETTE N.F. DESCHUTES State OREGON

SEE: CERT. BOOK 5/93 mtz

See Cards in Back of
T215 R9E

10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

Index
File No. 1571

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. V-15

Cor.
No. V-15

T 21 S. R. 9 E. R.D. BEND County DESCH. S/4 Cor. Sec. 27

Merid. WILLAMETTE N.F. DESCHUTES State OREGON N/4 Cor. Sec. 34

SF/NF 1978 *Pho*

Index
File No. 1771
21 S. R. 9 E. R.D. BOND County DESCH. Cor. No. V-17
Merid. WILLAMETTE N.F. DESCHUTES State OREGON Sec. Cor.

SEE: CERT. BOOK

See Cards in Back of
T215 R9E

BE Set 1978
R₄₆

Index

File No.

T 21 S. R. 9 E. R.D.

Merid. WILLAMETTE N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

BEND County

DESCHUTES State

Tract or

Survey No.

DESCH.

OREGON

Cor.

No.

V-19

3/4 Cor. Sec. 26

N/4 Cor. Sec. 35

SF/NF Rev 1978

Index		CORNER RECORD (SEARCH)		Tract or		Cor.	
File No.		(Ref. FSM 7151.4)		Survey No.		No.	
21 S. R. 9 E.		R.D.	BEND	County	DESCH.	V-21	
Merid. WILLAMETTE		N.F.	DESCHUTES	State	OREGON	Sec. Cor.	

SF/NF 1978 *Ring*

index File No.	2371	CORNER RECORD (SEARCH) (Ref. FSM 7151.4)		Tract or Survey No.	Cor. No.
T	21 S. R. 9 E.	R.D.	BEND	County	DESCH.
Merid.	WILLAMETTE	N.F.	DESCHUTES	State	OREGON
					3/4 Cor. Sec. 25 N/4 Cor. Sec. 36

SEE: CERT. BOOK

See Cards in Back of
T21S R9E

Beber
1978

Index
File No. 2571
T 21 S. R. 9 E. R.D. BENO County DESCH. Cor. No. V-25
Merid. WILLAMETTE N.F. DESCHUTES State OREGON Sec. cor.

SEE: CERT. BOOK

See Cards in Back
of TZ15 R9E

Be by RCO
1998

Index


File No. X-9 0973

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No. X-09T 21S R. 9ER.D. _____ County DeschutesMerid. Will.N.F. Deschutes State OregonE/4 Cor. Sec. 32W/4 Cor. Sec. 33

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Brass cap on pipe 2", 18" above ground

USDA-FS good condition

SEE: CERT. BOOK

* See Cards in
Back of
T21S R9E
Feb 1978 Res²

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A, 15" Lodgepole pine BEARS S 53° E 36.3 Ft.
(ORIGINAL BT)A 10" Lodgepole pine, DOWN & ROTTING
BEARS N 62° W 4.6 FT (ORIGINAL BT)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Pringle Falls Natural Research Area

LOCATION POSTER ON A 5" LPP ON WEST
SIDE OF RD-108' WEST OF CORNER

(Over)


LOC. POSTER ON AN 11" LPP S 43° E 8.2' FT

4

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By WH 4/27/92 Title LS Date _____ State Registration No. 2396
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

Survey done 10-76, Filed in Cadastral Plats

12

Index File No. T. R. M. Tract or Surv. No. Cor. X-09 13


Index
File No. X-1373

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. X-13T 215 R. 9ER.D. _____ County DeschutesE/4 Cor. SEC. 33Merid. WillN.F. Deschutes State OregonW/4 Cor. SEC. 34

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

F.S. Section Line board on tree and cruiser
Tag says 1/4 cor is 1320'N.
SF/NF 1978

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Pringle Falls Natural Research Area
(over)

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

Survey done 10-76, Filed in Cadastral Plats.

12

Index File No. T. R. M. Tract or Surv. No. Cor. *X-13* 13

Index

File No. 1773

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

21 S. R. 9 E. R.D.

BEND

County

DESCH.

Merid. WILLAMETTE N.F.

DESCHUTES

State

OREGON

X-17

E/4 Cor. Sec. 34

W/4 Cor. Sec. 35

SEE! CERT. BOOK

See Cards at Back of
TZ1S R9E

BC by USDA 1942
Ed 1978
R₂₀

X-17

Index


File No. 2173

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. X-21T 21 S R. 9 ER.D. D-1 County DeschutesE/4 Cor. Sec. 35Merid. WillametteN.F. Deschutes State OregonW/4 Cor. Sec. 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Brass cap & pipe U.S. D.A. (1942)

fair condition

2" above grd.

SEE: CERT. BOOK
FD. OK 1978 Ruo

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" tall snag S10°E 35' scribed

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

* See Cards at Back of
T21S R9E

Signature

B. Rogers

Title

Coal-Surveyor

Division

Headquarters

S-O

Date

5/74

7100-52-(3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No.

Cor. **X-21** 13

Index

File No. 2573

21 S. R. 9 E.

Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. BEND

County DESCH.

N.F. DESCHUTES

State OREGON

Tract or
Survey No.

Cor.
No.

X-25

E/4 Cor. Sec. 36

W/4 Cor. Sec. 31

SEE: CERT. BOOK

See Cards at Back of
TZIS R9E

Be by K60
1978

X-25

Index

File No.

2573

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

X-25

T 21 S. R. 9 E.

R.D.

BEND

County

DESCH.

E/4 Cor. Sec. 36

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

W/4 Cor. Sec. 31

SEE: CERT. BOOK

See Cards at Back of
TZ15 R9E

Be by Leo
1978

LAND CORNER RECORD

2-01 5680-2

1. T. 21S R. 9E No. 21 Cor. SEC Mer. Will State OREGON N. F. DESCHUTES Dist. BEND

2. Corner Status

3. Original Description Vol. Page Where Recorded

4. Description of Corners:

See Cards at Back of T21S R9E

5. Investigation Notes:

SEE:
~~Z-25, T21S, R9E, WM~~

6. Signed _____ Title _____ Date _____

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Etab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic _____
Needs Verif. _____ Monument _____
Re-establish. _____ Survey _____
Land Status _____

BC Set 1978
See Sep Report
This file
CERT. BOOK

ument:

PERPETUATION RECORD

ssories

y _____ Title _____		Field Book _____ Page _____	
_____ Agency _____ Date _____		13. Recorded By _____ Volume _____ Page _____	
		(Agency)	
		(Date) (City) (County) (State) ➤	

arks:

2-0

USDA-FOREST SERVICE

Index

File No. **0375**T. **21** S. R. **9** E.Merid. **WILLAMETTE**

CORNER DIAGRAM PER LEGEND

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

R.D. **BEND**County **DESCHUTES**N.F. **DESCHUTES**State **OREGON**

Cor.

No. **2-3****N¹/₄** COR. of SEC. **6**~~Cor. of Sec.~~

DESCRIBE CORNER MONUMENT FOUND

SEE A-3**T. 22 S.****R. 9 E.**

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.C.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Signature

Title

Division

Headquarters


Date

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STARTED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared ? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

11

REMARKS

12

Index File No. _____ T. _____ S., R. _____ E., W. M. _____ Tract or Surv. No. _____ Cor. _____

13

USDA-FOREST SERVICE

Index

File No. **0575**

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

2-5


Cor.

No.

T. **21** S. R. **9** E. R.D. **BEND**County **DESCHUTES****SW** COR. of SEC. **32**Merid. **WILLAMETTE**N.F. **DESCHUTES**State **OREGON****SE** COR. of SEC. **31**

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

~~SEE~~

SEE A-5

T. 22 S.

R 9 E.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.C.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Signature _____

Title _____

Division _____

Headquarters _____


Date _____

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STARTED



9

ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: Co. SURVEYOR'S OFFICE Date

11

REMARKS

12

Index File No. T. S., R. E., W. M. Tract or Surv. No. Cor. 13

USDA-FOREST SERVICE

Index

File No. 0775T. 21 S. R. 9Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.


Cor.

No. 2-7COR. of SEC. 5

COR. of SEC.

E. R.D. BENDCounty DESCHUTESN.F. DESCHUTESState OREGON

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

SEE**A-7****T. 22 S.****R 9 E**

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.C.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Signature

Title

Division

Headquarters


Date

D-7100-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STARTED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By PLAT PREPARED OR Title Co. SURVEYOR'S OFFICE Date _____ State Registration No. _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ or Agency _____ Date _____

11

REMARKS

12

Index File No. _____ T. _____ S., R. _____ E., W. M. _____ Tract or Surv. No. _____ Cor. _____

13

USDA-FOREST SERVICE

Index

File No. **0915**T. **21** S. R. **9**Merid. **WILLAMETTE**

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

E. R. D. **BEND**N. F. **DESCHUTES**

Tract or

Survey No.

County **DESCHUTES**State **OREGON**

Cor.

No. **Z-9**

COR. of SEC.

COR. of SEC.

CORNER DIAGRAM PER LEGEND




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

6

DESCRIBE CORNER MONUMENT FOUND

SEE A-9 T 22 S
R 9 E.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.C.

3

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

1

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Signature

Title

Division

Headquarters

Date


D-7100-52 (3/79)

5

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT SET



9

ACCESSORIES. DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

PLAT PREPARED OR

Certified Cor. Record Prepared? Yes

No

Filed At _____

Co. SURVEYOR'S OFFICE Date _____

11

REMARKS

12

Index File No. _____

T. _____

S., R.

E., W. M.

Tract or Surv. No. _____

Cor. _____

13


Index
File No. Z-11 1175T 21S R. 9EMerid. Will

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. 2-11R.D. _____ County DeschutesN.F. Deschutes State OregonS/A Cor. Sec. 33N/A Cor. Sec. 4

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

BC St 1978SEE: CERT. BOOK*See cards at Back
of T21S R9E

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

1 BT. scribed (Sec. 33)1 possible BT F.S. Tag.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Survey done 10-76, Filed in Cadastral Plats.

12

Index File No. T. R. M. Tract or Surv. No. Cor. **2-11**

13

D-7100-52 d (10/78)
USDA-FOREST SERVICE

Index

File No. 1375

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

2-13

T 21 S. R. 9

E. R.D. CRESCENT

County DESCHUTES

See. Cor.

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

~~SEE: A-13~~

~~T225 R9E~~

SEE: CERT. BOOK

See Cards at Back
of T21S R9E

PC Set 1978
Ryo

USDA-FOREST SERVICE

Index

File No. 1575T 21 S. R. 9 E.Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. BEND

County

DESCHUTESN.F. DESCHUTES

State

OREGON

Tract or


Survey No.

Cor.

No.

Z-155/4 Cor Sec 34N/4 Cor Sec 3

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

~~2" PIPE~~ — SPURIOUS SEE: A-15
BC by OTB&W
1985 ~~SP/NT~~ 1978 R

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

— NONE —

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature L. Kawashina

Title

Division


Headquarters

Date

10/78 D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



MONUMENT
STAMPED
9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No.

T.

S., R.

E., W. M.

Tract or Surv. No.

Cor.

2-15
12
13

Index
File No. 1775

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. Z-17T 21 S. R. 9 E.R.D. Bend

County

DeschutesSW Cor. Sec. 35Merid. Wmt.


N.F.

Deschutes

State

OregonNW Cor. Sec. 2

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: 1751/A-17, T. 22 S., R. 9 E.

BC Oct 1978 Ruo

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters


Date

7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor.

2-17 13

Index

File No. 1975T 21 S. R. 9 E.Merid. Wmt.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. BendN.F. Deschutes

County

State

Tract or


Survey No. _____

DeschutesOregon

Cor.

No. Z-19S/4 Cor. Sec. 35N/4 Cor. Sec. 2

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: 1951/A-19, T. 22 S., R. 9 E.

BC Set 1978 Rec. 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

Title

Division

Headquarters

Date


7100-52 (3 68)

5

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At _____ Date _____

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. **2-19**

12

13

Index

File No. 2175

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No.

Cor.

No. Z-21T 21 S R. 9 ER.D. D-1County DeschutesSec. Cor.Merid. WillametteN.F. DeschutesState Oregon

CORNER DIAGRAM



T21S

T22S

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

P. Rogers

Title

Co. Surveyor

Division

S.O.

Headquarters

Date

5/74

7100-52-13/68)

DESCRIBE CORNER MONUMENT FOUND

Brass cap and pipe (Green Empire) 1970
 good condition 6" above grd.

Ed. OK 1978 Ruo


DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

'2' original B.T.'s } 26" pine N 68° E 15'
 'A' new B.T.'s } 16" down pine S 85° E 45'
 by C.W.E.C. } orig. BT, DOWN (1985)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. 2175 T. 21 S R. 9 E M.

Tract or Surv. No.

Cor 12
Z-21 13

Index

File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.

No.

Z-23

T **27**

S. R. **9**

E.

R.D.

BEND

County

DESCHUTES

Merid.

WILLAMETTE

N.F.

DESCHUTES

State

OREGON

5/4 Cor Sec 36

N/4 Cor Sec 1

SEE: A-23

T 225 R 9E

New Accessorles
By OT Bd w ~ 1985

1978

Z-23

Index

File No. 2575

T 21 S. R. 9 E.

Merid. Wmt.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Bend

N.F. Deschutes

County

State

Tract or
Survey No.

Deschutes

Oregon


Cor.

No. Z-25

SE Cor. Sec. 36

NW Cor. Sec. 6

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: T. 21 S., R. 10 E., 0175/Z01

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date


7100-52 (3 68)

5

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor

Z-25

13

USDA-FOREST SERVICE

Index

File No.

T 21 S. R. 9 E. R.D.

Merid. WILLAMETTE N.F.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

BEND

County

DESCHUTES

State

OREGON

Tract or

Survey No.

Cor.

No.

CERTIFIED RECORD OF LAND CORNER MONUMENTATION
(Reference FSM 7154.9)


CORNER CODE DIAGRAM

.....INDEX (page 1 of 8)

T. 21 S. R. 9 E., W.M.

DESCHUTES COUNTY, OREGON

DESCHUTES NATIONAL FOREST



MONUMENT SET NOVEMBER 1978, wings indicate general BT position

MONUMENT FOUND, set prior to 1945 Platting Lev.

BT's FOUND (beyond state authority to monument).

BT's FOUND, ONE DETERIORATING (").

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Raymond E. Oman

OREGON
JULY 1978
RAYMOND E. OMAN
702

- 8 SEP 1978



Index
File No.

T 21 S. R. 9 E. R.D. BEND
Merid. WILLAMETTE N.F. DESCHUTES State OREGON

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No.

CERTIFIED RECORD OF LAND CORNER MONUMENTATION (page 3 of 8)

T. 21 S., R. 9 E., N. M., Deschutes County, Oregon...Deschutes National Forest

0971/W-09....Found 2" pipe with 2 1/2" brass cap, rising 18" above ground,
on east side of Road 219.

As witnesses:
a 20" pine bears N 65° E 26.4 feet (orig. ET); and
a 40" pine bears S 45° E 118.1 feet (orig. ET).

0971/X-09....Found 2" pipe with 2 1/2" brass cap, rising 17" above ground.

As witnesses:
a 15" lodgepole pine bears S 53° E 36.3 feet,
(original ET); and
a 10" lodgepole pine, down & rotted, bears
N 62° W 4.6 feet (original ET).

0971/2-09....Found 2" pipe with 2 1/2" brass cap, rising 16" above ground.

As witnesses:
a 15" lodgepole pine bears S 48° W 44.9 feet,
(original ET);
a 24" lodgepole pine bears N 88° W 15.2 feet,
(original ET);
a 12" lodgepole pine bears N 68° E 25.1 feet,
(original ET).

1163/W-11....Found two ET's.

Set 2 1/2" X 32" brass-capped steel pipe rising 2"
above ground.

As witnesses:
a 13" lodgepole pine bears N 10° E 11.0 feet,
(original ET); and
a 10" lodgepole pine bears S 30° W 26.4 feet.

1175/2-11....Found one ET.

Set 2 1/2" X 32" brass-capped steel pipe rising 5"
above ground, in dry stream bed, about 400' East
of Junction Roads 219 & 205.

As witnesses:
a 24" lodgepole pine bears N 03° W 52.8 feet,
(original ET); and
a 5" lodgepole pine bears S 28° W 52.5 feet,
blazed & scribed 1/4" S ET's.

1963/W-13....Found two ET's.

Set 2 1/2" X 32" brass-capped steel pipe rising 3"
above ground, about 100' South of Road 2116-E.

As witnesses:
an 8" lodgepole pine bears N 79° W 32.4 feet,
blazed & scribed 1/2" S ET';
a 15" lodgepole pine bears N 26° E 45.8 feet,
(original ET);
a 5" lodgepole pine bears S 32° E 22.0 feet,
blazed & scribed 1/2" S ET'; and
a 5" lodgepole pine bears S 36° W 57.9 feet,
blazed & scribed 1/2" S ET'.

REGISTERED
F. J. CNAAL
RAYMOND L. OMAN
1962

- 6 1/2" ET's

DEPARTMENT OF
AGRICULTURE
32123
51225
1942


DEPARTMENT OF
AGRICULTURE
32133
1942

DEPARTMENT OF
AGRICULTURE
32121S
51225
1942

T 21 S
R 9 E
16 21
R. OMAN FLS
UR-702

T 21 S
R 9 E
32 22 S
R. OMAN FLS
OR-702

T 21 S
R 9 E
16 11S
21 72
R. OMAN FLS
OR-702



Index
File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No.

T 21 S. R. 9 E. R.D. BEND

County DESCHUTES

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

CERTIFIED RECORD OF LAND CORNER MONUMENTATION (page 2 of 3)

T. 21 S., R. 9 E., W. M., Deschutes County, Oregon...Deschutes National Forest

0375/P-01....Found two original ET's; Sec. 36, 14" pine stump, 5' high with scribbing;

Sec. 1, 1" pine stump, tipped out of ground.

Set 24" X 22" brass-capped steel pipe rising 4" above ground, 1" above mound of stone, about 20' South of fsn: 210-4.

As witnesses:

a 5" lodgepole pine bears N 54° W 40.4 feet,

blazed & scribed "S36 ET";

a 5" lodgepole pine bears N 10° E 3.0 feet,

blazed & scribed "S31 ET";

a 4" lodgepole pine bears S 42° E 5.8 feet,

blazed & scribed "S6 ET"; and

a 4" lodgepole pine bears S 78° W 20.3 feet,

blazed & scribed "S1 ET".

0967/P-09....Found all four original ET's in good condition.

Set 24" X 22" brass-capped steel pipe rising 2" above ground, about 200' North of Road 2114.

As witnesses:

a 12" X 12" double lodgepole pine bears N 74° W 27.3 feet,

(original ET);

a 14" X 12" double lodgepole pine bears N 58° E 55.1 feet,

(original ET);

a 15" lodgepole pine bears S 40° E 56.5 feet,

(original ET); and

a 16" lodgepole pine bears S 42° W 40.0 feet,

(original ET).

0965/P-09....Found 2" pipe with 24" brass cap, rising 17" above ground, from which USDA BM 7724, 4231" bears N 76° E 12.6 feet and a 1 3/4" steel capped pipe rising 12" bears S 55° E 102.2 feet.

As witnesses:

a 24" lodgepole pine bears N 74° W 59.9 feet,

(original ET); and

a 13" lodgepole pine bears S 73° E 31.2 feet,

(original ET).

0967/P-09....Found 2" pipe with 24" brass cap, rising 17" above ground, from which the center of the intersection of Roads 215 & 219-C bears S 43° E 107 feet.

As RP's:

a 3" lodgepole pine bears S 21° E 11.1 feet;

a 13" " " S 52° E 2.0 feet; and

a 7" " " N 21° W 5.0 feet.

0969/T-09....Found 2" pipe with 24" brass cap, rising 5" above ground, from which USDA FS BM 7775 4322" bears N 78° E 4.5 feet.

As witness:

a pine stump scribed "T" bears S 72° E 16.5 feet.

RECEIVED
FEDERAL
CORNER

RECEIVED
FEDERAL
CORNER

- 6 -

T 21 S

R 36 31 R
9 11 6 R
E 1 1 6 E
T 22 S
R. OMAN PLS
OR-702

T 21 S

R 17 16 R
9 1 1 R
E 20 121 E

R. OMAN PLS
OR-702

U S
DEPARTMENT OF
AGRICULTURE

20 121

1942

U S
DEPARTMENT OF
AGRICULTURE

20 121

29 180

1942

U S
DEPARTMENT OF
AGRICULTURE

20 121

29 180

1942



Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

T 21 S. R. 9 E. R.D. BENDCounty DESCHUTESMerid. WILLAMETTE N.F. DESCHUTESState OREGON

CERTIFIED RECORD OF LAND CORNER MONUMENTATION
(page 5 of 8)

T. 21 S., R. 9 E., W. M., Deschutes County, Oregon...Deschutes National Forest

1767/R-17...Found all four original Bt's.

Set 2 1/2" X 32" brass-capped steel pipe rising 6" above ground, about 450' South of Road 205.

As witnesses:
 a 41" ponderosa pine bears N 38° W 16.5 feet,
 a 41" (original Bt);
 a 38" ponderosa pine bears N 44° E 41.5 feet,
 a 38" (original Bt);
 a 36" ponderosa pine bears S 21° E 41.5 feet,
 a 36" (original Bt); and
 a 5" ponderosa pine bears S 52° W 41.0 feet,
 blazed & scribed "S 27° E".

1771/W-17...Found three original Bt's.

Set 2 1/2" X 32" brass-capped steel pipe rising 5" above ground, about 70' West of Road 213-D.

As witnesses:
 a 4" ponderosa pine bears N 64° W 27.6 feet,
 a 4" blazed & scribed "S 27° E";
 a 4" ponderosa pine bears N 01° E 28.6 feet,
 a 4" blazed & scribed "S 26° E";
 a 28" ponderosa pine bears S 04° E 41.7 feet,
 a 28" (original Bt); and
 a 30" ponderosa pine bears S 52° W 42.7 feet,
 a 30" (original Bt).






1773/X-17...Found a 2" pipe with 2 1/2" brass cap, rising 12" above ground, from which USDA FS BN FPP 11 4368" bears N 40° W 7.3 feet.

As witnesses:
 a 40" ponderosa pine bears S 86° W 27.0 feet,
 a 40" (original Bt); and
 a 33" ponderosa pine bears S 80° E 5.3 feet,
 a 33" (original Bt).


1963/W-19...Found 2 1/2" pipe rising 2" above ground with one original Bt and two Rpi's, being the NW Corner of Wild River Subdivision.

Replaced pipe with 2 1/2" X 32" brass-capped steel pipe rising 1" above ground, about 75' South of Road 205, from which USDA FS BN FPP 2 4271" bears S 42° W 5.74 feet.

As witnesses:
 a 5" ponderosa pine bears N 73° W 23.71 feet,
 a 5" blazed & scribed "S 4° E" with a nail in NE base;
 a 14" ponderosa pine bears S 35° E 17.81 feet,
 a 14" (original Bt) with nail in East base; and
 a 9" lodgepole pine bears N 20° W 11.94 feet,
 a 9" (Rpi tree) with nail in SW base.



- 6 DEC 1978



Index
File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No.T 21 S. R. 9 E. R.D. BEND
Merid. WILLAMETTE N.F. DESCHUTES State OREGONCounty DESCHUTES
State OREGONCERTIFIED RECORD OF LAND CORNER MONUMENTATION (page 7 of 8)

T. 21 S., R. 9 E., N. H., Deschutes County, Oregon...Deschutes National Forest

2371/N-23...Found two original BT's.

Set 24" X 32" brass-capped steel pipe rising 7" above ground, about 200' West of Road 218-B.

As witnesses:

- a 4" ponderosa pine bears N 65° E 17.8 feet,
- a 22" (original BT); and
- a 24" ponderosa pine bears S 65° W 10.2 feet,
- (original BT).

2563/N-25...Found four original BT's, all down and rotting.

Set 24" X 32" brass-capped steel pipe rising 2" above ground, from which USDA FS BN "FF 15 4271" bears S 64° W 9.5 feet.

As witnesses:

- a 4" ponderosa pine bears N 57° W 38.1 feet,
- blazed & scribed "S 13 BT";
- a 4" ponderosa pine bears N 41° E 9.0 feet,
- blazed & scribed "S 18 BT";
- a 6" ponderosa pine bears S 65° E 28.6 feet,
- blazed & scribed "S 19 BT"; and
- a 5" ponderosa pine bears S 71° W 17.2 feet,
- blazed & scribed "S 24 BT".

2567/N-25...Found a 1" pipe with 3" brass cap, rising 12" above ground, with two original BT's, one a snag.

As witnesses:

- a 6" ponderosa pine bears N 30° W 26.4 feet,
- blazed & scribed "S 24 BT";
- a 4" ponderosa pine bears N 36° E 36.3 feet,
- blazed & scribed "S 19 BT";
- a 4" ponderosa pine bears S 52° E 32.9 feet,
- blazed & scribed "S 30 BT"; and
- a 28" ponderosa pine bears S 44° W 29.3 feet,
- (original BT).

2599/N-25...Found 1 1/2" pipe with 3" brass cap, rising 5" above ground, about 24' SW of C/L of Road N-204.

As witnesses:


- an 8" lodgepole pine bears S 48° W 44.24 feet,
- (RP with face blaze and FK nail); and
- an 8" lodgepole pine bears S 24° E 36.44 feet,
- (RP with face blaze and FK nail).

2571/N-25...Found two original BT's, one a sawn stump and one a down and rotting log.






Set 24" X 32" brass-capped steel pipe rising 4" above ground.

As witnesses:

- a 4" ponderosa pine bears N 54° W 9.3 feet,
- blazed & scribed "S 25 BT";
- a 5" ponderosa pine bears N 65° E 18.8 feet,
- blazed & scribed "S 30 BT";
- a 5" ponderosa pine bears S 42° E 52.5 feet,
- blazed & scribed "S 31 BT"; and
- a 4" ponderosa pine bears S 40° W 46.7 feet,
- blazed & scribed "S 36 BT".



- 6 DEC 1970





Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

T 21 S. R. 9 E. R.D. BENDCounty DESCHUTESMerid. WILLAMETTE N.F. DESCHUTESState OREGON

(page 8 of 8)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T. 21 S., R. 9 E., W. M., Deschutes County, Oregon...Deschutes National Forest

2573/X-25...Found 48" sawn pine stump with toe blase.


Set 24" X 32" brass-capped steel pipe rising 3" above ground.

As witnesses:

an 8" ponderosa pine bears N 10° W 47.5 feet,


blazed & scribed $\frac{1}{4}$ S. E.T. and

a 5" ponderosa pine bears N 56° E 49.3 feet,

blazed & scribed $\frac{1}{4}$ S. E.T.SURVEYOR'S REPORT


Field search for corners adjacent to Forest: Road R-204, undergoing survey for reconstruction, turned up monuments that had been set prior to the Oregon Planting Law of 1945 and therefore never brought to record. The monumentation for the west part, appeared to be in definition of the Fringle Falls Experimental Forest; thus it seemed likely that a search of all corners within the Experimental Forest was warranted.

Monumenting at this time was only done on those areas within the licensing authority of the State of Oregon, that is, for sections presently in or previously in other than Federal ownership or such "back up" corners as would provide substantiation of those same sections. All other corners can only be set under authority of the Bureau of Land Management of the US Department of the Interior.



Office of COUNTY SURVEYOR County of DESCHUTES
 State of OREGON
 for record on the day of 1978, at o'clock a.m., (signed)

..... by (DEPUTY)



Index
File No.

T 21 S. R. 9 E. R.D. BEND
Merid. WILLAMETTE N.F. DESCHUTES State OREGON

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No.

County

DESCHUTES

State

OREGON

CERTIFIED RECORD OF LAND CORNER MONUMENTATION (Page 4 of 8)

T. 21 S., R. 9 E., N. M., Deschutes County, Oregon...Deschutes National Forest

1965/P-13...Found original BT in Sec. 21, from which USDA FS BM "FF 3 4304" bears N 84° E 40.3 feet. Said BM bearing about N 59° E 17.1 feet from True Corner point. Found possible BT in Sec. 22, a 13" lodgepole pine.

1967/R-13...Found two BT's; Sec. 28, an 18" lodgepole pine; Sec. 22, a 10" lodgepole pine.

1971/W-13...Found three BT's; Sec. 27, a 13" pine; Sec. 34, a 20" pine; Sec. 33, a 19" pine.

1972/Z-13...Found one BT.

Set 2 1/2" X 3/2" brass-capped steel pipe rising 16" above ground, about 70' South of Road 220, from which USDA FS BM "FF 10 4288" bears N 23° W 8.85 feet.

As witnesses:

- a 5" ponderosa pine bears N 47° W 15.1 feet, blazed & scribed "S 33 BT";
- a 16" lodgepole pine bears N 70° E 9.9 feet, (original BT);
- a 5" lodgepole pine bears S 50° E 37.9 feet, blazed & scribed "S 3 BT"; and
- a 5" ponderosa pine bears S 70° W 28.5 feet, blazed & scribed "S 4 BT".

1965/W-15...Found two BT's, one dead and down, a 10" lodgepole pine in Sec. 22, and a 6" lodgepole pine in Sec. 15.

1965/W-7...Found original post lying on ground, rotted off, and two BT's.

Set 2 1/2" X 3/2" brass-capped steel pipe rising 5" above ground, about 100' North of Road 2116-S.

As witnesses:





- a 6" lodgepole pine bears N 04° W 27.8 feet, blazed & scribed "S 15 BT";
- a 13" lodgepole pine bears N 50° E 27.7 feet, (original BT);
- a 3" ponderosa pine bears S 72° E 12.4 feet, bark scribed "S 23 BT"; and
- an 8" lodgepole pine bears S 74° W 19.5 feet, blazed & scribed "S 22 BT".

1965/P-17...Found a 2" pipe with 2 1/2" brass cap, rising 18" above ground, about 45' SE of Road 219-D.

Raised a mound of stones around pipe.

As witnesses:

- a 10" lodgepole pine bears N 69° W 17.8 feet, (original BT); and
- an 8" lodgepole pine bears S 62° E 10.4 feet, (original BT).



8 DEC 1978





Index
File No.

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No.

T 21 S. R. 9 E.

R.D. BEND

County DESCHUTES

Merid. WILLAMETTE

N.F. DESCHUTES

State OREGON

CERTIFIED RECORD OF LAND CORNER MONUMENTATION (page 6 of 8)


T. 21 S., R. 9 E., W. M., Deschutes County, Oregon...Deschutes National Forest

1967/R-19...Found two original Br's, one a down & rotted stump with a "B" scribed blade.

Set a 2 1/2" X 3/2" brass-capped steel pipe rising 9" above ground in a mound of stone, about 75' South of a dirt road.

As witnesses:


- a 12" lodgepole pine bears N 14° E 15.8 feet, (original Br); and
- a 5" ponderosa pine bears S 16° E 33.9 feet, blazed & scribed 1/4 S Br's.



2163/W-21...Found 3 1/2" brass-capped pipe rising 4" above ground, about 200' West of Fringle Falls Campground Road.

As witnesses:


- a 12" lodgepole pine bears S 24° W 31.1 feet;
- a 28" ponderosa pine bears S 26° E 11.6 feet;
- a 10" lodgepole pine bears N 17° E 29.4 feet; and
- a 12" lodgepole pine bears N 54° W 14.2 feet; (all original Br's).



2165/P-21...Found #6 steel rod buried 2" below surface about 4' south of south edge of pavement on Road R-204.

As witnesses:

- a 36" ponderosa pine bears S 86° W 36.6 feet, (original Br);
- a 4" ponderosa pine bears N 48° E 57.1 feet, blazed & scribed "S 24 Br";
- USDA FS BM "R370" bears S 13° 53' E 21.57 feet, (a brass tablet in a concrete pier); and
- a #4 steel rod buried 4" below surface bears S 22° 05' W 3.96 feet.




2166/R-21...Found three original Br's, one a stub, one a stump.

Set 2 1/2" X 3/2" brass-capped steel pipe flush with surface, about 600' South of Road 218-B.

As witnesses:

- an 18" ponderosa pine bears N 41° W 41.3 feet, (original Br);
- a 3" ponderosa pine bears N 20° E 12.8 feet, bark scribed "S 24 Br";
- a 4" sugar pine bears N 84° E 25.0 feet, blazed & scribed "S 25 Br"; and
- a 4" ponderosa pine bears SOUTH 28.6 feet, blazed & scribed "S 26 Br".



2173/Y-21...Found a 2" pipe with 2 1/2" brass cap, rising 18" above ground, with two Br's, one down & rotting.

As witnesses:

- an 8" ponderosa pine bears N 90° W 8.1 feet, blazed & scribed 1/4 S Br"; and
- a 5" ponderosa pine bears S 20° E 5.5 feet, blazed & scribed 1/4 S Br".



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 6 1963
RAYMOND E. OMAN
702

- 6 DEC 1978

