

LEGEND

○ = Corner having information on form 7100-52 in this file.
Ledgend Conforms to Reporting Forms MPB 2/80

FILING INSTRUCTION

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. A-01

Index

Section No. 24 S. R. 14 E.

R.D. _____

County _____

Merid.

WILLAMETTE

N.F. _____

DESCHUTES

State _____

OREGON

SEE 2-25

T23S R13E

EV. FD.

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. A-01

T 24 S. R. 14 E. R.D. _____

County _____

Merid. WILLAMETTE

N.F. _____

DESCHUTES

State _____

OREGON

SEE 2-25

T 23S R 13E


EV. FO.

LAND CORNER RECORD

A-5

1. T 2 1/2 S R 1 1/2 E No A-5 Cor. Sec Mer. Wm. State Oregon (Rectangular) N. F. Deschutes Dist. Fort Rock

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

5. Investigation Notes:
See Z-5 T23S R1 1/2 E Wm.

7. Photo Identification

Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filed _____

9. Evaluation

Authentic _____
 Needs Verif. _____ Monument _____
 Re-estab. _____ Survey _____
 Land Status _____

6. Signed _____ Title _____ Date _____

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

License _____ Agency _____ Date _____

(Date)

(City)

(County)

(State)

14. Remarks:

US DA-FOREST SERVICE


Index

File No. 1351

T 24 S. R. 14 E

Merid. WMT

CORNER DIAGRAM



CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. ft. Rock

County Lake

N.F. Deschutes

State Oregon

Tract or Survey No. _____

Cor. No. A-13

NW COR

Sec. 3

DESCRIBE CORNER MONUMENT FOUND

Original basalt stone 16"x8"x4" with 5 grooves on the East and 3 grooves on the West edges.
 A Ponderosa pine, 42" dia. S.68°W., 92 lks. (60.7 ft. to face) with blazes. 2

PHOTO IDENTIFICATION DATA

Photo No. _____

File # At. _____

Object Ident. _____

Identified By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Established By _____

Agency

Signature

Title

Division

Headquarters

Date

William B. Ham

PLS

CS


SO

9/94

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set a 2 1/2" dia. x 50" long alum. pipe surmounted by a 2 1/2" dia. alum cap rising 5".
 Original stone buried alongside. A penny at base of pipe.
 A steel fence post is 3 ft. North.
 A Ponderosa pine 18" dia. N.14°E., 48.6 ft., mkd. T23S R14E S34 BT
 A Ponderosa pine 12" dia. S.35°E., 19.4 ft., mkd. T24S R14E S3 BT
 A Ponderosa pine 42" dia. S.68°W., 62.0 ft., Not re-marked, Original BT
 A Ponderosa pine 5" dia. N.23°W., 50.9 ft., mkd X BT

9 PRESERVE EXISTING EVIDENCE

A brass washer mkd LS 2396 nailed between the B & T in the scribe. Distances to side center at the root crown. A location poster on Rd.444 approx. 200 ft. W. of Cor.

Work Done By: <u>WB Ham</u>	Title: <u>PLS</u>	Date: <u>9/94</u>	State Registration No. or Agency: <u>2396</u>	10
Certified Cor. Record Prepared? <input checked="" type="radio"/> Yes <input type="radio"/> No	Filed At: <u>LAKO</u>	Date: <u>9/8/94</u>		11

REMARKS

Survey of 1880 by F.W. Campbell.
 G.O Record - Set Basalt stone 15x8x6 and dug pits as per instructions for corner to Secs 3,4,35 & 34 from which:
 A pine 36 in. diam. bears S.68°W. 91 lks dist

Index File No. <u>1351</u>	T. <u>24</u>	R. <u>14</u>	Tract or Surv. No. <u>RMT</u>	Cor. <u>A-13</u>	12
GPO: 1986 O-439-095					13

DA-FOREST SERVICE

In dex
Fi e No. 1751
T 24 S R. 14 E

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No.

Cor. No. A-17

M rid.

R.D. Crescent County Laake


State

NW cor. S.2

CO RNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

A basalt stone 15"X8"X7" set firmly in the ground with 4 grooves on West face and 2 fa notches on East edge. A 1" square marked on top of stone.
A Ponderosa Pine, 29" dia., N.70° W., 57 links dist. with face & scribing exposed.



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND



PH TO IDENTIFICATION DATA

Ph to No.
Fil d At.
Ob ect Ident.
Ide t. By
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLA NE COORDINATE POSITION DATA

Sta te Zone
X
Y
Est b. By
Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

William B. Hawn PLS


CS

SO

9/23

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set a 2½" dia. X 30" long alum. pipe with 2½" dia. alum. cap; 26" in the ground. A penny at base of pipe. Original stone buried alongside. A steel fence post is 3 ft. North.

EXISTING EVIDENCE

- A Ponderosa pine 16"dia., N.40° E., 16.4ft., marked T23S R14E S35 BT
- A Ponderosa pine 18"dia., S.32° E., 28.8ft., marked T24S R14E S2 BT
- A Ponderosa pine 15"dia., S.17° W., 78.2ft., marked T24S R14E S3 BT
- A Ponderosa pine 29"dia., N.70° W., 38.1ft., Original BT, not re-marked.

A location poster on East side of road #2350 approx. 8½ chains West of corner.

10

Work Done By Bill Ham Title PLS Date 9/93 State Registration No. 2396
 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: Lake Date 9 | 24 | 93 11

REMARKS

Survey of 1880 by Meldrum.
 GLO Record - Set Basalt stone 14X8X7 and dug pits per instructions for corner to Secs. 2,3,34 & 35, from which:
 A pine 24 in diam. bears N70°W 57 lks. dist.

12

Index File No. 1751 T. 24 R. 14 W.M.T Tract or Surv. No. _____ Cor. A-17¹³
 GPO: 1986 O-439-095

Index File No. E-9

T 245 R. 14E

Merid. WILL.

CORNER DIAGRAM

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

R.D. _____ County LAKE

N.F. DESCHUTES State OREGON

Tract or Survey No. _____

Cor. No. E-9
Sec. Cor.



1 DESCRIBE CORNER MONUMENT FOUND
 AT ORIG. COR. SEC'S 4, 5, 8 & 9, MON. BY E.W. CAMPBELL IN 1880 WITH A BASALT STONE, 12" X 10" X 8", FIRMLY SET 7" IN GRND., NO MKS. VISIBLE.

2 DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 A PINE, 33" DIA., BRS. S 33°E, 145 LKS. DIST. WITH SCRIBE MKS "S 9" VISIBLE ON FACE OPENED BY ME
 A NEARLY COMPLETELY DECAYED & DOWN PINE SNAG, 10" IN DIA., STUMPHOLE BRS., N 26°W, 94 LKS., NO MKS. VISIBLE.

3 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
FOREST SERV. RD. 1821

6 PHOTO IDENTIFICATION DATA
 Photo No. _____
 File # At _____
 Object Ident. _____
 Ident. By _____
 Signature _____ 7

8 PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Established By _____
 Agency _____
 Signature _____

9 Title SURVEY TECH. Division _____ Headquarters _____ Date 7/76
 1000-52-(3/68) 5

Index File No. E-9

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. E-9

T 245 R. 14E


R.D. _____ County LAKE

Sec. Cor.

Merid. WILL.

N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

AT ORIG. COR. SECS 4, 5, 8, & 9, MON. BY E.W. CAMPBELL IN 1880 WITH A BASALT STONE, 12" X 10" X 8", FIRMLY SET 7" IN GRND., NO MKS. VISIBLE.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A PINE, 33" DIA., BRS. S 33° E, 145 LKS. DIST. WITH SCRIBE MKS "S 9" VISIBLE ON FACE OPENED BY ME. A NEARLY COMPLETELY DECAYED, & DOWN PINE SNAG, 10" IN DIA. STUMPHOLE BRS., N 26° W, 94 LKS, NO MKS. VISIBLE.

3

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FOREST SERV. RD. 1821

4

Signature

Title

Division

Headquarters

Date

7/76 7100-52-(3,68)

DAN SANKWICH SURVEY TECH.

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

AT COR. PT. SET A 2 1/2" X 28" I.P. 24" IN GRND.
ORIG. STONE DEPOS. ALONGSIDE I.P.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

PINE, 14" DIA., BRS. N 23 3/4° E, 40 LKS., MKD. T24SR14E S4 BT
PINE, 12" DIA., BRS. S 46 3/4° W, 87 LKS., MKD. T24SR14E S8 BT
PINE, 19" DIA., BRS. N 31 1/4° W, 144 LKS., MKD. T24SR14E S5 BT
B.T. TAGS POSTED

10

Work Done By JOE GARRISON Title B.L.M. Date 7/76 State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. E-9 12 13

USDA-FOREST SERVICE

Index

File No. 1155

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. E-11

T 2A S R. 14S

R.D. Ft. Rock County Lake


5/4 Sec. 4

Merid. WMT

N.F. Deschutes State Ore

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



Original stone 11"x10"x7" with faint chisel mark on North face.
A Ponderosa pine windfall S47°E 65 lks. (41.6 ft.) with scribing visible.

2

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

4

William B. Ham Asst

CJ


SO

10/7/64

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set a 2 1/2" dia. x 30" long alum. pipe surmounted by a 2 1/2" dia. alum. cap rising 4".
 Original stone buried alongside. A penny at base of pipe.
 A Ponderosa pine 9" dia., N.41°E., 93.6 ft., mkd. 1/4 S4 BT
 A Ponderosa pine 4" dia., S.61°E., 74.1 ft., mkd. X BT
 A Ponderosa pine 26" dia., S.23°E., 61.5 ft., mkd. 1/4 S9 BT
 A Ponderosa pine 10" dia., N.67°W., 155.2 ft., mkd. X BT

DONE TO PRESERVE EXISTING EVIDENCE

A brass washer marked LS 2396 is nailed between the B & T of the scribe.
 Distances measured to the side center of the tree at the root crown.
 A Location poster on Rd. 995 approx. 600 ft. West of corner.

Work Done By William A Han Title PLS Date 9/94 State Registration No. 2396
 or Agency _____

Certified Cor. Record Prepared Yes No Filed At: Lake Co. Date 9/8/94

REMARKS

Survey of 1880 by Campbell.
 GLO Record- at 39.85 chains, Set Basalt stone 15x12x8 and dug
 pits as per instructions for 1/4 Sec. corner, from which:
 A pine 50 in. diam bears S47°E 65 lks. dist.

Index File No. 1155 T. 24 R. 14 WMT Tract or Surv. No. _____ Cor. E-11
 GPO: 1986 O-439-095

USDA-FOREST SERVICE

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. E-17


T 24S R. 19E

R.D. Bend Ft. Rock County Lake

Merid. W1

N.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SFNF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

6

7

8

2

3

4


5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

) GLO Record - Set Basalt Stone 15x10x10 and dug pits as per instructions for corner to Secs 2, 3, 10 & 11.
 Found - After diligent search following extensive traversing, No evidence of original monument or accessories.
 Set - by double proportion, a 2 1/2" dia. x 30" long steel pipe, surmounted by a 2 1/2" dia. brass cap, rising 6" in a mound of stone, from which:

ACCE: A rock outcrop, 5 ft. x 13 ft., N.32°49'E., 150.2 ft., mkd. X BO.
 GPS 8, a 5/8" re-bar with a 1 1/2" dia. alum. cap driven flush, S.71°32'E., 21.4 ft., mkd. GPS 8 PLS 2111 1994.
 A P.P. 21" dia., S.76°33'W., 244.3 ft., mkd. T24S R14E S10 BT.
 A P.P. 20" dia., N.39°55'W., 87.8 ft., mkd. T24S R14E S3 BT.
 A fence corner, N.42°W., 28 feet.



E EXISTING EVIDENCE

Work Done By W Miller Title _____ Date 1995 State Registration No. or Agency _____ 10

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____ 11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 12

Index
File No. E-19

CORNER RECORD (SEARCH)

(Ref., FSM 7151.4)

Tract or Survey No. _____
Cor. No. E-19


T 245 R. 14E

R.D. Fort Rock County Lake 1/4 Cor.

Merid. Will

N.F. Deschutes State Ore

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Pipe & Cap 1/2" diam 05ft above the grd in good condition set by Tenneson Engr. Corporation

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. GS-VDOH
Filed At. Menlo Park, Ca.
Object Ident. Cor. Pricked
Ident. By J.N. Tennant MSAS
7/77 Signature

(Line 1-exposure 134)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

At Gate by Fence corner.
Fence line goes East, West & North

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. *E-19*

12

13

Index File No. G-1

CORNER RECORD (SEARCH)


Tract or Survey No. _____ Cor. No. G-1

T 24S. R. 14E. R.D. Fort Rock County Lake 1/4 Cor

Merid. Will N.F. Deschutes State Oregon

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



SEE G-25, T24S, R13E, WM

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

B.C. set in 1976

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. **6-1**

12

13

USDA-FOREST SERVICE


Index
File No. 1357
T 24 S. R. 14 E.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Crescent County Lake Tract or Survey No. _____
N.F. Deschutes State Oregon Cor. No. G-13
WMT W/4 sec. 10

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Original stone 9" X 8" X 7" faintly marked 1/4. Fence corner N.55°W., 11.5 ft.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SF/NF

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

William B. Han

Title

PLS

Division

CS

Headquarters

SO


Date

9/93

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set 2½" X 30" aluminum pipe surmounted by a 2½"dia. aluminum cap; 26" in the ground. Penny at base of pipe. Original stone buried along side. Steel fence post 3ft. North.

TING EVIDENCE

Brooks-Scanlon well head, N.27°E., 357.7ft., marked X on the pump rod and marked BO PLS 2396 1993 on the pump jack arm.
5/8" Rebar 30" long with 1½" aluminum cap, driven flush, marked BO PLS 2396 1993.
S.45°E., 22.8ft.

A Ponderosa pine, 25"dia., S.73°W., 122.3ft., marked 1/4 S9 BT.
A Ponderosa pine, 20"dia., N.69°W., 147.2ft., marked 1/4 S9 BT.

Nailed brass washer marked LS 2396 between the B & T of the scribing and to the eastern wooden base support of the drive wheel at the well head.
Bearings taken by staff compass with a Magnetic deviation of 19° East.

Work Done By. <u>Bill Han</u>	Title <u>PLS</u>	Date <u>9/93</u>	State Registration No. <u>2396</u> or Agency
Certified Cor. Record Prepared? <input checked="" type="checkbox"/> (Yes)	No	Filed At: <u>Lake Co.</u>	Date <u>9/24/93</u>

REMARKS

Survey of 1880 by Campbell.
GLO Record - Set Basalt stone 9 X 8 x 8 and dug pits as per instructions for 1/4 sec. corner.

Index File No. <u>1357</u>	T. <u>2A</u>	R. <u>14</u>	C.M.T. <u>G.M.T.</u>	Tract or Surv. No.	Cor. <u>G-13</u>
GPO: 1986 O-439-095					

USDA-FOREST SERVICE

Index
File No. _____

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. G-17

T 245 R. 14E R.D. Bend-H Rock County Lake

Merid. W:1 N.F. Deschutes State ORE

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(11) GLO Record - Set Basalt Stone 14x10x6 and dug pits as per instructions for 1/4 Sec. corner.
Found - After diligent search following extensive traversing, No evidence of original monument or accessories.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date


FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set - by single proportion, a 2 1/2" dia. x 30" long alum. pipe, surmounted by a 2 1/2" dia. alum. cap, rising 5" in a mound of stone, from which:

- A P.P. 15" dia., N. 11° 26' E., 159.4 ft., mkd. 1/4 S11 BT.
- A P.P. 13" dia., S. 24° 59' E., 104.8 ft., mkd. X BT.
- GPS 13, a 5/8" re-bar with a 1 1/2" dia. alum. cap driven flush, N. 45° 04' W., 118.3 ft., mkd. GPS 13 PLS 2111 1994.
- A P.P. 12" dia., N. 81° 41' W., 73.9 ft., mkd. 1/4 S10 BT.
- A fence corner approximately N. 45° W., 60 feet.



RESERVE EXISTING EVIDENCE

10

Work Done By w. miller Title _____ Date Sept 95 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. _____

13

Index
File No. J-3

T 245 R. 14E
Mer. id. WILL.

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

R.D. _____ County LAKE
N.F. DESCHUTES State OREGON

Tract or
Survey No. _____

Cor.
No. J-3
1/4 COR.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

AT ORIG. $\frac{1}{4}$ COR. SECS 7 & 18, DET.
AT REC. BEARING & DIST. FROM E.W.
CAMPELL'S ORIG. 1880 B.T.'S.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A SAWED PINE STUMP, 36" DIA., 1' HIGH, BRS
S 41°E, 95 LKS. DIST., NO MKS VISIBLE. A PINE,
28" DIA., BRS DUE NORTH AT 94 LKS. DIST. WITH
SCRIBE MKS. " $\frac{1}{4}$ S" VISIBLE ON FACE
OPENED BY ME.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FOREST SERVICE ROAD 2227

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

DAN SANKWICH

Title

SURVEY TECH.

Division

Headquarters

Date

7/76

7100-52-(3/68)

Index
File No. J-3

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. J-3
1/4 COR.


T 245 R. 14E

R.D. _____ County LAKE

Merid. WILL.

N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

AT ORIG. 1/4 COR. SECS 7 & 18, DET.
AT REC. BEARING & DIST. FROM E.W.
CAMPELL'S ORIG. 1880 B.T.'S.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A SAWED PINE STUMP, 36" DIA., 1' HIGH, BRS
S 41°E, 95 LKS. DIST., NO MKS VISIBLE. A PINE,
28" DIA., BRS DUE NORTH AT 94' LKS. DIST. WITH
SCRIBE MKS. "1/4 S" VISIBLE ON FACE
OPENED BY ME.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FOREST SERVICE ROAD 2227

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature DAN SANKWICH Title SURVEY TECH. Division _____ Headquarters _____ Date 7/76 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

AT COR. PT. SET A 2 1/2" X 28" IP, 24" IN GRND.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A PINE, 9" DIA., BRS S 23 1/2° W, 28 1/2 LKS. DIST.

MKD. 1/4 S 18 BT

B.T. TAGS POSTED.

10

Work Done By JOE GARRISON Title B.L.M. Date 7/76 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

J-3

12

13


Index File No. J-5
 T 245 R. 14E
 Merid. WILL.

CORNER RECORD (SEARCH)
 (Ref. FSM 7151.4)

Tract or Survey No. _____
 Cor. No. J-5
 Sec. Cor.

R.D. _____ County LAKE
 N.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

AT ORIG. COR. SECS 7,8,17 & 18, MON. BY F.W. CAMPBELL IN 1880 WITH A BASALT STONE, 20" X 18" X 12", NO MKS. VISIBLE, FOUND COMPLETELY BURIED 10" UNDER SURFACE OF GRND. AT COR. PT. ANOTHER BASALT STONE, 16" X 13" X 9" DIRECTLY ABOVE THE ONE DESCRIBED AND FIRMLY ¹

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SET 10" IN GRND., APPEARS TO HAVE 5 FAINT NOTCHES VISIBLE ON E. FACE. ²
 A PINE, 22" DIA. BRS N 74°E, 77 LKS. (REC.=75LKS.), MKD. WITH HEALED DOUBLE BLAZE.
 A PINE, 34" DIA. BRS. S 64 1/2°W (REC = S 60°W), 65 LKS. DIST WITH ILLEG. SCRIBE MKS. VISIBLE ON PARTIALLY HEALED BLAZE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER ³

FOREST SERVICE ROAD 246

(Line 2 - exposure 143)

PHOTO IDENTIFICATION DATA

Photo No. GS-100H
 Filed At. Menlo Park Ca
 Object Ident. NW 1st Ident
 Ident. By J.N. Tennant USGS
9/77 *Signature* ⁷

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency ⁸

Signature DAN SANKWICH Title SURVEY TECH. Division _____ Headquarters _____ Date 7/76 ⁴
 7100-52-(3/68) ⁵

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

AT COR. PT. SET A 2 1/2" X 28" I.P. 24" IN GRND.
OP'G COR. STONE(S) DEPOS. ADJACENT TO I.P.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

PINE 15" DIA., S 48 1/4° E, 131 LKS., MKD. T 24 S R 14 E S 17 BT
PINE 15" DIA., BRS. N 32 3/4° W, 185 LKS., MKD. T 24 S R 14 E S 7 B
B.T. TAGS POSTED

NE + SW BT's are original

Work Done By JOE GARRISON Title B. L. M. Date 7/76 State Registration No. or Agency

Certified Cor. Record Prepared? Yes No Filed At: Date

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

J-5

Index File No. J-9

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. J-9


T 24S R. 14E

R.D. Fort Rock County Lake Sec. Cor.

Merid. Will

N.F. Deschute State Ore

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Stone 12"x10"x8"
0.5ft above the grd in good condition in a mound of stone.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

2 BT. S & USFS BT. Tags

PHOTO IDENTIFICATION DATA

Photo No. GS-100H
Filed At. Menlo Park, Ca
Object Ident. Sketch
Ident. By J. N. Tennant USFS
8/77 Signature

(Line 2 - exposure 144)

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____ Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

See Cert Book
BCSP by county Surveyor
1982

Signature _____ Title _____ Division _____ Headquarters _____ Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. **J-9**

Index
File No. _____

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. J-11

T 29 S R. 14 E R.D. Basalt/Ft. Rock County Wata

Merid. wil N.F. Deschutes State ORE

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(16) GLO Record - Set Basalt Stone 12x8x6 and dug pits as per instructions for 1/4 Sec. corner.
Found - After diligent search following extensive traversing, No evidence of original monument or accessories.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

6

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT


Set - by single proportion, a 2 1/2" dia. x 30" long steel pipe, surmounted by a 2 1/2" dia. brass cap, rising 4" in a mound of stone, from which:

A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N. 32° 49' E., 37.4 ft., marked BO 1 PLS 2111 1995.

A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S. 89° 37' E., 21.7 ft., marked BO 2 PLS 2111 1995.

A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S. 85° 59' W., 8.6 ft., marked BO 3 PLS 2111 1995.

GPS 18, a 5/8" re-bar with a 3 1/4" dia. alum. cap driven flush, N. 68° 55' W., 68.1 ft., mkd. GPS 18 PLS 2111 1994.



ACC

VE EXISTING EVIDENCE

Work Done By W. Miller Title _____ Date Sept 95 State Registration No. _____ or Agency _____ 10

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 12
13

Index
File No. _____

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. J-13

T 295 R. 14E R.D. Bend/ Ft. Rock County Lake

Merid. wil N.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(17) GLO Record - Set Basalt Stone 15x10x8 and dug pits as per instructions for corner to Secs 9, 10, 15 & 16.
Found - After diligent search following extensive traversing, No evidence of original monument or accessories.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

6

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

8

4

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

17

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

T24S R
 9 | 10 14
 16 | 15 E
 PLS2111
 1995

Set - by double proportion, a 2 1/2" dia. x 30" long steel pipe, surmounted by a 2 1/2" dia. brass cap, rising 6" in a mound of stone, from which:

- GPS 19, a 5/8" re-bar with a 3 1/4" dia. alum. cap driven flush, N.66°24'E., 18.2 ft., mkd. GPS 19 PLS 2111 1994.
- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S.38°28'E., 18.3 ft., marked BO 1 PLS 2111 1995.
- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S.41°09'W., 35.8 ft., marked BO 2 PLS 2111 1995.
- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N.47°02'W., 25.8 ft., marked BO 3 PLS 2111 1995.
- A fence corner N.8°W., 21 feet.

SAVE EXISTING EVIDENCE

Work Done By W. Miller Title _____ Date Sept 95 State Registration No. _____ or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

Index
File No. _____

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. J-17

T 245 R. 14E R.D. Bend/Ft. Rock County Lake

Merid. Wil N.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(18) GLO Record - Set Basalt Stone 15x12x12 and dug pits as per instructions for corner to Secs 9, 10, 15 & 16.
Found - After diligent search following extensive traversing, No evidence of original monument or accessories.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

8

4

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)


5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set - by double proportion, a 2 1/2" dia. x 30" long steel pipe, surmounted by a 2 1/2" dia. brass cap, rising 6" in a mound of stone, from which:

- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N.47°40'E., 78.6 ft., marked BO 1 PLS 2111 1995.
- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S.17°01'E., 17.0 ft., marked BO 2 PLS 2111 1995.
- AC: A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S.36°53'W., 27.8 ft., marked BO 3 PLS 2111 1995.
- GPS 21, a 5/8" re-bar with a 3 1/4" dia. alum. cap driven flush, N.83°54'W., 61.2 ft., mkd. GPS 21 PLS 2111 1994.
- A Fence corner/rockjack, N.27°W., 56 ft.
- A silver colored water tank, N.28°W., 397 ft.



ERVE EXISTING EVIDENCE

Work Done By W. Miller Title _____ Date Sept 1995 State Registration No. _____
 for Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 12
13

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. J-23


T 245 R. 14E

R.D. Bend/Ft. Rock County Lake

Merid. W1

N.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(19) GLO Record - Set Basalt Stone 11x8x7 and dug pits as per instructions for 1/4 Sec. corner.
Found - After diligent search following extensive traversing. Original stone, 14x10x8 inches, marked 1/4 on North face.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

6

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Loc. Poster in Fence line 1/4 mile East

3

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

Title

Division

Headquarters

Date


FS-7100-52 (3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set - A 2 1/2" dia. x 30" long alum. pipe, surmounted by a 2 1/2" dia. alum. cap, rising 9" in a mound of stone, with original stone buried alongside, from which:

- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N. 49° E., 15.6 ft., marked BO 1 PLS 2111 1995.
- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S. 32° E., 14.9 ft., marked BO 2 PLS 2111 1995.
- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S. 49° W., 13.7 ft., marked BO 3 PLS 2111 1995.
- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N. 32° W., 19.8 ft., marked BO 4 PLS 2111 1995.

ACCI

IVE EXISTING EVIDENCE

10
11

Work Done By W. Miller Title _____ Date Sept 95 State Registration No. _____ or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 12
13

USDA-FOREST SERVICE

Index
File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. _____ Cor. No. J-25

T 24S R. 14E R.D. Bank/Ft Rock County Lake

Merid. Wil N.F. Deschutes State OR

CORNER DIAGRAM

R14E R15E



DESCRIBE CORNER MONUMENT FOUND

(20) GLO Record - Set Basalt Stone 16x12x5 in mound for corner to Secs. 12, 13, 7 & 18.
 Found - Original stone as described, but with no visible marks.
 Set - Steel fence post approx. 5 ft. North. GPS 24 bears N.56°E., 557.9 ft.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Big P. Pine to the SE about 200 ft.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

Signature WJ

Title _____

Division _____

Headquarters _____

Date 9/95 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

11

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

12

13

Index File No. T. R. M. Tract or Surv. No. Cor.

USDA-FOREST SERVICE

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. L-5

T 24S R. 14E

R.D. Bend/Ft. Rock County Lake

Merid. W:1

N.F. Deschutes State ORE

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

(22) GLO Record - Set Basalt Stone 12x10x8 and dug pits as per instructions for 1/4 Sec. corner.
Found - After diligent search following extensive traversing, Original stone of call size.
Set - A steel fence post 3 ft. North. GPS 25 bears N.36°09E., 84.97 ft.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

6

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

About 1/4 mile south of Road

5

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature W Ham

Title

Division

Headquarters

Date 8/95-FS-7100-52 (3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ **Title** _____ **Date** _____ **State Registration No.**
or Agency _____

Certified Cor. Record Prepared ? Yes No **Filed At:** _____ **Date** _____

REMARKS

Index File No. _____ **T.** _____ **R.** _____ **M.** _____ **Tract or Surv. No.** _____ **Cor.** _____

Index
File No. _____

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. L-9

T 245 R. 14E R.D. Bend / Ft. Rock County Lake

Merid. Wil N.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(29) GLO Record - Set Basalt Stone 14x11x4 and dug pits as per instructions for 1/4 Sec. corner.
Found - After diligent search following extensive traversing, No evidence of original monument or accessories.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT


Set - by single proportion, a 2 1/2" dia. x 30" long steel pipe, surmounted by a 2 1/2" dia. brass cap, rising 9" in a mound of stone.

A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N.78°38'E., 14.6 ft., marked 80 1 PLS 2111 1995.

GPS 54, a 5/8" re-bar with a 1 1/2" dia. alum. cap driven flush, S.67°27'W., 29.1 ft., mkd. GPS 54 PLS 2111 1994.

A P.P. 18" dia., S.80°16'E., 118.6 ft., mkd. X BT.

A P.P. 19" dia., N.68°43'W., 121.2 ft., mkd. 1/4 S17 BT.



ACCESSORIES: DESCRIBE NEW SETS WITH LEGS, COPIES, ETC., ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By W. Miller Title _____ Date 9/95 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor.

13

USDA-FOREST SERVICE

Index File No. 1761

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. L-17

T 2AS R. 14E

R.D. Ft. Rock

County Lake


Merid. WMP

N.F. Deschutes

State Oregon

W/4 Sec. 14

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DE Original stone 8"x8"x8" marked 4. Top of stone has weathered away or was broken off. Stone appears to be firmly set in its original location. An old fence line runs South from the stone to the Section Corner of sections 14, 15, 22 & 23. There is no evidence of the pits. 2

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 3

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

William B. Ham As


CS

SO

9/94

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set a 2 1/2" dia. x 30" long steel pipe surmounted by a 2 1/2" dia. brass cap rising 4".
 A penny at base of pipe. Original stone buried alongside.
 A steel fence post 5 ft. North.
 A 3/8" dia. rebar, 30" long, N.45°E., 17.7 ft., with 3" dia. alum. cap
 marked RM 1 PLS 2396 1993
 A 5/8" dia. rebar, 30" long, S.45°E., 31.7 ft., with a 1 1/2" dia. alum. cap
 marked RM 2 PLS 2596 1993
 A 5/8" dia. rebar, 30" long, S.45°W., 26.7 ft., with a 3" dia. alum cap
 marked RM 3 PLS 2396 1993
 A 3/8" dia. rebar, 30" long, N.45°W., 27.0 ft., with a 1 1/2" dia. alum. cap
 marked RM 4 PLS 2396 1993

ONE TO PRESERVE EXISTING EVIDENCE

Road approx. 35 ft. North. Fence corner approx. N.88°W., 92.6 ft.

Work Done By W.B. Ham Title PLS Date 9/94 State Registration No. 2396
 or Agency

Certified Cor. Record Prepared? Yes No Filed At: Lake Date 9/8/94

REMARKS

Survey of 1880 by Campbell.
 GLO Record - Set Basalt stone 3x8x8 and dug pits as per instructions for 1/4 sec. corner.

Index File No. 1761 T. 24 R. 14 Tract or Surv. No. CM.T Cor. L-17
 GPO: 1986 O-439-095

USDA-FOREST SERVICE


Index
File No. 0163
T 24 S. R. 14 S
Merid. Wm

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Ft. Rock County Lake Tract or Survey No. _____
N.F. Deechnutes State Oregon Cor. No. N-01
SW Corner
See. 18

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

no evidence of original monument. Set corner by distance/distance intercept from SW BT and Stump of SE BT. From corner location:
Remains of a large stump in NE BT location.
no evidence of NW BT
A Ponderosa pine, 21" dia., S.72°W, 60 lks. (39.6 ft) to face with faint scribing exposed.
A burnt stump, S.20°E., 50 lks. (33.0 ft) no other evidence.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

William B. Ham

Asst

CS

SO


9/94

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set a 2½" dia. x 30" long alum. pipe surmounted by a 2½" dia. alum cap rising rising 4".
 A penny at base of pipe.
 A steel fence post 3 ft. North.
 A rebar 5/8" dia. x 30" long driven flush with a 3" dia. alum cap. N.35°E., 25.0 ft.
 marked BO PLS 2396 1994
 A Ponderosa pine, 26" dia., S.54°E., 189.0 ft., marked T24S R14E S19 BT
 A Ponderosa pine, 21" dia., S.72°W., 59.8 ft., Original BT, not re-marked.
 A Ponderosa pine, 28" dia., N.17°W., 96.6 ft., marked T24S R15E S15 BT
 A brass washer mkd. LS 2396 nailed between the B & T of the scribe. Distances to side-center
 E/W fence line approx. 5½ ft. North.
 Cattle guard on Road 2435 approx. 70 ft. West.

RESERVE EXISTING EVIDENCE

Work Done By W.B. Han Title PLS Date 9/94 State Registration No. 2396
 or Agency _____ Date 9/8/94

Certified Cor. Record Prepared? Yes No Filed At: Lace

REMARKS

Survey of 1880 by Campbell. GLO Record - Set post for Co
 to Secs. 15, 24, 18 & 19, from which:
 A pine 40 in. diam bears N 27°E 68 lks dist.
 A pine 14 " " " N12°30'W 64 " "
 A pine 7 " " " S 68°W 60 " "
 A pine 22 " " " S 23°E 50 " "

Index File No. 0163 T. 24 R. 14 W.M.T. Tract or Surv. No. Cor. N-01

GPO: 1986 O-439-095

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. N-9


T 24 S 14E R. _____

R.D. Bank / Ft Rock County Lake

Merid. Will

N.F. Deschutes State ORE

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(26) GLO Record - Set Basalt Stone 9x8x8 and dug pits as per instructions for corner to Secs 16, 17, 20 & 21.
 Found - After diligent search following extensive traversing. No evidence of original monument or accessories.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT


Set - by double proportion, a 2 1/2" dia. x 30" long steel pipe, surmounted by a 2 1/2" dia. brass cap, rising 6" in a mound of stone, from which:

A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N.60°12'E., 21.7 ft., marked BO 1 PLS 2111 1995.

GPS 31, a 5/8" re-bar with a 3 1/4" dia. alum. cap driven flush, S.72°25'E., 21.7 ft., mkd. GPS 31 PLS 2111 1994.

A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S.56°41'E., 83.7 ft., marked BO 2 PLS 2111 1995.

Stamped "X PLS 2111" in SE corner of cattle guard, N.59°05'W., 9.4 ft.



ERVE EXISTING EVIDENCE

10

Work Done By W. Miller Title _____ Date 9/95 State Registration No. _____ or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

12

13

Index File No. T. R. M. Tract or Surv. No. Cor.

US FOREST SERVICE

In ~~ex~~ File No. 1363

T 24S R. 14E

M rid. WMT

CO ~~NER~~ DIAGRAM

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Crescent

N.F. Deschutes

Tract or Survey No.

County Lake


State Oreg

Cor. No. N-1

Cor. Sec. NW

DESCRIBE CORNER MONUMENT FOUND

Original basalt stone 15" X 12" X 6", set firmly in the ground with 3 faint notches on E. edge. A small mound of stone around corner. A fence corner approx. 3 ft. East. Stone has an approx. 1" square chiseled on top. This is common with other corners found that were set by this GLO surveyor. No evidence of pits. Old dirt road running N/S approx. 10 ft. East of corner



T24S R 14E

PHOTO IDENTIFICATION DATA

Photo No. _____
File At. _____
Object Ident. _____
Date By _____
Signature

PLANE COORDINATE POSITION DATA

Station _____ Zone _____
X _____
Y _____
Established By _____
Agency _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

W. Diana B. Ham

Title

PLS

Division

CS

Headquarters

SD


Date

9/93

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set a 2½" dia. X 30" long alum pipe 26" in the ground, surmounted by a 2½" dia. alum. cap. A penny at base of pipe. Original stone buried alongside.
 A rebar, 5/8" dia. X 30" long, N.49° E., 37.1 ft., with 3" dia. alum. cap driven flush and marked NE BO PLS 2396 1993.
 A rebar, 5/8" dia. X 30" long, S.43° E., 37.2 ft., with 1½" dia. alum. cap driven flush and marked SE BO PLS 2396 1993.
 A rock outcrop 4ft. X 4ft. X 6", S.78° W., 169.3 ft., marked X BO.
 A boulder, 4½ft. X 4ft. X 3ft., N.55° W., 165.5 ft., marked X BO PLS 2396.
 A 6ft. steel fence post 3 ft. North of corner and all BO's.

ERVE EXISTING EVIDENCE

9

10

Work Done By Bill Ham Title PLS Date 9/93 State Registration No. 2396
 Certified Cor. Record Prepared? Yes No Filed At: Lake Co. Date 9/24/93 11
 er Agency _____

REMARKS

Survey of 1880 by Campbell.
 GLO Record - Set basalt stone 18 X 12 X 6 and dug pits as per instructions for corner to Secs. 15,16,21 & 22.

12

13

Index File No. 1363 T. 24 R. 14 W.M.P. Tract or Surv. No. _____ Cor. N-13
 GPO: 1986 O-439-095

US FOREST SERVICE


In Box
 File No. 1763
 T 24 S R. 14 E
 Merid. WMT

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Crescent County Lake Tract or Survey No. _____
 N.F. Daschutes State Oregon Cor. No. N-17
NW Cor 23

CORNER DIAGRAM



T. 24 S - R. 14 E.

DESCRIBE CORNER MONUMENT FOUND

Found - Original Basalt stone 13" X 8" X 6" with 2 grooves on East and 3 notches on South side. A 1" square chisled on top of stone which is common for this GLO surveyor. Corner surrounded by a small mound of stone. An old fence intersection bears East, 14 ft.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____


PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature William B Ham Title PLS Division CS Headquarters SO Date 9/93
 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Set a 2½" dia. alum. pipe, 30" long, surmounted by a 2½" dia. alum cap; 26" in the ground. A penny at base of pipe. Original stone buried alongside.

- A rebar, 5/8" X 30" long driven flush, N.45° E., 22.0 ft., marked B01 PLS 2396 1993
- A rebar, 5/8" X 30" long driven flush, S.45° E., 29.0 ft., marked B02 PLS 2396 1993
- A rebar, 5/8" X 30" long driven flush, S.45° W., 32.0 ft., marked B03 PLS 2396 1993
- A rebar, 5/8" X 30" long driven flush, N.45° W., 35.0 ft., marked B04 PLS 2396 1993

ERVE EXISTING EVIDENCE

A 6' steel fence post 3 ft. North. Bearings by hand compass. Mag. Dec. = 19° East.

10

Work Done By Bill Ham Title PLS Date 9/93 State Registration No. 2396
 or Agency
 Certified Cor. Record Prepared? No Filed At: Lake Co. Date 9/24/93

11

REMARKS

GLO Survey of 1880 by Campbell.
 GLO Record - Set a basalt stone 13 X 12 X 8 and dug pits as per instructions, for corner to Secs. 14, 15, 22 & 23.

12

Index File No. 1763 T. 24 R. 14 W.M.T Tract or Surv. No. Cor. N-17
 GPO: 1986 O-439-095

13

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. N - 25


T 24S R. 14E

R.D. Bend / Ft. Rock County Wakarusa

Merid. W.1

N.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(29) GLO Record - Set Basalt Stone 18x11x3 in mound of stone for corner to Secs 13, 24, 18 & 19.
 Found - After diligent search following extensive traversing, A stone of call size in a mound of stone but with no visible marks.
 GPS 34, a 10" spike driven through a Land Survey Monument sign.
 N.55°E., 64 ft. A location poster on a Juniper N.63°E., 63 ft. 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature 7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency 8

Signature W Ham

Title _____

Division _____

Headquarters _____

Date 8/95 FS-7100-52 (3/68) 4

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

10

11

12

13

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. P-9


T 29 S R. 14 E

R.D. Bend / Ft. Rock County Lake

Merid. wil

N.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

(32) GLO Record - Set Basalt Stone 10x8x7 and dug pits as per instructions for 1/4 Sec. corner.
 Found - After diligent search following extensive traversing, Original stone, 10x8x7 inches, marked 1/4 on West face.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

8

Signature _____ Title _____ Division _____ Headquarters _____ Date _____ FS-7100-52 (3/68)


4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

- Set - A 2 1/2" dia. x 30" long steel pipe, surmounted by a 2 1/2" dia. brass cap, rising 5" in a mound of stone, with original stone buried alongside, from which:
- A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N.53°E., 12.5 ft., marked B0 1 PLS 2111 1995.
 - A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S.24°E., 20.0 ft., marked B0 2 PLS 2111 1995.
 - A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, S.53°W., 17.8 ft., marked B0 3 PLS 2111 1995.
 - A 5/8" dia. x 30" long re-bar with a 1 1/2" dia. alum. cap driven flush, N.52°W., 17.3 ft., marked B0 4 PLS 2111 1995.



ERVE EXISTING EVIDENCE

10

11

Work Done By W. Miller Title _____ Date 9/95 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 12
13

USDA-FOREST SERVICE

Index

File No. 0565

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. P-05

T 24 S. R. 14 E.

R.D. Crescent

County Lake


w/4 S. 20

Merid. WMT

N.F. Deschutes

State Oreg.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Original stone 17" X 11" X 6" faintly marked 1/4 in small mound of stone.
No evidence of pits.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLAN E COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

William B. Ham

PLS

CS

SO

9/24

CORNER RECORD (PERPETUATION)


MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2½" X 30" aluminum pipe surmounted by a 2½" dia. aluminum cap; 12" in ground in a mound of earth and stone. Penny at base of pipe. Original stone buried alongside.

Steel fence post 3 ft. South.

A rock outcrop, 6ft. X 8ft. X 2ft., N.9°E., 28.8ft., marked X B0 in South end.
 A Ponderosa Pine, 12" dia., S.21°E., 91.6ft., marked 1/4 S20 BT.
 A Ponderosa Pine, 14" dia., S.47°W., 87.6ft., marked 1/4 S19 BT.
 A Ponderosa Pine, 11" dia., N.52°W., 78.8ft., marked 1/4 S19 BT.

A brass washer nailed between the B & T of the scribing.
 Bearings taken with a staff compass with a Magnetic Deviation of 19° East.



SERVE EXISTING EVIDENCE

Work Done By <u>Bill Ham</u>	Title <u>PLS</u>	Date <u>9/23</u>	State Registration No. <u>2396</u> or Agency	10
Certified Cor. Record Prepared? <input checked="" type="checkbox"/> Yes	No	Filed At: <u>Lake Co.</u>	Date <u>9/24/93</u>	11

REMARKS

Survey of 1880 by Campbell.
 GLO Record - Set Basalt stone 20 X 12 X 6 and dug pits as per instructions for 1/4 sec. corner.

Index File No. <u>0565</u>	T. <u>24</u>	R. <u>14</u>	M.T. <u>U.T</u>	Tract or Surv. No. GPO: 1986 O-439-095	Cor. <u>P-05</u>	12 13
-------------------------------	-----------------	-----------------	--------------------	-------------------------------------------	---------------------	----------

USDA-FOREST SERVICE

Index

File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. P-21


T 24 S R. 14E

R.D. Bend / Ft Rock County Lake

Merid. Wil

N.F. Deschutes State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

33. GLO Record - Set Basalt Stone 10x8x7 and dug pits as per instructions for 1/4 Sec. corner.
 Found - After diligent search following extensive traversing, Original stone, 10x8x8 inches, marked 1/4 on West face.
 Set - A steel fence post 3 ft. North. Corner is in a North/South fenceline.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature W Ham

Title _____

Division _____

Headquarters _____

Date 8/95 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.