

T 24S, R 5½E, M W

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
C	+	6	+			+	5	+		+	4	+		+	3	+		+	2	+		+	1	+	
D	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
E																									
F	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
G	+	7	+			+	8	+		+	9	+		+	10	+		+	11	+		+	12	+	
H	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
J																									
K	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
L	+	18	+			+	17	+		+	16	+		+	15	+		+	14	+		+	13	+	
M	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
N																									
O	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
P	+	19	+			+	20	+		+	21	+		+	22	+		+	23	+		+	24	+	
Q	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
R																									
S	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
T	+	30	+			+	29	+		+	28	+		+	27	+		+	26	+		+	25	+	
U	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
V																									
W	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
X	+	31	+			+	32	+		+	33	+		+	34	+		+	35	+		+	36	+	
Y	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	
Z																									

LEGEND

○ = Corner having information on form 7100-52 in this file.

*Legend Confirms To
Reporting Form 2/80
MPB*

FILING INSTRUCTION

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.

Index

File No. S-10

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. S-10T 24S R. 8ER.D. CrescentCounty KlamathNW 1/6 Cor Sec 28Merid. WillN.F. DeschutesState OR

CORNER DIAGRAM


NW $\frac{1}{16}$ 6

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER MONUMENT FOUND

To Verify

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

wood stake 4"x4"x3' good cond.Brooks - Scanlon Property sign and old B.S.
location posterSee attached notes

3

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52-(3,68)

4

5

Larry MooreFor TechPreSaleCrescent3-16-75

USDA-FOREST SERVICE

Index

File No.

2168

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

000250

Cor.


No.

S-21

T. 24 S. R. 8 E. R.D. CRESCENT County CLATSOP N/16 COR. of SEC.

Merid. WILLAMETTE N.F. DESCHUTES State OREGON 25/26 COR. of SEC.

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORN

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

Signature

Title

Division

Headquarters

Date

D-7100-52 (3/)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

#5x48" SR RSG. 4"

MONUMENT SET

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

RP3

12" L. PINE N85°W 208 FT.

5" L. PINE N49°E 272 FT.

Work Done By R. OMAN

Title RS

Date 7/79

State Registration No. OR-702
or Agency

☒ PLAT PREPARED OR
Certified Cor. Record Prepared? ☒ Yes

No

Filed At: KLAM.

CO. SURVEYOR'S OFFICE

Date 7/79

REMARKS

Index File No. 2168 T. 24 S., R. 8 E., W.M.

Tract or Surv. No.

000250

Cor. 5-21

USDA-FOREST SERVICE

Index

File No.

2268

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

000250

Cor.

No.

S-22

T. 24 S. R. 8 E.

R.D.

CRESENT

County

KCANATH

N~~1~~/~~16~~

COR. of SEC.

Merid. WILLAMETTE

N.F.

DESCHUTES


State

OREGON

2.5

COR. of SEC.

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No.

Filed At

Object Ident.

Ident. By

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Signature

Title

Division

Headquarters

Date

D-7100-52 (3/)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" X 30" BRASS-CAPPED STEEL PIPE

MONUMENT SET/STATED

NW 1/4
S. 25

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

RP's

5" L. PINE S53°W 66 FT.

10" L. PINE N14°E 15 FT.

Work Done By R. OMAN Title PLS Date 7/79 State Registration No. OR-702
 PLAT PREPARED OR Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KLAM. Co. SURVEYOR'S OFFICE Date 7/79

REMARKS

Index File No. 2268 T. 14 S., R. 8 E., W.M.

Tract or Surv. No. 000250 Cor. S-22

USDA-FOREST SERVICE

Index

File No.

2368

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

000250

Cor.

No.

S-23

T. 24 S. R. 8 E.

R.D. CRESCENT

County KLAMATH

NE 1/4

COR. of SEC.

Merid. WILLAMETTE

N.F. DESCHUTES


State OREGON

35

COR. of SEC.

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No.

Filed At

Object Ident.

Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found

☒ Evidence Found/Accept

☒ Permanent Monument

Signature

Title

Division

Headquarters

Date

D-7100-52 (3/7)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" X 30" BRASS-CAPPED STEEL PIPE

MONUMENT STAFFED

NO/L
S. 25

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

RP's
8" L. PINE N 21° W 255 FT.
12" L. PINE N 45° E 312 FT.

Work Done By

R. ROMAN

Title

PLS

Date

7/79

State Registration No. or Agency

OR-702

PLAT

PREPARED OR

Certified Cor. Record Prepared?

Yes

No

Filed At

KLAM.

Co. SURVEYOR'S OFFICE

Date

7/79

REMARKS

Index File No.

2368

T. 24S., R. 8

E., W.M.

Tract or Surv. No.

000250

Cor. 5-23

USDA-FOREST SERVICE

Index

File No. 2468

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

000249

Cor.

No.

S-24T. 24 S. R. 8 E.R.D. CRESCENTCounty KLAMATHNE 1/4

COR. of SEC.

Merid. WILLAMETTEN.F. DESCHUTESState OREGON25

COR. of SEC.

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accepted☒ Permanent Monument

Signature

Title

Division

Headquarters

Date

D-7100-52 (3/7)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

#5x48" ACSR RSG. 2"

MONUMENT SET

NE
16

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

RP's

9" L. PINE S86°E 57⁷ FT. & 60d NL. IN N. BASE

4" L. PINE N14°E 117⁷ FT. & 60d NL. IN W. BASE

1/2" PIPE N59°E 49⁸³ FT.

Work Done By R. OMAN Title PLS Date 9/79 State Registration No. OR-702
or Agency

PLAT PREPARED OR

Certified Cor. Record Prepared ? (Yes)

No

Filed At: KLAM.

Co. SURVEYOR'S OFFICE Date 9/79

REMARKS

Index File No. 2468 T. 24 S., R. 8 E., W.M.

Tract or Surv. No. 000249 Cor. S-24

Index
File No. 2568

T 24 R. 8

Merid. W.M.T

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. CRESCENT County KLAMATH


N.F. DES State OR

Tract or
Survey No.

Cor.
No. S-25

N/16 Cor Sec. 25 & 30

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

5 SR

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

2 BT's

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

BH

Title

Division

Headquarters

Date


1978 7100-52 (3 63)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

#5 X ~~48~~" STEEL ROD W/AL. CAP RSG 2"
SET BY TRAVERSE IN 1975



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

a 8" LP BRS N69°W 47 FT B/S N/16 S 25 BT
a 5" LP BRS N59°E 23⁰⁸ FT B/S N/16 S 30 BT

10

Work Done By R. OMAN Title PLS Date 1975 State Registration No. 04-702
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: PLAT 2735 KLAM. CO. SURV. OFFICE Date 1975

11

REMARKS

Index File No. 2568 T. 24 R. 8 M. Tract or Surv. No. Cor. 525

12

Index

File No. 0169T 24 R. 8Merid. WMT

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No. T-01R.D. CRESCENT


County

CLATSOPN.F. DES

State

ORW/4 Cor Sec 30E/4 Cor Sec 25

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature RH

Title

Division


Headquarters

Date 1978 7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. **T-01** 13

Index
File No. 0569
T 24 S R. 8 E
Merid. Will.

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. T-5

R.D. CRESCENT County KLAMATH.
N.F. DESCHUTES State ORE

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Wood - 3" Limb which has been squared at top,
3' above ground

NORTHING PETER 1978 R.H.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Three 5"-8" Trees with the following set of
blazes.



as reported by R. Jensen } 7/24/72
G. Foster

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Leave Crescent on paved county road (west) 5.1
miles to Jct. with Rd. 244 - Go along 244 0.2 mile.
on left side of road is F.S. location poster,
Follow blaze line So. Approx 250' to Cor.
(orange ribbon.)

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

H.M. Van Horn

ENR TECH.

S.O.

11/31/73

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. **T-05** 13

Index

File No. 0969

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____


Cor.

No. _____

T-9

T 24 S. R. 8 E.R.D. CrescentCounty KlamathMerid. WillametteN.F. DeschutesState Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

1" galvanized steel pipe, rising 7" above ground, but only 15 feet from orig. BT rather than called for 29.70 ft.-removed same.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S-28, an 18" P. Pine, scribed as called for

S-29, Nothing

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Agency _____

Signature _____

Title _____

PLS

Division _____

Headquarters _____

Deschutes N. F.


Date 30 DEC 1974

1004-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½ X 32" brass-capped steel pipe, rising 4" above ground,
stamped as shown:



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-28, an 18" P. Pine Brs. East 29.70 Ft., (orig. BT), nail set in north side

S-29, an, 18" P. Pine Brs. West 22.10 Ft., B/S "S 29 BT", nail set in north side

10

Work Done By R. E. Oman Title PLS Date 1 NOV 74 State Registration No. OR-702, WV-23
or Agency

Certified Cor. Record Prepared? Yes ☒ No Filed At: Klamath Falls, Klamath Co. Date 18 DEC 1974

11

REMARKS

12

Index File No. T.24 S. R. 8 E. M. Willamette Tract or Surv. No. Cor. T-9

13

Index

File No. 1369

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. _____

Cor.

No. T-13T 24 S R. 8 ER.D. CrescentCounty KlamathE/4 COR. SEC. 28Merid. WilliametteN.F. DeschutesState OregonW/4 COR. SEC. 27

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Nothing

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SNAG
S-28 a 19" L.P. Pine Brs. S 45° W 31° Scribbled as called for.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

The brass cap is set in the cut bank of Davis Lake road out of Crescent. About 3 1/2 miles and on the South side.

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

5


Darryl C. Hildebrand Civil Eng. Tech. Rec. Con. Bend

6-20-78

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a $2\frac{1}{2} \times 32$ " Brass Capped Galvanized steel Pipe
 rising about $1\frac{1}{2}$ " above the Ground Stamped as shown.
 at top of cutbank



Re-set 9/80 ERROR in INITIAL BPG.

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-27 a 8" LP Pine Brs. S $56^{\circ}E$ ¹⁶⁶ 22 1/2 ft B/S "1/4 B.T." 20 d NL on NE side

S-28 a 7" LP Pine Brs. S $47^{\circ}W$ ¹⁷⁵ 15 1/2 ft B/S "1/4 B.T." 20 d NL on SE side

Work Done By R. OMAN Title PLS Date _____ State Registration No. OR-702
 or Agency

Certified Cor. Record Prepared? ☒ Yes No Filed At: KL. Co. SURV. Office Date 7/78

REMARKS

The brass Cap was set from remaining original B.T.

Index File No. 1369

T. 245

R. 8E

M. Willamette Tract or Surv. No.

Cor. T-13

USDA-FOREST SERVICE

Index

File No. T-17

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.


000864

Cor.

No.

1769T 24S R. 8ER.D. Crescent County KlamathW/4 S26Merid. WilliametteN.F. Deschutes State ORE/4 S27

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SF/FF

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

B. Ham

Title

PLS

Division

OS

Headquarters

SO

Date

12/91

FS-7100-52 (3/68)

3

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT


Set 5/8" dia x 30" Long rebar 1ft below surface of the road, surmounted by a 3" dia aluminum cap
A penny below cap

(see below)

ACCESSORIES: DESCRIBE NEW B^T's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A L.P. 3" dia bears N 84° 03' E 31.95 FT marked X BT
" " 8" " " S 57° 57' E 56.30 " " 1/4 S26 BT
" " 12" " " S 74° 52' W 53.70 " " 27 BT
" " 4" " " N 33° 52' W 31.00 " " XBT

Work Done By W. Ham Title PLS Date 12/91 State Registration No. 2396
or Agency
Certified Cor. Record Prepared? ☒ Yes No Filed At: Klamath Co Date 2/19/92
REMARKS



Index File No. 1769 T. 24 R. B M. GPO: 1986 O-439-095 Tract or Surv. No. 000864 Cor. T-17

USDA-FOREST SERVICE

Index

File No. 2069T. 24 S. R. 8Merid. WILLAMETTE


CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

E. R. D. CRESCENT CountyN. F. DESCHUTES State OREGONTract or
Survey No. _____Cor.
No. 7-20COR. of SEC. 26

COR. of SEC. _____

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

3"x3" WOODEN POST, 3 FT. ABOVE GROUND - FAIR
CONDITION. NO MARKINGS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

THERE IS A "Y" SCRIBED IN A 10" PINE SNAG.
2 METAL SIGNS DESCRIBING CORNER, CORNER
IS TARGETED FOR AERIAL PHOTO FLIGHT.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☐ Permanent Monument

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

NOTE: THIS CORNER SHOULD BE RESTORED AS
SOON AS POSSIBLE

Signature

Title

Division

Headquarters

Date

D-7100-52 (3/79)

T. NELSON - D. BARNETT F.T.


D-2

6-25-23

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT SET



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By

Title

Date

State Registration No.
or Agency

PLAT PREPARED OR

Certified Cor. Record Prepared ? Yes

No

Filed At:

Co. SURVEYOR'S OFFICE Date

11

REMARKS

RCVD FROM D-2 FILES 4/82

12

Index File No.

2069

T.

S., R.

E., W.M.

Tract or Surv. No.

T-20 Cor.

13

Index

File No. T-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No.

Cor.

No.

T-212169T 24 S R. 8ER.D. CRESCENTCounty KLAMATHE/4 COR. SEC. 26Merid. WILLAMETTEN.F. DESCHUTESState OREGONW/4 COR. SEC. 25

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NO CORNER FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S-26 14" PINE STUMP BRS. N 75° W AT 13²
SCRIBED AS CALLED FOR

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At: _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

Harry C. Heldebrand Civil Eng. Tech. Pre. Con. Bend


9-7-78

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS CAPPED STEEL PIPE RISING ABOVE
THE GROUND 6" STAMPED AS SHOWN



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-26 9" L.P. PINE BRS. S 62° W AT 24 1/2 B/S " 1/45 BT "

S-25 11" L.P. PINE BRS. N 58° E AT 48 B/S " 1/45 BT "

Work Done By. R. OMAN Title DCS Date _____ State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Mc. Co. Surv. Office Date 2/78

REMARKS

Index File No. T-21 T. 245 R. 8E M. WILLAMETTE Tract or Surv. No. T-21
CR. 2169

USDA-FOREST SERVICE

Index

File No. 2269

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No. 000250

Cor.

No. T-22T. 24 S. R. 8 E. R.D. CRESCENTCounty CLATSOPW/16


COR. of SEC.

Merid. WILLAMETTEN.F. DESCHUTESState OREGON25

COR. of SEC.

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND



6

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

7

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Signature _____

Title _____

Division _____

Headquarters _____

Date _____

D-7100-52 (3/7)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" X 32" BRASS-CAPPED STEEL PIPE RSG. 0"

MONUMENT SET/STAMPED

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

RP's

#5 X 48" SR RSG. 3" N 00° 15' 54" E 129⁸⁵ FT @ N. R/W LINE

Work Done By

R. OMAN

Title

PLS

Date

7/79

State Registration No. or Agency

OR 702

PLAT PREPARED OR

Certified Cor. Record Prepared? Yes

No

Filed At

BLAN.

Co. SURVEYOR'S OFFICE

Date

7/79

REMARKS

000250

Index File No.

2269

T. 24

S., R.

8 E., W.M.

Tract or Surv. No.

000244

Cor. T-22

USDA-FOREST SERVICE

Index

File No. 2369

CORNER RECORD (SEARCH)


(Ref. FSM 7.151.4)

Tract or KL. CO. REC. SURV. Cor.Survey No. 3242No. T-23T. 24 S. R. 8E. R.D. CrescentCounty KlamathR.D. 244

e/4 COR. of SEC.

Merid. WILLAMETTEN.F. DESCHUTESState OREGON25 COR. of SEC.

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

1 1/4" Steel Rod Set by Koutynovich
100' N. of #4 S.R.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None Set.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORN

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accepted☒ Permanent Monument

Signature

Rocky H. Debrand

Title

P.L.S.

Division

Headquarters

3/81

Date

D-7100-52 (3/)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STATED

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By

Title

Date

State Registration No.
or Agency

PLAT PREPARED OR

Certified Cor. Record Prepared ?

☒ Yes

No

Filed At:

KLAM.

CO. SURVEYOR'S OFFICE

Date

REMARKS

Index File No. 2369 T. 24 S., R. 8 E., W.M.

Tract or Surv. No. 244

Cor. T-23

USDA-FOREST SERVICE

Index

File No. 2469

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.


000249

Cor.

No.

T-24T. 24 S. R. 8 E. R.D. CRESCENT County KLAMATH EC/16 COR. of SEC.Merid. WILLAMETTE N.F. DESCHUTES State OREGON 25 COR. of SEC.

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORN

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accepted☒ Permanent Monument

Signature _____

Title _____

Division _____

Headquarters _____

Date _____

D-7100-52 (3/)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

#5x48" AC SR RSG. 9"

± 9' S. of Top of ROAD CUT-BANK

MONUMENT SET/ED

EC
16

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By R. OMAN Title PLS Date 9/99 State Registration No. or Agency OR-702
☒ PLAT PREPARED OR
 Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KLAM. Co. SURVEYOR'S OFFICE Date 9/99

REMARKS

Index File No. 2469 T. 24 S., R. 8 E., W.M.

Tract or Surv. No.

000249

Cor. T-24

Index

File No. T-25

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.

No. 2569T 24S R. 8ER.D. CRESCENT County KLAMATHE/4 COR. SEC. 25Merid. WILLAMETTEN.F. DESCHUTES State OREGONN/4 COR. SEC. 30

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

APPROX. CENTER LINE
CRESCENTED.1" R.R. SPIKE
1" R.R. SPIKE

25 30

STONE THAT WAS 9" X 6" X 4" BURIED 12" BELOW
GROUND - BROKEN IN 1/2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NOTHING

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52 (3-68)

Larry C. Hildebrand

Civil Eng. Tech. Pre-Con.

Bend


9-7-78

CORNER RECORD (PERPETUATION)

MONUMENT
STANDARD

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS CAPPED STEEL PIPE BURIED
BELOW GROUND 1" STAMPED AS SHOWN



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-25 A 1" R.R. SPIKE BRS. N 42°W AT 39 45 IN PVMT.

S-30 A 1" R.R. SPIKE BRS. N 52°E AT 41 69 IN PVMT.

Work Done By R. OMAN Title PLS Date _____ State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KL. Co. SURV. Office Date 7/78

Revisited by Tom Miller 4/91
See: 000847

REMARKS

Index File No. T-25 T. 245 R. 8E M. WILLAMETTE Tract or Surv. No.

T-25
Cor. 256913

Index

File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

U-9

T 24 S. R. 8 E

R.D. Crescent

County

Klamath


Merid. Willamette

N.F. Deschutes

State

Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

PLANE COORDINATE POSITION DATA

State Zone

X

Y

Estab. By

Agency

Signature

Title

Division

Headquarters

Date

About 200 Ft. south of dirt road leading from Road 254 near south line of Sec. 29

PLS


Deschutes N. F.

80 DEC 1974 00-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 5/8" X 30" aluminum-capped steel rod, flush with ground,
stamped as shown:



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-28, a 14" L. Pine Brs. N 46 E 50.73 Ft., B/S "S 28 BT", nail in SE side

S-29, an 18" P. Pine Brs. N 32 W 38.00 Ft., B/S "S 29 BT", nail in NE side

10

Work Done By. R. E. Oman Title PLS Date 8 NOV 74 State Registration No. OR-702, WV-23
for Agency

Certified Cor. Record Prepared ? Yes ☒ No Filed At: Klamath Falls, Klamath Co. Date 18 DEC 1974

11

REMARKS

Traversed from SE to E $\frac{1}{4}$ corners of Sec. 29 to establish location.

12

Index File No. T. 24 S. R. 8 E M. Willamette Tract or Surv. No. Cor. U-9

13

USDA-FOREST SERVICE

Index

File No. 2170

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No. 000244

Cor.


No. U-21T. 24 S. R. 8E. R.D. CRESCENTCounty CLATSOP3/16

COR. of SEC.

Merid. WILLAMETTEN.F. DESCHUTESState OREGON25/26

COR. of SEC.

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

7

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accepted☒ Permanent Monument

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature _____

Title _____

Division _____

Headquarters _____

Date _____


D-7100-52 (3/)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" X 32" BRASS-CAPPED STEEL PIPE RSG. 2"

MONUMENT SET/STATED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" L. PINE N 68° W 2555 FT. & 60 d R/L. IN S. BASE
MAKD. 5/16 526 BT

5" L. PINE S 14° W 3807 FT. & 60 d N/L. IN W. BASE
MAKD. 5/16 526 BT

Work Done By R. OMAN Title PLS Date 7/80 State Registration No. OR-702
or Agency

PLAT PREPARED OR
Certified Cor. Record Prepared? ☒ Yes No Filed At HEAM. Co. SURVEYOR'S OFFICE Date 7/80

REMARKS

Index File No. 2170 T. 24 S., R. 8 E., W.M.

Tract or Surv. No.

Cor. U-21

USDA-FOREST SERVICE

Index

File No.

2270

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or
Survey No.

000244

Cor.
No.

4-22

T. 24 S. R. 8

E.

R.D. CRESCENT

County

KLAMATH

Merid. WILLAMETTE

N.F. DESCHUTES

State

OREGON

SW 1/6 COR. of SEC.

25 COR. of SEC.

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND




PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

6

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accepted☒ Permanent Monument

Signature

Title

Division

Headquarters

Date


D-7100-52 (3/)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" X 32" BRASS-CAPPED STEEL PIPE BURIED 5"
BELOW SE WHEEL TRACK ON DIRT ROAD

MONUMENT SET



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

#5 PC SR BRS N66°57'E 084 FT. MKD BEARING OBJECT
3/4" PIPE RSG. 15" BY FENCE COR. BRS. S09°27'W 872 FT.

Work Done By R. OMAN

Title PCS

Date 7/80

State Registration No. OR-702
or Agency

PLAT PREPARED OR
Certified Cor. Record Prepared

Yes

No

Filed At: KLAM

Co. SURVEYOR'S OFFICE Date 7/80

REMARKS

Index File No. 2270 T. 24 S., R. 8 E., W.M.

Tract or Surv. No. 000244 Cor. 24-22

USDA-FOREST SERVICE

Index

File No.

2370

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

000244

Cor.

No. 4-23

T. 24 S. R. 8

E. R.D. CRESCENT

County KLAMATH

S. 1/6

COR. of SEC.

Merid. WILLAMETTE

N.F. DESCHUTES


State OREGON

25

COR. of SEC.

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORN

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept☒ Permanent Monument

Signature

Title

Division

Headquarters

Date

D-7100-52 (3/)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT (SET) OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" X 32" BRASS-CAPPED STEEL PIPE RSG. 3"

North of AIRSTRIP ROAD

MONUMENT STARTED

7245
30/16
525
ROMAN PL
OR-702
1980

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

#5 PCSR BRS. N 57° 36' E 170 FT.

#8 SR MKD. "K" BRS. 589° 19' E 440 FT.

Work Done By R. OMAN
(PLAT PREPARED OR
Certified Cor. Record Prepared? Yes No

Title

PCS

Date

7/80

State Registration No.
or Agency

OR-702

Filed At:

ALAN. CO.

SURVEYOR'S OFFICE

Date

7/80

REMARKS

Index File No.

2370

T.

24 S., R. 8

E.

W.M.

Tract or Surv. No.

Cor. 4-23

Index
File No. 2570
T 24 R. 8
Merid. Walt

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No. U-25

R.D. CRESCENT


County MCANATH

5/16 Cor. Sec 25 30

N.F. DES

State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

#5 SR

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

— NONE —

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature RH

Title

Division

Headquarters

Date

1978


7100-52 (3 63)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

#5X30" ACSR SET FROM TRAVERSE
RSG 4"



IN MEADOW 122 FT NORTH & 12 WEST
OF FENCE CORNER

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

NOTHING AVAILABLE

Work Done By: R. OMAN Title: PLS Date: 1975 State Registration No. or Agency: OP-702
Certified Cor. Record Prepared? ☒ Yes No Filed At: CLAM. CO. SURV. OFFICE Date: 1975

REMARKS

Revisited 4/91 by Tom Miller
See: 000847

Index File No. 2570 T. 24 R. 8 M. Tract or Surv. No. 425 Cor. 12

Index
File No. 2570
T 24 R. 8
Merid. W.N.T.


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. U-25
5/16 Cor. Sec. 25 & 30

R.D. CRESCENT County KLANATH
N.F. DES State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

#5 SR

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

— NONE —

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature

RH

Title

Division

Headquarters

Date

1978


7100-52 (3 69)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

#5X30" ACSR SET FROM TRAVERSE
RSG 4"



IN MEADOW 122 FT NORTH 10 WEST
OF FENCE CORNER

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

NOTHING AVAILABLE

Work Done By

R. OMAN

Title

PLS

Date 1975

State Registration No. or Agency

OR-702

Certified Cor. Record Prepared ? ☒ Yes

No

Filed At

BLAINE CO. SURV. OFFICE

Date

1975

REMARKS

Revisited 4/91 by Tom Miller

See:

000847

Index File No.

2570 T. 24 R. 8 M.

Tract or Surv. No.

425 12

Index

File No. 0171T 24 S R. 8 E

Merid. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. _____Cor.
No. V-01R.D. CRESCENTCounty KLAMATH

S.W. Cor Sec 30

N.F. DESCHUTESState OREGON

N.E. Cor Sec 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Wood - 4" DIA. - 4' Above ground

No Good Run 1978 SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" Stump w/ F.S. location Poster.
as reported by R. Jensen - 7-24-72

NOT BT - NOTHING AVAILABLE TO SET MON.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

leave Crescent on paved County Rd. (West) 6 1/2 Miles
To First Major Jct. after Rd 244 - To the left (on
right side of County Rd. is sec. board Mkr. 19-30
Proceed to Jct. of Fire road E & F (Approx. 0.2 Miles).
Take Road F. for approx 1 1/2 mile. Corner is Approx
150' west of Fire Road "F"

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

H. M. Van Horn

Eng. Tech.

S.O.

1/31/73

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor. *Y-01* 13

Index

File No. V-3

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No.

Cor.

No. 0371**V-03**T 215 R 8ER.D. CrescentCounty KlamathS/4 COR. SEC. 30Merid. WilliametteN.F. DeschutesState OregonN/4 COR. SEC. 31

CORNER DIAGRAM

30



31

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER MONUMENT FOUND

Nothing

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S-30 A 10" L.P. Pine Brs. N 39°W 17⁸ ft Scribbled as Called for.S-31 A 14" L.P. Pine Brs. S 50°W 34³ ft. Scribbled as Called for.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Approximately 1800' West on Section Line from Location poster on a small dirt road.

Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

4

5

Harry C. Willard Civil Eng. Tech. Pre. Const.

Bend.


6-26-78

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set A 2 1/2" x 30" Brass Capped Galvanized Steel pipe
Rising 4" above the Ground Stamped as shown.



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-30 A 11" L.P. Pine Brs N 10°E 16 1/2 ft B/s "1/4 BT"

Work Done By R. OMANN Title PLS Date _____ State Registration No. or Agency OR-702

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KL. Co. SURV. Office Date 7/78

REMARKS

Index File No. V-3 T. 24S R. 8E M. Willamette Tract or Surv. No.

Cor. 0371

V-03₂

1

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Steel post with 54-9 Northwest.

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" LP bts, 569°E 68.3' marked T245 R8E S32 BT

Painted all BT's as per specifications & attached signs 54-9 to backs of all BT's.

Work Done By J. Collins Title LS Date 10/91 State Registration No. ORPLS 1020
or Agency

Certified ~~Cor. Record~~ Prepared (Yes) No Filed At Klamath County Surveyor Date 1991

REMARKS

Index File No. V-5 T. 245 R. 8E M. W. H. Tract or Surv. No. 1-2 Cor. 0571

USDA-FOREST SERVICE

Index

File No. V-7

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

000862

Cor.

No. 0771T 24S R. 8ER.D. Crescent


County

Klamath1/4 Cor.Merid. WillametteN.F. Deshutes

State

OregonSecs. 29-32

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found BCSP Cap marked
R.E. CHAN PLS
1/4 COR
29
32
OR 702

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

10" PP brs. S27°W 28.3'

12" PP brs. N63°E 40.4'

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From County Road 61; South on Rd.
5825 0.5 mi.; thence West 1/4 mi. to
corner.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Steel Post with 54-9 North.

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" DP bts. S59°E 65.6' marked 1/4 532 BT

6" DP bts. N29°W 64.8' marked 1/4 529 BT

Painted all BT's as per specifications and attached signs 54-9 to backs of all BT's.

10

Work Done By *J. Colvin* Title *LS* Date *10/91* State Registration No. *ORPLS 1020*
 Certified *Yes* Record Prepared? ☒ Yes ☐ No Filed At *Klamath County Surveyor* Date *1991*

11

REMARKS

12

Index File No. *V-7 T. 245 R. 8E* M. *W-11* Tract or Surv. No. *1-2* Cor. *0771*

13

Index
File No. 0871T 24 S. R. 8 E.Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Crescent


County

KlamathN.F. Deschutes

State

OregonTract or
Survey No. _____Cor.
No. V-8E/16 Cor Sec 29 & 32

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Nothing

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Nothing

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab. By _____

Signature _____

Agency _____

Title

PLS

Division

Headquarters


Deschutes N. F.Date 30 DEC 1974

1574-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 5/8" X 30" Aluminum-capped steel rod, flush with ground,
stamped as shown:
(Placed steel fence post on south side of corner.)



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-29, a 5" L. Pine Brs. N 34 E 13.57 ft., B/S "S 29 BT", nail set in SE side

10

Work Done By R. E. Oman Title PLS Date 8 NOV State Registration No. OR-702, WV-23
for Agency

Certified Cor. Record Prepared? Yes ☒ No Filed At: Klamath Falls, Klamath Co. Date 18 DEC 1974

11

REMARKS

Traversed from SE to SW corners of Sec. 29 to establish location. Section line poster presently along existing Road 254. Proposed relocation of Road 254 is about 280 feet further east.

12

Index File No.

T. 24 S. R. 8 E.

M. Willamette Tract or Surv. No.

Cor. V-8

13

Index
File No. V-9

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. 1-2

000862

Cor.
No. 0971T 245 R. 8ER.D. CrescentCounty KlamathCorner Secs.Merid. WillametteN.F. DeputiesState Oregon28-29-32-33

CORNER DIAGRAM

T245 R8E



DESCRIBE CORNER MONUMENT FOUND

Found 5/8" iron rod
with aluminum cap buried 2". Cap mtd.
Old posted lines run North
and West from corner position.

R. OMAN
SEC COR
29 | 28
32 | 33
WV23 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

10" LP brs, ~~N 38° E~~ W 53.4' blazes healed over,
31" PP brs, N 38° E 47.4' Scribes visible (Orig. BT)
14" PP brs, S 26° E 61.5' blazes healed over,
11" LP brs, S 59° W 60.8' Scribes visible,
orig. - PP stamp 20" dia S 85° E 67.3' with scribing visible.
All BTs alive and healthy,
Measurements taken to side center of root
crown.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From County Rd. 61; South on F.S. Rd. 5825
1/2 mile. Corner is East 1/4 mile. (Primitive
unmarked dirt road meanders easterly from
5825 for closer access.)

Loc. Poster on Unmarked Rd 10chs East of Cor.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

J. Cohen

LS

10/91

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set BCSP visting 4", No stones available,
Removed iron rod w/ aluminum cap from site,

Cap marked
T245 R8E
529 | 528
532 | 533
1991
LS1020

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Painted 6" red ring around all BT's and placed new signs
54-3 on all BT's. Full nails placed in sides of all BT's to
reflect my measurements, Placed signs 54-9 on backs of
all BT's.

Work Done By

J. Colvin

Title

LS

Date

10/91

State Registration No.
or Agency

OPPLS 1020

Certified Cor. Record Prepared ? ☒ Yes

No

Filed At

Klamath County

Surveyor

Date

1991

REMARKS

Index File No.

V-9 T. 245 R. 8E

M.

W. H.

Tract or Surv. No.

1-2

Cor. 0971

USDA-FOREST SERVICE

Index

File No. V-11

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

000862

Survey No.

1-2

Cor.

No.

1171

T 245 R. SER.D. Crescent


County

Wamath1/4 Cor.Merid. WillametteN.F. Douglas

State

OregonSecs. 28-33

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found GLSP Cap marked

175179 2"

T245

R	28	1
S	1	4
E	33	4

1980

R.OMAN OR 702

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

7" PP brs. $514^{\circ}W$ 23.6'30" PP brs. $N30^{\circ}E$ 37.6'

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estat. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From County Road 61; South on Rd. 6100-100
 0.95 mi.; thence right on unmarked dirt
 road 0.1 mi.; right at Y 0.2 mi.; right at
 Y 0.1 mi. Corner brs. $N68^{\circ}E$ 915'

Loc Tag 540' E on Rd. 6100-1000

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Steel Post with 54-9 North.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" PP bxs. S 70° W 35.2' marked 1/4 533 BT

5" PP bxs. N 30° E 26.0' marked X BT

Painted all BT's as per specifications and attached signs 54-9 to backs of all BT's.

Work Done By *J. Collins* Title *LS* Date *10/91* State Registration No. or Agency *ORPLS 1020*
 Certified ~~Cor~~ Record Prepared? ☒ Yes ☐ No Filed At *North County Surveyor* Date *1991*

REMARKS

Index File No. *V-11* T. *245* R. *8E* M. *Will.* Tract or Surv. No. *1-2* Cor. *1171*

USDA-FOREST SERVICE

Index

File No. 11-13T 245 R. 8E

Merid. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

Cor.

No. 1371R.D. Crescent

County


KlamathCor. to Secs.

N.F. _____

State

27-28-33-34

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND Found BCSP Cap marked
rising 3".T245 R8E528:527533:5341980LS1026

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

9" LP brs, N 77 1/2° W 20.0'8" LP brs, S 66° E 23.7'

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From County Road 61; South on Rd,
5100-100 0.95 mi.; thence East on
unmarked dirt road 0.45 mi. Corner
brs, North 1570'.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

See other
side

Steel Post with 54-9 North

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" LP brs. N2 1/2° E 23.2' marked X BT
7" LP brs. S61° W 45.2' marked T245 R8 E 533 BT

Painted all BT's as per specifications and attached signs
54-9 to backs of all BT's,

10

Work Done By J. L. Lohman Title LS Date 10/91 State Registration No. ORPLS 1020
or Agency

Certified Cor Record Prepared? Yes No Filed At Klamath County Surveyor Date 1991

11

plat

REMARKS

Revisited 12/91 By B. Ham - PLS 2396 see plat: 000864

12

Index File No. V-13 T.245 R. 8 E M. Will Tract or Surv. No. 1-2 Cor. 1371

13


Index
File No. V-15

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No. 1571T 24 S R. 8 ER.D. CRESCENT County KLAMATHS/A COR. SEC. 27Merid. WILLAMETTEN.F. DESCHUTES State OREGONN/A COR. SEC. 34

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NO CORNER FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S-27 17" P. PINE ^{SNAG} BRG. N 35° E AT 35°
 DESCRIBED AS CALLED FOR

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

8

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

4

5

Larry C. Hildebrand

Civil Eng. Tech. Pre. Con.

Bend


9-7-78

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS CAPPED STEEL PIPE
RISING ABOVE GROUND 5" AND ITS STAMPED
AS SHOWN



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-27 13" L.P. PINE BRS N 34° W AT 31 7' B/S " 1/4 S BT "
(12/91) Bill Ham set 4" L.P. pine brs. N 63° E @ 45.2' mkd X BT
" " " " 7" " brs S 67° W @ 61.2 " 1/4 S 34 BT

S-34 13" L.P. PINE BRS S 05° W AT 31 5' B/S " 1/4 S BT "

Work Done By R. ROMAN Title PLS Date _____ State Registration No. OR-702
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KL. Co. Surv. Office Date 7/78

REMARKS

Revisited & Mtc By Bill Ham (12/91) 000864

V-15

Index File No. V-15 T. 245 R. 8E

M. WILLAMETTE Tract or Surv. No.

Cor. 1571

USDA-FOREST SERVICE

Index

File No. 1771

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. 000864

Cor.

No. V-17T 24 S. R. B ER.D. CrescentCounty KlamathNW CorMerid. WMAN.F. DeschutesState OregonSec. 35

CORNER DIAGRAM



T.24S.-R.8E.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER MONUMENT FOUND

12/91 - Bill Ham fd BCSP set by Armstrong

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

12/91 - Bill Ham Accessories As set by Armstrong

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Bill Ham

Title

PLS

Division

CS

Headquarters

SO

Date

12/91


FS-7100-52 (3/68)

3

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BCSP



ACCESSORIES : DESCRIBE NEW BT% WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

12/91 - Bill Ham - PLS 2396 REMARKS

Found "BC & Accessories as set by Armstrong. However NO original corner card noting the Armstrong work existed in our files (SF/NF ~1978). 000864

12

13


Index File No. T. R. M. Tract or Surv. No. 000864 Cor. *1-17*
1771 24 8 GPO: 1986 O- 439-095

Index
File No. 1971
T 24 R. 8
Merid. WMT

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor. No. V-19
County CLATSOP 5/4 Sec. 26
N.F. DES State OR N/4 Cor. Sec. 35

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____


DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature RH Title _____ Division _____ Headquarters _____ Date 1978 7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. **V-19**

12

13

Index

File No. V-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.


No. 2171T 24S R. 8ER.D. CrescentCounty Klamath

SE COR. SEC. 26

Merid. WillametteN.F. DeschutesState Oregon

NW COR. SEC. 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found 4"x4"x3' Post scribbled as called for. Also
found a 1" Iron pin Set as Corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S-25 Nothing

S-26

S-35 17" L.P. Pine Brs. S 50°W 110' Ft. Scribbled as called for.

S-36 Nothing

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature

Title

Division

Headquarters

Date

7100-52-13/68

Harry C. Hildebrand

Civil Eng. Tech.

Pre. Const.


Bend

6-20-78

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2 x 30" Brass capped Galvanized Steel pipe
Rising 5" above the Ground. Stamped as shown.



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-26 A 11" L.P. Pine Brs. N 19° W 45 1/2 ft B/s "S-26 BT"

S-25 A 15" L.P. Pine Brs N 86° E 36 1/2 ft B/s "S 25 BT"

S-36 A 10" L.P. Pine Brs. S 86° E 30 3/4 ft B/s "S 36 BT"

Work Done By R.OMAN Title DLS Date _____ State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? ☒ Yes No Filed At: BL. Co. Surv. Office Date 7/78

REMARKS

Brass Cap Set from original post and iron pin.

Index File No. V-21 T. 24S R. 8 E M. Willamette Tract or Surv. No.

Cor. 2171

V-21

USDA-FOREST SERVICE

Index

File No. 2271

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No.

000244

Cor.

No.

V-22T. 24 S. R. 8E. R.D. CRESCENT

County

CLATSOPW/16

COR. of SEC.

Merid. WILLAMETTEN.F. DESCHUTES


State

OREGON25/36

COR. of SEC.

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept☒ Permanent Monument

Signature

Title

Division

Headquarters

Date

D-7100-52 (3/)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

#5X48" AL. - CAPPED STEEL ROD BURIED 2"
IN GATEWAY 13 W. of FENCE COR. POST

MONUMENT SET/STAMPED

W/16
- -

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

3/4" PIPE RSG. 14" IN FENCE COR. BRS. N70°08'W 170⁶ FT.

Work Done By R. OMAN Title PLS Date 7/80 State Registration No. OR-202
☒ PLAT PREPARED OR
 Certified Cor. Record Prepared? ☒ Yes No Filed At: FLAM CO. SURVEYOR'S OFFICE Date 7/80

REMARKS

Index File No. 2271 T. 24 S., R. 8 E., W.M.

Tract or Surv. No. 000244 Cor. V-22

Index

File No. 2371T 24 S. R. 8 E.Merid. W mt

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. V-73R.D. CRESCENT


County

KLAMATHS/A COR. SEC. 25N.F. DESCHUTES

State

OREGONN/A COR. SEC. 36

CORNER DIAGRAM



Meadow

DESCRIBE CORNER MONUMENT FOUND

1/2" x 24" STEEL ROD RSG. 3" BY BURTON'S SURVEY, REPLACING
1 1/4" STEEL ROD BY KOVTYNOVICH'S SURVEY.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Two RP's

a 10" LODGEPOLE PINE BRS. N 29° W 44° FEET; &
an 11" " " " N 40° E 50° FEET

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

PLS

Division

ENG.

Headquarters

SO

Date

26 OCT 1978


7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2½" X 30" BRASS-CAPPED STEEL PIPE RISING 4" ABOVE GROUND.



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

a 5" LODGEPOLE PINE BEARS N 16° W 84³ FT., B/S "¼ S BT"; and
a 13" " " " N 38° E 46⁶ FT., B/S "¼ S BT".

Work Done By: R.OMAN Title: PLS Date: _____ State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KL. Co. SURV. Office Date 7/78

REMARKS

Index File No. 2371 T. 245 R. 8E M. Wm t Tract or Surv. No.

Cor. V-73

Index

File No. 2571

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No.

Cor.

No.

V-25T 24S R. 8ER.D. CrescentCounty KlamathSECOR. SEC. 25Merid. WillametteN.F. DeschutesState OregonNE COR. SEC. 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Pumice Stone with an Iron pipe driven thru it
Buried about 4" under ground.

Revisited 4/91 By Tom. Miller

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S'-30 T. 24S. R. 8E. A. 16" Pine Brs. N 39°E 16² ft Scribed as called for

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

The Corner is about 5' north of a house belonging to Alvie Beshop.

4

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

5

Harry C. Hildebrand Civil Eng. Tech. Pres. Con.


Bend

6-20-78

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a $2\frac{1}{2} \times 30$ " brass Capped Galvanized Steel pipe
1" below the Ground - Stamped as Shown.



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-25 T. 24 S. R. 8 E. A 18" L.P. Pipe Brs. N 41° W 33 $\frac{1}{2}$ Ft. B/S "S 25 B.T."
S-31 T. 24 S. R. 9 E N.E corner of house Brs. 576° E 42 $\frac{3}{4}$ Ft "Not Scribbled."
S-36 T. 24 S. R. 8 E. N.W corner of house Brs. S. 52° W 7 $\frac{3}{4}$ Ft "Not Scribbled"

Work Done By R. OMAN Title DLS Date _____ State Registration No. OR-702
or Agency _____
Certified Cor. Record Prepared? ☒ Yes No Filed At K.C. Co. Surd. Office Date 7/78

REMARKS

The Brass Cap was set in place of Pumice stone and Iron pipe.
See: 000847

Index File No. 2571 T. 24 S R. 8 E M. W. Willamette Tract or Surv. No.

Cor. V-25

USDA-FOREST SERVICE

Index

File No. W-7

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No. 1-2

000862

Cor.

No. 0772T 245 R. 8ER.D. CrescentCounty Klamath6-N 1/16Merid. WillametteN.F. DeschutesState OregonSec. 32

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X. _____

Y. _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 5825-980; North on 5825 400' toCorner is West 220'

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 3". No Stones available.

Cap marked

Posted line run South & East from corner.

C
N $\frac{1}{16}$ 532
C
1991
LS1020

58.4'

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" LP bts, S 40 $\frac{3}{4}$ ° W 57.8' marked CN $\frac{1}{16}$ 532 BT.
8" PP bts, N 72 $\frac{1}{4}$ ° E 22.1' marked CN $\frac{1}{16}$ 532 BT.

Bearings from traverse

Work Done By J. Collins Title LS Date 10/91 State Registration No. ORPLS 1020
or Agency

Certified Cor. Record Prepared? ☒ Yes No Filed At: Hamath County Surveyor Date 1991

REMARKS

Rebar, S. 70° E, 30.4'

Index File No. W-7 T.24S R. 8E

M. Will

Tract or Surv. No. 1-2

Cor. 0772

USDA-FOREST SERVICE

Index

File No. W-8

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. 1-2

Cor.

No. 0872T 245 R. 8ER.D. CrescentCounty ClatsopNE 1/4Merid. WillametteN.F. DeschutesState OregonSec. 32

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd, 5825 - 980; North on 5825 400'Corner is East 1115'

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT *Cap marked*
Set ACAP rising 4", No stones available. NE 1/16 S32

West
 Posted lines run South & ~~East~~ from corner, 1991
 LS1020

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" PP bts, S28 3/4° E 68.2' marked NE 1/16 S32 BT
6" PP bts, N79 1/4° E 56.0' marked NE 1/16 S32 BT

Bearing 1995 from traverse

Work Done By *J. Colvin* Title *LS* Date *10/91* State Registration No. or Agency *ORPLS 1020*

Certified ^{*plat*} ~~Gov. Record~~ Prepared? ☒ (Yes) No Filed At *Hamath County Surveyor* Date *1991*

REMARKS

Index File No. *W-8 T. 245 R. 8E* M. *Will* Tract or Surv. No. *1-2* Cor. *0872*

USDA-FOREST SERVICE

Index

File No. W-12

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

000862

Cor.

Survey No. 1-2No. 12-72T 245 R. 8ER.D. CrescentCounty KlamathNE 1/4 Cor.Merid. WilliametteN.F. DeschutesState OregonSec. 33

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Junction of Rds. 6100-100 & 6100-132;
 North on 100 0.1 mi.; East on unmarked
 dirt Rd. 0.2 mi. to N-S posted line.
 Corner brs. North 500 ft.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 4", No stores available.

Cap marked

NE $\frac{1}{16}$ 533

1991

LS 1020

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" LP bts, S43 $\frac{1}{4}$ °W 20.1' marked NE $\frac{1}{16}$ 533 BT,
6" LP bts, S77 $\frac{3}{4}$ °E 8.3' marked NE $\frac{1}{16}$ 533 BT.

Bearings from traverse.

10

Work Done By J. Collins Title LS Date 10/91 State Registration No. or Agency ORPLS 1020

Certified ~~Cor. Record~~ Prepared? ☒ Yes No Filed At Klamath County Surveyor Date 1991

11

REMARKS

Index File No. W-12 T. 245 R. 8E

M. Will

Tract or Surv. No. 1-2

Cor. 1272

12

13

USDA-FOREST SERVICE

Index

File No. W-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

000862

Survey No. 1-2

Cor.

No. 1372T 245 R. 8ER.D. Crescent

County

KlamathN 1/16 Cor.Merid. WillametteN.F. Deshutes

State

OregonSacs. 33-34

CORNER DIAGRAM

N 1/16
N 533' 534'

DESCRIBE CORNER MONUMENT FOUND Found BCSP Cap marked
rising 3"

N 1/16
533' 534'
1980
LS1020

✓ 12/91 B. Ham

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

8" LP brs. N 30° E 36.1'

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

✓ 12/91 B. Ham
From County Road 61; South on Rd. 6100-
100 0.25 mi.; thence East on unmarked
dirt road 0.45 mi. Corner brs. North
250'

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

10/91

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

(see other side)

Steel Post with 54-9 & 54-2 West,

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" LP brs. 552°E ~~63.1'~~ marked N 1/16 S 34 BT
4" PP brs. 528°E 61.7' marked X BT

Painted all BT's as per specifications and attached signs
54-9 to backs of all BT's.

Work Done By J. Colvin Title LS Date 10/91 State Registration No. ORPLS 1020
or Agency

Certified Plat Cor. Record Prepared? (Yes) No Filed At Washoe County Surveyor Date 1991

Revisited 12/01 By B. Ham pls ^{REMARKS} 2396 ~~see plat~~ see plat: 000864 2

Why 2 new BTs on Parcel C?
same quad

Index File No. W-13 T. 24S R. 8E M. W. H. Tract or Surv. No. 1-2 Cor. 1372

USDA-FOREST SERVICE

Index

File No. 1572

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 000864

Cor.

No. W-15T 24 S. R. 0 E. R.D. Crescent County Klamath CN/16 Sec. 34Merid. WMT N.F. Deschutes State Oregon

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER MONUMENT FOUND

(12/91) Bill Ham Fd BC per Armstrong*

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

(12/91) Bill Ham found accessories per Armstrong*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Bill Ham

Title

PLS

Division

CS

Headquarters

SO

Date


12/91

FS-7100-52 (3/68)

3

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



Sec.
Stamp?

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

12/91 - Bill Hamm PLs 2396

REMARKS

Found Monument and Accessories per Armstrong ~1980. No
Card existed for this corner.

12

13

Index File No. 1572 T. 24 R. B M. GPO: 1986 O- 439-095 Tract or Surv. No. 000864 Cor. W-15

Index

File No. 2172

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No.

Cor.

No.

W-21T 24 R 8R.D. CRESCENT County MCANATH N/16 Cor Sec 35/36Merid. W.M.T.N.F. DES State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

2" AXLE SHAFT RSG. 3" ABOVE GROUND
ALONGSIDE 3"x3"x36" WOOD POST SCRIPED
N/16 NR. COR of FENCES

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Not on Record
To Verify

Signature PH

Title

Division


Headquarters

Date 1978 7100-52 (3 68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. **W-21**


Index
File No. 0173
T 24S R. 8E
Merid. WILL

CORNER RECORD (SEARCH)

R.D. CRESCENT County KLAMATH
N.F. DESCHUTES State OREGON

Tract or
Survey No. _____
Cor. No. X-1

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: X-25, T24S, R7E, WM

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52
REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. T. R. M. Tract, or Surv. No. Cor. **X-01** 13

Index
File No. X-05

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

Cor.

No. 0573T 245 R. 8ER.D. CrescentCounty Clatsop1/4 Cor.Merid. WillametteN.F. DeschutesState OregonSacs. 31-32

CORNER DIAGRAM

T245 R8E
 1/4
 N 531 | 532

DESCRIBE CORNER MONUMENT FOUND

SENFPost called for in original notes.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SENF

Original survey calls for 2 4" BTs which were probably Lodgepole Pine. I suspect same have died & rotted since no evidence was found.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From County Rd. 61; South on E.S. Rd. 9825 3/4 mi. to unmarked dirt Rd. West - Southwest; 0.6 mi. on unmarked dirt road to location tag on S side of Rd. Corner is South 1305'.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

10/91

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 5", No stones available,

Cap marked

T245 R8E

1/4

S31.532

1991

LS1020

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" LP brs, S63°E 23.0' marked X BT,

12" LP brs, S49°W 12.5' marked 1/4 S31 BT,

11" LP brs, N19 1/2°W 60.4' marked E 1/4 S31 BT,

11" LP brs, N48 3/4°E 30.3' marked 1/4 S32 BT,

Beakings from traverse

Work Done By A. C. C. C.

Title

LS

Date

10/91

State Registration No.

or Agency

ORPLS 1020

Certified ~~Cor~~ Record Prepared ?

(Yes)

No

Filed At

Klamath County Surveyor

Date 1991

REMARKS

Index File No. X-5 T. 245 R. 8E

M. W. H.

Tract or Surv. No. 1-2

Cor. 0573

USDA-FOREST SERVICE

Index

File No. X-7

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. 1-2

Cor.

No. 0773T E45 R. 8ER.D. Crescent County Klamath Center 1/4 Cor.Merid. WillametteN.F. Deschutes State Oregon Sec. 32

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd, 5825 - 980; South on 5825 0.2 mi.Corner is West 160'

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 5", No stones available.

Cap marked

T245 R8E

Posted lines run North & South from corner.

C/4 532

1991

LS 1020

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" LP brs, S68 1/2° W 75.0' marked C/4 532 BT,

9" LP brs, N59 1/2° W 98.3' marked C/4 532 BT,

10" LP brs, N51 1/2° E 48.8' marked C/4 532 BT,

9" LP brs, S68 3/4° E 84.1' marked C/4 532 BT,

Bearings from traverse.

Work Done By J. K. Kline

Title

LS

Date

10/91

State Registration No.
or Agency

ORPLS 1020

Certified Plot Cor. Record Prepared? ☒ Yes

No

Filed At:

Klamath County Surveyor

Date 1991

REMARKS

Index File No. X-7 T.245 R.8E

M. Will.

Tract or Surv. No. 1-2

Cor. 0773

USDA-FOREST SERVICE

Index

File No. X-8

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

000862

Cor.

Survey No. 1-2No. 0873T 245 R. 8ER.D. Crescent County Klamath C-E 1/6 Cor.Merid. WillametteN.F. Deschutes State Oregon Sec. 32

CORNER DIAGRAM



E 1/6
C--C
532

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 9770-800'; East on 9770 0.15 mi.; right
on unmarked dirt rd. 200'; right at Y 0.1 mi.;
left at Y 0.15 mi.; straight at T 0.3 mi.;
straight at T 0.2 mi.; straight at T 0.15
mi.; left at T 0.35 mi. to end of Rd. Corner
brs. N 15° W 1000'. Corner at West edge
of "near" clear cut.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 5". No stones available.

Cap marked

Pasted lines run North & South from corner,

E 1/16
C-16
5 32
1991
LS1020

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" PP bts. N 83 3/4° W 73.1' marked CE 1/16 532 BT,
9" LP bts. N 1 1/4° W 24.4' marked CE 1/16 532 BT.

Bearings from traverse.

Work Done By J. Colvin Title LS

Date 10/91 State Registration No. ORPLS 1020
or Agency

Certified - ~~Cor.~~ Record Prepared? ☒ Yes ☐ No

Filed At: Klamath County Surveyor Date 1991

REMARKS

Index File No. X-8 T. 24S R. 8E M. 11A.

Tract or Surv. No. 1-2

Cor. 0873

USDA-FOREST SERVICE

Index

File No. X-9

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

000862

Cor.

No. 0973T 245 R. SER.D. CrescentCounty Klamath1/4 Cor.

Merid. _____

N.F. _____

State ?Secs. 32-33

CORNER DIAGRAM

N
 1/4
 532 : 533

DESCRIBE CORNER MONUMENT FOUND

*Found original post in stone circle. Remnants of post found down 1'±.
 Brass capped steel pipe set on top of nearby steel fence post.*

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

*10" LP brs, N71°E 20.6' Scribes visible
 12" PP brs, 552°E 8.7' Scribes visible*

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

*From junction of Rds. 6100-100 & 6100-132;
 Westerly on unmarked dirt road 1/2 mile
 (to top of hill). Tag 54-5 on 5" LP right
 side of Rd. Corner brs, N77°W
 650'±.*

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

J. Colvin

LS

10/91

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set BCSD rising 4" in stone circle.
Original post lying on ground alongside.

Cap marked
T245 R8E
1/4
532! 533
1991
LS1020

Steel fence post with sign 54-9
attached brs. North 3'±,

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" PP brs, S55 1/2° E 29.3' marked 1/4 533 BT
12" PP brs, N11° W 45.3' marked 1/4 532 BT

Bearings by staff compass w/ 19 1/2° E 1/4, deduction.

Work Done By. J. C. C. Title LS Date 10/91 State Registration No. ORPLS 1020
or Agency

Certified Cor. Record Prepared ☒ Yes ☐ No Filed At: Khmanth County Surveyor Date 1991

REMARKS

Index File No. X-9 T. 245 R. 8E M. W-11 Tract or Surv. No. 1-2 Cor. 0973

Index

File No. X-11

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

000862

Cor.

No. 173T 245 R. 35R.D. Crescent County Klamath Center 1/4 Cor.Merid. WillametteN.F. Deschutes State Oregon Sec. 33

CORNER DIAGRAM

N
C 1/4 533

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Junction of Rds. 6100-100 & 6100-132
corner brs. ~~N 70°~~ 570°W 100 ft.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAD rising 4", No stones available.

Cap marked

T245 R8E

C 1/4 S33

1991

LS1020

E Post S 65° W 2'

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

4" PP b/s, N 51° W 32.3' marked X BT.

6" LP b/s, N 72 1/2° E 121.0' marked C 1/4 S33 BT

16" PP b/s, S 12 1/2° W 57.0' marked C 1/4 S33 BT

10" PP b/s, S 51 3/4° W 101.5' marked C 1/4 S33 BT

Bearings from traverse.

Work Done By LS Title LS Date 10/91 State Registration No. ORPLS 1020
or Agency

Certified Plot ~~Con-Record~~ Prepared? (Yes) No Filed At: Klamath County Surveyor Date 1991

REMARKS

Index File No. X-11 T. 245 R. 8E M. W-11 Tract or Surv. No. 1-2 Cor. 1173

USDA-FOREST SERVICE

Index

File No. X-12

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

Cor.

No. 1273

T E45 R. 8E

R.D. Crescent

County Klamath

6E 1/16 Cor.


Merid. Willamette

N.F. Deschutes

State Oregon

Sec. 33

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From junction of Rds. 6100-100 & 6100-132; East on 132 1/4 mile to N-S posted line, Corner brs. South 150'.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set BCSP rising 6" No stones available.

Cap marked

E 1/6

6-1-6

5 33

1991

LS1020

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

4" PP bts, N58 1/2° E 20.9' marked X BT.

6" LP bts, N32° W 43.2' marked CE 1/16 533 BT.

Bearings by staff compass 19 1/2° E 1/4, Dec.

Work Done By J. Colvin Title LS Date 10/91 State Registration No. or Agency ORPLS 1020

Certified ^{plat} ~~Gor.~~ Record Prepared? ☒ Yes No Filed At Hamath County, Surveyor Date 1991

REMARKS

Little Deschutes River 20'± South,

Index File No. X-12 T. 245 R. 8E M. W-11 Tract or Surv. No. 1-2 Cor. 1273

USDA-FOREST SERVICE

Index

File No. X-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

Cor.

No. 1373T 245 R. BER.D. CrescentCounty Klamath1/4 Cor.


Merid. _____

N.F. _____

State _____

Sacs. 33-34

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND Found BCSP Cap marked
rising 7"R 7245E 33 1/4F 1

R.OMAN ORTUE

✓ 12/91 B. Ham

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

All BTS by R. Oman dead & down.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

✓ 12/91 B. Ham

3

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 6100-100; East on Rd. 6100-132
0.5 mi. Corner brs. South 70'.

4

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

5

J. ColmanLS10/91

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

(see other side)

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" LP brs. N 31° E 58.6' marked W 1/4 534 BT
 7" LP brs. N 90° E 24.4' marked 1/4 534 BT
 6" LP brs. N 42° W 22.9' marked 1/4 533 BT
 4" LP brs. S 87° W 29.8' marked X BT

V 12/91 B. Ham

Work Done By J. Collins Title LS Date 10/91 State Registration No. or Agency ORPLS 1020

Certified Plat ~~Cor. Record~~ Prepared? ☒ Yes ☐ No Filed At Klamath County Surveyor Date 1991

REMARKS

T2/91 - Bill Ham - PLS 2396 - See Plat # 000864

Index File No. X-13 T. 245 R. 8E M. W.H. Tract or Surv. No. 1-2 Cor. 1373

USDA-FOREST SERVICE

Index

File No. X-15

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 000864

Cor.

No. 1573T 24S R. 8ER.D. CresecentCounty KlamathC 1/4 S 34Merid. WilliametteN.F. DeschutesState OR

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SF/NF

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

B. Ham

Title

PLS

Division

CS

Headquarters

SO

Date

12/91

FS-7100-52 (3/68)

3

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2 1/2" dia x 30" long pipe surmounted by a 2 1/2" BC rising 3" above ground. A penny at base of Cap. (see below)

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A steel fence post bears East 3ft

A L.P. 3" dia bears N 72° E 41.7 ft marked x BT.

A L.P. 16" dia Bears S 52° E 32.5 ft marked C 1/4 S 34 BT


" " 13" " " S 30° W 34.9 " " " "

" " 9" " " N 26° W 30.3 " " " "

Work Done By B. Ham Title PLS Date 12/91 State Registration No. 2396 or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Klamath Co Date 2/19/92

REMARKS



Index File No. 1573 T. 24 R. 8 M. 4 Tract or Surv. No. 000864 Cor. X-15
GPO: 1986 O-439-095

USDA-FOREST SERVICE

Index

File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No.

Cor.

No.

T 24 S. R. 8 E. R.D. CRESCENT County BLAINE E/COR. S. 34
Merid. WILLAMETTE N.F. DESCHUTES State OREGON W/COR. S. 35

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

#4 X 24" STEEL ROD RISING 3"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

22" L. PINE BRG. N80E47E FT. W/VIS.
SCRIAING

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____


Agency

Signature R. HILDEBRANDTitle S.T. Division _____Headquarters S.O.Date 4/80 D-7100-52 (10/78)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 32" BRASS-CAPPED STEEL PIPE
RISING 4", ABOUT 225 FT. NORTH OF
LOGGING ROAD. REMOVED STEEL ROD.



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" L. PINE BRS. N58°W 8 1/2 FT., MKD. 1/4 S34 BT

5" L. PINE BRS. N71°E 21 1/2 FT., MKD. 1/4 S35 BT

10/91 Set by W. Ham Rebar 5/8" dia x 2' Long bears S49°46'U 26.63 F1
Surmounted by a plastic cap with brass washer marked PLS 2396

Work Done By R.OMAN Title PLS Date 17 APR 80 State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KL. Co. SURV. OFFICE Date

REMARKS

12/91 - Bill Ham PLS 2396 See Plat # 000864 4

Index File No. 1773 T. 24 S., R. 8 E., W.M.

Tract or Surv. No.

Cor. X-17

X-21


Index
File No. X-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. 2173T 245 R. 8 ER.D. CRESCENT County KLAMATHE/4 COR. SEC. 35Merid. WILLAMETTEN.F. DESCHUTES State OREGONW/4 COR. SEC. 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

1" IRON PIN

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S-36 R.P. BEARS S 33° E AT 10²⁴

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

AgencySignatureTitleDivisionHeadquartersDate

7100-52-(3/68)


Harry C. Hildebrand Civil Eng. Tech. Pmt. Con. Bend9-7-78

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS CAPPED STEEL PIPE RISING OUT
OF GROUND 1" AND STAMPED AS SHOWN



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-35 9" L. P. PINE BRS N 59°N AT 52 5 B/S "1/4 S BT"

S-36 9" L. P. PINE BRS S 67°E AT 49 3 B/S "1/4 S BT"

Work Done By. R. OMAN Title PLS Date _____ State Registration No. OR-702
or Agency _____

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KL. Co. Surv. Office Date 7/78

REMARKS

Index File No. X-21 T. 245 R. 8E M. WILLAMETTE Tract or Surv. No.

X-21₁₂
Cor. 2173 ₁₃

Index

File No. X-25T 245 R. BEMerid. Willamette

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor. X-25
No. 2573R.D. Crescent County KlamathN.F. Deschutes State OR-gon

E/4 COR. SEC. 36

W/4 COR. SEC. 31

DESCRIBE CORNER MONUMENT FOUND

Iron pipe 1" x 24" rising 1" above ground in
good condition. No markings

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Nothing

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52 (3 68)

Harry C. Hildebrand Civil Eng. Tech. Pre Con.

Bend


9-7-78

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" brass capped galvanized steel pipe
Rising 7" above ground. Stamped as shown.



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S. 36 10" L.P. Pine Bears S 59° W at 47± B/S 1/4 S BT.
S. 31 9" L.P. Pine Bears S 53° E at 22± B/S 1/4 S BT.

10

Work Done By R. OMAN Title PLS Date _____ State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KL. Co. Surv. Office Date 7/78

11

REMARKS

Be Set from IRON pipe.

X-25 12

Index File No. X-25 T. 245 R. BE M. W.M

Tract or Surv. No.

Cor. 2573 13

USDA-FOREST SERVICE

Index

File No. Y-8

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

000862

Cor.

Survey No.

1-2

No.

0874

T 245 R. 8ER.D. Crescent


County

KlamathSE 1/4 Cor. 1Merid. WillametteN.F. Deschutes

State

OregonSec. 32

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

6 PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7 PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

3 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 9770-800; East on 9770 0.15 mi.; right on unmarked dirt rd, 200'; right at Y 0.1 mi.; left at Y 0.8 mi. to fourth T road left; left on T road 0.35 mi. to end of rd. Corner bis. $543^{\circ}W$ 460'. Corner is 100'± south of southwest corner of "bear" clear cut.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 4". No stones available.

Cap marked

SE $\frac{1}{16}$ 532

Pasted lines run North & East from corner.

1991

LS1020

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" PP b/s. N77 34° W 88.2' marked SE $\frac{1}{16}$ 532 BT.

5" PP b/s. S10 $^{\circ}$ W 71.6' marked X BT.

Work Done By LS Title LS Date 10/91 State Registration No. 08PLS 1020 or Agency

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: Klamath County, Oregon Date 1991

REMARKS

Index File No. X-8 T.245 R.8E M. W-11 Tract or Surv No 1-2 Cor. 0874

Index

File No. Y-9

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. 1-2

Cor.

No. 0974T 245 R. 8ER.D. CrescentCounty Klamath5 1/16 Cor.Merid. WillametteN.F. DeschutesState OregonSecs. 32-33

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 9770-800; East on 9770 0.15 mi.;
right on unmarked dirt rd. 200'; right
at Y 0.1 mi.; left at Y 0.8 mi. to fourth
T rd, left; left on T rd, 0.1 mi. Corner
is South of rd, 40' E.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 6". No stones available.

Cap marked

5 1/6

532 1/2 533

Posted lines run South & West from corner,

1991

LS 1020

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" PP bvs. 568°W 29.9' marked 5 1/16 532 BT,

6" PP bvs. 542°E 2.4' marked 5 1/16 533 BT,

Work Done By

J. Collins

Title

LS

Date

10/21

State Registration No. or Agency

ORPLS 1020

Certified Cor. Record Prepared ?

☒ Yes

No

Filed At:

Klamath County, Oregon

Surveyor

Date

1991

REMARKS

Index File No.

Y-9 T. 24S R. 8E

M. Will,

Tract or Surv. No.

1-2

Cor. 0974

USDA-FOREST SERVICE

Index

File No. Y-12

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. 1-2

Cor.

No. 1274T 245 R. 8E R.D. Crescent County Klamath SE 1/4 Cor.Merid. Willamette N.F. Deschutes State Oregon Sec. 33

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Junction of Rds, 9770 E 9770-800
corner brs. N 11° W 85.'

3

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 4", No stones available.

Cap marked

SE 1/16 S33

1991

LS 1020

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" LP b/s, N 18° W 44.8' marked SE 1/16 S33 BT,

7" PP b/s, N 58° E 16.8' marked SE 1/16 S33 BT,

Bearings from traverse.

Work Done By

J. Collins

Title

LS

Date

10/91

State Registration No.

or Agency

ORPLS 1020

Certified - ~~Cor. Record~~ Prepared? (Yes)

No

Filed At

Klamath County, Oregon

Date

1991

REMARKS

Index File No.

Y-12 T. 245 R. 8E M. 10-11

Tract or Surv. No.

1-2

Cor. 1274

USDA-FOREST SERVICE

Index

File No. Y-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

Cor.

No. 1374T 24.5 R. 3E R.D. Crescent County Klamath S 1/16 Cor.Merid. Willamette N.F. Deschutes State Oregon Secs. 33-34

CORNER DIAGRAM

N
5
3
3
1
5
3
4

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Junction of Rds. 9770 & 9770-800;
East on 9770 1/4 mile. Corner brs. N 10° E
450'±.

000862

2

3

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 5". No stones available.

Cap marked

5 $\frac{1}{16}$

533 $\frac{1}{16}$ 534

1991

LS 1020

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" LP brs. N 48 $\frac{3}{4}$ ° W 31.2' marked 5 $\frac{1}{16}$ 533 BT

8" LP brs. N 50 $\frac{1}{4}$ ° E 38.0' marked 5 $\frac{1}{16}$ 534 BT

Bearings determined from traverse.

Work Done By J. Colvin Title LS Date 10/91 State Registration No. or Agency ORPLS 1020

Certified ~~Cor. Record~~ Prepared? ☒ Yes ☐ No Filed At: Klamath County Surveyor Date 1991

REMARKS

Revisited 12/91 By B. Ham - PLs 2396 See plat # 000864

Index File No. Y-13 T.24S R. 8E M. Will Tract or Surv. No. 1-2 Cor. 1374

USDA-FOREST SERVICE

Index

File No. Y-14

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

000864

Cor.

No.

1474T 245 R. 8E

R.D.

Crescent

County

KlamathSW 1/16 S34Merid. Willamette


N.F.

Deschutes

State

OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SFNF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

B. Ham

Title

PLS

Division

CS

Headquarters

SO

Date

12/91


FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2 1/2" x 30" long pipe surmounted by a
2 1/2" BC rising 3" above ground
A penny at base of cap



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A steel fence post bears ~~East~~ West 3 ft.

A L.P. 8" dia bears N 04° E 44.5 ft marked SW 1/16 S 34 BT

A L.P. 11" dia bears S 13° E 50.1 ft marked SW 1/16 S 34 BT

10

Work Done By W. Ham Title PLS Date 12/91 State Registration No. 2396
or Agency

Certified Cor. Record Prepared ? ☒ Yes ☐ No Filed At: Klamath Date 2/19/92

11

REMARKS

See Plat # 000864

12

Index File No. Y-14 T. R. M. Tract or Surv. No. 000864 Cor. 1474

13

Index
File No. 2-01
T 245 R. BE
Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. Crescent County Klamath
N.F. Deschutes State Oregon

Tract or
Survey No.

Cor.

No. 0175

SW COR. SEC. 31

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER MONUMENT FOUND

2 1/2 X 30" BRASS cap Rising 7" above ground.
good condition. Marked. U.S. Dept of Interior,
Bur. of Land Management cadastral survey.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S. 36 - 9" BT-L.Pine BEARS N 44 1/2° W at 71 LKS B/S
T245, R7E, S36 BT.
S. 31 - 9" L. Pine - N 30° E at 44 Links B/S T245, R8E S31 BT.
S. 6 - 10" L. Pine - S 29 1/2° E at 86 LKS B/S T255, R8E S6 BT.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52 (3 68)

Harry C. Hildebrand

Civil Eng. Tech. Pre. Con.


Bend

9-7-78

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S. 1 9" L.P. Pine Bears S 26°W at 32' B/S T25 R9* 5 BT.

*Scribed wrong - should
Read R7

Work Done By R. OMAN Title PLS Date _____ State Registration No. OA-702
or Agency _____
Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: HL. CO. SURV. Office Date 7/78

REMARKS

File No. 2-1 T. 24S R. 0E M. WM

Tract or Surv. No.

Cor. 0175

2-01

Index

File No.

0375

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.

No.

2-03

T. 24 S. R. 8 E.

R.D.

Crescent

County

Clatsop

Merid. Willamette

N.F.

Deschutes

State

Oregon

Section

Cor. of

31

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

2 1/2" BCSP RSG, 6" in good condition
(USGLO)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

24" P. pine, bcs N 67° W, Scar grown over
w/ alum. tag.

14" L.P. pine bcs Due South with scar grown
over, w/ alum. tag

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

T.K. Larson

Title

F.T.

Division

TMBR

Headquarters

D-2

Date

5/31/83


1

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

10

Plat or Cor. Record Prepared? Yes No Filed At. Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No. 0375 T. 24 S. 8 E., W.M.

Contract or Surv. No

Cor.

203

13

USDA-FOREST SERVICE

Index

File No. 2-5

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

000862

Cor.

Survey No.


1-2

No.

0575

T 245 R. 8ER.D. Crescent County Klamath Cor. to Sacs.Merid. WillametteN.F. Deschutes State Oregon 31-32-5-6

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found BCSP Cap marked

Rising 4"

T245 R8E
31 32
6 5
T255 R8E
LS 706
1973

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

18" LP brs, N73°W 27 IRS, to face of blaze,
(Live BT)

2 dead BT's

19" LP brs, S80°E 15 IRS, to face of blaze.

16" LP brs, S31°W 60 IRS, to face of blaze,

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 8325-980; South on Rd. 5825

0.7 mi. Corner brs, West 2,300'

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

LS

10/91

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Steel Post with 54-9 North.

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" LP b/s, N51°E 57.7' marked T245 R8E 532 BT,
11" LP b/s, S34½°E 79.5' marked T255 R8E 55 BT,
7" LP b/s, S81°W 86.1' marked T255 R8E 56 BT,

Painted all live BTs as per specifications and attached
signs 54-9 to backs of all live BTs,

10

Work Done By A. Rubin Title LS Date 10/91 State Registration No. ORPLS 1020
or Agency
Certified Yes ~~Cor. Record~~ Prepared? ☒ Yes No Filed At Klamath County, Oregon Date 1991

11

REMARKS

12

Index File No. 2-5 T.245 R.8E M. Will Tract or Surv. No. 1-2 Cor. 0575

13

USDA-FOREST SERVICE

Index

File No. 2-7

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

000862

Cor.

No. 0775T 245 R. 8ER.D. Crescent County Klamath1/4 Cor.Merid. WillametteN.F. Deschutes State OregonSes. 32-5

CORNER DIAGRAM

T245 R8E

N
 $\frac{1}{4}$ S 32
 4 S 5

T255 R8E

DESCRIBE CORNER MONUMENT FOUND

Found BCSP Cap marked

rising 5"

T245 R8E

S 32

S 5

T255 R8E

1973 LS 706

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

17" LP brs, N10°E 101 lvs. to face of blaze.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Etab By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 5825-980; South on Rd. 5825

0.7 mi. Corner brs, East 370'

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Steel Post with 54-9 & 54-2 North.

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

*5" LP brs. N79°E 72.0' marked X BT
4" PP brs. S43°E 54.6' marked X BT
12" LP brs. S43°W 12.0' marked 1/4 55 BT
Painted all BTs as per specifications and attached signs
54-9 to backs of all BTs*

Work Done By *J. Collins* Title *LS* Date *10/91* State Registration No. or Agency *ORPLS 1020*

Certified *Plat* Cor. Record Prepared? ☒ Yes ☐ No Filed At *Klamath County Surveyor* Date *1991*

REMARKS

Index File No. *2-7 T.24S R.8E* M. *Will.* Tract or Surv. No. *1-2* Cor. *0775*

USDA-FOREST SERVICE

Index

File No. Z-8

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. 1-2

Cor.

No. 0875T 245 R. 8 ER.D. Crescent County Klamath E/W S-LineMerid. WillametteN.F. Deschutes State Oregon Sec. 32

CORNER DIAGRAM

T245

1 532
E 16 55

T255

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd, 5825- 940; South on Rd, 5825 approx.
 1/2 mi, to improved dirt road East. East on
 improved dirt road to bridge across
 the Little Deschutes River. Corner
 brs, North 1/2 mile.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set ACAP rising 4". No stones available.

Cap marked

E 1/16 - 532
S 5

1991

LS 1020

Steel post with 54-9 & 54-2 South.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" PP brs. N 85 1/2° E 44.2' marked E 1/16 532 BT

8" PP brs. S 9° E 49.2' marked E 1/16 S 5 BT

10

Work Done By

[Signature]

Title

LS

Date

10/91

State Registration No.
or Agency

ORPLS 1020

Certified Cor. Record Prepared? Yes

No

Filed At:

Klamath County Surveyor

Date 1991

11

REMARKS

12

Index File No. Z-8 T. 245 R. 8E

M. W-11

Tract or Surv. No. 1-2

Cor. 0875 13

USDA-FOREST SERVICE

Index

File No. Z-9

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

000862

Cor.

Survey No. 1-2No. 0975T 245 R. 8ER.D. CrescentCounty KlamathCor. to Secs. Merid. WillametteN.F. DeerhutsState Oregon32-33-4-5

CORNER DIAGRAM

N
 T245 R8E
 532 533
 55 54
 T255 R8E

DESCRIBE CORNER MONUMENT FOUND Klamath County Cap mld
Surveyor 2 1/2" brass cap on 1 1/4" (OD)
Galv. pipe, Rising 7".

T245 R8E
 532 533
 55 54
 T255 R8E
 1968
 LS 528 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

All BT's established in 1968 have been
cut or are dead & down,

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 9770-800; East on 9770 0.15 mi.;
right on unmarked dirt rd. 200'; right at
Y 0.1 mi.; left at Y 0.65 mi. to third T
rd. left; left on T rd. 0.1 to location
tag on West side of rd. Corner brs,
582°W 625'.

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

J. C. C. C.

LS

10/91

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set steel post with signs 54-9 & 54-2 North of corner 3'±.

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

4" PP bvs, 588°E 16.7' marked X BT.
10" PP bvs, 530°E 58.7' marked T255 R8E 54 BT.
6" PP bvs, 562½°W 54.0' marked T255 R8E 545 BT
5" PP bvs, N52°W 47.9' marked X BT

Bearings by staff compass w/ 19½° E 1/4 destination

Work Done By A. Collier Title LS Date 10/91 State Registration No. ORPLS 1020
or Agency

Certified Plat Gen. Record Prepared? (Yes) No Filed At: Klamath County, Oregon Date 1991

REMARKS

Remonumented in 1968 by LS 598 from existing evidence.
1968 BT's

12" Pine N71°E 24.4' 10" Pine S43°E 21.1'
10" Pine S32°W 85.2' 14" Pine N77°W 39.3'

Index File No. Z-9 T.24S R. 8E M. Will Tract or Surv. No. 1-2 Cor. 0975

USDA-FOREST SERVICE

Index

File No. Z-11

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

000862

Cor.

Survey No.

1-2

No.

1175

T 245 R. 8ER.D. Crescent

County

Klamath1/4 CornerMerid. WillametteN.F. Dechutes

State

OregonSes. 33-4

CORNER DIAGRAM

T245 R8E
 N
 1 533
 4 54
 T255 R8E

DESCRIBE CORNER MONUMENT FOUND

Klamath County Surveyor
2 1/2" brass cap on 1 1/2" (60) Galv. pipe. Cap mkd
Rising 7".

T245 R8E

1 533

4 54

T255 R8E

LS 528

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

10" PP brs, S 40° W 17.9' blazes healed over,
Low cut stump brs, N 76° E 7.3'.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd, 9770-800; East on 9770 0.15 mi.;
right on unmarked dirt rd. 200'; right at
Y 0.1 mi.; left at Y 0.15 mi. to T rd, left;
left on T rd, 0.25 mi. to T; right at T
0.1 mi.; right at Y 300'±. Corner is
South of road 40'±.

3

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Steel Post with sign 54-9 South of corner 3'±. 9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

4" PP brs. N43°W 21.1' marked X BT.

9" PP brs. S53°E 25.7' marked 1/4 SA BT.

8" PP brs. N60°E 44.4' marked 1/4 S33 BT.

Bearings by staff compass w/ 19 1/2° E 1/4, declination. 10

Work Done By J. Colvin Title LS Date 10/91 State Registration No. or Agency ORPLS 1020

Certified ^{Plot} Cor. Record Prepared? ☒ Yes ☐ No Filed At Klamath County Surveyor Date 1991 11

REMARKS

Remonumented by LS 598 from original evidence in 1968, 1968 BT's

8" Pine N76°E 7.3'

6" Pine S40°W 17.8'

Index File No. Z-11 T.24S R.8E M. W-11, Tract or Surv. No. 1-2 Cor. 1175 12

Z-12

Index

File No. **Z-12****CORNER RECORD (SEARCH)**

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.


No. **1275**T **245** R. **8E**R.D. **CRESCENT**County **KLAMATH**E/16 Cor Sec **33/4**Merid. **WMT**N.F. **DESCHUTES**State **OREGON****CORNER DIAGRAM****DESCRIBE CORNER MONUMENT FOUND****DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND****PHOTO IDENTIFICATION DATA**

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

*Signature***PLANE COORDINATE POSITION DATA**

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52-(3, 68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

5 STEEL ROD

9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At Box Surv. # 2267 Date _____

11

REMARKS

Needs BT's

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

2-12

13

USDA-FOREST SERVICE

Index

File No. 2-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

000862

Survey No.

1-2

Cor.

No.

1375

T 245 R. 8ER.D. Crescent

County

KlamathCar. to S.E.S.

Merid.

N.F.

State

33-34-3-4

CORNER DIAGRAM

T245 R8E

S33 S34

S4 S3

T255 R8E

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER MONUMENT FOUND

Found BCSP Cap marked
MISSING 2"

T245 R8E

S33 S34

S4 S3

T255 R8E

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

3 RP^s established at time of corner monumentation. 4th RP missing! Held existing nails & washers on 3 remaining RPs for distance measurements and established same as BTs this date.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Rd. 9770-800; East on Rd. 9770
0.4 mi. Corner brs. S36°W 935'

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

See other
side

Steel Post with 54-9 West.

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Existing RPS

18" PP brs. N59 1/2° W 60.8' marked T24S R8E S33 BT

14" PP brs. N22° E 43.8' marked T24S R8E S34 BT

13" LP brs. S47° W 43.8' marked T25S R8E S4 BT

New BT

10" PP brs. S83° E 31.7' marked T25S R8E S3 BT

10

Work Done By A. Chis Title LS Date 10/91 State Registration No. ORALE 1020
or Agency

Certified 1991 Cor. Record Prepared? ☒ Yes No Filed At: Monmouth County Surrogate Date 1991

11

REMARKS

Washers mkd LS 540 on 1st 3 B.T's

Revisited 12/91 By B. Ham PLS 2396 See plat # 000864

12

Index File No. 2-13 T.24S R.8E M. With. Tract or Surv. No. 1-2 Cor. 1375

13

USDA-FOREST SERVICE

Index

File No. 2-14

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. _____

Cor.

No. 1475T 245 R. 8ER.D. CrescentCounty KLAMATH0 1/163Merid. WillametteN.F. DeschutesState OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SFNF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SFNF

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

B. Ham

Title

PLS

Division

CS

Headquarters

SO

Date

12/9/1


FS-7100-52 (3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" x 30" pipe surmounted by a 2 1/2" dia BC 2" above ground. Penny buried at base of pipe



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Steel fence post bears North 3'

APP 12" dia bears N 37° 42' E 79.81 ft marked w 1/16 S34 BT

APP 30" dia bears S 00° 51' E 50.40 ft marked w 1/16 S3 BT

Work Done By. B. Ham Title PLS Date 12/91 State Registration No. 2396

Certified Cor. Record Prepared? ☒ Yes No Filed At: Klanath CO Date 2/19/92

REMARKS

See Plat # 000864

Index File No. 1A75 T. 24 R. 8 M. 000864 Tract or Surv. No. 000864 Cor. 2-14

Index
File No. 1575

CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 000864 Cor. No. Z-15

T 24 S. R. 8 E. R.D. Crescent County Klamath 574 Cor. of
Merid. WILLAMETTE N.F. DESCHUTES State OREGON Section 34

SEE: A-15 T. 25 S., R. 8 E., W.M.

BCSP

194 1971-74 1975-76
1977-78 1979-80 1981-82

Index
File No. 2-17

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tractor

Survey No.

Cor.

No.


2-17**1775**T 24 S R. 8 ER.D. Crescent County Klamath

SE COR. SEC. 34

Merid. WillametteN.F. Deschutes State Oregon

SW COR. SEC. 35

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found a 4"X4"X3' post scribed all 4 sides.
Also found an iron pin at the corner location.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

S-34 A 13" L.P. Pine Brs. N 5° W 11.9ft. NOTED 9/81
S-3 A 18" L.P. Pine Brs. S 72° W 23.1ft.
S-2 A 13" L.P. Pine Brs. S 1° E 13.5ft.

All trees scribed as called for.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner lies 90' North of road 257.

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

Harry C. Hildebrand

Civil Eng. Tech.

Pre. Const.

Bend


6-21-78

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" X 30" brass capped galvanized steel pipe
rising 5" above the ground, stamped as shown.



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-35 A 15" L.P. Pine Brs. N 49° E 16.5ft. B/S "S35 BT"

Work Done By: R. OMAN Title: PLS Date: _____ State Registration No. OP-702

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At: KL. Co. SURV. Office Date: 7/78

REMARKS

Brass cap set in original post hole.

revisited 12/91 By B. Ham PLS 2396 See Plat # 000864

REVISITED 9-81 FOUND AS STATED -

Index File No. Z-17 T. 245 R. 8 E M. Williamette Tract or Surv. No. Cor. 1775


Index
File No. 2-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. 2-19
1975T 24 S R. 8 ER.D. CRESCENTCounty KLAMATH5/4 COR. SEC. 35Merid. WILLAMETTEN.F. DESCHUTESState OREGONN/4 COR. SEC. 2

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

1" STEEL PIN 1 1/2 " OUT OF GROUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____


AgencySignatureTitleDivisionHeadquartersDate7100-52-(3/68)Harry C. HildebrandCivil Eng. Fed. Pre.Con.Beard9-7-78

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS CAPPED STEEL PIPE RISING
OUT OF GROUND 5" AND STAMPED AS SHOWN



ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-35 26" P. PINE BRS. N 40° E AT 88° B/S "1/4 S BT"
S-2 16" P. PINE BRS. S 30° N AT 80° B/S "1/4 S BT"

Work Done By R. OMAN Title PLS Date _____ State Registration No. OR-702
or Agency _____

Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KC. Co. Surv. Office Date 7/78

REMARKS

Index File No. 2-19 T. 245 R. 8E M. WILLAMETTE Tract or Surv. No.

2-19
Cor. 1975

Index


File No. Z-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No.Cor.
No.2-212175T 24S R. 8ER.D. CRESCENT County KLAMATHSE COR. SEC. 35Merid. WILLAMETTEN.F. DESCHUTES State OREGONSW COR. SEC. 36

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

A POST 4" X 4" STANDING 30" OUT OF THE GROUND
 BLAZED AND SCRIBED N.W. SIDE - T24S R8E S35/
 S.W. SIDE - T25S R8E S2 / SE. SIDE - T25S R8E S1/
 N.E. SIDE - T24S R8E S36

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NOTHING

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

Harry C. Hildebrand Civil Eng. Tech. Pres. Com.

Bend

9-7-78


CORNER RECORD (PERPETUATION)

MONUMENT

STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS CAPPED STEEL PIPE RISING 3"
ABOVE THE GROUND AND STAMPED AS SHOWN



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S- 35 10" L.P. PINE BRS. N 33° W AT 41 1/2 B/S "S 35 B.T."
S- 36 11" L.P. PINE BRS. N 30° E AT 41 1/2 B/S "S 36 BT"
S- 2 10" L.P. PINE BRS. S 73° W AT 31 9 B/S "S 2 BT"
S- 1 10" L.P. PINE BRS. S 28° E AT 27 1/2 B/S "S 1 BT"

Work Done By R. OMAN Title PLS Date _____ State Registration No. OR-702
or Agency

Certified Cor. Record Prepared? ☒ (yes) No _____ Filed At: KL. Co. Surv. Office Date 7/78

REMARKS

Index File No. Z-21 T. 245 R. 8E

M. WILLAMETTE Tract or Surv. No.

Cor. 2175

Index

File No. Z-23

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No.

Cor.

No. 2375T 24S R. 8ER.D. CRESCENT County KLAMATHS/4 COR. SEC. 36Merid. WILLAMETTEN.F. DESCHUTES State OREGONN/4 COR. SEC. 1

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

A POST 4"X4" STANDING 36" ABOVE THE GROUND
BLAZED AND SCRIBBED $\frac{1}{4}$ S 36 / $\frac{1}{4}$ S 1
ALSO A STEEL PIN

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NOTHING

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

Harry C. McElroy Civil Eng. Tech. Pres. Com. Bend

9-7-78.


CORNER RECORD (PERPETUATION)

MONUMENT

STAMPED:

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2 1/2" X 30" BRASS CAPPED STEEL PIPE
RISING OUT OF THE GROUND 2" STAMPED AS
SHOWN



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

S-36 A 13" L.P. PINE BRS. N 32° W AT 438 B/S " 1/4 BT "
S-1 A 17" L.P. PINE BRS. S 57° W AT 469 B/S " 1/4 BT "

Work Done By R. OMAN Title PLS Date _____ State Registration No. OR-702
or Agency _____

Certified Cor. Record Prepared ? (Yes) No Filed At KL. Co. Surv. Office Date 7/78

REMARKS

5/88 C. Hunt found BC and one bearing Tree ,

Index File No. Z-23 T. 245 R. 8E M. WILLAMETTE Tract or Surv. No. 2-23
Cor. 2375

2-25

Index

File No. 2-25

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No.

Cor.

No. 2575T 24 S R. 8 ER.D. CRESCENT County KLAMATHSE Cor Sec 36Merid. WMTN.F. DESCHUTES State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

2 1/2" BRASS-CAPPED STEEL PIPE 956.7"SEE: A-01 T25S R9E

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

3 BT's

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

PCCH

Title

Division

Headquarters

Date

1978


7100-52-(3-68)

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

BRASS CAP



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By.

Title

Date

State Registration No.
or Agency

Certified Cor. Record Prepared ? Yes

No

Filed At

Dec Survey # 348

Date

11

REMARKS

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

2-25