

LEGEND

○ = Corner having information on form 7100-52 in this file.

*Legend Confirms To
REPORTING FORM
MPB 2/80*

FILING INSTRUCTION

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N. W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.

CORNER RECORD FILE GUIDE (Rectangular Surveys)

Index
File No. 0151

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. Cor. No. A-1

T 25 S. R. 10 E. R.D. Crescent County Klamath NW COR. SEC. 6
Merid. WILLAMETTE N.F. DESCHUTES State OREGON SE COR. SEC. 36

See T25SR9E # A-25

BC Set 1980
by
HCH

A-01

Index

File No. 251

CORNER RECORD (SEARCH) Contract or


(Ref. FSM 7151.4)

T 25 S. R. 10 E.Survey No. 530441496481

Cor.

No. A-2Merid. WillametteR.D. CRESCounty KLAMN.F. DeschutesState OregonW¹/₄ Cor. of
Section 3/₄

CORNER DIAGRAM per legend

W¹/₄ 31
6

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other
☐ Searched For/Not Found
☒ Evidence Found/Accept.

☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS # 9772 & #9760
 PROCEED NORTHERLY 0.4 MILE TO 4x4
 WOOD POST & K-TAG ON EAST EDGE OF ROAD

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
29" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

3 1/2" P. PINE N64°E - 15.9'
9" L.P. PINE S58°W - 30.2'
6' F.G. POSTS 3.2' EAST & 2.4' NORTH

Work Done By C.W. COOK Title PLS Date 6-85 State Registration No. PLS 1098
or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No.

251

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

A-2

Index

File No. 351


CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H1476EN Cor. No. A-3T 25 S. R. 10 E. R.D. CRESCENTMerid. WillametteN.F. DeschutesCounty KLAMATHState OregonSection 31 Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

2" G.I.P. w/ 2 1/2" BRASS CAP

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

24" x 8' TALL PINE STUB (ORIG) 58°E-37.9' SCRIBES VISIBLE15" L.P. PINE (1966-DYING) N63°E-8.8'

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9772 & #9760 PROCEED
NORTH 0.3 MILE TO 4x4 WOOD POST & TAGS ON
EAST EDGE ROAD #9760 WHICH IS 322' WEST
OF CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____


Headquarters _____

Date _____

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" L.P. PINE 573°E - 45.2' "1/4 56 BT"

6" P. PINE N24°E - 32.3' "1/4 531 BT"

6' F.G. POST 2.0' WEST w/DECALS "LSM-130" & "BM-102"

ALL B.T.S HAVE TAGS 54-3, 54-4, 60D NAIL @ SIDE-BASE - NEW B.T.S HAVE ALUM.

DISK "PLS 1098" ON 60D NAIL

10

Work Done By C.W. COOK Title SURVEYOR Date 4-85 State Registration No. PLS 1098
or Agency

Plat or Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date

11

History G.L.O. - H. MELDRUM - 1879

of
Surveys,
G.L.O.,
etc.

Index File No.

351

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

A-3

12

13


Index
File No. 551CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 5304H1496ABN

Cor.

No. A-5T 25 S. R. 10 E. R.D. CRESCENTMerid. WillametteN.F. DeschutesCounty KLAMATHState OregonSEC. 31 Cor. of 32Section 65

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

2" G.I.P. w/ 2 1/2" BRASS CAP

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

30" PINE UP-ROOT (ORIG.) N24°W-53' Scribes visibleROTTEN PINE UP-ROOT (ORIG.) N48°E-67' NO Scribes11" L.P. PINE (1966) S57°W-8.8'7" L.P. PINE (1966) S68°E-26.4'13" L.P. PINE (1966-DYING) N72°E-26.7'

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNC. OF ROADS #9772 & #9760 PROCEED N.E. LY
ON ROAD #9772 0.8 MILE TO JUNC. - THEN WEST
0.15 MILE - CORNER IS 150' ± SOUTH OF ROAD

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____


Headquarters _____

Date _____

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES. DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

16" P. PINE NS9°W - 61.3' "T24S R10E S31 BT"

7" P. PINE N26°E - 20.1' "T24S R10E S32 BT"

6' F.G. POST 2.1' NORTH w/DECAL "LSM-130"

ALL B.T.'S HAVE TAGS 54-3, 54-4, 60 D NAIL @ SIDE-BASE - NEW B.T.'S HAVE 1 1/2"

ALUM. DISK "PLS 1098" ON 60 D NAIL

Work Done By C.W. COOK Title SURVEYOR Date 4-85 State Registration No. PLS 1098
or Agency

Plat or Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History of G.L.O. - MELDRUM - 1879

Surveys,
G.L.O.,
etc.

Index File No.

551

T.25 S., R.10 E., W.M.

Contract or Surv. No.

5304H149C4BN

Cor.

A-5

Index

File No. 751

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N Cor. No. A-7T 25 S. R. 10 E. R.D. CRESCENTCounty KLAMATH1/4

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 32
5

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

2" G.I.P. w/ 2 1/2" BRASS CAP

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

21" P. PINE (ORIG) 534°W - 6.9' FACE OPEN
SCRIMES VISIBLE6" P. PINE (1966) N22°W - 21.7'

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS 30' ± SOUTH OF ROAD #9772 -
4x4 WOOD POST & TAGS 112' EAST ON NORTH
EDGE OF ROAD

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____


Headquarters _____

Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE S42°E - 31.0' "1/4 SS BT"

ALL B.T.'S HAVE TAGS 54-3, 54-4

6' F.G. POST 1.8' SOUTH & 1.9' EAST w/DECALS "BM-102" & "LSM-150"

Work Done By C.W. COOK Title SURVEYOR Date 4-85 State Registration No. PLS 1098
or Agency

Plat 10 Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date 11

History of G.L.O. - H. MELDRUM - 1879

Surveys,
G.L.O.,
etc.

Index File No.

751

T.25 S., R.10 E., W.M.

Contract or Surv. No.

5304H1496484

Cor.

A-7

Index

File No. 851

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H/49648N

Cor.

No. A-8T 25 S. R. 10 E.R.D. CRESCENTCounty KLAMATHMerid. WillametteN.F. DeschutesState Oregon

E'1/6 Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

Section 32E'1/6 $\frac{32}{5}$

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other☐ ☐ Searched For/Not Found☒ ☒ Evidence Found/Accept.:☒ ☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNC. OF ROADS #9772 & #9772-700
PROCEED WESTERLY 1/2 mile to 4x4
WOOD POST & K-TAG ON SOUTH EDGE OF
ROAD #9772 -

Searched By:

Title

Division


Headquarters

Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



SET 2"x30" G.I.P. w/2 1/2" BRASS CAP
27" IN GROUND w/RING OF STONE

ACCESSORIES. DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" L.P. PINE N73°W - 82'-"
7" L.P. PINE S30°W - 46'-"
6' F.G. POSTS 2.0' SOUTH & 1.9' WEST

Work Done By C.W. COOK Title PLS Date 6-85 State Registration No. PLS 1098
or Agency

Plat or Certified Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No.

851

T.25S., R.10E., W.M.

Contract or Surv. No.

5304H/149648N

Cor.

A-8

Index
File No. _____

CORNER RECORD (SEARCH)

Tract or
Survey No. _____

Cor.
No. _____

T 25S. R. 10E.

R.D. Crescent

County Klamath


Sec. Cor

Merid. Will

N.F. Deschutes

State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

See: T24S, R10E, 2-9

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13

USDA-FOREST SERVICE

Index

File No. 1051

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No. _____

Cor.

No. A-10T 25 S. R. 10 E. R.D. CrescentCounty KlamathMerid. WILLAMETTEN.F. DESCHUTESState OREGONW/16

Cor. of

Section 33/4SEE: Z-10 T. 24 S., R. 10 E., W.M.

S.33

T.24S.

S.4 T.2S.S

BCSP

W/16 —



USDA-FOREST SERVICE

Index

File No. 1151CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No.Cor.
No.A-11T 25 S. R. 10 E. R.D.Crescent

County

KlamathN/4

Cor. of

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

Section


4SEE: Z-11 T. 24 S., R. 10 E. W.M.

S.33

T. 24 S.

T. 25 S.

N/4 S. 4




Index
File No. _____
T 25S, R. 10E,
Merid. Will

CORNER RECORD (SEARCH)

Tract or
Survey No. _____
Cor. No. A-13
Sec. Cor. _____

R.D. Crescent County Klamath
N.F. Deschutes State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: Z-13, T24S, R10E, WM.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor.

13

Index
File No. 1451

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No. 5304H14968

Cor.

A-14T ZS S. R. 10 E.R.D. CRES.

County

KLAM.Merid. WillametteN.F. Deschutes

State

OregonW 1/4

Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

Section 343W 1/4 $\frac{34}{3}$

T24S

T28S

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or	Unverified	
Contr.	Other	
☐	☐	Searched For/Not Found
☒	☒	Evidence Found/Accept.
☒	☒	Permanent Mon. Set/Fd.

FROM JUNCTION OF ROADS #9407 & #9772
 PROCEED ~~W~~ EASTERLY ON #9407 TO 4x4
 WOOD POST & TAG SOUTH OF CORNER

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P. PINE S10°W - 73.9'
8" P. PINE N4°W - 77.7'
6' F.G. POSTS 2.2' SOUTH & 2.0' EAST

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat or Cor Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No
1451

T. 25 S., R. 10 E., W. M.

Contract or Surv. No
5304H149648N

Cor. A-14

Index

File No. 1551

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 6304H149648 No. A-15T 25 S. R. 10 E. R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState OregonSection 34 Cor. of 3

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

 $\frac{1}{4}$ $\frac{34}{3}$ POST - ROTTED OFF UPPER PORTION MARKEN " $\frac{1}{4}$ " " $\frac{1}{4}$ "

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

12" PINE STUB 40" HIGH S17°W - 17.8' TO ESTIMATED FACE

18.2' TO SIDE-CENTER (ORIG.)

16" L.P. PINE N42°W - 56.8' TO FACE

57.8' TO SIDE-CENTER (ORIG.)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS ON SOUTH EDGE OF

CLEAR-CUT 250' ± NORTH OF ROAD # 9407

SEE MAP

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" C.I.P. w/ 3" BRASS CAP
26" IN GROUND IN PLACE OF ROTTED
OF ORIGINAL POST IN RING OF STONE

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE S24°E - 47.1'
10" P. PINE N80°W - 119.1'
6' F.G. POSTS 3.6' WEST & 4.0' EAST

10

Work Done By C.W. COOK Title LS Date 4/85 State Registration No. PLS 1098
or Agency

Plat or Cor Record Prepared? ☒ Yes No Filed At KLAM. Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

H. MELDRUM - 1879
16" PINE S16°W - 27 LKS.
6" PINE N37°W - 86 LKS.

Index File No
1551

T.25 S., R. 10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. A-15

12

13

Index

File No. 1651

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)


Survey No. 53044149648N

Cor.

No. A-16T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. DeschutesCounty KLAM.State OregonE $\frac{1}{16}$ Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

E $\frac{1}{16}$ $\frac{34}{3}$ 

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9772 & #9407
 PROCEED EASTERLY TO 4x4 POST &
 K-TAG SOUTH OF CORNER

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

27" IN GROUND w/ RING OF STONE

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P. PINE N48°W - 24.6'

7" P. PINE S53°W - 75.1'

6" F.G. POSTS 25' WEST & 2.1' SOUTH

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Flat or
Certified Cor Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No

1651

T. 25 S., R. 10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

A-16

D-7100-52d (10/78)
USDA-FOREST SERVICE

Index

File No.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

T 25 S. R. 10 E. R.D. CRESCENT County BLAMATH
Merid. WILLAMETTE N.F. DESCHUTES State OREGON

SEZ: Z-17

T24S R10E


BC Set



Index	CORNER RECORD (SEARCH)		Tract or	Cor.
File No.	(Ref. FSM 7151.4)		Survey No.	No. <u>A-19</u>
T <u>25</u> S. R. <u>10</u> E.	R.D. <u>CRESCENT</u>	County <u>KLAMATH</u>		
Merid. <u>WILLAMETTE</u>	N.F. <u>DESCHUTES</u>	State <u>OREGON</u>		

SEE: 2-19
T 245 R10E

BC



Index

File No. 2051

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648

Cor.

No. A-20T 25 S. R. 10 E.R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState Oregon

E/16

Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

Section 352E/16 $\frac{35}{2}$ 

T24S

T25S

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

CORNER FALLS 7' EAST OF EAST EDGE
OF ROAD #9407 (CRS. N15°E x S25°W)

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

27" IN GROUND w/ MOUND OF ROCK

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P. PINE N25°W - 62.0'

11" P. PINE S76°E - 86.4'

6' F.G. POSTS 2.3' NORTH & 2.4' WEST

9

10

11

12

13

Work Done By C.W. COOK Title LS Date 5/85 State Registration No. PLS 1098
or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No

2051

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.
5304H149648N

Cor. A-20

Index

File No. 2151

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648 No. A-21

Cor.

T 25 S. R. 10 E. R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState Oregon

SEC. Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

2 1/2" ALUM. PIPE w/ 3/4" ALUM. CAP.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

32" x 8" HIGH PINE STUMP S70°W-25.9 (ORIG.)10" P. PINE N53°E-7.3'25" x 3' HIGH PINE STUMP S52°E-42.4 (ORIG.)8" P. PINE N52°W-7.1'6 BADLY ROTTEN DEAD & DOWN PINE N40°E-51 (ORIG.)12" P. PINE S18°E-107.7'9" P. PINE S34°W-18.7'

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS @ N.W. CORNER OFCLEAR-CUT 100' S.E. OF SECONDARYROAD - SEE MAP

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____

Date _____

1

CORNER RECORD (PERPETUATION)


MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

CLEARED BRUSH & DEBRIS - NEW TAGS

WHERE NEEDED - RED PAINT BAND ON

ALL B.T.s

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE N72°E - 34.4'

6" F.G. POSTS S. 8' EAST & 2.6' SOUTH

Work Done By: C.W. COOK Title: LS Date: 7/85 State Registration No. or Agency: PLS 109B

Platform or Record Prepared ☒ Yes ☐ No Filed At: KLAM. Co. Surveyor's Office Date:

History of Surveys, G.L.O., etc.	H. Meldrum 1879	SHINN & STEERS 1983
	20" PINE S22°W - 38 LKS. (25.1')	7" P. PINE N53°E - 7.2'
	20" PINE S52°E - 63 LKS. (41.6')	8" P. PINE N52°W - 7.1'
	20" PINE N40°E - 77 LKS. (50.8')	10" P. PINE S16°E - 107.9'
	20" PINE N65°W - 56 LKS. (37.0')	10" P. PINE S37°W - 18.6'

Index File No
2151

T. 25 S., R. 10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. A-21

Index
File No. _____

CORNER RECORD (SEARCH)

Tract or
Survey No. _____ Cor.
No. A-23


T 25S R. 10E

R.D. CRESCENT County KLAMATH

Merid. WILL

N.F. DESCHUTES State OREGON 1/4 COR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE: Z-23, T24S, R10E, WM

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

13

Index
File No. _____
T 25 S. R. 10 E. R.D. CRESCENT County ALAMATH
Merid. WILLAMETTE N.F. DESCHUTES State OREGON
CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. A-25


SEE: 2-25

T 245 RIDE

Also: 2-01

T 245 RIDE

BC




Index
File No. 552

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149LAB Cor. No. B-5T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. DeschutesCounty KLAM.State OregonN $\frac{1}{16}$ Cor. of
Section 6/5

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 5' WEST OF THE WEST EDGE
OF A LOOP ROAD - SEE TRANSPORTATION
MAP

CORNER LEGEND:

FS or Unverified

Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
27" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE S51°E - 29.5'
5" P. PINE N37°W - 41.9'
6" F.G. POSTS 4.9' EAST & 4.5' SOUTH

10

Work Done By C.W. COOK Title PLS Date 6-85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No.

552

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

B-5

13

Index

File No. 751

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

T 25 S. R. 10 E.

R.D. CRES

Survey No. 5304H14964BN

Cor.

No. B-7

Merid. Willamette

N.F. Deschutes

County KLAM


CN 1/4 Cor. of

State Oregon

Section 5

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

1/4 CORNER 32 IS ON SOUTH EDGE
OF ROAD # 9772 - CN 1/4 IS 1/4 MILE
SOUTH

CORNER LEGEND:

FS or Unverified
Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w 1 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE N49°W - 53.1'
7" P. PINE S81°E - 49.0'
6" F.G. POSTS 2.0' NORTH & 2.0' WEST

Work Done By C.W. COOK Title PLS Date 6-85 State Registration No. PLS 1098
or Agency

Plat of OR Certified for Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No.

751

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

B-7

Index

File No. 852

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149C48N Cor. No. B-8T 25 S. R. 10 E.R.D. CRESCENT

County

KLAMATHMerid. WillametteN.F. Deschutes

State

Oregon

NE 1/4 Cor. of

Section 5

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

NE 1/4 SEC. 5

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNC. OF ROADS #9772 & #9772-700
PROCEED WESTERLY 1/2 MILE -CORNER IS 400-500' SOUTH OF ROAD
ON EAST EDGE OF THINNING - 4x4 POST
& K-TAG ON ROAD

Searched By: _____

Title

Division


Headquarters

Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES. DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE N52°W-51.3'
5" P. PINE S31°E-61.1'
6' F.G. POSTS 1.9' NORTH & 1.9' EAST

10

Work Done By C.W. COOK Title SURVEYOR Date 1985 State Registration No. PLS 1098
or Agency

Plat or Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No.

852

T.25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

B-8

13

Index

File No. 952

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)


Survey No. 5304H1496ABN No. B-9T 25 S. R. 10 E. R.D. CRESCENTMerid. WillametteN.F. DeschutesCounty KLAMATHState Oregon

N'16 Cor. of

Section 5/4

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS VISIBLE FROM ROAD #9772 -
80' SOUTH OF ROAD

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE N67°E - 18.9' "N 1/4 S4BT"
9" P. PINE N10°W - 60.2' "N 1/4 S5BT"
6" F.G. POSTS 2.2' SOUTH & 2.7' WEST w/DECALS "BM-102" & "LSM-130"
B.T.'S HAVE TAGS 54-3, 54-9, 60D NAIL & DISK "PLS 1098" @ SIDE BASE

Work Done By C.W. COOK Title SURVEYOR Date 6-85 State Registration No. PLS 1098
or Agency

Platform Cor. Record Prepared? (Yes) No Filed At KLAM. Co. Surveyor's Office Date

History of Surveys, G.L.O., etc. G.L.O. - MELDRUM - 1879

Index File No. 952 T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648A1

Cor. B-9

Index

File No. 1052

CORNER RECORD (SEARCH) Contract or


(Ref. FSM 7151.4)

Survey No. 5304H/4964BA Cor. No. B-10T 25 S. R. 10 E. R.D. CRESCENTMerid. WillametteN.F. DeschutesCounty KLAMATHState OregonNW 1/4 Cor. of
Section 4

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

NW 1/4 4



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other☐ ☐ Searched For/Not Found☒ ☒ Evidence Found/Accept.:☒ ☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS 350' E. N.E. OF THE JUNCTION OF
ROADS #9772 & #9775-700 AT THE S.W. CORNER
OF A CLEAR-CUT

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

28" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" L.P. PINE S10°W - 80.4' "NW 1/4 S4 BT"

5" P. PINE S60°W - 104.7' "NW 1/4 S4 BT"

6' F.G. POSTS 1.8' NORTH & 1.9' EAST w/ DECALS "BM-102" & "LSM-130"

B.T.'S HAVE TAGS S4-3, S4-9, 60D NAIL w/ DISK "PLS 1098" @ SIDE-BASE

10

Work Done By C.W. COOK Title SURVEYOR Date 6-85 State Registration No. PLS 1098
or Agency

Plat. of Eor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History G.L.O. - MELDRUM - 1879

of

Surveys,

G.L.O.,

etc.

12

Index File No.

1052

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

B-10

13

Index

File No. 1152

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H14924B No. B-11T 25 S. R. 10 E. R.D. CRESCENTMerid. WillametteN.F. DeschutesCounty KLAMATHC.N. 1/16 Cor. of

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

C.N. 1/16 4

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PROCEED WEST 1/2 MILE ON ROAD "9772 FROM
 LINE POST SECS. 4/3 - SPUR RD. TO RIGHT (N.W.) &
 SKID ROAD COMES IN 300' SOUTH OF CORNER

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

28" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE N5°W - 64.7' "CN 1/16 S4 BT"

7" P. PINE S74°E - 89.6' "CN 1/16 S4 BT"

6" F.G. POSTS 2.0' EAST & 1.8' WEST w/ DECALS "BM-102" & "LSM-130"

BT'S HAVE TAGS S4-3, S4-9, GOD NAIL w/ DISK "PLS 1098" @ SIDE-BASE

10

Work Done By C.W. COOK Title SURVEYOR Date 6-85 State Registration No. PLS 1098
or Agency

Plat OF Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM CO. Surveyor's Office Date

11

History G.L.O. - MEMORUM - 1879

of
Surveys,
G.L.O.,
etc.

12

Index File No.

1152

T.25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

B-11

13

Index

File No. 1252

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N No. B-12

Cor.

T 25 S. R. 10 E. R.D. CRESCENTMerid. WillametteN.F. DeschutesCounty KLAMATHState Oregon

NE 1/4 Cor. of

Section 4

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

NE 1/4 4

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM ROAD #9772 PROCEED NORTH ON SPUR

#750 0.15 MILES - CORNER IS 30' EAST OF

ROAD AND 115' SOUTH OF CLEAR-CUT

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

27" IN GROUND IN RING OF STONE

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE N32°W - 89.1' "NE 1/4 S4 BT"

13" P. PINE S21°E - 109.8' "NE 1/4 S4 BT"

6' F.G. POSTS 2.5' WEST & 1.8' SOUTH w/ DECALS "BM-102" & "LSM-130"

BT's HAVE TAGS 54-7, 54-9, 60 D NAIL w/ DISK "PLS 1098" @ SIDE-BASE

10

Work Done By C.W. COOK Title SURVEYOR Date 6-85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History of G.L.O. - MELDRUM - 1879

of
Surveys,
G.L.O.,
etc.

12

Index File No. T. 25 S., R. 10 E., W.M.

1252

Contract or Surv. No.

5304H149648N

Cor.

B-12

13

Index


File No. 1352

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N Cor. No. B-13T 25 S. R. 10 E.R.D. CRESCENTCounty KLAMATHN¹/₁₆ Cor. ofMerid. WillametteN.F. DeschutesState OregonSection 4/3

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9407 & #9772
 PROCEED EAST ON #9407 0.1 MILE TO 4x4
 POST & TAGS ON SOUTH EDGE OF RD #9407 WHEN
 IS 334' SOUTH OF CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2' x 30" G.I.P. w/ 2 1/2" BRASS CAP
27" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE S76°E - 23.0' "N 1/4 S3 BT"
10" P. PINE N63°W - 69.1' "N 1/4 S4 BT"
6' F.G. POST 1.7' SOUTH & 2.1' EAST w/ DECALS "LSM-170" & "BM-102"
BT'S HAVE TACS 54-3, 54-9, 60 D NAIL w/ DISK "PLS 1098" @ SIDE BASE

Work Done By. C.W. COOK Title SURVEYOR Date 6-85 State Registration No. PLS 1098
or Agency

Plat or Cor. Record Prepared? ☒ Yes No Filed At KLAM Co. Surveyor's Office Date

History of Surveys, G.L.O., etc. G.L.O. - MELDRUM - 1879

Index File No. 1352 T. 25 S., R. 10 E., W.M. Contract or Surv. No. 5304H149648H Cor. B-13

Index

File No. 1452

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 53044149648 No. B-14T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. DeschutesCounty KLAM.State Oregon

Nw 1/4 Cor. of

Section 3

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

NW 1/4 S3

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other☐ ☐ Searched For/Not Found☒ ☒ Evidence Found/Accept.☒ ☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9772 & #9407
PROCEED EASTERLY ON #9407 TO 4x4 WOOD
POST & K-TAG NORTH OF CORNER

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/2 1/2" BRASS CAP

28" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE N84°E - 19.1'

8" P. PINE S60°E - 48.8'

6' F.G. POSTS 2.1' NORTH, 1.9' SOUTH, 2.1' EAST, & 2.7' WEST.

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

13

Index File No

1452

T. 25 S., R. 10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

B-14

Index

File No. 1552

CORNER RECORD (SEARCH)

Contract or

(Ref. FSM 7151.4)

Survey No. 5304H/49648N

Cor.

No. B-15T ZS S. R. 10 E.R.D. CRES.

County

KLAM.

CN'/16 Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 3

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

CN'/16 3

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or
Contr. Unverified
Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS ON NORTH SLOPE 600'±EAST OF SPUR ROAD #850 - SEE MAP

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

28" IN GROUND w/ MOUND OF ROCK

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" P. PINE S61°W - 45.0'

12" P. PINE N22°E - 69.3'

6' F.G. POSTS 2.3' SOUTH & 2.3' WEST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared? Yes No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No
1552

T.25 S., R. 10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. B-15

12

13

Index

File No. 1652

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149648A

Cor.

No. B-16T 25 S. R. 10 E.

R.D.

CRES.

County

KLAM.Merid. Willamette

N.F.

Deschutes

State

Oregon

NE 1/4

Cor. of

Section 3

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

NE 1/4 S3

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9407 & #9772
 PROCEED EASTERLY TO 4x4 POST & K-TAG
 NORTH OF THE CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2"x30" G.I.P. w/2 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" P. PINE N30°W - 75.2'
6" P. PINE S8°E - 41.2'
6' F.G. POSTS 2.9' NORTH & 2.9' EAST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No
1652

T. 25 S., R. 10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. B-16

12

13

Index

File No.

1752

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149648

Cor.

B-17

T 25 S. R. 10 E.

R.D.

CRES.

County

KLAM.

Merid. Willamette

N.F.

Deschutes


State

Oregon

N $\frac{1}{4}$ Cor. of

Section 3/2

CORNER DIAGRAM, per legend

N $\frac{1}{4}$ 3/2

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9407 & #9772
 PROCEED EASTERLY TO 4x4 POST & K-TAG
 NORTH OF CORNER

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
29" IN GROUND w/ MOUND OF ROCK

MONUMENT STAMPED



ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" L.P. PINE N37°E - 12.9'
6" L.P. PINE S77°W - 31.9'
6' F.G. POSTS 2.0' WEST & 2.2' NORTH

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat or Certified for Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No
1752

T.25 S., R. 10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. B-17

Index
File No. 0153CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey N^o.

Cor. No. C-01

T 25 S. R. 10 E. R.D. Crescent

County Klamath

W/4 Cor. of

Merid. Willamette

N.F. Deschutes

State Oregon

Section 6

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

2½" BCSP Rising 5"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

10" LP Pine S81°W @ 12.0 Ft. B/S 1/4S S1 BT

7" " " S89°E @ 40.0 " " 1/4S S6 BT

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Location tag on road #1972 (60')

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.


Searched By: Steve Chamberlain ST

Division
SurveyHeadquarters
SODate
6-28-83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Plat or Certified Cor. Record Prepared ? Yes No Filed At: Co. Surveyor's Office Date _____

History
of
Surveys,
G.L.O.,
etc.

Index File No. T. S., R. E., W.M. Contract or Surv. No. Cor. _____

0153

C-01

USDA-FOREST SERVICE D-7100-52(2/82)

Index
File No. 353

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

T 25 S. R. 10 E. R.D. CRES

Survey No. 5304H1948N

Cor. No. C-3

Merid. Willamette

N.F. Deschutes

County KLAM

State Oregon


C1/4 Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

Section 6

C1/4 SEC. 6



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS 400' ± SOUTH OF JUNCTION
OF ROADS # 9772 & # 9760

CORNER LEGEND:

FS or Unverified
Contr. Other
☐ ☐ Searched For/Not Found
☒ ☒ Evidence Found/Accept.
☒ ☒ Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/2 1/2" BRASS CAP
29" INGROUND

MONUMENT STAMPED



9

ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

11" L.P. PINE S14°E - 45.9'
12" L.P. PINE N82°E - 22.0'
6' F.C. POST 1.0' NORTH
FOUND STEEL FENCE POST S2°E - 5.65' w/TAG "54-2"

10

Work Done By C.W. COOK Title PLS Date 6-85 State Registration No. PLS 1098
or Agency

Plat or Certified Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No.

353

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

C-3


12

13

Index 0553

File No. _____ CORNER RECORD (SEARCH) Contract or
 (Ref. FSM 7151.4) Survey No. _____ Cor. C-05
 T 25 S. R. 10 E. R.D. Crescent County Klamath W/4 _____
 Merid. Willamette N.F. Deschutes State Oregon Section 5 Cor. of _____

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

2 1/2" BCSP rising 11" in a rock mound. Steel post 2.0 feet NE
 with boundary sign. ##### Appears posted to the East.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

29" P. Pine brs N60°W w/window and bottom blaze w/60d nail in base.

11" Sugar Pine brs SE with healed blaze w/60d nail base of blaze

6 Stump in NE location fits original call.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other

☐ ☐ Searched For/Not Found

☒ ☒ Evidence Found/Accept.

☒ ☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3 Set location tag 500' South on spur. Corner lies on Westerly
 slope of ridge. From Junction 9772 and 9407, go West on 9772
 1.6 miles to spur rod, turn left, go 0.65 mi to location tag
 on South side of road.


Searched By: Ross Taylor

Title
STDivision
SurveyHeadquarters
SODate
7-7-83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 Certified Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc.

WOOD POST

30" Pine brs N70°E 95 lks

18" " " N 60°W 42 lks.

Index File No. 0553 T. S., R. E., W.M. Contract or Surv. No. Cor. C-05

Index

File No. 753

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

6304 H149648

Cor.

No.

C-7T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. Deschutes

County

KLAM.State OregonSection 5

Cor. of

CORNER DIAGRAM, per legend

C1/4 SS

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 100' E NORTH OF
SECONDARY ROAD # 673 - SEE
TRANSPORTATION MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. W/ 2 1/2" BRASS CAP
29" IN GROUND

MONUMENT STAMPED



ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE S64°W - 53.6'
6" P. PINE N58°W - 53.4'
6' F.G. POST 2.2' WEST

10

Work Done By C.W. COOK Title LS Date 6/85 State Registration No. PLS 1098
or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No.

753

T.25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

C-7

13

Index

File No. 0953

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor. C-09

No.

T 25 S. R. 10 E. R.D. Crescent

County Klamath

W/4

Cor. of

Merid. Willamette

N.F. Deschutes

State Oregon

Section

4

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

2 1/2" BCSP Rising 9" above ground

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

16" P. Pine brs S18°W @ 33.0 Ft. Blaze healed over

10" " " " N86°W @ 27.0 Ft. " " "

25" Pine Stump brs N56°E @ 29.0 Ft. With axe marks and faint scribing.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Sign board on road (100)Ft.

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.


Searched By: Steve Chamberlain ST

Division
SurveyHeadquarters
SODate
6-28-83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 Plat or Cor. Record Prepared? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc. _____

Index File No. 0953 T. S., R. E., W.M. Contract or Surv. No. Cor. C-09

Index

File No. 1153

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N Cor. No. C-11T 25 S. R. 10 E. R.D. CRESCENTMerid. WillametteN.F. DeschutesCounty KLAMATHState OregonC/A Cor. of
Section 4

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

C/A 4

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

4x4 WOOD POST & TAGS ON NORTH EDGE RD. #9407
14' SOUTH OF CORNER

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2"x30" G.I.P. w/ 1/2" BRASS CAP
29" IN GROUND IN MOUND OF ROCK

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE N12°E - 6.1' "C1/4S4BT"
6" P. PINE N45°W - 35.3' "C1/4S4BT"
6" F.G. POSTS 1.7' SOUTH & 2.1' WEST w/ DECALS "BM-102" & "LSM-130"
B.T.'S HAVE TAGS S4-3, S4-9, GOD NAIL w/ DISK "RS1098" @ SIDE-BASE

Work Done By: C.W. - COOK Title: SURVEYOR Date: 5-85 State Registration No. or Agency: PLS 1098

Plat or Cor. Record Prepared? (Yes) No Filed At: KLAM Co. Surveyor's Office Date

History of Surveys, G.L.O., etc. G.L.O. - MELDRUM - 1879

Index File No. 1153

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

53044149648N

Cor. C-11

Index

File No. 1253

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648A Cor. No. C-12T 25 S. R. 10 E. R.D. CRESCENTMerid. WillametteN.F. DeschutesCounty KLAMATHState OregonCE/16 Cor. of
Section 4

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

CE/16 4

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

4x4 WOOD POST & BOUNDARY TAG ON NORTH
EDGE OF ROAD #9407 130' NORTH OF CORNER

Searched By: _____

Title _____

Division _____

Headquarters _____

Date _____


CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

22" IN GROUND IN MOUND OF ROCK

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE S59°W - 10.6" "CE 1/4 S4BT"

7" P. PINE N14°W - 26.5' "CE 1/4 S4BT"

6' F.G. POSTS 2.2' SOUTH & 2.9' NORTH w/ DECAUS "BM-102" & "LSM-130"

B.T.'S HAVE TAGS S4-3, S4-9, 60D NAIL w/ DISK "PLS 1098" @ SIDE-BASE

10

Work Done By C.W. COOK Title SURVEYOR Date 5-85 State Registration No. PLS 1098
or Agency

Platted For Record Prepared? ☒ Yes No Filed At KLAM. Co. Surveyor's Office Date

11

History of G.L.O. - MELDRUM - 1879

Surveys,
G.L.O.,
etc.

12

Index File No. 1253 T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

Cor.

13

5304H149648N

C-12

Index

File No. 1353

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H1496AEN

Cor.

No. C-13T 25 S. R. 10 E.R.D. CRESCENT

County

KLAMATH1/4

Cor. of

Merid. WillametteN.F. Deschutes

State

Oregon

Section

4/3

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

23" P. PINE 379°W - 33.3' SCRIBES VISIBLE

44" PINE STUMP 568°E - 48.2' NO SCRIBES

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9772 & SPUR #800 PROCEED

SOUTH ON #800 0.4 MILE TO 4x4 POST & TAG ON

EAST EDGE OF ROAD - 800' WEST TO CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

C.W. COOK

Title

PLS

Division

Headquarters

Date


4-85

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" G.I.P. w/ 3" BRASS CAP
27" IN GROUND

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE S82°E - 18.8' "1/4 S3 BT"

17" P. PINE S19°W - 76.6' "1/4 S4 BT"

6' F.G. POSTS 29' NORTH & 3.5' EAST w/ DECALS "LSM-130" & "BM-102"

ALL B.T.'S HAVE 60D NAIL @ SIDE-CENTER BASE, TAGS S43, S44 - S.E. STUMP HAS

NAIL IN TOP CENTER - NEW B.T.'S HAVE 1 1/2" ALUM. DISK "PLS1098" ON 60D NAIL

Work Done By C.W. COOK Title SURVEYOR Date 4-85 State Registration No. PLS1098
or Agency

Plat DE Cor. Record Prepared? ☒ Yes No Filed At KLAM Co. Surveyor's Office Date

History GLO - MELDRUM - 1879

of 6" PINE S82°W - 50 LKS.

Surveys, 60" PINE S73°E - 70 LKS.

G.L.O.,
etc.

Index File No.

1353

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

C-13

12

13

Index

File No. 1453

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N No. C-14T 25 S. R. 10 E. R.D. CKES.Merid. WillametteN.F. DeschutesCounty KLAM.State OregonCW'1/16 Cor. of
Section 3

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

CW'1/16 3

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

CORNER FALLS 500' E EAST OF ROAD #800
(K-TAG & 4x4 POST ON ROAD)

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE S87°W - 14.4'
4" P. PINE N5°E - 30.5'
6' F.C. POSTS 2.1' NORTH & 1.9' WEST

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No
1453

T. 25 S., R. 10 E., W. M.

Contract or Surv. No
5304H17964BN

Cor.
C-14

Index

File No. 1553

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.

T 25 S. R. 10 E.

R.D.

CRES.5304H149648N

No.

C-15Merid. Willamette

N.F.

Deschutes

County

KLAM.

State

Oregon

C/A

Cor. of

Section 3

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

C/A 3

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 97' EAST OF ROAD & 100' E
WEST OF PARALLEL NORTH/SOUTH ROAD
ON RIDGE-TOP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
27" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE N55°W - 48.3'
7" P. PINE N44°E - 45.0'
6' F.C. POSTS 2.3' NORTH & 1.9' SOUTH

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared? Yes No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No

1553

T. 25 S., R. 10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

C-15

LAND CORNER RECORD

1. T 2 5S R 10E No. C-17 Cor. 1/4 Mer. W State Oregon (Rectangular) N. F. Deschutes Dist. C-17 5680-2

2. Cor. or Status

3. Original Description Vol. Page Where Recorded

4. Description of Corners: Original Description:

Set post for 1/4 sec. cor.; from which:

- (1) A pine, 40 ins. diam., bears N.70°E., 41 lks. dist.
(2) " " 20 " " " S.22°W., 38 " "

5. Investigation Notes:


Both bearing trees were in good condition.

#1 35" P. Pine Stump NE scribing visible in Burnt Blaze
#2 28 1/2" " " S 22°W 25' Chopped open nothing visible

Located 300' ± W of Rd on 40' N of Spur.
From Junc 9775 & 9410 proceed W 12 mi turn left, proceed
0.5 mi to 67C loc tag on turn Right and proceed 300' to Cor

R Taylor

6. Signed Wm. Steers Title Land Surveyor Date 7-6-83
Dec. 1966



7. Photo Identification

Photo No.

Ident. By

8. Plan Coordinate Position Data

State Zone

X

Y

Estab. By

Field Book No.

Where Filed

9. Evaluation


Authentic

Needs Verification if Monument X

Re-estab. Survey

Land Status

2. Corner Status



7. Photo Identification

Photo No.

Ident. By:

8. Plane Coordinate Position Data

State

Zone

X

Y

Estab. By

Field Book No.

Where Filed

9. Evaluation

Authentic

Needs Verif. Monument ☒

Re-estab. Survey

Land Status

1. T 25S R 10E No. C-17 Cor. 1/4 Mer. W

(Rectangular)

3. Original Description

Vol.

Page

Where Recorded

4. Description of Corners: Original Description:

Set post for 1/4 sec. cor.; from which:

- (1) A pine, 40 ins. diam., bears N. 70° E., 41 lks. dist.
(2) A pine, 20 ins. diam., bears S. 22° W., 38 lks. dist.

5. Investigation Notes:

Both bearing trees were in good condition.

#135" Pine stump NE scribbing visible in burnt place
#228" " " 522° W 25' chopped open, nothing visible

Located 300' ± W of rd on 40' N of spur.

From Sunct 9775 ± 9410 proceeds W 12 mi. turn left, proceed
0.5 mi. to 67C loc tag on turn right and proceed 300' to corner

6. Signed Wm. Steers Title Land Surveyor Date Dec. 1966

R Taylor

7-6-83

PERPETUATION RECORD


10. Monument: Using a staff compass and engineers tape I laid off the record distances and bearings from each bearing tree and located the corner. I monumented the corner with a 2 inch galvanized iron pipe w/brass cap, 30 inches long, set 24 inches into the ground; From which:
 (1) A ponderosa pine, 39.0 inches in diameter, bears N.68°E., a distance of 26.2 feet to a 60d nail in the base of the tree.
 (2) A ponderosa pine, 27.5 inches in diameter, bears S.22°W., a distance of 24.1 feet to a 60d nail in the base of the tree.
 3" Alum Cap on 2 1/2" Alum Pipe R56.5" in rock collar
 10 1/2" L.P. Pipe N 41° E 100' ± 1/4 S 28° T 60d @ base

Field Book _____ Page _____

12. Set By <u>Wm. Steers</u> Title <u>Land Surveyor</u> Agency <u>G.I.L. Tbr. Co.</u> Date <u>Dec. 1966</u>	13. Recorded By _____ Volume _____ Page _____
14. Remarks:	(Date) _____ (City) _____ (County) _____ (State) _____

MONUMENT STAMPED

STEERS, Wm. Steers, C. H. D. Not M.K.D.



T255 R10E 1/4 S3/4 1983 RPL 5 1846

1753

C-17

USDA-FOREST SERVICE D-7100-52(2/82)

Index

File No. 1953

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H/49648A

Cor.

No. C-19T 25 S. R. 10 E.R.D. CRES.

County

KLAM.Merid. WillametteN.F. Deschutes

State

Oregon

C1/4 Cor. of

Section 2

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

C1/4 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Pd.

CORNER FALLS ON EAST EDGE OF
ROAD - N10°E x SOUTH - SEE MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
30" IN GROUND (FLUSH w/ROAD)
w/MOUND OF ROCK

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE N 9° W - 71.0'
8" P. PINE S 82° E - 60.5'
6' F.G. POSTS 1.5' NORTH & 1.5' SOUTH

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No
1953

T.25 S., R. 10 E., W.M.

Contract or Surv. No.
5304H149648N

Cor. C-19

13

Index

File No. 2053

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648A

Cor.

No. C-20T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. DeschutesCounty KLAM.

CE'1/16 Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

Section 2

CE'1/16 S2

3

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 120' ± EAST OF ROAD -
SEE MAP

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

28" IN GROUND w/ MOUND OF ROCK

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE N 11° W - 13.8'

6" P. PINE S 84° W - 29.9'

6' F.G. POSTS 2.3' EAST & 2.3' SOUTH

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat. of Cor. Record Prepared? ☒ Yes No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No
2053

T.255., R.10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.


C-20

LAND CORNER RECORD

C-21 5680-2

1. T 25S R 10E No. C-21 Cor. 1/4 Mer. W State Oregon (Rectangular) N. F. Deschutes Dist. Crescent

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument X

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: Original Description:

Set post on 1/4 sec. cor.; from which:

(1) A pine, 20 ins. diam., bears N. 83°W, 29 lks. dist.

(2) " " 24 " " " S. 63°E, 22 " "

5. Investigation Notes:

B.T. # 1 was a green tree in good condition - OPEN BLAZE w/ FAINT SCRIB

B.T. #2 was a stump. - 4" HIGH - FACE BLAZE & TOE BLAZE
WITH VERY FAINT SCRIBING

6. Signed W. MILLER Title LS Date 6/28/84

Signed Wm., Steers Title Land Surveyor

Date Dec. 1966

PERPETUATION RECORD

10. Monument: Using a staff compass and engineers tape I located the corner from the record bearings and distances from both bearing trees. I blazed and scribed one new bearing tree. I monumented the corner with a 2 inch galvanized iron pipe w/brass cap, 30 inches long, set 24 inches into the ground; *RSG. 6"*

From which:

Dec. 20°E.

-11- A ponderosa pine, *17* inches in diameter, scribed 1/4 S1BT, bears S.85°E., a distance of 51.8 feet to a 60d nail in the base of the tree. (*60d - SOUTH SIDE - CENTER - 15" HIGH*)

(1) A ponderosa pine, 30 inches in diameter, bears N.85°W., a distance of 18.5 feet to a 60d nail in the base of the tree.

Field Book _____ Page _____



12. Set By Wm. Steers Title Land Surveyor
License ORE 622 Agency Gil.Tbr.Co. Date Dec. 1966

13. Recorded By _____ Volume _____ Page _____
(Agency)

(Date) (City) (County) (State)

14. Remarks: **MONUMENT STAMPED!**

*STEERS' CAP
NOT MKD.*




USDA-FOREST SERVICE D-7100-52(2/82)

Index
File No. 2353 CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 5304H149648A No. C-23
T 25 S. R. 10 E. R.D. CRES. County KLAM. C/4 Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 1

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

C/4 1



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other

☐ ☐ Searched For/Not Found

☒ ☒ Evidence Found/Accept.

☒ ☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 52' NORTH OF ROAD -
CRS. N85°W x S85°E -
SEE MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE N75°E - 27.2'

8" P. PINE S46°W - 23.5'

6' F.G. POSTS 1.6' NORTH & 2.3' EAST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat. of Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAMCO. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No
2353

T255S., R. 10 E., W.M.

Contract or Surv. No
5304H/149648N

Cor. C-23

12

13

Index

File No. 2553


CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648A Cor. No. C-25T 25 S. R. 10 E.R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState OregonE 1/4 Cor. of
Section 1

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND



IRON PIPE w/ 2" BRASS CAP IN

MOUND OF ROCK (ROTTED SCRIBED)
POST ALONGSIDE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

33" x 3' HIGH PINE STUMP N70°W - 12.1' (ORIG.)

14" P. PINE N32°E - 33.2' (ORIG.) FOR REF. ONLY

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 150' EAST OF ROAD -
SEE TRANSPORTATION MAP

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

CLEARED BRUSH - PAINT BAND ON B.T.S

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P. PINE S59°W - 83.9'

6" P. PINE S11°W - 99.4'

6' F.G. POST 2.1' WEST

10

Work Done By C.W. COOK Title LS Date 7/85 State Registration No. PLS 1098
or Agency

Plat DE Certified For Record Prepared? ☒ Yes No Filed At KLAM Co. Surveyor's Office Date

11

History of
Surveys,
G.L.O.,
etc.

D. THOMPSON - 1865

24" PINE N70°W - 17 LKS.

8" PINE N30°E - 50 LKS.

RESTORATION BY

W. STEERS IN 1966

12

Index File No.
2553

T.25 S., R. 10 E., W.M.

Contract or Surv. No.
5304H149648N

Cor. C-25

13

USDA-FOREST SERVICE D-7100-52(2/82)

Index

File No. 254

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No. 5304H(19648N)

Cor.

No. D-2

T 25 S. R. 10 E. R.D. CRES

Merid. Willamette

N.F. Deschutes

County KLAM

State Oregon

SW $\frac{1}{4}$ Cor. of
Section 6

CORNER DIAGRAM, per legend

SW $\frac{1}{4}$ SEC. 6



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9772 & #9760
PROCEED SOUTHERLY $\frac{1}{2}$ MILE - CORNER
IS 300' EAST OF ROAD

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
29" IN GROUND

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

11" L.P. PINE S66°E - 29.4'
9" L.P. PINE S10°W - 30.5'
6" F.G. POSTS 3.1' SOUTH & 2.5' EAST

10

Work Done By C.W. COOK Title PLS Date 6-85 State Registration No. PLS 1098
or Agency

Platform Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No.

254

T.25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

D-2

12

13

Index

File No. 354

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

53044 H9648N

Cor.

No.

D-3T 25 S. R. 10 E.

R.D.

CRES.

County

KLAMMerid. Willamette

N.F.

Deschutes

State

Oregon

CS 1/16

Cor. of

Section

6

CORNER DIAGRAM, per legend

CS 1/16 SC



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS ON N.W. SLOPE NEAR
S.E. CORNER OF CLEAR-CUT - END OF
OLD SPUR ROAD IS WESTERLY 300' ±

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" x 30" G.I.P. w/ 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE N86°E - 3.4'
6" P. PINE S64°W - 28.6'
6" F.G. POSTS 1.8' EAST & 2.7' WEST

Work Done By C.W. COOK Title LS Date 6-85 State Registration No. PLS 1098
or Agency

Plat or Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No.

354

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

D-3

Index

File No. 454

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H/149648W

Cor.

No. D-4

T 25 S. R. 10 E. R.D. CRES

Merid. Willamette

N.F. Deschutes

County KLAM


State Oregon

Section SE 1/4 Cor. of C

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

SE 1/4 SL



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS ON NNW SLOPE 260'
NORTH OF RIM-ROCK RIDGE-TOP
SEE TRANSPORTATION MAP FOR ROAD
ACCESS

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2"x30" ALUM. PIPE w/2 1/2" ALUM. CAP.
27" IN GROUND w/RING OF STONE

MONUMENT STAMPED



ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" L.P. PINE N81°E - 34.9'
6" SUGAR PINE S34°E - 26.0'
6" F.G. POSTS 2.8' SOUTH & 2.1' WEST

10

Work Done By C.W. COOK Title PLS Date 7-85 State Registration No. PLS 1098
or Agency

11

Plat. of Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

12

Index File No.

454

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

S304H149648N

Cor.

D-4

13

Index

File No. 0155

CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No.

Cor. E-01

No.

T 25 S. R. 10 E. R.D. Crescent

County Klamath

NW

Merid. Willamette

N.F. Deschutes

State Oregon

Section 7

Cor. of

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

BCSP

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

12" LP Pine, S40°E @ 42.0 Ft. B/S T25S R10E S7 BT

8" " " N45°E @ 42.0 Ft. " T25S R10E S6 BT

8" " " N42°W @ 51.0 " " T25S R9E S1 BT

7" " " S40°W @ 64.0 " " T25S R9E S12 BT

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: Steve Chamberlain ST


Title

Division
SurveyHeadquarters
SODate
6-30-83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 Plat or Cor. Record Prepared? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc. _____

Index File No. T. S., R. E., W.M. Contract or Surv. No. Cor. E-01

Index

File No. 255

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149148 Cor. No. E-2

T 25 S. R. 10 E. R.D. CRES.

Merid. Willamette

N.F. Deschutes

County KLAM.


State Oregon

W 1/4 Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

W 1/4 6
7



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

☐ ☐ Searched For/Not Found

☒ ☒ Evidence Found/Accept.;

☒ ☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS ON WEST EDGE OF SPUR ROAD
NORTH OFF OF ROAD #9760-600 NEAR S.E.
CORNER OF CLEAR-CUT

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P. PINE N30°W - 8.4'
6" P. PINE S14°E - 35.2'
6' F.G. POSTS 2.6' NORTH } 2.1' WEST

Work Done By C.W. COOK Title PLS Date 6-85 State Registration No. PLS 1098
or Agency

Plat. or Certified Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No.

255

T. 25 S., R. 10 E., W. M.

Contract or Surv. No.

5304H149648N

Cor.


E-2

LAND CORNER RECORD

5680-2

1. T. 25S R. 10E No. 0335 E-3 Cor. 1/4 Mer. W State Oregon (Rectangular) N. F. Deschutes Dist. Crescent

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument X

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: ORIGINAL DESCRIPTION:

Set post for 1/4 sec. corner; from which:

(1) A pine, 18 ins. diam., bears S.24°E., 63 lks. dist.

(2) " " 20 " " " N.03°W., 80 " "

5. Investigation Notes:

B.T. 1 is a down dead tree.

B.T. 2 there is a stump at the proper location.

6. Signed Wm. Steers Title Land Surveyor Date April 1967

PERPETUATION RECORD

10. Monument: Using a staff compass and engineers tape I laid off the record distance and bearing from bearing tree number one and located the corner. I found a low stump at the record distance and bearing for bearing tree number 2. I blazed and scribed two new bearing trees. I monumented the corner with a 2 inch galvanized iron pipe w/brass cap, 30 inches long, set 24 inches into the ground;

From which: Dec. 20°E.

11. Accessories

A ponderosa pine, 12 inches in diameter, scribed 1/4⁶SBT, bears N.39°E., a distance of 8.3 feet to a 60d nail in the base of the tree. ✓

A sugar pine, 13⁴⁵ inches in diameter, scribed 1/4⁶S7BT, bears N S.36°W., a distance of 69.0 feet to a 60d nail in the base of the tree. ✓

Field Book _____ Page _____

12. Set By Wm. Steers Title Land Surveyor
License ORE 622 Agency Gil.Tbr.Co. Date April 1967

13. Recorded By _____ Volume _____ Page _____
(Agency)

(Date) (City) (County) (State)

14. Remarks: MONUMENT STAMPED

T25S R10E
S6
1/4 S7
April 1967
L.S. 622

✓ CAP RISING - 13" ABOVE
GROUND. ORIG. WOOD
POST. WEST OF CAP.
CAP IS BLANK!!

✓ CORNER REVISITED 6-30-83
BY STEVE CHAMBERLAIN (CST)

0355

E-03

Index
File No. 455
T 25 S. R. 10 E. R.D. CRS. (Ref. FSM 7151.4) Contract or Survey No. 5304H149648 No. E-4
Merid. Willamette N.F. Deschutes County KLAM. E/lc Cor. of
CORNER DIAGRAM per legend DESCRIBE CORNER MONUMENT FOUND Section 6 7




PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

CORNER LEGEND:
PS or Unverified
Constr. Other
☐ ☐ Searched For/Not Found
☒ ☒ Evidence Found/Accept.
☒ ☒ Permanent Mon. Set/Fd.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 400-500' WEST OF ROAD
673 - SEE TRANSPORTATION MAP -
4x4 WOOD POST & K-TAG ON EDGE OF ROAD

Searched By:


Title Division Headquarters Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" ALUM. PIPE w/ 2 1/2" ALUM. CAP
27" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" P. PINE N 40° E - 23.6'

7" P. PINE S 86° W - 20.6'

6' F.G. POSTS 2.4' NORTH & 2.2' EAST

Work Done By C.W. COOK Title LS Date 7/85 State Registration No. PLS 1098
or Agency

Flat of Certified Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM, Co. Surveyor's Office Date

History
of
Surveys,
G.L.O.,
etc.

Index File No.

455

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

E-4

USDA-FOREST SERVICE D-7100-52(2/82)

Index

File No. 555

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H14964B Cor. No. E-5

T 25 S. R. 10 E.

R.D. CRESCENT

County KLAMATH

Merid. Willamette

N.F. Deschutes

State Oregon

SEC. 615 Cor. of 718

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

2" G.I.P. w/ 2 1/2" BRASS CAP

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

31" P. PINE (ORIG.) N35°W - 42.4'

24" x 4' TALL PINE STUMP (ORIG.) N54°E - 23.4' NO SCRIBE MARKS

PINE ROOT-WAD (ORIG.) S64°W - 27' ± NO SCRIBE MARKS

30" P. PINE (1966) N7°E - 27.9'

32" P. PINE (1966) S46°W - 58.6'

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNC. OF ROADS #9760 & #9760-600 PROCEED

EAST'LY ON #9760-600 FOR 1 1/4 MILES TO JUNCTION.

ON SMALL SADDLE IN RIDGE - CONT. TO RIGHT 1/4 MILE -

CORNER IS 200' ± NORTH OF ROAD (VISIBLE FROM ROAD)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____


Headquarters _____

Date _____

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES. DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

11" P. PINE S34°E - 43.2' "T255 R10E 58 BT"
 6' F.G. POST 2-8' WEST w/DECALS "LSM-130" & "BM-102"
 ALL B.T.s HAVE TAGS 54-3, 54-4, GOD NAIL @ SIDE-BASE (EX. ROOT-WAD) -
 NEW B.T. HAS 1 1/2" ALUM. DISK "PLS 1098" ON GOD NAIL

Work Done By C.W. COOK Title SURVEYOR Date 4-85 State Registration No. PLS 1098
 or Agency

Plate of Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date

History of G.L.O. - H. MELDRUM - 1879
 Surveys,
 G.L.O.,
 etc.


Index File No. 555 T.25 S., R. 10 E., W.M. Contract or Surv. No. 5304H149648N Cor. E-5

LAND CORNER RECORD

(Rectangular)

1. T 25S R 10E No. E-7 Cor. 1/4 Mer. W State Oregon N. F. Deschutes Dist. Crescent E-7 5680-2

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By : _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument X

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 1/4 Section corner common to Sections 5 and 8

Original notes:

- (1) A pine, 30 ins. diam., bears N48°W, 41 lks. dist.
 (2) " " , 24 " " , " S38°W, 45 " " "

5. Investigation Notes:

At the corner I found bearing tree number 1 to be in good condition, number 2 is a stump. I located the corner and blazed and scribed one new bearing tree.

IN ADDITION @ #2 - DOWN LOG SCRIBED S BT

STEVE CHAMBERLIN ST ENG SO.

6. Signed Wm. Steers Title Land SurveyorDate April 1966


6/30/83

LAND CORNER RECORD

E-7 5680-2

1. T. 25S R. 10E No. 0735 E-7 Cor. 1/4 Mer. W State Oregon (Rectangular) N. F. Deschutes Dist. Crescent

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Etab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument X

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 1/4 Section corner common to Sections 5 and 8

Original notes:

(1) A pine, 30 ins. diam., bears N48°W, 41 lks. dist.

(2) " " , 24 " " , " S38°W, 45 " " ."

5. Investigation Notes:

At the corner I found bearing tree number 1 to be in good condition, number 2 is a stump. I located the corner and blazed and scribed one new bearing tree.

IN ADDITION @ #2 - DOWN LOG SCRIBED BT

STEVE CHAMBERLIN ST ENG SO.

6/30/83

6. Signed Wm. Steers Title Land Surveyor

Date April 1966

PERPETUATION RECORD

10. Monument: I monumented the corner with a 2 inch galvanized iron pipe, w/brass cap, 30 inches long set 24 inches into the ground, and marked it: *RSG. 9"*

T25SR10E

1/4 $\frac{S5}{S8}$

Reg. No. 622

~~xxxxxx~~

From which:

(1) A ponderosa pine, 32.2 inches in diameter, bears N61°W, a distance of 27.0 feet to the blazed face. *AXE MARKS (ORIG.)*

A lodgepole pine, ²⁰15.5 inches in diameter, scribed 1/4S8BT, bears S75°W, a distance of 74.5 feet to the blazed face.

Field Book _____ Page _____

12. Set By Wm. Steers Title Land Surveyor
License ORE 622 Agency Gil.Tbr.Co. Date April 1966

13. Recorded By _____ Volume _____ Page _____
(Agency)

(Date) (City) (County) (State)

14. Remarks:

0755


E-07

Index
File No. 955

CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 5304H14964EN Cor. No. E-9

T 25 S. R. 10 E. R.D. CRESCENT County KLAMATH SEC. 514
Merid. Willamette N.F. Deschutes State Oregon Cor. of 514
Section 514

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

2" G.I.P. / 2 1/2" BRASS CAP

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

17" PINE STUMP (ORIG.) N43°E - 16.2' SCRIBES VISIBLE

24" PINE UP-ROOT (ORIG.) N50°W - 16.3' ± NO SCRIBES VISIBLE - AX-WORK & OPEN FACE

20" PINE UP-ROOT (ORIG.) S48°E - 28.3' ± SCRIBES VISIBLE

29" SUGAR PINE (1966) N26°E - 59.5' 10" P. PINE (1966) N13°W - 37.0'

14" SUGAR PINE (1966) S65°W - 32.5' 20" P. PINE (1966) S56°E - 44.7'

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF ROADS #9772 & #9407 PROCEED S.W.'LY

ON #9407 - WOOD 4x4 POST ON NORTH EDGE OF ROAD

AT C/4 SEC. 4 - TURN SOUTH 200' ± WEST OF POST -

STAY TO THE RIGHT FOR 1 MILE ± - CORNER IS

30' ± SOUTH OF RD - 4x4 WOOD POST N. EDGE RD.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

Searched By: C.W. COOK

Title

PLS

Division

Headquarters

Date

5-85


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

CLEARED AROUND CORNER $\frac{1}{2}$ TO ALL

B.T.s

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

FOUND F.G. POSTS 5.8' WEST AND 2.5' S.W. w/DECALS

ALL B.T.s HAVE USFS TAGS 54-3, 54-4, 6" RED PAINT BAND

STEERS 1966 B.T.s HAVE GOD NAIL @ SIDE-CENTER BASE

N.E. ORIG. STUMP HAS GOD NAIL @ TOP-CENTER

Work Done By C.W. COOK Title SURVEYOR Date 5-85 State Registration No. PLS 1098
or Agency

Plat or Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date 11

History of Surveys, G.L.O., etc. G.L.O. - H. MELDRUM - 1879

Index File No.

955

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

E-9

Index

File No. 1155

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N

Cor.

No. E-11T 25 S. R. 10 E. R.D. CRESCENTCounty KLAMATH1/4

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 4

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

ORIG. POST BESIDE MOUND OF ROCK

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

21" P. PINE STUMP NB°W-32.6' SCRIBE "B" VISIBLE
 42" PINE STUMP S9°W-97.3' SCRIBING VISIBLE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNC. OF ROADS #9772 & #9407 PROCEED 1/4 MILE
 S.W.'LY ON #9407 - THEN SOUTH 1/2 MILE ON
 SECONDARY ROAD TO TUNCTION. - THEN S.W.'LY
 0.1 MILE - CORNER IS 500' E WEST OF ROAD
 UP EAST SLOPE ON EDGE OF RIDGE-TOP

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.;



Permanent Mon. Set/Fd.

Searched By:

C.W. COOK

Title

PLS

Division

Headquarters

Date

4-85


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" ALUM. PIPE w/ 2 1/2" ALUM. CAP

18" IN GROUND IN OLD MOUND OF ROCK

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW B.T.'s WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE S50°W - 13.9' "1/4 S9 BT"

10" P. PINE N25°E - 35.3' "1/4 S4 BT"

6' F.G. POSTS 2.8' NORTH & 3.4' WEST w/ DECALS "BM-102" & "LSM-130"

ALL B.T.'S HAVE TAGS S4-3, S4-4 - NEW B.T.'S HAVE 60D NAIL & 1 1/2" ALUM. DISK "PLS 1098"

@ SIDE-CENTER BASE - S.W. ORIG. HAS 60D NAIL @ TOP-CENTER - N.W. ORIG @ SIDE-CENTER

Work Done By: C.W. COOK Title: SURVEYOR Date: 4-85 State Registration No. or Agency: PLS 1098

Plat or Record Prepared? ☒ Yes ☐ No Filed At: KLAM Co. Surveyor's Office Date: 11

History of G.L.O. - H. MELDRUM - 1879

16" PINE N5°W - 48 LKS.

G.L.O., 40" PINE S13°W - 146 LKS.

etc.

12

Index File No.

1155

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

E-11

13

Index

File No. 1255


CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N Cor. No. E-12T 25 S. R. 10 E. R.D. CRESCENTCounty KLAMATHMerid. WillametteN.F. DeschutesState OregonE'1/6 Cor. of Section 4

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

PROCEED S.W.'LY ON SPUR RD. # 800 TO
 MARKED BOUNDARY LINE IN DRAW- CORNER
 IS 300'± WEST UP EAST SLOPE

Searched By: _____

Title _____

Division _____

Headquarters _____

Date _____


CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

26" IN GROUND

MONUMENT STAMPED



ACCESSORIES. DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" P. PINE N64°E - 48.8' "E 1/4 S4 BT"

11" P. PINE S31°E - 140.1' "E 1/4 S9 BT"

6' F.G. POSTS 1.8' NORTH / 1.8' EAST w/ DECALS "BM-102" & "SM-110"

D.T.S HAVE TAGS 54-3, 54-7, 60D NAIL w/ 1 1/2" ALUM-DISK "R51098" @ SIDE-CENTER BASE

Work Done By C.W. COOK Title SURVEYOR Date 5-85 State Registration No. PLS 1098
or Agency

Plat. of Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

History of
Surveys,
G.L.O.,
etc.

MELDRUM - 1879

Index File No.

1255

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

E-12

Index

File No. 1355

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149CABN

Cor.

No. E-13T 25 S. R. 10 E.R.D. CRESCENT

County

KLAMATH

SEC.

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 4139110

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

POST

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

24" x 4' HIGH PINE STUMP N32°E - 26.0' SCRIBE "BT" VISIBLE

30" x 4' HIGH PINE STUMP N35°W - 50.5' NO SCRIBES

52" x 30" HIGH PINE STUMP S60°W - 43.7' SCRIBES VISIBLE

28" x 12" HIGH PINE STUMP S37°E - 39.0' NO SCRIBES

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM JUNCTION OF SPUR RDS #800 & #850 TAKE
ROAD SOUTH 0.6 MILE - 4x4 POST & TACS ON

EAST EDGE ROAD #2573 IS 293' WEST OF CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

C.W. COOK

Title

PLS

Division

Headquarters

Date

4-85


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

26" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

11" P. PINE N64°E - 50.3' "T255R10E S3 BT"

PROPER TAGS - ALL B.T.'S

9" P. PINE N9°W - 36.1' "T255R10E S4 BT"

60D NAIL w/ 1 1/2" ALUM. DISK

6" P. PINE S62°E - 71.6' "T255R10E S10 BT"

"RS 1098" ON NEW B.T.'S

9" P. PINE S36°W - 50.7' "T255R10E S9 BT"

6' F.G. POSTS 3.0' EAST & 2.8' WEST w/ DECALS "BM-102" LSM-1X0"

10

Work Done By: C.W. COOK Title: SURVEYOR Date: 4-85 State Registration No. or Agency: PLS 1098

Plat. or Record Prepared? ☒ Yes ☐ No Filed At: KLAM. Co. Surveyor's Office Date: 11

History of G.L.O. - MEMORUM - 1879

20" PINE N34°E - 39 LKS.

40" PINE N33°W - 75 LKS.

60" PINE S62°W - 65 LKS.

30" PINE S38°E - 61 LKS.

12

Index File No.

1355

T. 25 S., R. 10 E., W.M.

Contract or Surv. No.

5304H1976A8N

Cor.

E-13

13

USDA-FOREST SERVICE D-7100-52(2/82)

Index
File No. 1555

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648

Cor.

T 25 S. R. 10 E. R.D. CRES.

Merid. Willamette

N.F. Deschutes

County KLAM.

State Oregon

1/4

Cor. of

Section 3
10

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other

☐ Searched For/Not Found

☒ Evidence Found/Accept.

☒ Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 68' SOUTH OF ROAD ON
RIDGE-TOP (CRS. S50°W x N50°E)
SEE MAP FOR ACCESS

Searched By: C.W. COOK

Title LS

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

29" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" P. PINE NS2°E - 26.1'

14" P. PINE S18°W - 22.7'

6' F.G. POSTS 2.6' NORTH & 2.6' WEST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat OF Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History of Surveys, G.L.O., etc.
H. MECLORUM - 1879

12

Index File No

1555

T.25 S., R. 10 E., W.M.

Contract or Surv. No

6304H149648N

Cor.

E-15

13

USDA-FOREST SERVICE D-7100-52(2/82)

Index

File No. 1755

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N No. E-17T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. DeschutesCounty KLAM.State OregonSEC. Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

NONE - EXCEPT 1/2" I.R. 4.3' WEST OF
MY RESTORATION (NOT OF RECORD)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

26"x1' HIGH PINE STUMP N45°E-35.9' TOP CENTER (ORIG.)

26"x1' HIGH PINE STUMP N27°W-62.6' TOP CENTER (ORIG.)

30" P. PINE S55°W-34.1' SIDE-CENTER (ORIG.)

26" DEAD & DOWN PINE - ROOT STUB IN PLACE - SIZE-30.7' TO
EST. CENTER (ORIG.)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 11' SOUTH OF GROWN-UP
LOOP ROAD - SEE MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2"x30" ALUM. PIPE w/2 1/2" ALUM. CAP 26" IN
GROUND @ RECORD FROM ORIG. FACES OR EST. FACES
OF S.E., S.W., & N.E. B.T.s (N.W. APPEARS TO BE MIS-CHAIN)

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW B.T.s WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" P. PINE N29°E - 26.3'
9" P. PINE N43°W - 35.9'
6" P. PINE S80°E - 50.5'
6" F.G. POST 1.5' NORTH

Work Done By C.W. COOK Title LS Date 4/85 State Registration No. PLS 1098
or Agency

Flat or Cor Record Prepared ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date

History of Surveys, G.L.O., etc.
H. MELDRUM - 1879 9" PINE N47°E - 53 LKS.
20" PINE N27°W - 70 LKS.
20" PINE S58°W - 50 LKS.
24" PINE S12°E - 45 LKS.

Index File No

1755

T.Z.S.S., R.10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

E-17

Index

File No. 1955

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)


Survey No. 5304H14968N Cor. No. E-19T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. DeschutesCounty KLAM.State OregonSection 1/4 Cor. of 2/11

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

 $\frac{1}{4}$ $\frac{2}{11}$

3



NONE

$\frac{1}{2}$ " IRON ROD N88 $\frac{3}{4}$ E -
27.89' w/M.R. - NOT OF RECORD

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS NEAR TOP OF HILL
WEST OF LOOP ROAD - SEE MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2"x30" G.I.P. w/2 1/2" BRASS CAP
29" IN GROUND w/MOUND OF ROCK

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE N21°W - 33.6'
6" P. PINE S78°W - 51.7'
6' F.G. POST 1.8' EAST

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Flat of Cor Record Prepared Yes No Filed At KLAM Co. Surveyor's Office Date

History of Surveys, G.L.O., etc. H. MECDRUM - 1879

Index File No
1955

T.25 S., R.10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. E-19

Index

File No.

2055

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149648N

Cor.

No. E-20

T 25 S. R. 10 E. R.D. CRES.

County

KLAM.

Merid. Willamette

N.F. Deschutes

State Oregon


Section

Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

E 1/4 2/11



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 15' WEST OF SKID ROAD
IN GULLY - 4x4 POST & K-TAG ON
ROAD 200' SOUTH OF CORNER - SEE MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
27" IN GROUND w/ MOUND OF ROCK

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE N86°W - 21.0'
10" P. PINE S16°W - 21.6'
6' F.G. POSTS - 2.7' NORTH & 2.2' SOUTH

10

Work Done By: C.W. COOK Title: LS Date: 8/85 State Registration No. or Agency: PLS 1098

Plat of Cor. Record Prepared? ☒ Yes ☐ No Filed At: KLAM Co. Surveyor's Office Date:

11

History
of
Surveys,
G.L.O.,
etc.

Index File No
2055

T.25S., R. 10E., W.M.

Contract or Surv. No
5304N149648N

Cor. E-20

12

13

Index

File No. 2155

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)


Survey No. 5304H149648N

Cor.

No. E-21T 25 S. R. 10 E. R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState OregonSEC. 21 Cor. ofSection 11/12

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND



ROTTED SUB-SURFACE PORTION OF POST IN CENTER OF
RING OF STONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

26" x 1' HIGH PINE STUMP N48°W-105.3' (ORIG.)

DEAD & DOWN BADLY ROTTED PINE N60°E-33' ± EST. (ORIG.)
(ROOT SYSTEM IN PLACE)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

30" x 1' HIGH PINE STUMP S18°E-38.4' (ORIG.)

28" x 45' SNAG UP-ROOT 30' ± EAST OF ORIG. POSITION

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 800' ± EAST OF SECONDARY
ROAD - SEE MAP

Searched By: _____

Title _____

Division _____

Headquarters _____

Date _____

CORNER RECORD (PERPETUATION)


MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2"x30" G.I.P. w/ 2 1/2" BRASS CAP

22" IN GROUND IN PLACE OF FOUND

PORTION OF ORIGINAL POST

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P. PINE N52°W - 59.0'

8" P. PINE S26 1/2°W - 54.5'

8" P. PINE N47°E - 48.0'

8" P. PINE S36°E - 71.1'

6' F.G. POST 1.8' EAST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat. of Cor. Record Prepared ☒ (Yes) No Filed At KLAM. Co. Surveyor's Office Date

11

History of Surveys, G.L.O., etc.
H. MELORUM - 1879 10" PINE N42°W - 158 LKS. (104.3')
14" PINE N68°E - 50 LKS. (33.0')
18" PINE S18°E - 58 LKS. (38.3')
18" PINE S25°W - 55 LKS. (36.3')

12

Index File No
2155

T.25 S., R. 10 E., W.M.

Contract or Surv. No
5304H/49648N

Cor. E-21

13

Index

File No. 2255


CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H196ABN Cor. No. E-22T 25 S. R. 10 E.R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState OregonW $\frac{1}{4}$ Cor. of Section 12

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 500' E N.W. OF
ROAD - 4x4 POST & K-TAG ON ROAD -
SEE MAP

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Pd.

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w / 2 1/2" BRASS CAP

28" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" L.P. PINE N28°E - 13.8'

8" L.P. PINE 559°W - 28.0'

4" P. PINE N36°E - 37.45'

5" P. PINE S18°W - 9.5'

C' F.G. POSTS 2.1' EAST & 2.2' SOUTH

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098 or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAMCO, Surveyor's Office Date

History of Surveys, G.L.O., etc.


Index File No T25 S., R.10 E., W.M. Contract or Surv. No 5304H149648N Cor. E-22
2255

LAND CORNER RECORD

E-23 5680-2

1. T. 25S R. 10E No. 2355 Cor. 1/4 Mer. W State Oregon (Rectangular) N. F. Deschutes Dist. Crescent

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument X

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: 1/4 Section corner common to Sections 1 and 12
Original notes:

"Set post for 1/4 sec. cor.; from which:

(1) A pine, 15 ins. diam., bears S50°E, 50 lks. dist.

(2) " " , 9 " " " N34°E, 58 " "

5. Investigation Notes:

At the corner I found bearing tree number 1 to be a down, very badly decayed snag. I found no trace of number 2. I located the corner and blazed and scribed two new bearing trees.

6. Signed M. HEATH Title S.T.

Date 6/28/83
July 1966

PERPETUATION RECORD

10. Monument: I monumented the corner with a 2 inch galvanized iron pipe w/brass cap, 30 inches long, set 24 inches into the ground, and marked it:

T25S R10E

1/4 $\frac{S1}{S12}$

~~11. Accession~~ From which: 7 Reg. No. 622

A lodgepole pine, 8 inches in diameter, scribed 1/4S1BT, bears N13°W, a distance of 14.9 feet to a 60d nail in the base of the tree.

A lodgepole pine, 18 inches in diameter, scribed 1/4S12BT, bears S39°W, a distance of 3.9 feet to a 60d nail in the base of the tree.

NOTE: NAILS IN FACE

Field Book _____ Page _____

12. Set By Wm. Steers Title Land Surveyor
License ORE 622 Agency Gil.Tbr.Co. Date July 1966

13. Recorded By _____ Volume _____ Page _____
(Agency)

(Date) (City) (County) (State)

14. Remarks:

Index

File No. 2555

CORNER RECORD (SEARCH)

Contract or

Cor.

(Ref. FSM 7151.4)

Survey No.

No.


E-25T 25 S. R. 10 E. R.D. CRESCENTCounty KLAMATHSE

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 1SE

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

3 1/4" A.C. - RSG. 5 1/2"ORIG. POST - S7 R11E, S1 R10E, S12 T25S

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

10" P. PINE S74°W C 22° SCRIBED RIP !!! C 127" " S69°E C 60° " S7 BT"

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.


DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Searched By: S. CHAMBERLINTitle S.T.Division ENG.Headquarters S.O.Date 7/11/83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. _____
 Plat or _____ or Agency _____
 Certified Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History
 of
 Surveys,
 G.L.O.,
 etc.

Index File No. **2555** T. S., R. E., W.M.

Contract or Surv. No.

Cor. **E-25** 13

Index

File No.

0154

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or

Survey No.

Cor.

No.

F-01

T 25 S. R. 10 E.

R.D.

CRESCENT

County

KLANATH

N/16

Cor. of

Merid. WILLAMETTE

N.F.

DESCHUTES

State

OREGON

Section 7, W.L.N.

SEE: F-25

T. 25

S., R. 9

E.W.H.

BC

F-01

USDA-FOREST SERVICE D-7100-52(2/82)

Index
File No. 356

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N Cor. No. F-3

T 25 S. R. 10 E.

R.D. CRES.

County KLAM.

Merid. Willamette

N.F. Deschutes


State Oregon

CN'14 Cor. of
Section 7

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

CN'14 S7



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 300' ± SOUTH OF LOOP ROAD
OFF OF ROAD # 9760-600 ON NORTH SLOPE -
SEE MAP

CORNER LEGEND:

FS or	Unverified	
Contr.	Other	
☐	☐	Searched For/Not Found
☒	☒	Evidence Found/Accept.
☒	☒	Permanent Mon. Set/Pd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
26" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" P. PINE S15°E - 24.2'
7" P. PINE N72°W - 53.1'
6' F.C. POSTS 1.5' SOUTH & 2.2' EAST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Flat or Certified Cor Record Prepared ☒ Yes ☐ No Filed At KCAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No

356

T.25 S., R. 10 E., W.M.

Contract or Surv. No.

53044149648N

Cor.

F-3

12

13

Index

File No. 556


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or 5304H14964EN Cor.Survey No. 0534No. F-5T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. DeschutesCounty KLAMState OregonN $\frac{1}{4}$ Cor. ofSection 7/8

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

N $\frac{1}{4}$ 7/8

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SKID ROAD IS N60°W-25' (CRES. S.W.)

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" C.I.P. w/ 2 1/2" BRASS CAP
25" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE N46°E - 3.7'

11" P. PINE N48°W - 15.0'

6' F.G. POSTS 1.9' SOUTH & 2.6' WEST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat or Certified Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM-Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No

556

T.25 S., R. 10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

F-5

13

Index

File No. 2056

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N Cor. No. F-20T 25 S. R. 10 E.R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState OregonNE $\frac{1}{4}$ Cor. of
Section 11

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 81' NORTH OF ROAD -
 CRS. $555^{\circ}E \times N40^{\circ}W$ - SEE MAP

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.T.P. w/ 2 1/2" BRASS CAP
27" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE N16°E - 53.2'
10" L.P. PINE S3°W - 56.4'
6' F.G. POSTS 1.9' NORTH & 1.7' EAST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat. of Eor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No

2056

T. 25S., R. 10 E., W.M.

Contract or Surv. No.

5304H149648N

Cor.

F-20

13

Index

File No. 2156

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149648N

Cor.

No. F-21T 25 S. R. 10 E.

R.D.

CRES.

County

KLAM.Merid. Willamette

N.F.

Deschutes

State

Oregon

N'/16


Cor. of

Section 11/12

CORNER DIAGRAM, per legend

N'/16

11/12



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS ON EAST SLOPE250' ± N.E. OF CORNER OF LOOP ROADSEE MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
15" IN GROUND w/ MOUND OF ROCK

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" P. PINE - S34°W - 28.2'

8" P. PINE S53°E - 24.0'

6' F.G. POSTS 2.3' SOUTH & 3.3' WEST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No
2156

T.25 S., R.10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. F-21

12

13

Index
File No. 0157CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No.Cor. G-01
No.T 25 S. R. 10 E. R.D. CrescentCounty Klamath

W/4

Cor. of

Merid. WillametteN.F. DeschutesState OregonSection 7

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

BCSP (2½") rising 5"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

9" LP Pine brs N27°W @ 15.1 Ft. B/S 1/4 S12 BT

7" LP pine brs N85°E @ 48.0 Ft. B/S 1/4 S7 BT

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Compass and paced east from the center of Section 12.

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Steve Chamberlin ST

Title

Division
SurveyHeadquarters
SODate
7-5-83


4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Plat or Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History of Surveys, G.L.O., etc. _____
WOOD POST
16" S42°E @ 14.0 Ft
20" N78°W @ 6.6 Ft.

Index File No. 0157 T. S., R. E., W.M. Contract or Surv. No. Cor. G-01

Index

File No. 357T 25 S. R. 10 E. R.D. CRES.Merid. WillametteN.F. Deschutes

County

Contract or

Survey No. 5304H149648N

Cor.

No. G-3

State

OregonC1/4

Cor. of

Section 7

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS 95' ± SOUTH OF ROAD -
 COURSE N60°E - AT BOTTOM OF STEEP
 NORTH SLOPE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
27" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE S38°E - 70.4'
8" P. PINE N17°W - 56.3'
6' F.G. POSTS 2.1' EAST & 3.2' SOUTH

10

Work Done By: C.W. COOK Title: LS Date: 8/85 State Registration No. or Agency: PLS 1098

Plat or Cor. Record Prepared ☒ Yes ☐ No Filed At: KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No

357

T.25 S., R.10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

G-3

12

13

Index

File No. 557T ZS S. R. 10 E.Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Contract or 53041199648N Cor.Survey No. 53041199648N No. G-5County KLAMState OregonSection 7/8 Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

32" x 5' HIGH PINE STUMP N68°E-21.8' TO FACE

22.9' TO SIDE-CENTER (ORIG.)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or
Contr. Unverified
Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 10 1/2' NORTH OF ROAD #655
AND 60' WEST OF JUNCTION W/ROAD #700

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" ALUM. PIPE W/ 2 1/2" ALUM. CAP
28" IN GROUND. P RECORD DIST. FROM ORIG
N.E. B.T.

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW B.T.'s WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. PINE S6°E - 36.6'
6" P. PINE N41°W - 78.5'
6' F.G. POSTS 2.2' WEST & 2.6' NORTH

9

10

Work Done By C.W. COOK Title LS Date 6/85 State Registration No. PLS 1098
or Agency

Plat 1098 Certified or Record Prepared? ☒ Yes No Filed At KLAM. Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

H. MELDRUM - 1879

24" PINE N68°E - 33 LKS. (21.8')

5" PINE S63°W - 17 LKS. (11.2')

12

Index File No

557

T.25 S., R.10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

G-5

13

Index

File No. 957

CORNER RECORD (SEARCH) Contract or


(Ref. FSM 7151.4)

Survey No. 5304H149648 Cor. No. G-9T 25 S. R. 10 E.R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState Oregon1/4

Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

Section 8/91/4 8/9

POST - ROTTED OFF UPPER PORTION MARKED "1/4S", "59",
 "1/4S", "58" - REMAINS OF LOWER PORTION IN
 RING OF STONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

BURNT REMAINS OF SHELL & ROOT-SYSTEM
 N30°E-61'± TO ESTIMATED FACE (ORIG.)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

26" PINE SNAG UP-ROOT N56°W-33.5' TO
 ESTIMATED FACE (ORIG.)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 150'± NORTH OF SECONDARY
 ROAD # 657 - CORNER IS VISIBLE
 FROM ROAD

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
24" IN GROUND IN MOUND OF ROCK IN
PLACE OF ORIGINAL POST

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" P. PINE N50°W - 22.2'
7" P. PINE S43°E - 65.3'
6' F.G. POSTS 2.3' NORTH & 2.1' WEST

10

Work Done By C.W. COOK Title LS Date 6/85 State Registration No. PLS 1098
or Agency

Plat of OR For Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

H. MELDRUM - 1879

30" PINE N37°E - 89 LKS. (58.7')

30" PINE N56°W - 51? LKS. (33.7')

12

Index File No

957

T. 25 S., R. 10 E., W.M.

Contract or Surv. No

5304H/149648N

Cor.

G-9

13

Index

File No.

1757

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149C48A

Cor.

No. B-17

T 25 S. R. 10 E.

R.D.

CRES.

County

KLAM.

Merid. Willamette

N.F.

Deschutes

State


Oregon

1/4

Cor. of

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND



NONE (1/2" I.R. 376°W-9.46'
FROM MY RESTORATION - NOT OF RECORD)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

20" x 18" HIGH PINE STUMP S52°W-17.7' (ORIG.)
31" P. PINE N77°E-38.6' (ORIG.)

17.2 TO FACE
38.3 TO FACE

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

CORNER LEGEND:

FS or Unverified
Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

ROAD IS EAST-44' CRS. N30°E x S20°W
CORNER FALLS ON WEST SLOPE
SEE MAP FOR ROAD ACCESS

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2"x30" G.I.P. w/2 1/2" BRASS CAP

28" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9" P. PINE N40°W - 46.6'

6" P. PINE N44°E - 58.2'

6' F.G. POST 1.8' S.E.

10

Work Done By C.W. COOK Title LS Date 6/85 State Registration No. PLS 1098
or Agency

Plat or Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

H. MECORUM - 1879

15" PINE S59°W - 26 LKS. (17.2')

15" PINE N78°E - 58 LKS. (38.3')

12

Index File No

1757

T.25 S., R.10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

G-17

13

Index

File No. 1957

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149698

Cor.

No. G-19T 25 S. R. 10 E.

R.D.

CRES

County

KLAM.Merid. Willamette

N.F.

Deschutes

State

Oregon

C/A

Cor. of

CORNER DIAGRAM per Legend

DESCRIBE CORNER MONUMENT FOUND

Section 11

C/A 11

1/2" IRON ROD S71°E-75'
(NOT OF RECORD)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 100' WEST OF ROAD
ON RIDGE-TOP - SEE MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

12" P. PINE S71°W - 28.4'
5" P. PINE S61°E - 61.1'
6' F.G. POST 1.7' SOUTH

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat or Cor Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No
1957

T25 S., R. 10 E., W.M.

Contract or Surv. No
5304H/49648N

Cor. G-19

12

13

USDA-FOREST SERVICE D-7100-52(2/82)

Index

File No. 2057

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H196A8A

Cor.

No. G-20T 25 S. R. 10 E.

R.D.

CRES.

County

KLAM.Merid. Willamette

N.F.

Deschutes

State

Oregon

CE'16 Cor. of

Section 11

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

CE'16 11

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 28 1/2' WEST OF ROAD -
CRES. N45°E x S45°W - SEE MAP

Searched By:

Title

Division

Headquarters

Date


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP

29" IN GROUND

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

14" P. PINE S76°W - 23.0'

10" P. PINE N4°E - 67.6'

6' F.G. POSTS 1.9' EAST & 2.4' SOUTH

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat DE
Certified For Record Prepared? ☒ Yes No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No
2057

T. 25 S., R. 10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. G-20

13


LAND CORNER RECORD

5680-2

1. T. 25S R. 10E No. G-21 Cor. 1/4 Mer. W State Oregon (Rectangular) N. F. Deschutes

G-21
Dist. Crescent

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

1/4 Section corner common to Sections 11 and 12

Original notes:

"Set post for 1/4 Sec. cor. ~~common to Section~~ from which:

(1) A pine, 16 ins. diam., bears S38°E, 88 lks. dist.

(2) " 24 " " N83°W, 65 "

5. Investigation Notes:

At the corner I found bearing tree number 1 to be in good condition, number 2 was missing. I located the corner and blazed and scribed one new bearing tree.

7-5-83 Tree #1 33" P. Pine

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument X

Re-estab. _____ Survey _____

Land Status _____

6. Signed R Taylor Title Land Surveyor

Date 7-5-83 July 1966

PERPETUATION RECORD

Alum Cap on 2 1/2" Alum. Pipe RS630

10. Monument: I monumented the corner with a 2 inch galvanized iron pipe w/brass cap, 30 inches long, set 24 inches into the ground, and marked it:

STEERS' CAP
NOT MFD.

~~T25S R10E~~
~~1/4~~
~~S11 S12~~
~~Reg. No. 622~~

T25S R10E
1/4
S11 S12
1983
RPLS 1846

11X Accession

From which:

A ponderosa pine, 5 inches in diameter, scribed 1/4 S11 BT, bears N17°W, a distance of 11.7 feet to a 60d nail in the base of the tree.

(1) A ponderosa pine, 30 inches in diameter, bears S38°E a distance of 56.6 feet to a 60d nail in the base of the tree.

Field Book _____ Page _____

12. Set By Wm. Steers Title Land Surveyor

License ORE 622 Agency Gil. Tbr. Co. Date 7-66

13. Recorded By _____ Volume _____ Page _____

(Agency)

(Date) (City) (County) (State)

14. Remarks:

Cor. located 300' ± W of Rd

2157

G-21

Index

File No. 2257

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648A

Cor.

No. G-22T 25 S. R. 10 E. R.D. CRES.

County

KLAM.Merid. Willamette

N.F.

Deschutes

State

OregonCW 1/4 Cor. of
Section 12

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

CW 1/4 12



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS 100' NORTH OF ROAD -CRES. S80°W x N80°E -SEE MAP - 4x4 POST & K-TAG ONMAIN ROAD WEST OF CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
28" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

5" P. PINE N14°E - 32.0'
13" P. PINE N78°E - 39.1'
6' F.G. POSTS 1.9' NORTH { 2.1' WEST

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

12

Index File No
2257

T.25 S., R. 10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. G-22

13

Index

File No. 2357

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149648N

Cor.

G-23T 25 S. R. 10 E. R.D. CRES.County KLAM.Merid. WillametteN.F. DeschutesState Oregon

C/4 Cor. of

Section 12

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

C/4 12

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

CORNER FALLS ON WEST EDGE OF
 PARTIAL-CUT - ROAD IS 200' +
 WEST - SEE MAP

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
27" IN GROUND

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" L.P. PINE N70°E - 38.8'
6" L.P. PINE N37°W - 51.9'
6' F.G. POSTS 2.0' NORTH & 1.9' SOUTH

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat or Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No
2357

T25 S., R10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. G-23

12

13

Index

File No.

2557

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

Cor.

No.

G-25

T 25 S. R. 10 E.

R.D. CRESCENT

County KLAMATH

E 1/4

Cor. of

Merid. Willamette

N.F. Deschutes


State Oregon

Section 12

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

3 1/2" ALUM. CAP, RSG. 3"



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DOWN BURNED LOG - N 63° E @ 20° FT.

30" STUMP - N 81° W @ 5° FT. (HEALED OVER)

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

245' SOUTH OF B.C. FOR W 1/4 S7, 155' EAST OF
RD. W/SIGN BOARD

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By: S. CHAMBERLIN

Title

S.T.

Division

ENG.

Headquarters

S.O.


Date

7/11/83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

6" P.PINE - N82°E @ 57⁴ FT - SCRIBED S1 BT W/NAIL & WASHER IN FACE
 6" " - S56°W @ 45° " - " S12 BT " " " "

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 Plat or _____
 Certified Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

11

History
 of
 Surveys,
 G.L.O.,
 etc.

12

Index File No. 2557 T. S., R. E., W.M.

Contract or Surv. No.

Cor. G-25 13

Index

File No. 1958

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149648

Cor.

H-19T 25 S. R. 10 E.R.D. CRS.

County

KLAM.Merid. WillametteN.F. DeschutesState Oregon

CS'1/4 Cor. of

Section 11

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

CS'1/4 S11

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

CORNER FALLS ON WEST EDGE
OF ROAD - CRS. $N120^{\circ}E \times S30^{\circ}W$ -
SEE MAP

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/2 1/2" BRASS CAP
20" IN GROUND w/ RING OF STONE

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

19" P. PINE S78°E - 48.6'
12" P. PINE N72°W - 24.8'
6' F.G. POSTS 1.0' EAST & 1.8' SOUTH

9

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of OR Certified for Record Prepared? ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No

1958

T25 S., R10 E., W.M.

Contract or Surv. No

5304H149648N

Cor.

H-19

12

13

Index

File No. 2058

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No.

5304H149648N

Cor.

No. H-20T 25 S. R. 10 E.

R.D.

CRS.

County

KLAMMerid. Willamette

N.F.

Deschutes

State

OregonSE 1/4

Cor. of

Section 11

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

SE 1/4 11

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.:



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS AT TOP OF STEEPN.W. SLOPE - 4x4 POSTS & K-TAGSON ROAD WEST & NORTH OF CORNER

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2" x 30" G.I.P. w/ 2 1/2" BRASS CAP
3" IN GROUND w/ MOUND OF ROCK

MONUMENT STAMPED



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" L.P. PINE S24°W - 37.9'
6" L.P. PINE S65°E - 33.9'
6' F.G. POSTS 9.4' NORTH & 11.2' WEST

9

10

Work Done By C.W. COOK Title LS Date 8/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

Index File No
2058

T.25S., R.10E., W.M.

Contract or Surv. No
53044149648N

Cor. H-20

12

13

Index
File No. 0159

CORNER RECORD (SEARCH)

Tract or
Survey No. _____


Cor.
No. J-1

T 25S. R. 10E.
Merid. Will

R.D. Crescent County Klamath
N.F. Deschutes State Oregon

SW Sec Cor Sec 7

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

SEE T25S., R9E., W.M. J-25

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

J-01

13

Index

File No. 359

CORNER RECORD (SEARCH)

Contract or

(Ref. FSM 7151.4)

Survey No.

5304H/49648

Cor.

No.

J-3T 25 S. R. 10 E.

R.D.

CRES.

County

KLAM.1/4

Cor. of

Merid. Willamette

N.F.

Deschutes

State

Oregon

Section

7

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

1/4 7/18POST - ROTTED UPPER PORTION SCRIBED "1/45" "ST" "1/45" "SIB"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

21" PINE SNAG S74°W - 5.7' TO FACE (6.5' SIDE-CEN.) (ORIG.)26" x 5' HIGH PINE STUMP N47°E - 4.0' TO FACE4.8' TO SIDE-CENTER (ORIG.)

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS 300' ± EAST OF END OF
SPUR # 660 ON SLIGHT N.E. SLOPE

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

PS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters


Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2" x 30" ALUM. PIPE w/ 2 1/2" ALUM. CAP
29" IN GROUND @ RECORD DIST. FROM ORIG.
B.T. FACES.

MONUMENT STAMPED



9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" P. PINE S1°W - 31.7'
13" P. PINE N77°E - 65.7'
6' F.G. POSTS 2.1' WEST & 2.1' NORTH

10

Work Done By C.W. COOK Title LS Date 6/85 State Registration No. PLS 1098
or Agency

Plat of Cor. Record Prepared? ☒ Yes ☐ No Filed At KLAM. Co. Surveyor's Office Date

11

History
of
Surveys,
G.L.O.,
etc.

N. MELDRUM - 1879
30" PINE S73°W - 9 LKS. (5.9')
30" PINE N47°E - 6 LKS. (4.0')

12

Index File No

359

T.25 S., R.10 E., W.M.

Contract or Surv. No

5304H149648N


Cor.

J-3

13

Index
File No. 0559 CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 5-05
T 25 S. R. 10 E. R.D. CRESCENT County KLAMATH SE Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 7

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

2 1/2" ALUM CAP, RSG. 4"
STEEL POST 1.5' SOUTH W/ATN SIGN

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

(ORIG) 29" P.PINE - S60°E @ 38' (CLOSED FACE) ALUM. NAIL IN N. BASE
(ORIG) 60" " STUMP (2' HIGH) IN N.E. LOCATION

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

(ORIG) 31" " - S68°W @ 41' Scribed T255 RIDE S8 ET - ALUM NAIL N. BASE
(ORIG) 14" L.P. PINE - N36°W @ 11' w/ORIG. POST @ BASE
ALUM NAIL W. BASE

29" P.PINE - S42°W Scribed T255 RIDE S18 BT ROOF NAIL w/WASHER

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SET LOC. TAG. 260' EAST ON RD. # 9407, COR. LIES 260' W.

ON TOP OF HILL

CORNER LEGEND:

FS or Unverified
Contr. Other

○ ◇ Searched For/Not Found

⊗ ⊗ Evidence Found/Accept.

● ◆ Permanent Mon. Set/Fd.

NOTE: SEEMS TO BE SOME CONFUSION IN BEARINGS BETWEEN

WHAT CREW FOUND & THE ORIG. CALLS.


Searched By: R. TAYLOR

Title S.T. Division ENG. Headquarters S.O. Date 7/7/83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
 Plat or _____ or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

11

History 20" PINE - N60°W - 89 LKS
 of 75" " - N23°E - 87 "
 Surveys, 5" " - S36°E - 17 "
 G.L.O., 5" " - S42°W - 48 "
 etc. 5" " - S42°W - 48 "

12

Index File No 0559 T. S., R. E., W.M.

Contract or Surv. No.

Cor. J-05 13

Index
File No. 0759 CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. 5-07
T 25 S. R. 10 E. R.D. KLAMATH CRES. County KLAMATH S 1/4 Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 8

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

2 1/2" ALUM. CAP, RSG. 5"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

(ORIG) DOWN LOG - S 5° W @ 46° FT SCRIBED 'BT'11" W. PINE - S 8° W @ 56° " " 1/4 517 BT12" P. " - N 87° W @ 43° " " 1/4 58 BT

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

TREES IN GOOD SHAPE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

280' SOUTH OF SIGN BOARD

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division


Headquarters

Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Plat or _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

11

History of Surveys, G.L.O., etc.
 10" PINE - S5°W @ 46' FT (70 LKS.)
 16" " - N32E @ 23' " (35 ")

12


Index File No. 0759 T. S., R. E., W.M. Contract or Surv. No. Cor. J-07

13

Index
File No. 0959CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No. _____Cor.
No. J-09T _____ S. R. _____ E. R.D. _____ County _____ SE Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 8

CORNER DIAGRAM per legend

DESCRIBE CORNER MONUMENT FOUND

2 1/2" B.C., RSG. 3"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

25" P. PINE - N41°W @ 72° FT SCRIBED T255 RIDE S8 BT
28" " - S60°W @ 25° " SCRIBE HEALED (PROB. ORIG.)
33" " - S62°E @ 46° " " T255 RIDE S16 BT
8" " - N12°E @ 19 1/2 " " T255 RIDE S9 BT

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____

STUMP - S63°E @ 15 1/2 FT SCRIBED " "

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature _____

STUMP N48°E @ 59 1/2 FT SCRIBED " " 15 FT
" S29°E @ 33° FT BLADE ONLY

CORNER LEGEND:

FS or Unverified
 Contr. Other
☐ ☐ Searched For/Not Found
☒ ☒ Evidence Found/Accept.
☒ ☒ Permanent Mon. Set/Fd.

Searched By: _____

Title _____

Division _____


Headquarters _____

Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE


Work Done By _____ Title _____ Date _____ State Registration No. _____
 Plat or Certified Cor. Record Prepared ? Yes No Filed At _____ Co. Surveyor's Office Date _____

History 20" PINE - N48°E @ 90 LKS
 of 20" " - N29°W @ 51 LKS
 Surveys, 16" " - S60°W @ 39 "
 G.L.O., 16" " - S60°W @ 39 "
 etc. 40" " - S68°E @ 23 LKS.

Index File No. 0959 T. S., R. E., W.M. Contract or Surv. No. _____ Cor. J-09

Index
File No. 1359 CORNER RECORD (SEARCH). Contract or
(Ref. FSM 7151.4) Survey No. _____Cor.
No. J-13T 25 S. R. 10 E. R.D. CRESCENT County KLAMATH SE Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 9

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

ALUM. CAP/PIPE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

P. PINE STUMP - N 76° E @ 42.2'" " " - S 59° E @ 71.3'" " " - S 69° W @ 83.8'

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LEGEND:

FS or Unverified

Contr. Other



Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

Searched By:

Title

Division

Headquarters

Date

W. MILLERLSCSSO6/84


CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" A.C. - RSG. 1"

FENCE POST W/PROP. BOUNDARY AND ATTENTION SIGN 2' S,
LINE POSTED TO SOUTH.

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10"	P. PINE	- N 77°E @ 72 ⁶⁵	- T25S R10E S10 BT -	BRASS WASHER	IN BT BLAZE				
6"	"	- S 17°E @ 95 ¹⁵	- T25S R10E S15 BT -	"	"	"	"	"	"
8"	"	- S 26°W @ 67 ²¹	- T25S R10E S16 BT -	"	"	"	"	"	"
14"	"	- N 48°W @ 53 ⁷⁶	- T25S R10E S9 BT -	"	"	"	"	"	"

Work Done By _____	Title _____	Date _____	State Registration No. or Agency _____
Plat or _____	Certified Cor. Record Prepared ? Yes No	Filed At: _____	Co. Surveyor's Office Date _____

History
of
Surveys,
G.L.O.,
etc.

Index File No.

1359

T. S., R. E., W.M.

Contract or Surv. No.

Cor.


J-13

12

13

Index
File No. 1759CORNER RECORD (SEARCH) Contract or
(Ref. FSM 7151.4) Survey No.Cor. J-17
No.T 25 S. R. 10 E. R.D. Crescent County Klamath NW Cor. of
Merid. Willamette N.F. Deschutes State Oregon Section 14

CORNER DIAGRAM per legend



DESCRIBE CORNER MONUMENT FOUND

2½" Alum. Cap an Alum. Pipe Rising 2" in a rock mound.

Steel post 3.0 Ft. South with boundary and attention signs.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

34" P. pine stump, 4' high scribing visible.

6 18" P. Pinebrs N73°W @ 45.13 Ft. blaze healed over.

29" " " " N19°W @ 68.5 Ft. " " " , w/ nail N side.

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

7 Located on East side of ridge. Many spur roads up and down ridge.

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.


Searched By: Ross Taylor

Title
STDivision
SurveyHeadquarters
SODate
7-7-83

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAMPED



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

7" P. Pine brs S46°W @ 104.07 Ft. B/S T25S R10E S15 BT, with 16D nail/washer in E face.

9" " " " N59°W @ 105.50 Ft. " T25S R10E S11 BT, " " " " " W "

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Plat or Cor. Record Prepared ? Yes No Filed At: _____ Co. Surveyor's Office Date _____

History
of
Surveys,
G.L.O.,
etc.

36" Pine S62°W 71 lks (46.86 Ft.)

10" " N17°W 106 lks (69.96 Ft.)

20" " N57°E 67 lks (44.22)Ft.)

7" " S72°E 70 lks (46.20 Ft.)

Index File No. 1759 T. S., R. E., W.M. Contract or Surv. No. Cor. J-17

Index

File No. 1959

CORNER RECORD (SEARCH) Contract or

(Ref. FSM 7151.4)

Survey No. 5304H149648N

Cor.

No. J-19T 25 S. R. 10 E.

R.D.

CRES.

County

KLAM.Merid. Willamette

N.F.

Deschutes

State

Oregon

Section

Cor. of

14

CORNER DIAGRAM, per legend

DESCRIBE CORNER MONUMENT FOUND

 $\frac{1}{4}$ $\frac{11}{14}$ 2" G.I.P. w/ 2 1/2" BRASS CAP

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DEAD & DOWN BADLY ROTTEN PINE N77°E - 18' ± (ORIG.)11" DEAD L.P. PINE N59°E - 42.5' (STEERS-1983)14" DEAD L.P. PINE S39°E - 13.5' (STEERS-1983)

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

CORNER LEGEND:

FS or Unverified
Contr. Other

Searched For/Not Found



Evidence Found/Accept.



Permanent Mon. Set/Fd.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS 30' ± EAST OF ROAD -CRES. S10°W x N10°E -SEE MAP - (4x4 POST & K-TAG ON ROAD)

Searched By: _____

Title _____

Division _____

Headquarters _____


Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

CLEARED BRUSH & DEBRIS - RED PAINT
BAND ON ALL B.T.S.

MONUMENT STAMPED



9

ACCESSORIES: DESCRIBE NEW B.T.'s WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

4" P. PINE N54°E - 58.2'
8" L.P. PINE S20°E - 67.0'
6' F.G. POSTS 2.3' NORTH & 1.4' WEST

10

Work Done By C.W. COOK Title LS Date 7/85 State Registration No. PLS 1098
or Agency

Plate of Cor. Record Prepared ☒ Yes ☐ No Filed At KLAM Co. Surveyor's Office Date

11

History of Surveys, G.L.O., etc.
14. MELDORUM - 1879 (~~RESTORATION~~) W. STEERS - 1983
9" PINE N77°E - 27 LKS. (17.8') 10" L.P. PINE N59°E - 42.3'
14" PINE S7°E - 40 LKS. (26.4') 12" L.P. PINE S39°E - 12.9'

12

Index File No
1959

T. 25 S., R. 10 E., W.M.

Contract or Surv. No
5304H149648N

Cor. J-19

13

Index

File No. 2059

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or

Survey No. _____

Cor.

No. J-20T 25 S R. 10 ER.D. CrescentCounty KlamathE 1/4 Cor 1Merid. WillametteN.F. DeschutesState OregonSec. 11 & 14

CORNER DIAGRAM

N
↑

DESCRIBE CORNER MONUMENT FOUND

Working corner
wood post 2 1/2" -
post on the grd.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature

Means - Erikson

Title

Division

Headquarters

Date

D-2

8/75

7100-52-(3/68)

Index


File No. 2059

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. J-20T 25 S R. 10 ER.D. CrescentCounty KlamathE 1/16 Cor 1Merid. WillametteN.F. DeschutesState Oregonc Sec. 11 & 14

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Working corner
wood post 2 1/2" -
post on the grd.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

none

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Means - Erikson

Title

Division

Headquarters

D-2

Date

8/75

7100-52 (3/68)

USDA-FOREST SERVICE

Index

File No. 2159

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or


Survey No. _____

Cor.

No. J-21T. 25 S. R. 10E. R.D. CRESCENTCounty KLAMATHSE COR. of SEC. 11Merid. WILLAMETTEN.F. DESCHUTESState OREGON

COR. of SEC. _____

CORNER DIAGRAM PER LEGEND



DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

18" PINE BRS. S62°W @ 90 IKS - ROTTED STUMP48" PINE BRS S17°E @ 68 IKS - HIGH STUMP

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Spur Rd 200'± W of Cor" " 200'± E " "

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent MonumentSignature JOHN J. JANNTitle STPLSDivision CSHeadquarters SOGTCDate 7-5-87


D-7110-52 (3/79)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

32" x 2" STEEL PIPE WITH BRASS CAP RISING 6"
 ABOVE GROUND STAMPED...
 Steel Post 42 S w/ Htn. & Bdry. signs

MONUMENT STARTED



ACCESSORIES DESCRIBE NEW B's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A.P. PINE, 57" dia, brs. S 5° 15' W	23 ⁴ FT	mkd. S 14 BT
A.P. PINE, 15" dia, brs. N 57° W	39 ² FT	mkd. S 11 BT
A.P. PINE, 27 1/2" dia, brs. N 34° E	39 ⁵ FT	mkd. S 12 BT
A.P. PINE, 35" dia, brs. S 40° 30' E	57 ⁵ FT	mkd.

DIST MEASURED TO A #60 NAIL AT BASE OF BLAZES.

10

Work Done By JOHN SHINN Title PLS Date _____ State Registration No. 1846
 or Agency _____
 PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes ☐ No ☐ Filed At _____ Co. SURVEYOR'S OFFICE Date _____

11

REMARKS

CARD REVID FROM D-2 FILES 4/82

12

Index File No. 2159 T. S, R. E, W. M. Tract or Surv. No. Cor. J-21

13

Index
File No. 2359

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or
Survey No. _____Cor.
No. J-23T. 25 S. R. 10 E.R.D. CRESCENT

County

KLAMATH5/4COR. of SEC. 12Merid. WILLAMETTEN.F. DESCHUTES

State

OREGON

COR. of SEC. _____

CORNER DIAGRAM PER LEGEND




PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

Corner Legend:

- ☐ Searched for/Not Found
- ☒ Evidence Found/Accept.
- ☒ Permanent Monument

DESCRIBE CORNER MONUMENT FOUND

SF/NF

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

20" PINE BRS. S 23° E 28 LKS DIST. HIGH
STUMPED - SCRIBING VISIBLE

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Located 20'S & 300'W of spur RdsSignature R Taylor 65JOHN SHINN

Title

SF

Division

CS

Headquarters

SO

Date

7-5-79
D-7100-52 (3/79)PLSGTC

1

5


CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

32'x2" BC/SP RISES 6" ABOVE GROUND STAMPED

Set Cassinite 3 E. w/BM 102
30 N " " "

MONUMENT SET



ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

ALPINE, 3 ins. dia, brs. N38°30'W	15 FT	mkd.	
ALPINE, 36 ins. dia, brs. S.65°30'W	36 FT	mkd.	1/4 SEC 13 RT
A, ins. dia, brs.		mkd.	
A, ins. dia, brs.		mkd.	

Work Done By: JOHN SHAW Title: PLS Date: _____ State Registration No. 1846
 or Agency _____
 Certified Cor. Record Prepared? ☒ Yes No Filed At: KLAMATH Co. SURVEYOR'S OFFICE Date _____

REMARKS
CARD REC'D 4/82 (FROM D-2 FILES)

Index File No. 2259 T. S., R. E., W. M. Tract or Surv. No. Cor. J-23

Index
File No. 2559
T 25 S R. 10 E
Merid. WMT

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No.

Cor.
No. J-25

R.D. CRESCENT
N.F. DES.

County KLAMATH
State OR.

Sec 12
NECN Sec 13 ONLY

CORNER DIAGRAM




PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER MONUMENT FOUND

2" Ø WOOD POST RSG. 4' 3 1/2" A.C. - RSG. 3"
SQD. & PTD. RED

ORIG. POST w/ SCRIBING LYING ON GROUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

POSS. BT BRG. S34W

7" W. PINE - S74W @ 32° SCRIBED T25S R10ES
10" P. " - S55°E @ 9° " T25S R11ES18 BT
14" W. " - N40°W @ 32° " T25S R11ES18 BT

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

300' SOUTH OF CC OF 7
12/13

Signature S. CHAMBERLIN Title S.T. Division ENG

Headquarters D-2 S.O. S.O.


Date 7/11/83
8/75 7100-52 (3 63)

MEANS & NELSON F/FT

CORNER RECORD (PERPETUATION)

MONUMENT
STAMPED:

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT



ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. 2559 T.

R.

M.

Tract or Surv. No.

Cor. J-25

USDA-FOREST SERVICE

Index

File No. 0161

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or

Survey No. _____

Cor.

No. 2-1T. 25S S. R. 10EE. R.D. CRESENTCounty KIAMATHW/4 COR. of SEC. 18Merid. WILLAMETTEN.F. DESCHUTESState OREGON

COR. of SEC. _____

CORNER DIAGRAM PER LEGEND

DESCRIBE CORNER MONUMENT FOUND

SEE T25S R9E L1

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

3

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

1

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

7

Corner Legend:

☐ Searched for/Not Found☒ Evidence Found/Accept.☒ Permanent Monument

Signature

C.K. Tyson

Title

Sun Tech

Division

Headquarters

Date

10/80


D-7100-52 (3/79)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

MONUMENT STAFFED



ACCESSORIES: DESCRIBE NEW BT's, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE


Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
PLAT PREPARED OR
 Certified Cor. Record Prepared? Yes No Filed At: **Co. SURVEYOR'S OFFICE** Date _____

REMARKS

Index File No. _____ T. _____ S., R. _____ E., W. M. _____ Tract or Surv. No. _____ Cor. **L-01** _____

Index
File No. 0163 CORNER RECORD (SEARCH) Tract or
Survey No. _____ Cor.
T 25S. R. 10E. R.D. Crescent County Klamath SW No. N-1
Merid. Will N.F. Deschutes State Oregon Sec Cor Sec 18

CORNER DIAGRAM



6
PO

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

8

DESCRIBE CORNER MONUMENT FOUND

SEE: T. 25S., R. 9E., W. 1M N-25

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52

REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No.

Cor.

N-01

13

Index

File No. 0165

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.

P.01

T 25 S. R. 10 E. R.D.

County KLAMATH

W/4 SEC 19


Merid. WILLAMETTE N.F.

DESCHUTES

State OREGON

WINEMA

T. 25 S.



SEE: T. 25 S - R 9 E

P-25

SOME ORIGINAL EVIDENCE
FOUND. (INCONCLUSIVE)

BC

P-01

Index
File No. 0167


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. R-01

T 25 S. R. 10 E. R.D. WINEMA NF. County Klamath SW Cor Sec 19

Merid. WILLAMETTE N.F. DESCHUTES State OREGON



T. 25. S.

SEE : R-25

T. 25 S - R 9 E.

B.C.

R-01